I tried different solutions in connecting my devices. When the WAX610 is booted, the GS105PE only gets 803.2af. The LED at Port 5 switches to orange.
At 2. And 3. – I deactivated the power supply on the GS308EP at the specific port.
Solution 4 works very well, but I can't use this.

1. **This was my plan - doesn't work**

```
        GS308EP
        /       \
   WAX610      GS105PE
```

2. **Connecting the WAX610 with a POE injector – doesn't work**

```
        GS308EP
        /       \
    POE
   injector
        \
     WAX610        GS105PE
```

3. **Connecting the GS105PE with a POE injector – doesn't work**

```
        GS308EP
        /       \
          POE
         injector
     WAX610        GS105PE
```

4. **Connection the WAX610 with the GS105PE – this works?!**

```
          GS308EP
              |
         _____
        /           \
   WAX610          GS105PE
```