Time	Priority	Description
2020-3-17, 17:45:33	Critical (3)	Received Response to Broadcast Maintenance Request, But no Unicast Maintenance opportunities received - T4 time out;CM-MAC=a0:04:60:c0:d2:a0;CMTS-MAC=00:bc:60:92:54:e9;CM-QOS=1.1;CM-VER=3.0;
2020-3-17, 17:46:00	Critical (3)	Unicast Ranging Received Abort Response - Re-initializing MAC;CM-MAC=a0:04:60:c0:d2:a0;CMTS-MAC=00:bc:60:92:54:e9;CM-QOS=1.1;CM-VER=3.0;
2020-3-17, 17:46:24	Critical (3)	Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=a0:04:60:c0:d2:a0;CMTS-MAC=00:bc:60:92:54:e9;CM-QOS=1.1;CM-VER=3.0;
2020-3-17, 17:46:24	Critical (3)	Unicast Maintenance Ranging attempted - No response - Retries exhausted;CM-MAC=a0:04:60:c0:d2:a0;CMTS-MAC=00:bc:60:92:54:e9;CM-QOS=1.1;CM-VER=3.0;
2020-3-17, 17:46:24	Critical (3)	16 consecutive T3 timeouts while trying to range on upstream channel 1;CM-MAC=a0:04:60:c0:d2:a0;CMTS-MAC=00:bc:60:92:54:e9;CM-QOS=1.1;CM-VER=3.0;
2020-3-17, 17:46:32	Critical (3)	Received Response to Broadcast Maintenance Request, But no Unicast Maintenance opportunities received - T4 time out;CM-MAC=a0:04:60:c0:d2:a0;CMTS-MAC=00:bc:60:92:54:e9;CM-QOS=1.1;CM-VER=3.0;
2020-3-17, 17:47:00	Critical (3)	Unicast Ranging Received Abort Response - Re-initializing MAC;CM-MAC=a0:04:60:c0:d2:a0;CMTS-MAC=00:bc:60:92:54:e9;CM-QOS=1.1;CM-VER=3.0;
2020-3-17, 17:47:26	Critical (3)	No Ranging Response received - T3 time-out;CM-MAC=a0:04:60:c0:d2:a0;CMTS-MAC=00:bc:60:92:54:e9;CM-QOS=1.0;CM-VER=3.0;
2020-3-17, 17:48:22	Critical (3)	Unicast Ranging Received Abort Response - Re-initializing MAC;CM-MAC=a0:04:60:c0:d2:a0;CMTS-MAC=00:bc:60:92:54:e9;CM-QOS=1.1;CM-VER=3.0;
2020-3-17, 17:48:24	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;;CM-MAC=a0:04:60:c0:d2:a0;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.0;CM-VER=3.0;
2020-3-17, 17:48:59	Critical (3)	Unicast Ranging Received Abort Response - Re-initializing MAC;CM-MAC=a0:04:60:c0:d2:a0;CMTS-MAC=00:bc:60:92:54:e9;CM-QOS=1.1;CM-VER=3.0;
2020-3-17, 17:49:01	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;;CM-MAC=a0:04:60:c0:d2:a0;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.0;CM-VER=3.0;
2020-3-17, 17:49:18	Critical (3)	No UCDs Received - Timeout;;CM-MAC=a0:04:60:c0:d2:a0;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.0;CM-VER=3.0;
2020-3-17, 17:49:19	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;;CM-MAC=a0:04:60:c0:d2:a0;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.0;CM-VER=3.0;
2020-3-17, 17:49:36	Critical (3)	No UCDs Received - Timeout;;CM-MAC=a0:04:60:c0:d2:a0;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.0;CM-VER=3.0;
2020-3-17, 17:49:37	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;;CM-MAC=a0:04:60:c0:d2:a0;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.0;CM-VER=3.0;
2020-3-17, 17:49:54	Critical (3)	No UCDs Received - Timeout;;CM-MAC=a0:04:60:c0:d2:a0;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.0;CM-VER=3.0;
2020-3-17, 17:49:55	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;;CM-MAC=a0:04:60:c0:d2:a0;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.0;CM-VER=3.0;
2020-3-17, 17:50:12	Critical (3)	No UCDs Received - Timeout;;CM-MAC=a0:04:60:c0:d2:a0;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.0;CM-VER=3.0;
2020-3-17, 17:50:13	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;;CM-MAC=a0:04:60:c0:d2:a0;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.0;CM-VER=3.0;
2020-3-17, 17:50:30	Critical (3)	No UCDs Received - Timeout;;CM-MAC=a0:04:60:c0:d2:a0;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.0;CM-VER=3.0;

2020-3-17, 17:50:31	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;;CM-MAC=a0:04:60:c0:d2:a0;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.0;CM-VER=3.0;
2020-3-17, 17:50:48	Critical (3)	No UCDs Received - Timeout;;CM-MAC=a0:04:60:c0:d2:a0;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.0;CM-VER=3.0;
2020-3-17, 17:50:49	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;;CM-MAC=a0:04:60:c0:d2:a0;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.0;CM-VER=3.0;
2020-3-17, 17:51:06	Critical (3)	No UCDs Received - Timeout;;CM-MAC=a0:04:60:c0:d2:a0;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.0;CM-VER=3.0;
2020-3-17, 17:51:07	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;;CM-MAC=a0:04:60:c0:d2:a0;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.0;CM-VER=3.0;
2020-3-17, 17:51:24	Critical (3)	No UCDs Received - Timeout;;CM-MAC=a0:04:60:c0:d2:a0;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.0;CM-VER=3.0;
2020-3-17, 17:51:25	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;;CM-MAC=a0:04:60:c0:d2:a0;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.0;CM-VER=3.0;
2020-3-17, 17:51:42	Critical (3)	No UCDs Received - Timeout;;CM-MAC=a0:04:60:c0:d2:a0;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.0;CM-VER=3.0;
2020-3-17, 17:51:43	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;;CM-MAC=a0:04:60:c0:d2:a0;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.0;CM-VER=3.0;
2020-3-17, 17:52:00	Critical (3)	No UCDs Received - Timeout;;CM-MAC=a0:04:60:c0:d2:a0;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.0;CM-VER=3.0;
2020-3-17, 17:52:01	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;;CM-MAC=a0:04:60:c0:d2:a0;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.0;CM-VER=3.0;
2020-3-17, 17:52:18	Critical (3)	No UCDs Received - Timeout;;CM-MAC=a0:04:60:c0:d2:a0;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.0;CM-VER=3.0;
2020-3-17, 17:52:19	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;;CM-MAC=a0:04:60:c0:d2:a0;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.0;CM-VER=3.0;
2020-3-17, 18:07:41	Critical (3)	Resetting the cable modem due to docsDevResetNow
1970-1-1, 00:00:22	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;;CM-MAC=a0:04:60:c0:d2:a0;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.0;CM-VER=3.0;
1970-1-1, 00:00:34	Notice (6)	Honoring MDD; IP provisioning mode = IPv4
1970-1-1, 00:00:36	Warning (5)	DHCP WARNING - Non-critical field invalid in response ;CM-MAC=a0:04:60:c0:d2:a0;CMTS-MAC=00:bc:60:92:54:e9;CM-QOS=1.0;CM-VER=3.0;
2020-3-17, 18:08:32	Notice (6)	TLV-11 - unrecognized OID;CM-MAC=a0:04:60:c0:d2:a0;CMTS-MAC=00:bc:60:92:54:e9;CM-QOS=1.1;CM-VER=3.0;
2020-3-17, 18:10:00	Warning (5)	Unicast DSID PSN startup error