Time	Priority	Description
Thu May 27 08:10:05 2021	Critical (3)	No Ranging Response received - T3 time-out;CM-MAC=28:80:88:af:7e:40;CMTS-MAC=00:01:5c:b2:9c:67;CM-QOS=1.1;CM-VER=3.1;
Thu May 27 08:09:14 2021	Critical (3)	16 consecutive T3 timeouts while trying to range on upstream channel 3;CM-MAC=28:80:88:af:7e:40;CMTS-MAC=00:01:5c:b2:9c:67;CM-QOS=1.1;CM-VER=3.1;
Thu May 27 08:09:14 2021	Critical (3)	Ranging Request Retries exhausted;CM-MAC=28:80:88:af:7e:40;CMTS-MAC=00:01:5c:b2:9c:67;CM-QOS=1.1;CM-VER=3.1;
Thu May 27 08:09:14 2021	Critical (3)	No Ranging Response received - T3 time-out;CM-MAC=28:80:88:af:7e:40;CMTS-MAC=00:01:5c:b2:9c:67;CM-QOS=1.1;CM-VER=3.1;
Thu May 27 08:08:16 2021	Critical (3)	16 consecutive T3 timeouts while trying to range on upstream channel 2;CM-MAC=28:80:88:af:7e:40;CMTS-MAC=00:01:5c:b2:9c:67;CM-QOS=1.1;CM-VER=3.1;
Thu May 27 08:08:16 2021	Critical (3)	Ranging Request Retries exhausted;CM-MAC=28:80:88:af:7e:40;CMTS-MAC=00:01:5c:b2:9c:67;CM-QOS=1.1;CM-VER=3.1;
Thu May 27 08:08:16 2021	Critical (3)	No Ranging Response received - T3 time-out;CM-MAC=28:80:88:af:7e:40;CMTS-MAC=00:01:5c:b2:9c:67;CM-QOS=1.1;CM-VER=3.1;
Thu May 27 08:05:38 2021	Critical (3)	16 consecutive T3 timeouts while trying to range on upstream channel 1;CM-MAC=28:80:88:af:7e:40;CMTS-MAC=00:01:5c:b2:9c:67;CM-QOS=1.1;CM-VER=3.1;
Thu May 27 08:05:38 2021	Critical (3)	Ranging Request Retries exhausted;CM-MAC=28:80:88:af:7e:40;CMTS-MAC=00:01:5c:b2:9c:67;CM-QOS=1.1;CM-VER=3.1;
Thu May 27 08:05:38 2021	Critical (3)	No Ranging Response received - T3 time-out;CM-MAC=28:80:88:af:7e:40;CMTS-MAC=00:01:5c:b2:9c:67;CM-QOS=1.1;CM-VER=3.1;
Thu May 27 08:04:28 2021	Critical (3)	16 consecutive T3 timeouts while trying to range on upstream channel 3;CM-MAC=28:80:88:af:7e:40;CMTS-MAC=00:01:5c:b2:9c:67;CM-QOS=1.1;CM-VER=3.1;
Thu May 27 08:04:28 2021	Critical (3)	Ranging Request Retries exhausted;CM-MAC=28:80:88:af:7e:40;CMTS-MAC=00:01:5c:b2:9c:67;CM-QOS=1.1;CM-VER=3.1;
Thu May 27 08:04:28 2021	Critical (3)	No Ranging Response received - T3 time-out;CM-MAC=28:80:88:af:7e:40;CMTS-MAC=00:01:5c:b2:9c:67;CM-QOS=1.1;CM-VER=3.1;
Thu May 27 08:03:43 2021	Critical (3)	16 consecutive T3 timeouts while trying to range on upstream channel 2;CM-MAC=28:80:88:af:7e:40;CMTS-MAC=00:01:5c:b2:9c:67;CM-QOS=1.1;CM-VER=3.1;
Thu May 27 08:03:43 2021	Critical (3)	Ranging Request Retries exhausted;CM-MAC=28:80:88:af:7e:40;CMTS-MAC=00:01:5c:b2:9c:67;CM-QOS=1.1;CM-VER=3.1;
Thu May 27 08:03:43 2021	Critical (3)	No Ranging Response received - T3 time-out;CM-MAC=28:80:88:af:7e:40;CMTS-MAC=00:01:5c:b2:9c:67;CM-QOS=1.1;CM-VER=3.1;
Thu May 27 07:59:06 2021	Notice (6)	CM-STATUS message sent. Event Type Code: 7; Chan ID: 2 3 4; DSID: N/A; MAC Addr: N/A; OFDM/OFDMA Profile ID: N/A.;CM-MAC=28:80:88:af:7e:40;CMTS-MAC=00:01:5c:b2:9c:67;CM-QOS=1.1;CM-VER=3.1;
Thu May 27 07:59:05 2021	Critical (3)	No Ranging Response received - T3 time-out;CM-MAC=28:80:88:af:7e:40;CMTS-MAC=00:01:5c:b2:9c:67;CM-QOS=1.1;CM-VER=3.1;
Thu May 27 07:58:59 2021	Critical (3)	16 consecutive T3 timeouts while trying to range on upstream channel 2;CM-MAC=28:80:88:af:7e:40;CMTS-MAC=00:01:5c:b2:9c:67;CM-QOS=1.1;CM-VER=3.1;
Thu May 27 07:58:59 2021	Critical (3)	Unicast Maintenance Ranging attempted - No response - Retries exhausted;CM-MAC=28:80:88:af:7e:40;CMTS-MAC=00:01:5c:b2:9c:67;CM-QOS=1.1;CM-VER=3.1;
Thu May 27 07:58:59 2021	Critical (3)	Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=28:80:88:af:7e:40;CMTS-MAC=00:01:5c:b2:9c:67;CM-QOS=1.1;CM-VER=3.1;
Thu May 27 07:58:58 2021	Critical (3)	No Ranging Response received - T3 time-out;CM-MAC=28:80:88:af:7e:40;CMTS-MAC=00:01:5c:b2:9c:67;CM-QOS=1.1;CM-VER=3.1;
Thu May 27 07:58:57 2021	Critical (3)	Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=28:80:88:af:7e:40;CMTS-MAC=00:01:5c:b2:9c:67;CM-QOS=1.1;CM-VER=3.1;
Thu May 27 07:58:56 2021	Critical (3)	16 consecutive T3 timeouts while trying to range on upstream channel 3;CM-MAC=28:80:88:af:7e:40;CMTS-MAC=00:01:5c:b2:9c:67;CM-QOS=1.1;CM-VER=3.1;
Thu May 27 07:58:56 2021	Critical (3)	Unicast Maintenance Ranging attempted - No response - Retries exhausted;CM-MAC=28:80:88:af:7e:40;CMTS-MAC=00:01:5c:b2:9c:67;CM-QOS=1.1;CM-VER=3.1;
Thu May 27 07:58:56 2021	Critical (3)	Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=28:80:88:af:7e:40;CMTS-MAC=00:01:5c:b2:9c:67;CM-QOS=1.1;CM-VER=3.1;
Thu May 27 07:58:55 2021	Critical (3)	No Ranging Response received - T3 time-out;CM-MAC=28:80:88:af:7e:40;CMTS-MAC=00:01:5c:b2:9c:67;CM-QOS=1.1;CM-VER=3.1;
Thu May 27 07:58:55 2021	Critical (3)	Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=28:80:88:af:7e:40;CMTS-MAC=00:01:5c:b2:9c:67;CM-QOS=1.1;CM-VER=3.1;
Thu May 27 07:58:55 2021	Critical (3)	16 consecutive T3 timeouts while trying to range on upstream channel 1;CM-MAC=28:80:88:af:7e:40;CMTS-MAC=00:01:5c:b2:9c:67;CM-QOS=1.1;CM-VER=3.1;
Thu May 27 07:58:55 2021	Critical (3)	Unicast Maintenance Ranging attempted - No response - Retries exhausted;CM-MAC=28:80:88:af:7e:40;CMTS-MAC=00:01:5c:b2:9c:67;CM-QOS=1.1;CM-VER=3.1;
Thu May 27 07:58:55 2021	Critical (3)	Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=28:80:88:af:7e:40;CMTS-MAC=00:01:5c:b2:9c:67;CM-QOS=1.1;CM-VER=3.1;
Thu May 27 07:58:41 2021	Notice (6)	CM-STATUS message sent. Event Type Code: 5; Chan ID: 41; DSID: N/A; MAC Addr: N/A; OFDM/OFDMA Profile ID: N/A.;CM-MAC=28:80:88:af:7e:40;CMTS-MAC=00:01:5c:b2:9c:67;CM-QOS=1.1;CM-VER=3.1;
Thu May 27 07:58:40 2021	Critical (3)	Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=28:80:88:af:7e:40;CMTS-MAC=00:01:5c:b2:9c:67;CM-QOS=1.1;CM-VER=3.1;
Thu May 27 07:58:33 2021	Critical (3)	Unicast Maintenance Ranging attempted - No response - Retries exhausted;CM-MAC=28:80:88:af:7e:40;CMTS-MAC=00:01:5c:b2:9c:67;CM-QOS=1.1;CM-VER=3.1;
Thu May 27 07:58:33 2021	Critical (3)	Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=28:80:88:af:7e:40;CMTS-MAC=00:01:5c:b2:9c:67;CM-QOS=1.1;CM-VER=3.1;
Thu May 27 07:58:32 2021	Critical (3)	Unicast Maintenance Ranging attempted - No response - Retries exhausted;CM-MAC=28:80:88:af:7e:40;CMTS-MAC=00:01:5c:b2:9c:67;CM-QOS=1.1;CM-VER=3.1;
Thu May 27 07:58:32 2021	Critical (3)	Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=28:80:88:af:7e:40;CMTS-MAC=00:01:5c:b2:9c:67;CM-QOS=1.1;CM-VER=3.1;
Thu May 27 07:58:31 2021	Critical (3)	Unicast Maintenance Ranging attempted - No response - Retries exhausted;CM-MAC=28:80:88:af:7e:40;CMTS-MAC=00:01:5c:b2:9c:67;CM-QOS=1.1;CM-VER=3.1;
Thu May 27 07:58:31 2021	Critical (3)	Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=28:80:88:af:7e:40;CMTS-MAC=00:01:5c:b2:9c:67;CM-QOS=1.1;CM-VER=3.1;
Thu May 27 07:58:10 2021	Notice (6)	DS profile assignment change. DS Chan ID: 32; Previous Profile: ; New Profile: 1 2 3.;CM-MAC=28:80:88:af:7e:40;CMTS-MAC=00:01:5c:b2:9c:67;CM-QOS=1.1;CM-VER=3.1;