

Fri Jan 8 12:30:01 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:01 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:01 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:30:01 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:01 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:30:01 2021 kern.warn kernel: vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41176 event 0 reason 0
Fri Jan 8 12:30:01 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:30:01 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state transition INIT -> SCAN
Fri Jan 8 12:30:01 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_START[9]
Fri Jan 8 12:30:01 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9 not handled in state INIT
Fri Jan 8 12:30:02 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:30:02 2021 user.notice led_function: RSSI24G -63
Fri Jan 8 12:30:02 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:30:02 2021 kern.warn kernel: [wifi2] FWLOG: [47792313] WAL channel change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:02 2021 kern.warn kernel: [wifi2] FWLOG: [47792450] WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:30:02 2021 kern.warn kernel: [wifi2] FWLOG: [47792626] WAL channel change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:02 2021 kern.warn kernel: [wifi2] FWLOG: [47792764] WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:30:02 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:02 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:30:02 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:30:03 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:30:03 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:30:03 2021 user.notice led_function: led check timeout elapsed:46589 duration:180
Fri Jan 8 12:30:03 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:30:03 2021 user.notice led_function: CUR_STATE: RE_LocationSuitable
Fri Jan 8 12:30:03 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:30:03 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:30:03 2021 kern.warn kernel: [wifi2] FWLOG: [47792940] WAL channel change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:03 2021 kern.warn kernel: [wifi2] FWLOG: [47793253] WAL channel change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1

Fri Jan 8 12:30:03 2021 kern.warn kernel: [wifi2] FWLOG: [47793566] WAL channel change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:03 2021 kern.warn kernel: [wifi2] FWLOG: [47793880] WAL channel change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:03 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:30:03 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:03 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:03 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:30:03 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:03 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:30:03 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:03 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:30:03 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1132 duration:170
Fri Jan 8 12:30:03 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:03 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:30:03 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:30:03 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:03 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:03 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:30:04 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:04 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41176 event 1 reason 1
Fri Jan 8 12:30:04 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:30:04 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition SCAN -> INIT
Fri Jan 8 12:30:04 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0 (c9e36000)
Fri Jan 8 12:30:04 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_END[3]
Fri Jan 8 12:30:04 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3 not handled in state INIT
Fri Jan 8 12:30:04 2021 kern.warn kernel: [wifi2] FWLOG: [47794193] WAL channel change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:04 2021 kern.warn kernel: [wifi2] FWLOG: [47794331] WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:30:04 2021 kern.warn kernel: [wifi2] FWLOG: [47794534] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:30:04 2021 kern.warn kernel: [wifi2] FWLOG: [47794534] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:30:05 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:30:05 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key

Fri Jan 8 12:30:05 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Printing wds entries [No. of entries:0]
Fri Jan 8 12:30:05 2021 kern.warn kernel: DA Next Hop
flags
Fri Jan 8 12:30:05 2021 kern.warn kernel:
Fri Jan 8 12:30:05 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:30:05 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:30:05 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:30:06 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:06 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:30:07 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:30:07 2021 kern.warn kernel: Printing wds entries [No. of entries:0]
Fri Jan 8 12:30:07 2021 kern.warn kernel: DA Next Hop
flags
Fri Jan 8 12:30:07 2021 kern.warn kernel:
Fri Jan 8 12:30:07 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:30:07 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:30:07 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:30:07 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:08 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:08 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:30:08 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:08 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:08 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:08 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 ::: force_down_5g:0
Fri Jan 8 12:30:08 2021 user.debug repacd.wifimon: repacd check timeout elapsed:1136 duration:170
Fri Jan 8 12:30:08 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:30:08 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:30:08 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:08 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:08 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:08 2021 user.notice led_function: RSSI24G -63
Fri Jan 8 12:30:08 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:30:08 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid

keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:30:08 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:30:09 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:09 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:30:09 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41177 event 0 reason 0
Fri Jan 8 12:30:09 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:30:09 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state transition INIT -> SCAN
Fri Jan 8 12:30:09 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_START[9]
Fri Jan 8 12:30:09 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9 not handled in state INIT
Fri Jan 8 12:30:09 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:30:09 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:30:09 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:30:09 2021 user.notice led_function: led check timeout elapsed:46595 duration:180
Fri Jan 8 12:30:09 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:30:09 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:30:09 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:30:09 2021 kern.warn kernel: [wifi2] FWLOG: [47799669] WAL channel change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:09 2021 kern.warn kernel: [wifi2] FWLOG: [47799806]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:30:09 2021 kern.warn kernel: [wifi2] FWLOG: [47799982] WAL channel change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:10 2021 kern.warn kernel: [wifi2] FWLOG: [47800296] WAL channel change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:10 2021 kern.warn kernel: [wifi2] FWLOG: [47800609] WAL channel change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:10 2021 kern.warn kernel: [wifi2] FWLOG: [47800922] WAL channel change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:10 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:30:11 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:30:11 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41177 event 1 reason 1
Fri Jan 8 12:30:11 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:30:11 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state transition SCAN -> INIT
Fri Jan 8 12:30:11 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0

```
(c9e36000)
Fri Jan 8 12:30:11 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_END[3]
Fri Jan 8 12:30:11 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3
not handled in state INIT
Fri Jan 8 12:30:11 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:30:11 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:11 2021 kern.warn kernel: Inst RSSI value of
node-08:c5:e1:c2:a4:0c: 39
Fri Jan 8 12:30:11 2021 kern.warn kernel: Inst RSSI value of
node-08:c5:e1:c2:a4:0c: 39
Fri Jan 8 12:30:11 2021 kern.warn kernel: [wifi2] FWLOG: [47801236] WAL channel
change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:11 2021 kern.warn kernel: [wifi2] FWLOG: [47801549] WAL channel
change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:11 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:30:11 2021 kern.warn kernel: [wifi2] FWLOG: [47801686]
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan 8 12:30:11 2021 kern.warn kernel: [wifi2] FWLOG: [47801889]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan 8 12:30:11 2021 kern.warn kernel: [wifi2] FWLOG: [47801889]
RESMGR_OCS_GEN_PERIODIC_NOA (
Fri Jan 8 12:30:11 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key0x0 )
Fri Jan 8 12:30:11 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:30:11 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:30:12 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:12 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:30:12 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
2, off 0, len 1
Fri Jan 8 12:30:12 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:30:12 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:30:12 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:30:12 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:12 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:30:12 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:30:12 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:30:12 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:30:12 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:12 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:12 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:12 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:30:12 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1141 duration:170
```

Fri Jan 8 12:30:13 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:13 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:30:13 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:30:13 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:13 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:13 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:13 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:13 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:13 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:14 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:14 2021 user.notice led_function: RSSI24G -63
Fri Jan 8 12:30:14 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:30:15 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:15 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:30:15 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:30:15 2021 user.notice led_function: led check timeout
elapsed:46602 duration:180
Fri Jan 8 12:30:15 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:30:15 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:30:16 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Sending SCAN START cmd
Fri Jan 8 12:30:16 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41178 event 0 reason 0
Fri Jan 8 12:30:16 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:30:16 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:30:16 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:30:16 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan 8 12:30:16 2021 kern.warn kernel: [wifi2] FWLOG: [47807014] WAL channel
change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:16 2021 kern.warn kernel: [wifi2] FWLOG: [47807152]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:30:16 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:30:17 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:30:17 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:30:17 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:30:17 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:30:17 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key

Fri Jan 8 12:30:17 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

Fri Jan 8 12:30:17 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected

Fri Jan 8 12:30:17 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key

Fri Jan 8 12:30:17 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key

Fri Jan 8 12:30:17 2021 kern.warn kernel: [wifi2] FWLOG: [47807328] WAL channel change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1

Fri Jan 8 12:30:17 2021 kern.warn kernel: [wifi2] FWLOG: [47807465] WHAL_ERROR_RESET_OFFSETCAL ()

Fri Jan 8 12:30:17 2021 kern.warn kernel: [wifi2] FWLOG: [47807641] WAL channel change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1

Fri Jan 8 12:30:17 2021 kern.warn kernel: [wifi2] FWLOG: [47807954] WAL channel change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1

Fri Jan 8 12:30:17 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key

Fri Jan 8 12:30:17 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 ::: force_down_5g:0

Fri Jan 8 12:30:17 2021 user.debug repacd.wifimon: repacd check timeout elapsed:1146 duration:170

Fri Jan 8 12:30:17 2021 user.info repacd: AssocTimeout

Fri Jan 8 12:30:17 2021 user.info repacd: Boot time count=-1

Fri Jan 8 12:30:17 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-0(ath2):wlan_get_key: invalid key

Fri Jan 8 12:30:17 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-0(ath2):wlan_get_key: invalid key

Fri Jan 8 12:30:17 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key

Fri Jan 8 12:30:17 2021 user.notice led_function: =====LOOP END=====

Fri Jan 8 12:30:17 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid keyvap-0(ath2):wlan_get_key: invalid key

Fri Jan 8 12:30:18 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key

Fri Jan 8 12:30:18 2021 kern.warn kernel: vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41178 event 1 reason 1

Fri Jan 8 12:30:18 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state event 3, cur_state=1, vap_deleted_is_set=0

Fri Jan 8 12:30:18 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state transition SCAN -> INIT

Fri Jan 8 12:30:18 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0 (c9e36000)

Fri Jan 8 12:30:18 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_END[3]

Fri Jan 8 12:30:18 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3 not handled in state INIT

Fri Jan 8 12:30:18 2021 kern.warn kernel: [wifi2] FWLOG: [47808268] WAL channel change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1

Fri Jan 8 12:30:18 2021 kern.warn kernel: [wifi2] FWLOG: [47808581] WAL channel change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1

Fri Jan 8 12:30:18 2021 kern.warn kernel: [wifi2] FWLOG: [47808895] WAL channel change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1

Fri Jan 8 12:30:18 2021 kern.warn kernel: [wifi2] FWLOG: [47809235] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)

Fri Jan 8 12:30:18 2021 kern.warn kernel: [wifi2] FWLOG: [47809235]

RESMGR_OCS_GEN_PERIODIC_NOA (0x0)

Fri Jan 8 12:30:18 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:18 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:30:19 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:30:19 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:30:19 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:30:19 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:19 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:30:20 2021 user.notice led_function: RSSI24G -63
Fri Jan 8 12:30:20 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:30:21 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:30:21 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:30:21 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:21 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:30:21 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:30:21 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:30:21 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:30:21 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:21 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:21 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:21 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:21 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:30:21 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:30:21 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:30:21 2021 user.notice led_function: led check timeout
elapsed:46608 duration:180
Fri Jan 8 12:30:21 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:30:21 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:21 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:30:21 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:21 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:21 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:30:21 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1150 duration:170
Fri Jan 8 12:30:21 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key


```
Fri Jan 8 12:30:21 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:30:21 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:30:21 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:22 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:30:22 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:22 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:30:22 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:30:22 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:23 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:23 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:30:23 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41179 event 0 reason 0
Fri Jan 8 12:30:23 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:30:23 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:30:23 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:30:23 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan 8 12:30:23 2021 kern.warn kernel: [wifi2] FWLOG: [47814371] WAL channel
change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:23 2021 kern.warn kernel: [wifi2] FWLOG: [47814508]
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan 8 12:30:23 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:30:23 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:24 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:24 2021 kern.warn kernel: [wifi2] FWLOG: [47814684] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:24 2021 kern.warn kernel: [wifi2] FWLOG: [47814821]
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan 8 12:30:24 2021 kern.warn kernel: [wifi2] FWLOG: [47814998] WAL channel
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:24 2021 kern.warn kernel: [wifi2] FWLOG: [47815311] WAL channel
change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:24 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:30:25 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:30:25 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:30:25 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:30:25 2021 kern.warn kernel: [wifi2] FWLOG: [47815624] WAL channel
change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:25 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41179 event 1 reason 1
```

Fri Jan 8 12:30:25 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:30:25 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state transition SCAN -> INIT
Fri Jan 8 12:30:25 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0 (c9e36000)
Fri Jan 8 12:30:25 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_END[3]
Fri Jan 8 12:30:25 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3 not handled in state INIT
Fri Jan 8 12:30:25 2021 kern.warn kernel: [wifi2] FWLOG: [47815938] WAL channel change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:25 2021 kern.warn kernel: [wifi2] FWLOG: [47816251] WAL channel change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:25 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:30:26 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:30:26 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:26 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:26 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:26 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:30:26 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:26 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 ::: force_down_5g:0
Fri Jan 8 12:30:26 2021 user.debug repacd.wifimon: repacd check timeout elapsed:1154 duration:170
Fri Jan 8 12:30:26 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:26 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:30:26 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:30:26 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:26 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:26 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:26 2021 kern.warn kernel: RX Rate Info:
Fri Jan 8 12:30:26 2021 kern.warn kernel: MCS counts (0..9): 665, 1501, 3920, 14982, 38711, 43462, 54303, 34939, 3446, 833
Fri Jan 8 12:30:26 2021 kern.warn kernel: SGI counts (0..9): 240, 689, 1647, 7331, 13127, 16901, 27958, 17203, 1578, 459
Fri Jan 8 12:30:26 2021 kern.warn kernel: [wifi2] FWLOG: [47816593] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:30:26 2021 kern.warn kernel: [wifi2] FWLOG: [47816593] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:30:26 2021 kern.warn kernel: NSS counts: 1x1 125964, 2x2 70798, 3x3 0, 4x4 0
Fri Jan 8 12:30:26 2021 kern.warn kernel: NSTS count: 571
Fri Jan 8 12:30:26 2021 kern.warn kernel: BW counts: 20MHz 197692, 40MHz 0, 80MHz 0, 160MHz 0
Fri Jan 8 12:30:26 2021 kern.warn kernel: Preamble counts: 113016, 89173, 0,

108519, 0, 0
Fri Jan 8 12:30:26 2021 kern.warn kernel: STBC rate counts (0..9): 238, 187, 51, 49, 23, 0, 1, 22, 0, 0
Fri Jan 8 12:30:26 2021 kern.warn kernel: LDPC Counts: 196659
Fri Jan 8 12:30:26 2021 kern.warn kernel: RSSI (data, mgmt): 32, 35
Fri Jan 8 12:30:26 2021 kern.warn kernel: RSSI Chain 0 (0x80 0x80 0x80 0x1e)
Fri Jan 8 12:30:26 2021 kern.warn kernel: RSSI Chain 1 (0x80 0x80 0x80 0x1c)
Fri Jan 8 12:30:26 2021 kern.warn kernel: RSSI Chain 2 (0x00 0x00 0x00 0x00)
Fri Jan 8 12:30:26 2021 kern.warn kernel: RSSI Chain 3 (0x00 0x00 0x00 0x00)
Fri Jan 8 12:30:26 2021 kern.warn kernel: RSSI (comb_ht): 32
Fri Jan 8 12:30:26 2021 user.notice led_function: RSSI24G -63
Fri Jan 8 12:30:27 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:30:27 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:30:27 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:30:27 2021 kern.warn kernel: RX Rate Info:
Fri Jan 8 12:30:27 2021 kern.warn kernel: MCS counts (0..9): 4586, 0, 0, 0, 77, 20188, 68397, 129938, 501811, 27607
Fri Jan 8 12:30:27 2021 kern.warn kernel: SGI counts (0..9): 0, 0, 0, 0, 76, 20070, 66924, 126215, 498615, 15530
Fri Jan 8 12:30:27 2021 kern.warn kernel: NSS counts: 1x1 4580, 2x2 1557, 3x3 552329, 4x4 194138
Fri Jan 8 12:30:27 2021 kern.warn kernel: NSTS count: 0
Fri Jan 8 12:30:27 2021 kern.warn kernel: BW counts: 20MHz 29, 40MHz 56, 80MHz 757477, 160MHz 0
Fri Jan 8 12:30:27 2021 kern.warn kernel: Preamble counts: 135383, 56, 0, 757506, 0, 5271
Fri Jan 8 12:30:27 2021 kern.warn kernel: STBC rate counts (0..9):
Fri Jan 8 12:30:27 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key0, 0, 0, 0, 0, 0, 0, 0, 0, 0
Fri Jan 8 12:30:27 2021 kern.warn kernel: LDPC Counts: 748012
Fri Jan 8 12:30:27 2021 kern.warn kernel: RSSI (data, mgmt): 40, 7
Fri Jan 8 12:30:27 2021 kern.warn kernel: RSSI Chain 0 (0x80 0x25 0x21 0x24)
Fri Jan 8 12:30:27 2021 kern.warn kernel: RSSI Chain 1 (0x80 0x21 0x1e 0x22)
Fri Jan 8 12:30:27 2021 kern.warn kernel: RSSI Chain 2 (0x80 0x24 0x21 0x20)
Fri Jan 8 12:30:27 2021 kern.warn kernel: RSSI Chain 3 (0x80 0x1f 0x22 0x24)
Fri Jan 8 12:30:27 2021 kern.warn kernel: RSSI (comb_ht): 41
Fri Jan 8 12:30:28 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:30:28 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:30:28 2021 user.notice led_function: led check timeout elapsed:46614 duration:180
Fri Jan 8 12:30:28 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:30:28 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:30:28 2021 kern.warn kernel: TX Rate Info:
Fri Jan 8 12:30:28 2021 kern.warn kernel: MCS counts (0..9): 562, 704, 1316, 1625, 8547, 48583, 87235, 127492, 48445, 22270
Fri Jan 8 12:30:28 2021 kern.warn kernel: MCS counts SU (0..9): 562, 704, 1316, 1625, 8547, 48583, 87235, 127492, 48445, 22270
Fri Jan 8 12:30:28 2021 kern.warn kernel: MCS counts MU (0..9): 0, 0, 0, 0, 0, 0, 0, 0, 0, 0
Fri Jan 8 12:30:28 2021 kern.warn kernel: SGI counts (0..9): 0, 0, 0, 0, 4949,

20338, 31648, 102113, 38553, 16570
Fri Jan 8 12:30:28 2021 kern.warn kernel: NSS counts: 1x1 152324, 2x2 194455, 3x3 0 4x4 0
Fri Jan 8 12:30:28 2021 kern.warn kernel: BW counts: 20MHz 346779, 40MHz 0, 80MHz 0, 160MHz 0
Fri Jan 8 12:30:28 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:30:28 2021 kern.warn kernel: Preamble (O C H V) counts: 0, 13120, 143104, 204643
Fri Jan 8 12:30:28 2021 kern.warn kernel: STBC rate counts (0..9): 562, 672, 1181, 1496, 1737, 10581, 33052, 50289, 0, 0
Fri Jan 8 12:30:28 2021 kern.warn kernel: LDPC Counts: 203675
Fri Jan 8 12:30:28 2021 kern.warn kernel: RTS Counts: 27095
Fri Jan 8 12:30:28 2021 kern.warn kernel: Ack RSSI: 32
Fri Jan 8 12:30:28 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:30:29 2021 kern.warn kernel: TX Rate Info:
Fri Jan 8 12:30:29 2021 kern.warn kernel: MCS counts (0..9): 0, 0, 0, 0, 0, 8324, 125481, 166019, 365434, 217694
Fri Jan 8 12:30:29 2021 kern.warn kernel: MCS counts SU (0..9): 0, 0, 0, 0, 0, 8324, 125481, 166019, 365434, 217694
Fri Jan 8 12:30:29 2021 kern.warn kernel: MCS counts MU (0..9): 0, 0, 0, 0, 0, 0, 0, 0, 0, 0
Fri Jan 8 12:30:29 2021 kern.warn kernel: SGI counts (0..9): 0, 0, 0, 0, 0, 8294, 124427, 149841, 319175, 185317
Fri Jan 8 12:30:29 2021 kern.warn kernel: NSS counts: 1x1 0, 2x2 332, 3x3 545719 4x4 336901
Fri Jan 8 12:30:29 2021 kern.warn kernel: BW counts: 20MHz 391, 40MHz 0, 80MHz 882561, 160MHz 0
Fri Jan 8 12:30:29 2021 kern.warn kernel: Preamble (O C H V) counts: 2, 0, 0, 882952
Fri Jan 8 12:30:29 2021 kern.warn kernel: STBC rate counts (0..9): 0, 0, 0, 0, 0, 0, 0, 0, 0, 0
Fri Jan 8 12:30:29 2021 kern.warn kernel: LDPC Counts: 882952
Fri Jan 8 12:30:29 2021 kern.warn kernel: RTS Counts: 814
Fri Jan 8 12:30:29 2021 kern.warn kernel: Ack RSSI: 36
Fri Jan 8 12:30:30 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:30:30 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:30 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:30:30 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:30:30 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:30 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:30 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:30 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:30:30 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:30 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid keySending SCAN START cmd
Fri Jan 8 12:30:30 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41180 event 0 reason 0

```
Fri Jan 8 12:30:30 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:30:30 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:30:30 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:30:30 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:30:30 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:30:30 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan 8 12:30:30 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1159 duration:170
Fri Jan 8 12:30:30 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:30:30 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:30:30 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:30 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:30 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:31 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:31 2021 kern.warn kernel: [wifi2] FWLOG: [47821744] WAL channel
change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:31 2021 kern.warn kernel: [wifi2] FWLOG: [47821882]
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan 8 12:30:31 2021 kern.warn kernel: [wifi2] FWLOG: [47822058] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:31 2021 kern.warn kernel: [wifi2] FWLOG: [47822195]
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan 8 12:30:31 2021 kern.warn kernel: [wifi2] FWLOG: [47822371] WAL channel
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:31 2021 kern.warn kernel: [wifi2] FWLOG: [47822684] WAL channel
change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:32 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:30:32 2021 kern.warn kernel: [wifi2] FWLOG: [47822998] WAL channel
change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:32 2021 kern.warn kernel: [wifi2] FWLOG: [47823311] WAL channel
change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:32 2021 kern.warn kernel: [wifi2] FWLOG: [47823624] WAL channel
change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:32 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41180 event 1 reason 1
Fri Jan 8 12:30:32 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:30:32 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition SCAN -> INIT
Fri Jan 8 12:30:32 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0
(c9e36000)
Fri Jan 8 12:30:32 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_END[3]
```

Fri Jan 8 12:30:32 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3 not handled in state INIT
Fri Jan 8 12:30:33 2021 user.notice led_function: RSSI24G -63
Fri Jan 8 12:30:33 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:30:33 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:33 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key[wifi2] FWLOG: [47823965] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:30:33 2021 kern.warn kernel: [wifi2] FWLOG: [47823965] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:30:34 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:30:34 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:30:34 2021 user.notice led_function: led check timeout elapsed:46620 duration:180
Fri Jan 8 12:30:34 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:30:34 2021 user.notice led_function: CUR_STATE: RE_LocationSuitable
Fri Jan 8 12:30:34 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:30:34 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:30:34 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:35 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:35 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:35 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:30:35 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:35 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 ::: force_down_5g:0
Fri Jan 8 12:30:35 2021 user.debug repacd.wifimon: repacd check timeout elapsed:1163 duration:170
Fri Jan 8 12:30:35 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:35 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:30:35 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:30:35 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:35 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:36 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:36 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:30:36 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:30:36 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:30:36 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:37 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:37 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:30:37 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1

Fri Jan 8 12:30:37 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:37 2021 kern.warn kernel: vap-2(ath01):[a6:c9:eb:1a:a6:a1] send null data frame on channel 13, pwr mgt dis
Fri Jan 8 12:30:37 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:30:37 2021 kern.warn kernel: vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41181 event 0 reason 0
Fri Jan 8 12:30:37 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:30:37 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state transition INIT -> SCAN
Fri Jan 8 12:30:37 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_START[9]
Fri Jan 8 12:30:37 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9 not handled in state INIT
Fri Jan 8 12:30:37 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:30:38 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:38 2021 kern.warn kernel: [wifi2] FWLOG: [47829092] WAL channel change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:38 2021 kern.warn kernel: [wifi2] FWLOG: [47829229] WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:30:38 2021 kern.warn kernel: [wifi2] FWLOG: [47829405] WAL channel change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:38 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:38 2021 kern.warn kernel: [wifi2] FWLOG: [47829542] WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:30:38 2021 kern.warn kernel: [wifi2] FWLOG: [47829719] WAL channel change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:38 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:38 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:39 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:39 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:30:39 2021 user.notice led_function: RSSI24G -63
Fri Jan 8 12:30:39 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:30:39 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:30:39 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:30:39 2021 kern.warn kernel: [wifi2] FWLOG: [47830032] WAL channel change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:39 2021 kern.warn kernel: [wifi2] FWLOG: [47830345] WAL channel change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:39 2021 kern.warn kernel: [wifi2] FWLOG: [47830659] WAL channel change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:39 2021 kern.warn kernel: [wifi2] FWLOG: [47830796] WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:30:39 2021 user.debug repacd.wifimon: CHECK associatd

Fri Jan 8 12:30:39 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:39 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:39 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:30:39 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:39 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41181 event 1 reason 1
Fri Jan 8 12:30:39 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:30:39 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state transition SCAN -> INIT
Fri Jan 8 12:30:39 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:39 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0 (c9e36000)
Fri Jan 8 12:30:40 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_END[3]
Fri Jan 8 12:30:40 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3 not handled in state INIT
Fri Jan 8 12:30:40 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:40 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 ::: force_down_5g:0
Fri Jan 8 12:30:40 2021 user.debug repacd.wifimon: repacd check timeout elapsed:1168 duration:170
Fri Jan 8 12:30:40 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:40 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:30:40 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:30:40 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:40 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:40 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:40 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:30:40 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:30:40 2021 user.notice led_function: led check timeout elapsed:46627 duration:180
Fri Jan 8 12:30:40 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:30:40 2021 user.notice led_function: CUR_STATE: RE_LocationSuitable
Fri Jan 8 12:30:40 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
[wifi2] FWLOG: [47830972] WAL channel change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:40 2021 kern.warn kernel: [wifi2] FWLOG: [47831316] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:30:40 2021 kern.warn kernel: [wifi2] FWLOG: [47831316] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:30:41 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:30:42 2021 kern.warn kernel: vap-0(ath1):


```
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:30:42 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:30:42 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:43 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:43 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:44 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:30:44 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:30:44 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:44 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:44 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:30:44 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:44 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:44 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:30:44 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1173 duration:170
Fri Jan 8 12:30:44 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:30:44 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:30:44 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:44 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:44 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:45 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:45 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:30:45 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41182 event 0 reason 0
Fri Jan 8 12:30:45 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:30:45 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:30:45 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:30:45 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan 8 12:30:45 2021 kern.warn kernel: [wifi2] FWLOG: [47836440] WAL channel
change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:45 2021 kern.warn kernel: [wifi2] FWLOG: [47836577]
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan 8 12:30:45 2021 kern.warn kernel: [wifi2] FWLOG: [47836753] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:45 2021 kern.warn kernel: [wifi2] FWLOG: [47836890]
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan 8 12:30:45 2021 user.notice led_function: RSSI24G -63
Fri Jan 8 12:30:45 2021 user.notice led_function: PING IS WELL
```

```
Fri Jan 8 12:30:45 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:30:46 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:30:46 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:30:46 2021 kern.warn kernel: [wifi2] FWLOG: [47837066] WAL channel
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:46 2021 kern.warn kernel: [wifi2] FWLOG: [47837380] WAL channel
change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:46 2021 kern.warn kernel: [wifi2] FWLOG: [47837693] WAL channel
change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:46 2021 kern.warn kernel: [wifi2] FWLOG: [47838007] WAL channel
change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:46 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:30:46 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:30:46 2021 user.notice led_function: led check timeout
elapsed:46633 duration:180
Fri Jan 8 12:30:46 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:30:46 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:30:47 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:30:47 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41182 event 1 reason 1
Fri Jan 8 12:30:47 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:30:47 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition SCAN -> INIT
Fri Jan 8 12:30:47 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0
(c9e36000)
Fri Jan 8 12:30:47 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_END[3]
Fri Jan 8 12:30:47 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3
not handled in state INIT
Fri Jan 8 12:30:47 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:30:47 2021 kern.warn kernel: [wifi2] FWLOG: [47838320] WAL channel
change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:47 2021 kern.warn kernel: [wifi2] FWLOG: [47838660]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan 8 12:30:47 2021 kern.warn kernel: [wifi2] FWLOG: [47838660]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan 8 12:30:47 2021 auth.err passwd: no record of root in /etc/shadow,
using /etc/passwd
Fri Jan 8 12:30:47 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:30:47 2021 auth.info passwd: Password for root changed by root
Fri Jan 8 12:30:48 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:30:48 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:30:48 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
```

Fri Jan 8 12:30:48 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:48 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:30:48 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:49 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:49 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:49 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:30:49 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:49 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:30:49 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1177 duration:170
Fri Jan 8 12:30:49 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:30:49 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:30:49 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:49 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:49 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:30:49 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:30:49 2021 auth.info passwd: Password for admin changed by root
Fri Jan 8 12:30:49 2021 daemon.info utelnetd[9711]: utelnetd (port: 23, ifname:
br0, login: /bin/login) startup succeeded
Fri Jan 8 12:30:49 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:49 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
1, off 0, len 1
Fri Jan 8 12:30:50 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:30:50 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:30:50 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:30:51 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:30:51 2021 user.notice led_function: RSSI24G -63
Fri Jan 8 12:30:51 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:30:52 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:30:52 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41183 event 0 reason 0
Fri Jan 8 12:30:52 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:30:52 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:30:52 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:30:52 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9

not handled in state INIT
Fri Jan 8 12:30:52 2021 kern.warn kernel: [wifi2] FWLOG: [47843788] WAL channel
change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:52 2021 kern.warn kernel: [wifi2] FWLOG: [47843926]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:30:52 2021 kern.warn kernel: [wifi2] FWLOG: [47844102] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:52 2021 kern.warn kernel: [wifi2] FWLOG: [47844239]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:30:52 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:30:52 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:30:53 2021 user.notice led_function: led check timeout
elapsed:46639 duration:180
Fri Jan 8 12:30:53 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:30:53 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:30:53 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:30:53 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:30:53 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:30:53 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:30:53 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:30:53 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:30:53 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:53 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key[wifi2] FWLOG: [47844415] WAL channel change freq=5620, mode=0 flags=0
rx_ok=1 tx_ok=1
Fri Jan 8 12:30:53 2021 kern.warn kernel: [wifi2] FWLOG: [47844728] WAL channel
change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:53 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:30:53 2021 kern.warn kernel: [wifi2] FWLOG: [47845042] WAL channel
change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:53 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:30:53 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:53 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:53 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:30:53 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1182 duration:170
Fri Jan 8 12:30:53 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:30:53 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:30:53 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:53 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
1, off 0, len 1
Fri Jan 8 12:30:53 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key

Fri Jan 8 12:30:53 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:54 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:54 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:30:54 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41183 event 1 reason 1
Fri Jan 8 12:30:54 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:30:54 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state transition SCAN -> INIT
Fri Jan 8 12:30:54 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0 (c9e36000)
Fri Jan 8 12:30:54 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_END[3]
Fri Jan 8 12:30:54 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3 not handled in state INIT
Fri Jan 8 12:30:54 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:30:54 2021 kern.warn kernel: [wifi2] FWLOG: [47845355] WAL channel change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:54 2021 kern.warn kernel: [wifi2] FWLOG: [47845668] WAL channel change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:54 2021 kern.warn kernel: [wifi2] FWLOG: [47846009] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:30:54 2021 kern.warn kernel: [wifi2] FWLOG: [47846009] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:30:54 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:30:55 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:30:55 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:30:55 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:55 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:30:55 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:30:56 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:30:56 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:56 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:30:56 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:30:56 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:30:57 2021 kern.warn kernel: vap-0(ath1):

[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:30:57 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:30:57 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:30:57 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:30:57 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:30:57 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:30:57 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:30:58 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:58 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:30:58 2021 user.notice led_function: RSSI24G -63
Fri Jan 8 12:30:58 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:58 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:30:58 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:58 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:30:58 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1186 duration:170
Fri Jan 8 12:30:58 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:30:58 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:30:58 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:58 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:58 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:30:58 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:30:58 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:30:58 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:30:58 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:30:58 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:30:59 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:30:59 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:30:59 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:30:59 2021 user.notice led_function: led check timeout
elapsed:46645 duration:180
Fri Jan 8 12:30:59 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:30:59 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:30:59 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:30:59 2021 kern.warn kernel:

vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41184 event 0 reason 0
Fri Jan 8 12:30:59 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:30:59 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state transition INIT -> SCAN
Fri Jan 8 12:30:59 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_START[9]
Fri Jan 8 12:30:59 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9 not handled in state INIT
Fri Jan 8 12:30:59 2021 kern.warn kernel: [wifi2] FWLOG: [47851146] WAL channel change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:30:59 2021 kern.warn kernel: [wifi2] FWLOG: [47851283] WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:30:59 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:30:59 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:31:00 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:31:00 2021 kern.warn kernel: [wifi2] FWLOG: [47851459] WAL channel change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:00 2021 kern.warn kernel: [wifi2] FWLOG: [47851596] WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:31:00 2021 kern.warn kernel: [wifi2] FWLOG: [47851773] WAL channel change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:00 2021 kern.warn kernel: [wifi2] FWLOG: [47852086] WAL channel change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:00 2021 kern.warn kernel: [wifi2] FWLOG: [47852399] WAL channel change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:01 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:31:01 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:31:01 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:01 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:31:01 2021 kern.warn kernel: vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41184 event 1 reason 1
Fri Jan 8 12:31:01 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:31:01 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state transition SCAN -> INIT
Fri Jan 8 12:31:01 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0 (c9e36000)
Fri Jan 8 12:31:01 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_END[3]
Fri Jan 8 12:31:01 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3 not handled in state INIT
Fri Jan 8 12:31:01 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:31:01 2021 kern.warn kernel: [wifi2] FWLOG: [47852713] WAL channel change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:01 2021 kern.warn kernel: [wifi2] FWLOG: [47853026] WAL channel

change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:01 2021 kern.warn kernel: [wifi2] FWLOG: [47853367]
RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:31:01 2021 kern.warn kernel: [wifi2] FWLOG: [47853367]
RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:31:02 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:31:02 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:31:02 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:31:02 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:31:02 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:31:02 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:31:02 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:02 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:02 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:31:02 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1191 duration:170
Fri Jan 8 12:31:02 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:31:02 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:31:02 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:02 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:02 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:31:03 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:31:03 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:31:03 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:31:03 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:31:04 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:31:04 2021 user.notice led_function: RSSI24G -63
Fri Jan 8 12:31:04 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:31:04 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:31:05 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:05 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:31:05 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:31:05 2021 user.notice led_function: led check timeout
elapsed:46652 duration:180
Fri Jan 8 12:31:05 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:31:05 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable

Fri Jan 8 12:31:05 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyPrinting wds entries [No. of entries:0]
Fri Jan 8 12:31:05 2021 kern.warn kernel: DA Next Hop
flags
Fri Jan 8 12:31:05 2021 kern.warn kernel:
Fri Jan 8 12:31:05 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:31:06 2021 kern.warn kernel: Inst RSSI value of
node-08:c5:e1:c2:a4:0c: 43
Fri Jan 8 12:31:06 2021 kern.warn kernel: Inst RSSI value of
node-08:c5:e1:c2:a4:0c: 43
Fri Jan 8 12:31:06 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:31:06 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:31:06 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41185 event 0 reason 0
Fri Jan 8 12:31:06 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:31:06 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:31:06 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:31:06 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan 8 12:31:06 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:31:06 2021 kern.warn kernel: [wifi2] FWLOG: [47858503] WAL channel
change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:06 2021 kern.warn kernel: [wifi2] FWLOG: [47858640]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:31:06 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:31:06 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:31:06 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:31:06 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:31:06 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:06 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:07 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:31:07 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1195 duration:170
Fri Jan 8 12:31:07 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:31:07 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:31:07 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:07 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:07 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:31:07 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending

2, off 0, len 1
Fri Jan 8 12:31:07 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:31:07 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:31:07 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:07 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:31:07 2021 kern.warn kernel: [wifi2] FWLOG: [47858816] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:07 2021 kern.warn kernel: [wifi2] FWLOG: [47858953]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:31:07 2021 kern.warn kernel: [wifi2] FWLOG: [47859129] WAL channel
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:07 2021 kern.warn kernel: [wifi2] FWLOG: [47859443] WAL channel
change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:07 2021 kern.warn kernel: Printing wds entries [No. of
entries:0]
Fri Jan 8 12:31:08 2021 kern.warn kernel: DA Next Hop
flags
Fri Jan 8 12:31:08 2021 kern.warn kernel:
Fri Jan 8 12:31:08 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
1, off 0, len 1
Fri Jan 8 12:31:08 2021 kern.warn kernel: [wifi2] FWLOG: [47859756] WAL channel
change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:08 2021 kern.warn kernel: [wifi2]
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41185 event 1 reason 1
Fri Jan 8 12:31:08 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:31:08 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition SCAN -> INIT
Fri Jan 8 12:31:08 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0
(c9e36000)
Fri Jan 8 12:31:08 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_END[3]
Fri Jan 8 12:31:08 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3
not handled in state INIT
Fri Jan 8 12:31:08 2021 kern.warn kernel: FWLOG: [47860070] WAL channel change
freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:08 2021 kern.warn kernel: [wifi2] FWLOG: [47860207]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:31:08 2021 kern.warn kernel: [wifi2] FWLOG: [47860383] WAL channel
change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:09 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:31:09 2021 auth.info login[12046]: root login on 'pts/0'
Fri Jan 8 12:31:09 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:31:09 2021 kern.warn kernel: [wifi2] FWLOG: [47860725]
RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:31:09 2021 kern.warn kernel: [wifi2] FWLOG: [47860725]
RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:31:10 2021 user.notice led_function: RSSI24G -63

```
Fri Jan  8 12:31:10 2021 user.notice led_function: PING IS WELL
Fri Jan  8 12:31:11 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan  8 12:31:11 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan  8 12:31:11 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan  8 12:31:11 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:31:11 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan  8 12:31:11 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan  8 12:31:11 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan  8 12:31:11 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:31:11 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan  8 12:31:11 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1200 duration:170
Fri Jan  8 12:31:11 2021 user.info repacd: AssocTimeout
Fri Jan  8 12:31:11 2021 user.info repacd: Boot time count=-1
Fri Jan  8 12:31:11 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:31:11 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:31:11 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan  8 12:31:11 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan  8 12:31:11 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan  8 12:31:11 2021 user.notice led_function: led check timeout
elapsed:46658 duration:180
Fri Jan  8 12:31:11 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan  8 12:31:11 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan  8 12:31:13 2021 user.notice led_function: =====LOOP END=====
Fri Jan  8 12:31:13 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:31:13 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan  8 12:31:13 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan  8 12:31:13 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41186 event 0 reason 0
Fri Jan  8 12:31:13 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan  8 12:31:13 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan  8 12:31:13 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan  8 12:31:13 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan  8 12:31:14 2021 kern.warn kernel: [wifi2] FWLOG: [47865880] WAL channel
change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan  8 12:31:14 2021 kern.warn kernel: [wifi2] FWLOG: [47866017]
```

```
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan 8 12:31:14 2021 kern.warn kernel: [wifi2] FWLOG: [47866193] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:14 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:31:14 2021 kern.warn kernel: [wifi2] FWLOG: [47866331]
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan 8 12:31:14 2021 kern.warn kernel: [wifi2] FWLOG: [47866507] WAL channel
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:14 2021 kern.warn kernel: [wifi2] FWLOG: [47866820] WAL channel
change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:14 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:15 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:31:15 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key[wifi2] FWLOG: [47867134] WAL channel change freq=5660, mode=0 flags=0
rx_ok=1 tx_ok=1
Fri Jan 8 12:31:15 2021 kern.warn kernel: [wifi2] FWLOG: [47867447] WAL channel
change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:15 2021 kern.warn kernel: [wifi2] FWLOG: [47867585]
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan 8 12:31:15 2021 kern.warn kernel: [wifi2] FWLOG: [47867760] WAL channel
change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:15 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:31:15 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:31:15 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:15 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:31:15 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:31:15 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000
scan_id 41186 event 1 reason 1
Fri Jan 8 12:31:15 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:31:15 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition SCAN -> INIT
Fri Jan 8 12:31:15 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0
(c9e36000)
Fri Jan 8 12:31:15 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_END[3]
Fri Jan 8 12:31:15 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3
not handled in state INIT
Fri Jan 8 12:31:15 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:15 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:31:16 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1204 duration:170
Fri Jan 8 12:31:16 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:31:16 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:31:16 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:31:16 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
```

Fri Jan 8 12:31:16 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:31:16 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:16 2021 kern.warn kernel: [wifi2] FWLOG: [47868101] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:31:16 2021 kern.warn kernel: [wifi2] FWLOG: [47868101] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:31:16 2021 user.notice led_function: RSSI24G -63
Fri Jan 8 12:31:16 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:31:16 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:31:17 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:31:17 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:31:17 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:31:17 2021 user.notice led_function: led check timeout
elapsed:46664 duration:180
Fri Jan 8 12:31:17 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:31:17 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:31:18 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:31:19 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:31:19 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:31:19 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:31:19 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:31:20 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:31:20 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:31:20 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:31:20 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:31:20 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:20 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:20 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:31:20 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1208 duration:170
Fri Jan 8 12:31:20 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:31:20 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:31:20 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:20 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:20 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:31:20 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key

Fri Jan 8 12:31:20 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:31:20 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41187 event 0 reason 0
Fri Jan 8 12:31:20 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:31:20 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:31:20 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:31:20 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan 8 12:31:21 2021 kern.warn kernel: [wifi2] FWLOG: [47873239] WAL channel
change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:21 2021 kern.warn kernel: [wifi2] FWLOG: [47873376]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:31:21 2021 kern.warn kernel: [wifi2] FWLOG: [47873552] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:21 2021 kern.warn kernel: [wifi2] FWLOG: [47873689]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:31:21 2021 kern.warn kernel: [wifi2] FWLOG: [47873866] WAL channel
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:22 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:31:22 2021 kern.warn kernel: [wifi2] FWLOG: [47874179] WAL channel
change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:22 2021 kern.warn kernel: [wifi2] FWLOG: [47874492] WAL channel
change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:22 2021 kern.warn kernel: [wifi2] FWLOG: [47874806] WAL channel
change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:22 2021 user.notice led_function: RSSI24G -63
Fri Jan 8 12:31:22 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:31:23 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41187 event 1 reason 1
Fri Jan 8 12:31:23 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:31:23 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition SCAN -> INIT
Fri Jan 8 12:31:23 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0
(c9e36000)
Fri Jan 8 12:31:23 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_END[3]
Fri Jan 8 12:31:23 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3
not handled in state INIT
Fri Jan 8 12:31:23 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:31:23 2021 kern.warn kernel: [wifi2] FWLOG: [47875119] WAL channel
change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:23 2021 kern.warn kernel: [wifi2] FWLOG: [47875459]
RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:31:23 2021 kern.warn kernel: [wifi2] FWLOG: [47875459]
RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:31:23 2021 kern.warn kernel: vap-0(ath1):

```
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan  8 12:31:23 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan  8 12:31:23 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan  8 12:31:23 2021 user.notice led_function: led check timeout
elapsed:46670 duration:180
Fri Jan  8 12:31:23 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan  8 12:31:23 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan  8 12:31:24 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan  8 12:31:24 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan  8 12:31:24 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan  8 12:31:24 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:31:24 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan  8 12:31:24 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan  8 12:31:24 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:31:24 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan  8 12:31:24 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1213 duration:170
Fri Jan  8 12:31:24 2021 user.info repacd: AssocTimeout
Fri Jan  8 12:31:24 2021 user.info repacd: Boot time count=-1
Fri Jan  8 12:31:24 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:31:24 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:31:24 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan  8 12:31:25 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan  8 12:31:26 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
2, off 0, len 1
Fri Jan  8 12:31:26 2021 user.notice led_function: =====LOOP END=====
Fri Jan  8 12:31:26 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:31:26 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan  8 12:31:26 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan  8 12:31:27 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan  8 12:31:27 2021 kern.warn kernel: RX Rate Info:
Fri Jan  8 12:31:27 2021 kern.warn kernel: MCS counts (0..9): 665, 1501, 3920,
15047, 38932, 43535, 54307, 34939, 3446, 833
Fri Jan  8 12:31:27 2021 kern.warn kernel: SGI counts (0..9): 240, 689, 1647,
7396, 13291, 16911, 27958, 17203, 1578, 459
Fri Jan  8 12:31:27 2021 kern.warn kernel: NSS counts: 1x1 125964, 2x2 71161,
3x3 0, 4x4 0
Fri Jan  8 12:31:27 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
```

Fri Jan 8 12:31:27 2021 kern.warn kernel: NSTS count: 571
Fri Jan 8 12:31:27 2021 kern.warn kernel: BW counts: 20MHz 198055, 40MHz 0,
80MHz 0, 160MHz 0
Fri Jan 8 12:31:27 2021 kern.warn kernel: Preamble counts: 113216, 89173, 0,
108882, 0, 0
Fri Jan 8 12:31:27 2021 kern.warn kernel: STBC rate counts (0..9): 238, 187,
51, 49, 23, 0, 1, 22, 0, 0
Fri Jan 8 12:31:27 2021 kern.warn kernel: LDPC Counts: 197022
Fri Jan 8 12:31:27 2021 kern.warn kernel: RSSI (data, mgmt): 32, 33
Fri Jan 8 12:31:27 2021 kern.warn kernel: RSSI Chain 0 (0x80 0x80 0x80 0x1e)
Fri Jan 8 12:31:27 2021 kern.warn kernel: RSSI Chain 1 (0x80 0x80 0x80 0x1b)
Fri Jan 8 12:31:27 2021 kern.warn kernel: RSSI Chain 2 (0x00 0x00 0x00 0x00)
Fri Jan 8 12:31:27 2021 kern.warn kernel: RSSI Chain 3 (0x00 0x00 0x00 0x00)
Fri Jan 8 12:31:27 2021 kern.warn kernel: RSSI (comb_ht): 32
Fri Jan 8 12:31:27 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:31:27 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:31:28 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:31:28 2021 kern.warn kernel: RX Rate Info:
Fri Jan 8 12:31:28 2021 kern.warn kernel: MCS counts (0..9): 4586, 0, 0, 0, 77,
20188, 68397, 129938, 501811, 27607
Fri Jan 8 12:31:28 2021 kern.warn kernel: SGI counts (0..9): 0, 0, 0, 0, 76,
20070, 66924, 126215, 498615, 15530
Fri Jan 8 12:31:28 2021 kern.warn kernel: NSS counts: 1x1 4580, 2x2 1557, 3x3
552329, 4x4 194138
Fri Jan 8 12:31:28 2021 kern.warn kernel: NSTS count: 0
Fri Jan 8 12:31:28 2021 kern.warn kernel: BW counts: 20MHz 29, 40MHz 56, 80MHz
757477, 160MHz 0
Fri Jan 8 12:31:28 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:31:28 2021 kern.warn kernel: Preamble counts: 135383, 56, 0,
757506, 0, 5271
Fri Jan 8 12:31:28 2021 kern.warn kernel: STBC rate counts (0..9):
Fri Jan 8 12:31:28 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:31:28 2021 kern.warn kernel: 0, 0, 0, 0, 0, 0, 0, 0, 0
Fri Jan 8 12:31:28 2021 kern.warn kernel: LDPC Counts: 748012
Fri Jan 8 12:31:28 2021 kern.warn kernel: RSSI (data, mgmt): 40, 18
Fri Jan 8 12:31:28 2021 kern.warn kernel: RSSI Chain 0 (0x80 0x25 0x21 0x24)
Fri Jan 8 12:31:28 2021 kern.warn kernel: RSSI Chain 1 (0x80 0x21 0x1e 0x22)
Fri Jan 8 12:31:28 2021 kern.warn kernel: RSSI Chain 2 (0x80 0x24 0x21 0x20)
Fri Jan 8 12:31:28 2021 kern.warn kernel: RSSI Chain 3 (0x80 0x1f 0x22 0x24)
Fri Jan 8 12:31:28 2021 kern.warn kernel: RSSI (comb_ht): 41
Fri Jan 8 12:31:28 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41188 event 0 reason 0
Fri Jan 8 12:31:28 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:31:28 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:31:28 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:31:28 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9

not handled in state INIT
Fri Jan 8 12:31:28 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:31:28 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:31:28 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:31:28 2021 kern.warn kernel: [wifi2] FWLOG: [47880610] WAL channel
change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:28 2021 kern.warn kernel: [wifi2] FWLOG: [47880747]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:31:28 2021 kern.warn kernel: [wifi2] FWLOG: [47880923] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:28 2021 kern.warn kernel: [wifi2] FWLOG: [47881060]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:31:28 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:31:28 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:31:28 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:31:28 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:31:29 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:31:29 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:31:29 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:29 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:31:29 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:29 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyTX Rate Info:
Fri Jan 8 12:31:29 2021 kern.warn kernel: MCS counts (0..9): 562, 704, 1316,
1625, 8547, 48752, 87878, 127536, 48445, 22270
Fri Jan 8 12:31:29 2021 kern.warn kernel: MCS counts SU (0..9): 562, 704, 1316,
1625, 8547, 48752, 87878, 127536, 48445, 22270
Fri Jan 8 12:31:29 2021 user.notice led_function: RSSI24G -63
Fri Jan 8 12:31:29 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:31:29 2021 kern.warn kernel: MCS counts MU (0..9): 0, 0, 0, 0, 0,
0, 0, 0, 0, 0
Fri Jan 8 12:31:29 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:31:29 2021 kern.warn kernel: SGI counts (0..9): 0, 0, 0, 0, 4949,
20507, 32271, 102113, 38553, 16570
Fri Jan 8 12:31:29 2021 kern.warn kernel: NSS counts: 1x1 152324, 2x2 195311,
3x3 0 4x4 0
Fri Jan 8 12:31:29 2021 kern.warn kernel: BW counts: 20MHz 347635, 40MHz 0,
80MHz 0, 160MHz 0
Fri Jan 8 12:31:29 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:31:29 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1217 duration:170
Fri Jan 8 12:31:29 2021 kern.warn kernel: Preamble (O C H V) counts: 0, 13120,
143104, 205499
Fri Jan 8 12:31:29 2021 kern.warn kernel: STBC rate counts (0..9): 562, 672,

1181, 1496, 1737, 10581, 33052, 50289, 0, 0
Fri Jan 8 12:31:29 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:29 2021 kern.warn kernel: LDPC Counts: 204531
Fri Jan 8 12:31:29 2021 kern.warn kernel: RTS Counts: 27147
Fri Jan 8 12:31:29 2021 kern.warn kernel: Ack RSSI: 32
Fri Jan 8 12:31:29 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:31:29 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:31:29 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:31:29 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:31:29 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:29 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:31:29 2021 kern.warn kernel: [wifi2] FWLOG: [47881236] WAL channel
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:29 2021 kern.warn kernel: [wifi2] FWLOG: [47881550] WAL channel
change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:29 2021 kern.warn kernel: [wifi2] FWLOG: [47881863] WAL channel
change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:29 2021 kern.warn kernel: [wifi2] FWLOG: [47882001]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:31:29 2021 kern.warn kernel: [wifi2] FWLOG: [47882177] WAL channel
change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:29 2021 kern.warn kernel: [wifi2] FWLOG: [47882314]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:31:30 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:31:30 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:31:30 2021 kern.warn kernel: TX Rate Info:
Fri Jan 8 12:31:30 2021 kern.warn kernel: MCS counts (0..9): 0, 0, 0, 0, 0,
8324, 125481, 166019, 365434, 217694
Fri Jan 8 12:31:30 2021 kern.warn kernel: MCS counts SU (0..9): 0, 0, 0, 0, 0,
8324, 125481, 166019, 365434, 217694
Fri Jan 8 12:31:30 2021 kern.warn kernel: MCS counts MU (0..9): 0, 0, 0, 0, 0,
0, 0, 0, 0, 0
Fri Jan 8 12:31:30 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:31:30 2021 kern.warn kernel: SGI counts (0..9): 0, 0, 0, 0, 0,
8294, 124427, 149841, 319175, 185317
Fri Jan 8 12:31:30 2021 kern.warn kernel: NSS counts: 1x1 0, 2x2 332, 3x3
545719 4x4 336901
Fri Jan 8 12:31:30 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:31:30 2021 kern.warn kernel: BW counts: 20MHz 391, 40MHz 0, 80MHz
882561, 160MHz 0
Fri Jan 8 12:31:30 2021 kern.warn kernel: Preamble (O C H V) counts: 2, 0, 0,
882952
Fri Jan 8 12:31:30 2021 kern.warn kernel: STBC rate counts (0..9): 0, 0, 0, 0,
0, 0, 0, 0, 0, 0
Fri Jan 8 12:31:30 2021 kern.warn kernel: LDPC Counts: 882952
Fri Jan 8 12:31:30 2021 kern.warn kernel: RTS Counts: 814
Fri Jan 8 12:31:30 2021 kern.warn kernel: Ack RSSI: 36

```
Fri Jan  8 12:31:30 2021 user.notice led_function: led check timeout
elapsed:46676 duration:180
Fri Jan  8 12:31:30 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan  8 12:31:30 2021 user.notice led_function:  CUR_STATE:
RE_LocationSuitable
Fri Jan  8 12:31:30 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41188 event 1 reason 1
Fri Jan  8 12:31:30 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan  8 12:31:30 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan  8 12:31:30 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition SCAN -> INIT
Fri Jan  8 12:31:30 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0
(c9e36000)
Fri Jan  8 12:31:30 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_END[3]
Fri Jan  8 12:31:30 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3
not handled in state INIT
Fri Jan  8 12:31:30 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan  8 12:31:30 2021 kern.warn kernel: vap-2(ath01):[a6:c9:eb:1a:a6:a1] send
null data frame on channel 13, pwr mgt dis
Fri Jan  8 12:31:30 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan  8 12:31:30 2021 kern.warn kernel: [wifi2] FWLOG: [47882490] WAL channel
change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan  8 12:31:30 2021 kern.warn kernel: [wifi2] FWLOG: [47882839]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan  8 12:31:30 2021 kern.warn kernel: [wifi2] FWLOG: [47882839]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan  8 12:31:31 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan  8 12:31:31 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan  8 12:31:32 2021 user.notice led_function: =====LOOP END=====
Fri Jan  8 12:31:32 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:31:32 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan  8 12:31:32 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan  8 12:31:33 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan  8 12:31:33 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan  8 12:31:33 2021 kern.warn kernel: Inst RSSI value of
node-08:c5:e1:c2:a4:0c: 43
Fri Jan  8 12:31:33 2021 kern.warn kernel: Inst RSSI value of
node-08:c5:e1:c2:a4:0c: 43
Fri Jan  8 12:31:33 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan  8 12:31:33 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan  8 12:31:33 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
```

Fri Jan 8 12:31:33 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:31:33 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:33 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:33 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
0, off 0, len 1
Fri Jan 8 12:31:33 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:31:33 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1222 duration:170
Fri Jan 8 12:31:33 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:31:33 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:31:33 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:33 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:33 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:31:35 2021 user.notice led_function: RSSI24G -63
Fri Jan 8 12:31:35 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:31:35 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:31:35 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41189 event 0 reason 0
Fri Jan 8 12:31:35 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:31:35 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:31:35 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:31:35 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan 8 12:31:35 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:31:35 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:35 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key[wifi2] FWLOG: [47887965] WAL channel change freq=5580, mode=0 flags=0
rx_ok=1 tx_ok=1
Fri Jan 8 12:31:35 2021 kern.warn kernel: [wifi2] FWLOG: [47888103]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:31:35 2021 kern.warn kernel: [wifi2] FWLOG: [47888279] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:35 2021 kern.warn kernel: [wifi2] FWLOG: [47888416]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:31:36 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:31:36 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:31:36 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:31:36 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:31:36 2021 user.notice led_function: led check timeout
elapsed:46683 duration:180

Fri Jan 8 12:31:36 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:31:36 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:31:36 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:31:36 2021 kern.warn kernel: [wifi2] FWLOG: [47888592] WAL channel
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:36 2021 kern.warn kernel: [wifi2] FWLOG: [47888905] WAL channel
change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:36 2021 kern.warn kernel: [wifi2] FWLOG: [47889219] WAL channel
change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:36 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:31:37 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:31:37 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41189 event 1 reason 1
Fri Jan 8 12:31:37 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:31:37 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition SCAN -> INIT
Fri Jan 8 12:31:37 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0
(c9e36000)
Fri Jan 8 12:31:37 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_END[3]
Fri Jan 8 12:31:37 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3
not handled in state INIT
Fri Jan 8 12:31:37 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:31:37 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:31:37 2021 kern.warn kernel: [wifi2] FWLOG: [47889532] WAL channel
change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:37 2021 kern.warn kernel: [wifi2] FWLOG: [47889845] WAL channel
change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:37 2021 kern.warn kernel: [wifi2] FWLOG: [47890186]
RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:31:37 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:31:37 2021 kern.warn kernel: [wifi2] FWLOG: [47890186]
RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:31:37 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:31:37 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
0, off 0, len 1
Fri Jan 8 12:31:37 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:31:37 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:31:38 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:38 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:38 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0

```
Fri Jan 8 12:31:38 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1226 duration:170
Fri Jan 8 12:31:38 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:31:38 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:31:38 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:38 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:38 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:31:38 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
2, off 0, len 1
Fri Jan 8 12:31:38 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:31:38 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:38 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
0, off 0, len 1
Fri Jan 8 12:31:39 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:31:39 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
2, off 0, len 1
Fri Jan 8 12:31:40 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:31:41 2021 user.notice led_function: RSSI24G -64
Fri Jan 8 12:31:41 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:31:42 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:31:42 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:31:42 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:31:42 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:42 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:31:42 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:31:42 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:31:42 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:42 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:31:42 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1231 duration:170
Fri Jan 8 12:31:42 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keySending SCAN START cmd
Fri Jan 8 12:31:42 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41190 event 0 reason 0
Fri Jan 8 12:31:42 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:42 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:31:42 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
```

Fri Jan 8 12:31:42 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:31:42 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:31:42 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_START[9]
Fri Jan 8 12:31:42 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:31:42 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9 not handled in state INIT
Fri Jan 8 12:31:42 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:42 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:31:42 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:31:42 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:31:42 2021 user.notice led_function: led check timeout elapsed:46689 duration:180
Fri Jan 8 12:31:42 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:31:42 2021 user.notice led_function: CUR_STATE: RE_LocationSuitable
Fri Jan 8 12:31:42 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
[wifi2] FWLOG: [47895310] WAL channel change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:42 2021 kern.warn kernel: [wifi2] FWLOG: [47895448] WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:31:42 2021 kern.warn kernel: [wifi2] FWLOG: [47895624] WAL channel change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:42 2021 kern.warn kernel: [wifi2] FWLOG: [47895761] WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:31:43 2021 kern.warn kernel: [wifi2] FWLOG: [47895937] WAL channel change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:43 2021 kern.warn kernel: [wifi2] FWLOG: [47896250] WAL channel change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:43 2021 kern.warn kernel: [wifi2] FWLOG: [47896564] WAL channel change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:44 2021 kern.warn kernel: vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41190 event 1 reason 1
Fri Jan 8 12:31:44 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:31:44 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:31:44 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state transition SCAN -> INIT
Fri Jan 8 12:31:44 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0 (c9e36000)
Fri Jan 8 12:31:44 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_END[3]
Fri Jan 8 12:31:44 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3 not handled in state INIT
Fri Jan 8 12:31:44 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:44 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:31:44 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:31:44 2021 kern.warn kernel: [wifi2] FWLOG: [47896877] WAL channel

```
change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan  8 12:31:44 2021 kern.warn kernel: [wifi2] FWLOG: [47897190] WAL channel
change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan  8 12:31:44 2021 kern.warn kernel: [wifi2] FWLOG: [47897531]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan  8 12:31:44 2021 kern.warn kernel: [wifi2] FWLOG: [47897531]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan  8 12:31:46 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan  8 12:31:46 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan  8 12:31:46 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan  8 12:31:46 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:31:46 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:31:46 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan  8 12:31:46 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan  8 12:31:46 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:31:46 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:31:46 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan  8 12:31:46 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1235 duration:170
Fri Jan  8 12:31:46 2021 user.info repacd: AssocTimeout
Fri Jan  8 12:31:46 2021 user.info repacd: Boot time count=-1
Fri Jan  8 12:31:46 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:31:46 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:31:47 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan  8 12:31:47 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
2, off 0, len 1
Fri Jan  8 12:31:47 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan  8 12:31:47 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan  8 12:31:47 2021 user.notice led_function: RSSI24G -64
Fri Jan  8 12:31:47 2021 user.notice led_function: PING IS WELL
Fri Jan  8 12:31:48 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan  8 12:31:48 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan  8 12:31:48 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan  8 12:31:48 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan  8 12:31:48 2021 user.notice led_function: led check timeout
elapsed:46695 duration:180
Fri Jan  8 12:31:48 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan  8 12:31:48 2021 user.notice led_function: CUR_STATE:
```


RE_LocationSuitable

```
Fri Jan 8 12:31:49 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:31:49 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:31:49 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41191 event 0 reason 0
Fri Jan 8 12:31:49 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:31:49 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:31:49 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:31:49 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan 8 12:31:49 2021 kern.warn kernel: [wifi2] FWLOG: [47902654] WAL channel
change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:49 2021 kern.warn kernel: [wifi2] FWLOG: [47902792]
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan 8 12:31:50 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:31:50 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:50 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:31:50 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:31:50 2021 kern.warn kernel: [wifi2] FWLOG: [47902968] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:50 2021 kern.warn kernel: [wifi2] FWLOG: [47903105]
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan 8 12:31:50 2021 kern.warn kernel: [wifi2] FWLOG: [47903281] WAL channel
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:50 2021 kern.warn kernel: [wifi2] FWLOG: [47903594] WAL channel
change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:50 2021 kern.warn kernel: [wifi2] FWLOG: [47903908] WAL channel
change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:51 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:31:51 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:31:51 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:31:51 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:31:51 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:51 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:51 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:31:51 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1239 duration:170
Fri Jan 8 12:31:51 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:31:51 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:31:51 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:51 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
```

Fri Jan 8 12:31:51 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:31:51 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:31:51 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:31:51 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41191 event 1 reason 1
Fri Jan 8 12:31:51 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:31:51 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition SCAN -> INIT
Fri Jan 8 12:31:51 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0 (c9e36000)
Fri Jan 8 12:31:51 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_END[3]
Fri Jan 8 12:31:51 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3 not handled in state INIT
Fri Jan 8 12:31:51 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:31:51 2021 kern.warn kernel: [wifi2] FWLOG: [47904221] WAL channel change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:51 2021 kern.warn kernel: [wifi2] FWLOG: [47904535] WAL channel change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:51 2021 kern.warn kernel: [wifi2] FWLOG: [47904875] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:31:51 2021 kern.warn kernel: [wifi2] FWLOG: [47904875] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:31:52 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:31:53 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:31:53 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:31:53 2021 user.notice led_function: RSSI24G -64
Fri Jan 8 12:31:53 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:31:54 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:31:54 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:31:54 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:31:54 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:31:55 2021 user.notice led_function: led check timeout elapsed:46701 duration:180
Fri Jan 8 12:31:55 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:31:55 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:31:55 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:31:55 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:

```
Fri Jan 8 12:31:55 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:31:55 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:31:55 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:31:55 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
2, off 0, len 1
Fri Jan 8 12:31:55 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:31:55 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:55 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:55 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:31:55 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1244 duration:170
Fri Jan 8 12:31:55 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:31:55 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:31:55 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:55 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
0, off 0, len 1
Fri Jan 8 12:31:55 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:55 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:31:56 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
1, off 0, len 1
Fri Jan 8 12:31:56 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:56 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
1, off 0, len 1
Fri Jan 8 12:31:56 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:31:56 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:31:56 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41192 event 0 reason 0
Fri Jan 8 12:31:56 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:31:56 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:31:56 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:31:56 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan 8 12:31:56 2021 kern.warn kernel: [wifi2] FWLOG: [47910000] WAL channel
change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:56 2021 kern.warn kernel: [wifi2] FWLOG: [47910137]
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan 8 12:31:57 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:31:57 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:31:57 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
```

```
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:31:57 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:31:57 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:31:57 2021 kern.warn kernel: [wifi2] FWLOG: [47910313] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:58 2021 kern.warn kernel: [wifi2] FWLOG: [47910450]
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan 8 12:31:58 2021 kern.warn kernel: [wifi2] FWLOG: [47910626] WAL channel
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:58 2021 kern.warn kernel: [wifi2] FWLOG: [47910940] WAL channel
change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:58 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:31:58 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:31:58 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:31:58 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:31:58 2021 kern.warn kernel: [wifi2] FWLOG: [47911253] WAL channel
change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:59 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41192 event 1 reason 1
Fri Jan 8 12:31:59 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:31:59 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition SCAN -> INIT
Fri Jan 8 12:31:59 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0
(c9e36000)
Fri Jan 8 12:31:59 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_END[3]
Fri Jan 8 12:31:59 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3
not handled in state INIT
Fri Jan 8 12:31:59 2021 kern.warn kernel: [wifi2] FWLOG: [47911567] WAL channel
change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:59 2021 kern.warn kernel: [wifi2] FWLOG: [47911880] WAL channel
change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:31:59 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:31:59 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:31:59 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:31:59 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:31:59 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:31:59 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:31:59 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key[wifi2] FWLOG: [47912221] RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan 8 12:31:59 2021 kern.warn kernel: [wifi2] FWLOG: [47912221]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
```

Fri Jan 8 12:32:00 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:32:00 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:00 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:00 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:32:00 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1248 duration:170
Fri Jan 8 12:32:00 2021 user.notice led_function: RSSI24G -64
Fri Jan 8 12:32:00 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:32:00 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:32:00 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:32:00 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:00 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:00 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:01 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:01 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:32:01 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:32:01 2021 user.notice led_function: led check timeout
elapsed:46707 duration:180
Fri Jan 8 12:32:01 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:32:01 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:32:02 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:02 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:32:02 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:32:02 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:32:03 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:32:03 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:32:03 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:03 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:03 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:32:03 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:32:03 2021 kern.warn kernel: Inst RSSI value of
node-08:c5:e1:c2:a4:0c: 44
Fri Jan 8 12:32:03 2021 kern.warn kernel: Inst RSSI value of
node-08:c5:e1:c2:a4:0c: 43
Fri Jan 8 12:32:03 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:32:04 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:32:04 2021 kern.warn kernel:

vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41193 event 0 reason 0
Fri Jan 8 12:32:04 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:32:04 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state transition INIT -> SCAN
Fri Jan 8 12:32:04 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_START[9]
Fri Jan 8 12:32:04 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9 not handled in state INIT
Fri Jan 8 12:32:04 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:32:04 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:32:04 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:04 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:04 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:04 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:32:04 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:04 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 ::: force_down_5g:0
Fri Jan 8 12:32:04 2021 user.debug repacd.wifimon: repacd check timeout elapsed:1253 duration:170
Fri Jan 8 12:32:04 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:04 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:32:04 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:32:04 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:04 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:04 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:04 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:32:04 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:32:04 2021 kern.warn kernel: [wifi2] FWLOG: [47917372] WAL channel change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:04 2021 kern.warn kernel: [wifi2] FWLOG: [47917509]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:32:05 2021 kern.warn kernel: [wifi2] FWLOG: [47917685] WAL channel change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:05 2021 kern.warn kernel: [wifi2] FWLOG: [47917822]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:32:05 2021 kern.warn kernel: [wifi2] FWLOG: [47917999] WAL channel change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:05 2021 kern.warn kernel: [wifi2] FWLOG: [47918312] WAL channel change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:05 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:32:05 2021 kern.warn kernel: vap-0(ath1):

[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:32:05 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:32:05 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:32:05 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:32:05 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:32:05 2021 kern.warn kernel: [wifi2] FWLOG: [47918625] WAL channel
change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:05 2021 kern.warn kernel: [wifi2] FWLOG: [47918939] WAL channel
change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:06 2021 kern.warn kernel: [wifi2] FWLOG: [47919076]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:32:06 2021 kern.warn kernel: [wifi2] FWLOG: [47919252] WAL channel
change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:06 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41193 event 1 reason 1
Fri Jan 8 12:32:06 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:32:06 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition SCAN -> INIT
Fri Jan 8 12:32:06 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0
(c9e36000)
Fri Jan 8 12:32:06 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_END[3]
Fri Jan 8 12:32:06 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3
not handled in state INIT
Fri Jan 8 12:32:06 2021 kern.warn kernel: Printing wds entries [No. of
entries:0]
Fri Jan 8 12:32:06 2021 kern.warn kernel: DA Next Hop
flags
Fri Jan 8 12:32:06 2021 kern.warn kernel:
Fri Jan 8 12:32:06 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:32:06 2021 user.notice led_function: RSSI24G -64
Fri Jan 8 12:32:06 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:32:06 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:06 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:06 2021 kern.warn kernel: [wifi2] FWLOG: [47919593]
RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:32:06 2021 kern.warn kernel: [wifi2] FWLOG: [47919593]
RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:32:07 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:32:07 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:32:07 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:32:07 2021 user.notice led_function: WPS CHECK LOOP:1 wps:

```
Fri Jan 8 12:32:07 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:32:07 2021 user.notice led_function: led check timeout
elapsed:46713 duration:180
Fri Jan 8 12:32:07 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:32:07 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:32:07 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:32:08 2021 kern.warn kernel: Printing wds entries [No. of
entries:0]
Fri Jan 8 12:32:08 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:32:08 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:32:08 2021 kern.warn kernel: DA Next Hop
flags
Fri Jan 8 12:32:08 2021 kern.warn kernel:
Fri Jan 8 12:32:08 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:09 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:09 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:32:09 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:09 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:32:09 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1257 duration:170
Fri Jan 8 12:32:09 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:09 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:32:09 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:32:09 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:09 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:09 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:32:09 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:09 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:10 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:11 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keySending SCAN START cmd
Fri Jan 8 12:32:11 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41194 event 0 reason 0
Fri Jan 8 12:32:11 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:32:11 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:32:11 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:32:11 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
```


not handled in state INIT
Fri Jan 8 12:32:11 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:11 2021 kern.warn kernel: [wifi2] FWLOG: [47924730] WAL channel change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:12 2021 kern.warn kernel: [wifi2] FWLOG: [47924868] WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:32:12 2021 kern.warn kernel: [wifi2] FWLOG: [47925044] WAL channel change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:12 2021 kern.warn kernel: [wifi2] FWLOG: [47925181] WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:32:12 2021 kern.warn kernel: [wifi2] FWLOG: [47925357] WAL channel change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:12 2021 user.notice led_function: RSSI24G -64
Fri Jan 8 12:32:12 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:32:13 2021 kern.warn kernel: [wifi2] FWLOG: [47925670] WAL channel change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:13 2021 kern.warn kernel: [wifi2] FWLOG: [47925984] WAL channel change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:13 2021 kern.warn kernel: [wifi2] FWLOG: [47926121] WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:32:13 2021 kern.warn kernel: [wifi2] FWLOG: [47926297] WAL channel change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:13 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:32:13 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:32:13 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:13 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:13 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:32:13 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:13 2021 kern.warn kernel: vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41194 event 1 reason 1
Fri Jan 8 12:32:13 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:32:13 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state transition SCAN -> INIT
Fri Jan 8 12:32:13 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0 (c9e36000)
Fri Jan 8 12:32:13 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_END[3]
Fri Jan 8 12:32:13 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3 not handled in state INIT
Fri Jan 8 12:32:13 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:13 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 ::: force_down_5g:0
Fri Jan 8 12:32:13 2021 user.debug repacd.wifimon: repacd check timeout elapsed:1262 duration:170
Fri Jan 8 12:32:13 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:13 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:32:13 2021 user.info repacd: Boot time count=-1

```
Fri Jan 8 12:32:13 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:13 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:32:13 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:32:13 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:13 2021 user.notice led_function: led check timeout
elapsed:46720 duration:180
Fri Jan 8 12:32:13 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:32:13 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:32:13 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:13 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
key[wifi2] FWLOG: [47926611] WAL channel change freq=5700, mode=0 flags=0
rx_ok=1 tx_ok=1
Fri Jan 8 12:32:14 2021 kern.warn kernel: [wifi2] FWLOG: [47926951]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan 8 12:32:14 2021 kern.warn kernel: [wifi2] FWLOG: [47926951]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan 8 12:32:15 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:32:15 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:16 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:17 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
2, off 0, len 1
Fri Jan 8 12:32:17 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:17 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:32:17 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:32:17 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:32:17 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:32:17 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:32:17 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:32:17 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:17 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:32:17 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:32:17 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:32:17 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:32:17 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:17 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:17 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:17 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:32:17 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1266 duration:170
```

```
Fri Jan 8 12:32:17 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:32:18 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:32:18 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:32:18 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:18 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:32:18 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:32:18 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:18 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:32:18 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:32:18 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:18 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:32:18 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:32:18 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41195 event 0 reason 0
Fri Jan 8 12:32:18 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:32:18 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:32:18 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:32:18 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan 8 12:32:18 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:32:18 2021 user.notice led_function: RSSI24G -64
Fri Jan 8 12:32:18 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:32:18 2021 kern.warn kernel: [wifi2] FWLOG: [47932086] WAL channel
change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:19 2021 kern.warn kernel: [wifi2] FWLOG: [47932223]
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan 8 12:32:19 2021 kern.warn kernel: [wifi2] FWLOG: [47932399] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:19 2021 kern.warn kernel: [wifi2] FWLOG: [47932536]
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan 8 12:32:19 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:32:19 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:32:19 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:32:19 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:32:19 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:32:19 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:32:19 2021 user.notice led_function: led check timeout
elapsed:46726 duration:180
```

```
Fri Jan 8 12:32:19 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:32:19 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:32:19 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:32:19 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:32:19 2021 kern.warn kernel: [wifi2] FWLOG: [47932713] WAL channel
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:20 2021 kern.warn kernel: [wifi2] FWLOG: [47933026] WAL channel
change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:20 2021 kern.warn kernel: [wifi2] FWLOG: [47933339] WAL channel
change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:20 2021 kern.warn kernel: [wifi2] FWLOG: [47933653] WAL channel
change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:20 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:32:20 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:32:20 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:32:20 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41195 event 1 reason 1
Fri Jan 8 12:32:20 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:32:20 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition SCAN -> INIT
Fri Jan 8 12:32:20 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0
(c9e36000)
Fri Jan 8 12:32:20 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_END[3]
Fri Jan 8 12:32:20 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3
not handled in state INIT
Fri Jan 8 12:32:20 2021 kern.warn kernel: [wifi2] FWLOG: [47933966] WAL channel
change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:21 2021 kern.warn kernel: [wifi2] FWLOG: [47934306]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan 8 12:32:21 2021 kern.warn kernel: [wifi2] FWLOG: [47934306]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan 8 12:32:21 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:32:21 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:21 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:32:22 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:32:22 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:22 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:22 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:22 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:32:22 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:22 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
```

force_down_5g:0
Fri Jan 8 12:32:22 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1270 duration:170
Fri Jan 8 12:32:22 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:22 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:32:22 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:32:22 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:22 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:22 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:23 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):[a6:c9:eb:1a:a6:a1] send null data frame on channel 13, pwr mgt
dis
Fri Jan 8 12:32:24 2021 user.notice led_function: RSSI24G -64
Fri Jan 8 12:32:24 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:32:25 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:32:25 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:32:25 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41196 event 0 reason 0
Fri Jan 8 12:32:25 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:32:25 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:32:25 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:32:25 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan 8 12:32:25 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:32:25 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:32:25 2021 user.notice led_function: led check timeout
elapsed:46732 duration:180
Fri Jan 8 12:32:25 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:32:26 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:32:26 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:32:26 2021 kern.warn kernel: [wifi2] FWLOG: [47939430] WAL channel
change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:26 2021 kern.warn kernel: [wifi2] FWLOG: [47939568]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:32:26 2021 kern.warn kernel: [wifi2] FWLOG: [47939744] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:26 2021 kern.warn kernel: [wifi2] FWLOG: [47939881]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:32:26 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:32:26 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:32:26 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key

Fri Jan 8 12:32:26 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:26 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:32:26 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:26 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:26 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 ::: force_down_5g:0
Fri Jan 8 12:32:26 2021 user.debug repacd.wifimon: repacd check timeout elapsed:1275 duration:170
Fri Jan 8 12:32:26 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:32:26 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:32:26 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:26 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:26 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:27 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:32:27 2021 kern.warn kernel: [wifi2] FWLOG: [47940057] WAL channel change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:27 2021 kern.warn kernel: [wifi2] FWLOG: [47940371] WAL channel change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:27 2021 kern.warn kernel: [wifi2] FWLOG: [47940684] WAL channel change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:27 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:32:27 2021 kern.warn kernel: RX Rate Info:
Fri Jan 8 12:32:27 2021 kern.warn kernel: MCS counts (0..9): 665, 1501, 3938, 15085, 39037, 43604, 54378, 34959, 3447, 833
Fri Jan 8 12:32:27 2021 kern.warn kernel: SGI counts (0..9): 240, 689, 1658, 7420, 13352, 16955, 28021, 17208, 1578, 459
Fri Jan 8 12:32:27 2021 kern.warn kernel: NSS counts: 1x1 126095, 2x2 71352, 3x3 0, 4x4 0
Fri Jan 8 12:32:27 2021 kern.warn kernel: NSTS count: 571
Fri Jan 8 12:32:27 2021 kern.warn kernel: BW counts: 20MHz 198380, 40MHz 0, 80MHz 0, 160MHz 0
Fri Jan 8 12:32:27 2021 kern.warn kernel: Preamble counts: 113428, 89173, 0, 109207, 0, 0
Fri Jan 8 12:32:27 2021 kern.warn kernel: STBC rate counts (0..9): 238, 187, 51, 49, 23, 0, 1, 22, 0, 0
Fri Jan 8 12:32:27 2021 kern.warn kernel: LDPC Counts: 197344
Fri Jan 8 12:32:27 2021 kern.warn kernel: RSSI (data, mgmt): 32, 34
Fri Jan 8 12:32:27 2021 kern.warn kernel: RSSI Chain 0 (0x80 0x80 0x80 0x1e)
Fri Jan 8 12:32:27 2021 kern.warn kernel: RSSI Chain 1 (0x80 0x80 0x80 0x1b)
Fri Jan 8 12:32:27 2021 kern.warn kernel: RSSI Chain 2 (0x00 0x00 0x00 0x00)
Fri Jan 8 12:32:27 2021 kern.warn kernel: RSSI Chain 3 (0x00 0x00 0x00 0x00)
Fri Jan 8 12:32:27 2021 kern.warn kernel: RSSI (comb_ht): 32
Fri Jan 8 12:32:27 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:32:27 2021 kern.warn kernel:

vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41196 event 1 reason 1
Fri Jan 8 12:32:27 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:32:27 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state transition SCAN -> INIT
Fri Jan 8 12:32:27 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0 (c9e36000)
Fri Jan 8 12:32:27 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_END[3]
Fri Jan 8 12:32:27 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3 not handled in state INIT
Fri Jan 8 12:32:27 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:28 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:32:28 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:28 2021 kern.warn kernel: [wifi2] FWLOG: [47940997] WAL channel change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:28 2021 kern.warn kernel: [wifi2] FWLOG: [47941311] WAL channel change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:28 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
key
Fri Jan 8 12:32:28 2021 kern.warn kernel: [wifi2] FWLOG: [47941448] WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:32:28 2021 kern.warn kernel: [wifi2] FWLOG: [47941651] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:32:28 2021 kern.warn kernel: [wifi2] FWLOG: [47941651] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:32:28 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
keyRX Rate Info:
Fri Jan 8 12:32:28 2021 kern.warn kernel: MCS counts (0..9): 4586, 0, 0, 0, 77, 20188, 68397, 129938, 501811, 27607
Fri Jan 8 12:32:28 2021 kern.warn kernel: SGI counts (0..9): 0, 0, 0, 0, 76, 20070, 66924, 126215, 498615, 15530
Fri Jan 8 12:32:28 2021 kern.warn kernel: NSS counts: 1x1 4580, 2x2 1557, 3x3 552329, 4x4 194138
Fri Jan 8 12:32:28 2021 kern.warn kernel: NSTS count: 0
Fri Jan 8 12:32:28 2021 kern.warn kernel: BW counts: 20MHz 29, 40MHz 56, 80MHz 757477, 160MHz 0
Fri Jan 8 12:32:28 2021 kern.warn kernel: Preamble counts: 135383, 56, 0, 757506, 0, 5271
Fri Jan 8 12:32:28 2021 kern.warn kernel: STBC rate counts (0..9): 0, 0, 0, 0, 0, 0, 0, 0, 0, 0
Fri Jan 8 12:32:28 2021 kern.warn kernel: LDPC Counts: 748012
Fri Jan 8 12:32:28 2021 kern.warn kernel: RSSI (data, mgmt): 40, 18
Fri Jan 8 12:32:28 2021 kern.warn kernel: RSSI Chain 0 (0x80 0x25 0x21 0x24)
Fri Jan 8 12:32:28 2021 kern.warn kernel: RSSI Chain 1 (0x80 0x21 0x1e 0x22)
Fri Jan 8 12:32:28 2021 kern.warn kernel: RSSI Chain 2 (0x80 0x24 0x21 0x20)
Fri Jan 8 12:32:28 2021 kern.warn kernel: RSSI Chain 3 (0x80 0x1f 0x22 0x24)
Fri Jan 8 12:32:28 2021 kern.warn kernel: RSSI (comb_ht): 41
Fri Jan 8 12:32:29 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
key
Fri Jan 8 12:32:29 2021 kern.warn kernel: TX Rate Info:

Fri Jan 8 12:32:29 2021 kern.warn kernel: MCS counts (0..9): 562, 704, 1316, 1625, 8547, 49038, 88327, 127559, 48445, 22270
Fri Jan 8 12:32:29 2021 kern.warn kernel: MCS counts SU (0..9): 562, 704, 1316, 1625, 8547, 49038, 88327, 127559, 48445, 22270
Fri Jan 8 12:32:29 2021 kern.warn kernel: MCS counts MU (0..9): 0, 0, 0, 0, 0, 0, 0, 0, 0, 0
Fri Jan 8 12:32:29 2021 kern.warn kernel: SGI counts (0..9): 0, 0, 0, 0, 4949, 20793, 32675, 102113, 38553, 16570
Fri Jan 8 12:32:29 2021 kern.warn kernel: NSS counts: 1x1 152324, 2x2 196069, 3x3 0 4x4 0
Fri Jan 8 12:32:29 2021 kern.warn kernel: BW counts: 20MHz 348393, 40MHz 0, 80MHz 0, 160MHz 0
Fri Jan 8 12:32:29 2021 kern.warn kernel: Preamble (O C H V) counts: 0, 13120, 143104, 206257
Fri Jan 8 12:32:29 2021 kern.warn kernel: STBC rate counts (0..9): 562, 672, 1181, 1496, 1737, 10581, 33052, 50289, 0, 0
Fri Jan 8 12:32:29 2021 kern.warn kernel: LDPC Counts: 205289
Fri Jan 8 12:32:29 2021 kern.warn kernel: RTS Counts: 27235
Fri Jan 8 12:32:29 2021 kern.warn kernel: Ack RSSI: -128
Fri Jan 8 12:32:30 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:30 2021 kern.warn kernel: TX Rate Info:
Fri Jan 8 12:32:30 2021 kern.warn kernel: MCS counts (0..9): 0, 0, 0, 0, 0, 8324, 125481, 166019, 365434, 217694
Fri Jan 8 12:32:30 2021 kern.warn kernel: MCS counts SU (0..9): 0, 0, 0, 0, 0, 8324, 125481, 166019, 365434, 217694
Fri Jan 8 12:32:30 2021 kern.warn kernel: MCS counts MU (0..9): 0, 0, 0, 0, 0, 0, 0, 0, 0, 0
Fri Jan 8 12:32:30 2021 kern.warn kernel: SGI counts (0..9): 0, 0, 0, 0, 0, 8294, 124427, 149841, 319175, 185317
Fri Jan 8 12:32:30 2021 kern.warn kernel: NSS counts: 1x1 0, 2x2 332, 3x3 545719 4x4 336901
Fri Jan 8 12:32:30 2021 kern.warn kernel: BW counts: 20MHz 391, 40MHz 0, 80MHz 882561, 160MHz 0
Fri Jan 8 12:32:30 2021 kern.warn kernel: Preamble (O C H V) counts: 2, 0, 0, 882952
Fri Jan 8 12:32:30 2021 kern.warn kernel: STBC rate counts (0..9): 0, 0, 0, 0, 0, 0, 0, 0, 0, 0
Fri Jan 8 12:32:30 2021 kern.warn kernel: LDPC Counts: 882952
Fri Jan 8 12:32:30 2021 kern.warn kernel: RTS Counts: 814
Fri Jan 8 12:32:30 2021 kern.warn kernel: Ack RSSI: 36
Fri Jan 8 12:32:30 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:32:30 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:32:30 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:30 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:30 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:32:30 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:30 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:31 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 ::: force_down_5g:0


```
Fri Jan 8 12:32:31 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1279 duration:170
Fri Jan 8 12:32:31 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:32:31 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:32:31 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:31 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:31 2021 user.notice led_function: RSSI24G -64
Fri Jan 8 12:32:31 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:31 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:32:31 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
1, off 0, len 1
Fri Jan 8 12:32:32 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:32:32 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:32:32 2021 user.notice led_function: led check timeout
elapsed:46738 duration:180
Fri Jan 8 12:32:32 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:32:32 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:32:32 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:32:32 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:32:32 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:32:32 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41197 event 0 reason 0
Fri Jan 8 12:32:32 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:32:32 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:32:32 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:32:32 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan 8 12:32:33 2021 kern.warn kernel: [wifi2] FWLOG: [47946775] WAL channel
change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:33 2021 kern.warn kernel: [wifi2] FWLOG: [47946913]
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan 8 12:32:34 2021 kern.warn kernel: [wifi2] FWLOG: [47947089] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:34 2021 kern.warn kernel: [wifi2] FWLOG: [47947226]
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan 8 12:32:34 2021 kern.warn kernel: [wifi2] FWLOG: [47947402] WAL channel
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:34 2021 kern.warn kernel: [wifi2] FWLOG: [47947716] WAL channel
change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:34 2021 kern.warn kernel: [wifi2] FWLOG: [47948029] WAL channel
change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:34 2021 user.notice led_function: =====LOOP END=====
```

Fri Jan 8 12:32:34 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:34 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:34 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41197 event 1 reason 1
Fri Jan 8 12:32:34 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:32:34 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition SCAN -> INIT
Fri Jan 8 12:32:34 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0
(c9e36000)
Fri Jan 8 12:32:34 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_END[3]
Fri Jan 8 12:32:34 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3
not handled in state INIT
Fri Jan 8 12:32:35 2021 kern.warn kernel: [wifi2] FWLOG: [47948342] WAL channel
change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:35 2021 kern.warn kernel: [wifi2] FWLOG: [47948480]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:32:35 2021 kern.warn kernel: [wifi2] FWLOG: [47948656] WAL channel
change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:35 2021 kern.warn kernel: [wifi2] FWLOG: [47948793]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:32:35 2021 kern.warn kernel: [wifi2] FWLOG: [47948996]
RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:32:35 2021 kern.warn kernel: [wifi2] FWLOG: [47948996]
RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:32:35 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:32:35 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:32:35 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:32:35 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:35 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:35 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:32:35 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:35 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:32:35 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1284 duration:170
Fri Jan 8 12:32:35 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:35 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:32:35 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:32:35 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:35 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:36 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:36 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid

keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:32:37 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:32:37 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:32:37 2021 kern.warn kernel: Inst RSSI value of
node-08:c5:e1:c2:a4:0c: 44
Fri Jan 8 12:32:37 2021 kern.warn kernel: Inst RSSI value of
node-08:c5:e1:c2:a4:0c: 44
Fri Jan 8 12:32:37 2021 user.notice led_function: RSSI24G -64
Fri Jan 8 12:32:37 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:32:37 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:32:37 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:32:38 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:38 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:32:38 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:32:38 2021 user.notice led_function: led check timeout
elapsed:46745 duration:180
Fri Jan 8 12:32:38 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:32:38 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:32:39 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:39 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:32:39 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:32:39 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:32:39 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:32:39 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:32:39 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:39 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:32:39 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:32:39 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:32:39 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:39 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:39 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:39 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:32:39 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1288 duration:170
Fri Jan 8 12:32:39 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:32:39 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:32:39 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:32:39 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key

Fri Jan 8 12:32:39 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:32:39 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:32:39 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:32:39 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:39 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41198 event 0 reason 0
Fri Jan 8 12:32:39 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:32:39 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:32:39 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:32:39 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan 8 12:32:40 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:32:40 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:40 2021 kern.warn kernel: [wifi2] FWLOG: [47954132] WAL channel
change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:40 2021 kern.warn kernel: [wifi2] FWLOG: [47954270]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:32:40 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:32:40 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:32:40 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:40 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:40 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:32:40 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:32:41 2021 kern.warn kernel: [wifi2] FWLOG: [47954446] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:41 2021 kern.warn kernel: [wifi2] FWLOG: [47954583]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:32:41 2021 kern.warn kernel: [wifi2] FWLOG: [47954759] WAL channel
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:41 2021 kern.warn kernel: [wifi2] FWLOG: [47955073] WAL channel
change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:41 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:32:41 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:32:42 2021 kern.warn kernel: [wifi2] FWLOG: [47955386] WAL channel
change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:42 2021 kern.warn kernel: [wifi2]
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41198 event 1 reason 1
Fri Jan 8 12:32:42 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 3, cur_state=1, vap_deleted_is_set=0

Fri Jan 8 12:32:42 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition SCAN -> INIT
Fri Jan 8 12:32:42 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0
(c9e36000)
Fri Jan 8 12:32:42 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_END[3]
Fri Jan 8 12:32:42 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3
not handled in state INIT
Fri Jan 8 12:32:42 2021 kern.warn kernel: FWLOG: [47955699] WAL channel change
freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:42 2021 kern.warn kernel: [wifi2] FWLOG: [47955837]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:32:42 2021 kern.warn kernel: [wifi2] FWLOG: [47956013] WAL channel
change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:42 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:32:43 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:32:43 2021 kern.warn kernel: [wifi2] FWLOG: [47956355]
RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:32:43 2021 kern.warn kernel: [wifi2] FWLOG: [47956355]
RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:32:43 2021 user.notice led_function: RSSI24G -63
Fri Jan 8 12:32:43 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:32:43 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:32:44 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:32:44 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:32:44 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:44 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:32:44 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:44 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:44 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:32:44 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1292 duration:170
Fri Jan 8 12:32:44 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:32:44 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:32:44 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:44 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:44 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:44 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:32:44 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:32:44 2021 user.notice led_function: led check timeout
elapsed:46751 duration:180
Fri Jan 8 12:32:44 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:32:44 2021 user.notice led_function: CUR_STATE:

RE_LocationSuitable

```
Fri Jan 8 12:32:46 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:46 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:32:46 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:32:46 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:32:46 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:32:46 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:46 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:32:46 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:32:46 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:32:47 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:32:47 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:32:47 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41199 event 0 reason 0
Fri Jan 8 12:32:47 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:32:47 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:32:47 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:32:47 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan 8 12:32:47 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:32:48 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:32:48 2021 kern.warn kernel: [wifi2] FWLOG: [47961515] WAL channel
change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:48 2021 kern.warn kernel: [wifi2] FWLOG: [47961652]
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan 8 12:32:48 2021 kern.warn kernel: [wifi2] FWLOG: [47961828] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:48 2021 kern.warn kernel: [wifi2] FWLOG: [47961965]
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan 8 12:32:48 2021 kern.warn kernel: [wifi2] FWLOG: [47962141] WAL channel
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:48 2021 kern.warn kernel: [wifi2] FWLOG: [47962455] WAL channel
change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:48 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:32:48 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:32:48 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:32:48 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:48 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
```

```
Fri Jan 8 12:32:48 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:48 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:48 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:32:48 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1297 duration:170
Fri Jan 8 12:32:48 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:32:48 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:48 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:32:48 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:48 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:48 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:49 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:49 2021 kern.warn kernel: [wifi2] FWLOG: [47962768] WAL channel
change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:49 2021 kern.warn kernel: [wifi2] FWLOG: [47963082] WAL channel
change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:49 2021 kern.warn kernel: [wifi2] FWLOG: [47963395] WAL channel
change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:49 2021 kern.warn kernel: [wifi2] FWLOG: [47963532]
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan 8 12:32:49 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41199 event 1 reason 1
Fri Jan 8 12:32:49 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:32:49 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition SCAN -> INIT
Fri Jan 8 12:32:49 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0
(c9e36000)
Fri Jan 8 12:32:49 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_END[3]
Fri Jan 8 12:32:49 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3
not handled in state INIT
Fri Jan 8 12:32:49 2021 user.notice led_function: RSSI24G -64
Fri Jan 8 12:32:49 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:32:50 2021 kern.warn kernel: [wifi2] FWLOG: [47963735]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan 8 12:32:50 2021 kern.warn kernel: [wifi2] FWLOG: [47963735]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan 8 12:32:50 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:32:50 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:32:50 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:32:50 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
```

Fri Jan 8 12:32:50 2021 user.notice led_function: led check timeout
elapsed:46757 duration:180
Fri Jan 8 12:32:50 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:32:50 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:32:51 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:32:51 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:51 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:32:51 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:32:51 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:32:52 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:32:52 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:32:52 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:32:52 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:32:52 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:32:52 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:32:52 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:52 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:32:53 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:53 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:53 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:32:53 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:32:53 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:32:53 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:53 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:53 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:32:53 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1301 duration:170
Fri Jan 8 12:32:53 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:53 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:32:53 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:32:53 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:32:53 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:32:53 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key

Fri Jan 8 12:32:53 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:54 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Sending SCAN START cmd
Fri Jan 8 12:32:54 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41200 event 0 reason 0
Fri Jan 8 12:32:54 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:32:54 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state transition INIT -> SCAN
Fri Jan 8 12:32:54 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_START[9]
Fri Jan 8 12:32:54 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9 not handled in state INIT
Fri Jan 8 12:32:54 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:32:54 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:32:55 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:55 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:32:55 2021 kern.warn kernel: [wifi2] FWLOG: [47968871] WAL channel change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:55 2021 kern.warn kernel: [wifi2] FWLOG: [47969009]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:32:55 2021 kern.warn kernel: [wifi2] FWLOG: [47969185] WAL channel change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:55 2021 kern.warn kernel: [wifi2] FWLOG: [47969322]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:32:55 2021 kern.warn kernel: [wifi2] FWLOG: [47969498] WAL channel change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:55 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:32:55 2021 user.notice led_function: RSSI24G -64
Fri Jan 8 12:32:56 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:32:56 2021 kern.warn kernel: [wifi2] FWLOG: [47969811] WAL channel change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:56 2021 kern.warn kernel: [wifi2] FWLOG: [47970125] WAL channel change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:56 2021 kern.warn kernel: [wifi2] FWLOG: [47970262]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:32:56 2021 kern.warn kernel: [wifi2] FWLOG: [47970438] WAL channel change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:56 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41200 event 1 reason 1
Fri Jan 8 12:32:56 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:32:56 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state transition SCAN -> INIT
Fri Jan 8 12:32:56 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0 (c9e36000)

Fri Jan 8 12:32:56 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_END[3]
Fri Jan 8 12:32:56 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3 not handled in state INIT
Fri Jan 8 12:32:56 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:32:57 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:32:57 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:32:57 2021 user.notice led_function: led check timeout elapsed:46763 duration:180
Fri Jan 8 12:32:57 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:32:57 2021 user.notice led_function: CUR_STATE: RE_LocationSuitable
Fri Jan 8 12:32:57 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:57 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:32:57 2021 kern.warn kernel: [wifi2] FWLOG: [47970751] WAL channel change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:32:57 2021 kern.warn kernel: [wifi2] FWLOG: [47971092] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:32:57 2021 kern.warn kernel: [wifi2] FWLOG: [47971092] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:32:57 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:32:57 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:32:57 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:57 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:57 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:57 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:32:57 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:57 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 ::: force_down_5g:0
Fri Jan 8 12:32:57 2021 user.debug repacd.wifimon: repacd check timeout elapsed:1306 duration:170
Fri Jan 8 12:32:57 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:57 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:32:57 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:32:57 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:57 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:58 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:58 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:32:58 2021 kern.warn kernel: Inst RSSI value of node-08:c5:e1:c2:a4:0c: 39
Fri Jan 8 12:32:58 2021 kern.warn kernel: Inst RSSI value of

node-08:c5:e1:c2:a4:0c: 39
Fri Jan 8 12:32:58 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:32:59 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:32:59 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:59 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:32:59 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:32:59 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:33:00 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:33:00 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:33:00 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:33:00 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:33:00 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:33:01 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:33:01 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:33:01 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41201 event 0 reason 0
Fri Jan 8 12:33:01 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:33:01 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:33:01 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:33:01 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan 8 12:33:01 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:33:01 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:33:01 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:33:01 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:01 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:33:02 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:02 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:02 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:33:02 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1310 duration:170
Fri Jan 8 12:33:02 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:33:02 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:33:02 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key

```
Fri Jan 8 12:33:02 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key[wifi2] FWLOG: [47976215] WAL channel change freq=5580, mode=0 flags=0
rx_ok=1 tx_ok=1
Fri Jan 8 12:33:02 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:02 2021 kern.warn kernel: [wifi2] FWLOG: [47976352]
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan 8 12:33:02 2021 kern.warn kernel: [wifi2] FWLOG: [47976528] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:02 2021 kern.warn kernel: [wifi2] FWLOG: [47976665]
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan 8 12:33:02 2021 kern.warn kernel: [wifi2] FWLOG: [47976841] WAL channel
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:02 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:33:02 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:33:02 2021 user.notice led_function: RSSI24G -64
Fri Jan 8 12:33:02 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:33:02 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:03 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:03 2021 kern.warn kernel: [wifi2] FWLOG: [47977155] WAL channel
change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:03 2021 kern.warn kernel: [wifi2] FWLOG: [47977468] WAL channel
change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:03 2021 kern.warn kernel: [wifi2] FWLOG: [47977782] WAL channel
change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:03 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:33:03 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:33:03 2021 user.notice led_function: led check timeout
elapsed:46769 duration:180
Fri Jan 8 12:33:03 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:33:03 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:33:03 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:03 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000
scan_id 41201 event 1 reason 1
Fri Jan 8 12:33:03 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:33:03 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition SCAN -> INIT
Fri Jan 8 12:33:03 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0
(c9e36000)
Fri Jan 8 12:33:03 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_END[3]
Fri Jan 8 12:33:03 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3
not handled in state INIT
Fri Jan 8 12:33:04 2021 kern.warn kernel: [wifi2] FWLOG: [47978095] WAL channel
change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:04 2021 kern.warn kernel: [wifi2] FWLOG: [47978435]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
```

```
Fri Jan 8 12:33:04 2021 kern.warn kernel: [wifi2] FWLOG: [47978435]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan 8 12:33:05 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:33:05 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:06 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:33:06 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:33:06 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:06 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:06 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:06 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:33:06 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:06 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:06 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:33:06 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1315 duration:170
Fri Jan 8 12:33:06 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:33:06 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:33:06 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:06 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:06 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:06 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyPrinting wds entries [No. of entries:0]
Fri Jan 8 12:33:07 2021 kern.warn kernel:          DA          Next Hop
flags
Fri Jan 8 12:33:07 2021 kern.warn kernel:
Fri Jan 8 12:33:07 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:33:07 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:33:07 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:33:07 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:33:07 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:33:08 2021 user.notice led_function: RSSI24G -64
Fri Jan 8 12:33:08 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:33:08 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:33:08 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41202 event 0 reason 0
Fri Jan 8 12:33:08 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:33:08 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
```

Fri Jan 8 12:33:08 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_START[9]
Fri Jan 8 12:33:08 2021 kern.warn kernel: Printing wds entries [No. of entries:0]
Fri Jan 8 12:33:08 2021 kern.warn kernel: DA Next Hop flags
Fri Jan 8 12:33:08 2021 kern.warn kernel:
Fri Jan 8 12:33:08 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9 not handled in state INIT
Fri Jan 8 12:33:09 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:33:09 2021 kern.warn kernel: [wifi2] FWLOG: [47983559] WAL channel change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:09 2021 kern.warn kernel: [wifi2] FWLOG: [47983696] WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:33:09 2021 kern.warn kernel: [wifi2] FWLOG: [47983872] WAL channel change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:09 2021 kern.warn kernel: [wifi2] FWLOG: [47984009] WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:33:09 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:33:09 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:33:09 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:33:09 2021 user.notice led_function: led check timeout elapsed:46776 duration:180
Fri Jan 8 12:33:09 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:33:09 2021 user.notice led_function: CUR_STATE: RE_LocationSuitable
Fri Jan 8 12:33:09 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:10 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:10 2021 kern.warn kernel: [wifi2] FWLOG: [47984186] WAL channel change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:10 2021 kern.warn kernel: [wifi2] FWLOG: [47984499] WAL channel change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:10 2021 kern.warn kernel: [wifi2] FWLOG: [47984813] WAL channel change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:10 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:33:10 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:33:10 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:10 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:10 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:33:10 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:10 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:10 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41202 event 1 reason 1
Fri Jan 8 12:33:10 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:

VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:33:10 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition SCAN -> INIT
Fri Jan 8 12:33:10 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0
(c9e36000)
Fri Jan 8 12:33:10 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_END[3]
Fri Jan 8 12:33:10 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3
not handled in state INIT
Fri Jan 8 12:33:10 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:33:10 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1319 duration:170
Fri Jan 8 12:33:10 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:33:10 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:33:10 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:10 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:10 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:11 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
key[wifi2] FWLOG: [47985126] WAL channel change freq=5680, mode=0 flags=0
rx_ok=1 tx_ok=1
Fri Jan 8 12:33:11 2021 kern.warn kernel: [wifi2] FWLOG: [47985439] WAL channel
change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:11 2021 kern.warn kernel: [wifi2] FWLOG: [47985780]
RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:33:11 2021 kern.warn kernel: [wifi2] FWLOG: [47985780]
RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:33:11 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:33:11 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:11 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:11 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:33:11 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:33:12 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:33:12 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:33:12 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:33:12 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:33:12 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:33:13 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:33:13 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:33:13 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:33:13 2021 kern.warn kernel: vap-0(ath1):

[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:33:14 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:33:14 2021 kern.warn kernel: Inst RSSI value of
node-08:c5:e1:c2:a4:0c: 47
Fri Jan 8 12:33:14 2021 kern.warn kernel: Inst RSSI value of
node-08:c5:e1:c2:a4:0c: 47
Fri Jan 8 12:33:14 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:33:14 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:33:14 2021 user.notice led_function: RSSI24G -63
Fri Jan 8 12:33:14 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:33:14 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:33:14 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:33:14 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:33:15 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:33:15 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:15 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:33:15 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:15 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:33:15 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:15 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:33:15 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1323 duration:170
Fri Jan 8 12:33:15 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:15 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:33:15 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:33:15 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:15 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:15 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:33:15 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:33:15 2021 user.notice led_function: led check timeout
elapsed:46782 duration:180
Fri Jan 8 12:33:15 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:33:15 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:33:15 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:15 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keySending SCAN START cmd
Fri Jan 8 12:33:15 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41203 event 0 reason 0

Fri Jan 8 12:33:15 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:33:15 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:33:15 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:33:15 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan 8 12:33:16 2021 kern.warn kernel: [wifi2] FWLOG: [47990916] WAL channel
change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:16 2021 kern.warn kernel: [wifi2] FWLOG: [47991054]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:33:16 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:33:16 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:33:16 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:33:16 2021 kern.warn kernel: vap-2(ath01):[a6:c9:eb:1a:a6:a1] send
null data frame on channel 13, pwr mgt dis
Fri Jan 8 12:33:16 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:33:17 2021 kern.warn kernel: [wifi2] FWLOG: [47991230] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:17 2021 kern.warn kernel: [wifi2] FWLOG: [47991367]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:33:17 2021 kern.warn kernel: [wifi2] FWLOG: [47991543] WAL channel
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:17 2021 kern.warn kernel: [wifi2] FWLOG: [47991856] WAL channel
change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:17 2021 kern.warn kernel: [wifi2] FWLOG: [47992170] WAL channel
change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:17 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:33:17 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:33:17 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:33:17 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:33:17 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:18 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:18 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41203 event 1 reason 1
Fri Jan 8 12:33:18 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:33:18 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition SCAN -> INIT
Fri Jan 8 12:33:18 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0
(c9e36000)
Fri Jan 8 12:33:18 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_END[3]
Fri Jan 8 12:33:18 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3

not handled in state INIT
Fri Jan 8 12:33:18 2021 kern.warn kernel: [wifi2] FWLOG: [47992483] WAL channel
change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:18 2021 kern.warn kernel: [wifi2] FWLOG: [47992796] WAL channel
change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:18 2021 kern.warn kernel: [wifi2] FWLOG: [47993137]
RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:33:18 2021 kern.warn kernel: [wifi2] FWLOG: [47993137]
RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:33:19 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:33:19 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:33:19 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:33:19 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:19 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:19 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:33:19 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:19 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:33:19 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1328 duration:170
Fri Jan 8 12:33:19 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:33:19 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:33:19 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:19 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:19 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:19 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:19 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:33:19 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:20 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
0, off 0, len 1
Fri Jan 8 12:33:20 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:33:20 2021 user.notice led_function: RSSI24G -63
Fri Jan 8 12:33:20 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:33:20 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:33:21 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:33:21 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:33:21 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:33:21 2021 user.notice led_function: led check timeout
elapsed:46788 duration:180
Fri Jan 8 12:33:21 2021 kern.warn kernel: vap-0(ath1):

```
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:33:21 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:33:21 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:33:22 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:33:22 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:33:22 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:33:22 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:33:23 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:33:23 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41204 event 0 reason 0
Fri Jan 8 12:33:23 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:33:23 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:33:23 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:33:23 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan 8 12:33:23 2021 kern.warn kernel: [wifi2] FWLOG: [47998261] WAL channel
change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:23 2021 kern.warn kernel: [wifi2] FWLOG: [47998398]
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan 8 12:33:23 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:33:23 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:33:23 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:33:23 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:33:23 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:23 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:33:23 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:33:23 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:24 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:24 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:24 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:33:24 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1332 duration:170
Fri Jan 8 12:33:24 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:24 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:33:24 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:33:24 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
```

Fri Jan 8 12:33:24 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:24 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key[wifi2] FWLOG: [47998574] WAL channel change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:24 2021 kern.warn kernel: [wifi2] FWLOG: [47998711] WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:33:24 2021 kern.warn kernel: [wifi2] FWLOG: [47998888] WAL channel change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:24 2021 kern.warn kernel: [wifi2] FWLOG: [47999201] WAL channel change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:24 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:24 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:33:24 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:33:24 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:33:25 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:25 2021 kern.warn kernel: [wifi2] FWLOG: [47999514] WAL channel change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:25 2021 kern.warn kernel: vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41204 event 1 reason 1
Fri Jan 8 12:33:25 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:33:25 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state transition SCAN -> INIT
Fri Jan 8 12:33:25 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0 (c9e36000)
Fri Jan 8 12:33:25 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_END[3]
Fri Jan 8 12:33:25 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3 not handled in state INIT
Fri Jan 8 12:33:25 2021 kern.warn kernel: [wifi2] FWLOG: [47999828] WAL channel change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:25 2021 kern.warn kernel: [wifi2] FWLOG: [47999965] WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:33:25 2021 kern.warn kernel: [wifi2] FWLOG: [48000141] WAL channel change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:25 2021 kern.warn kernel: [wifi2] FWLOG: [48000278] WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:33:26 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:26 2021 kern.warn kernel: [wifi2] FWLOG: [48000483] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:33:26 2021 kern.warn kernel: [wifi2] FWLOG: [48000483] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:33:27 2021 user.notice led_function: RSSI24G -63
Fri Jan 8 12:33:27 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:33:27 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:33:27 2021 kern.warn kernel: vap-0(ath1):

```
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:33:27 2021 kern.warn kernel: RX Rate Info:
Fri Jan 8 12:33:27 2021 kern.warn kernel: MCS counts (0..9): 665, 1501, 3938,
15102, 39165, 43690, 54437, 35025, 3470, 835
Fri Jan 8 12:33:27 2021 kern.warn kernel: SGI counts (0..9): 240, 689, 1658,
7437, 13450, 16991, 28066, 17266, 1584, 459
Fri Jan 8 12:33:27 2021 kern.warn kernel: NSS counts: 1x1 126262, 2x2 71566,
3x3 0, 4x4 0
Fri Jan 8 12:33:27 2021 kern.warn kernel: NSTS count: 571
Fri Jan 8 12:33:27 2021 kern.warn kernel: BW counts: 20MHz 198762, 40MHz 0,
80MHz 0, 160MHz 0
Fri Jan 8 12:33:27 2021 kern.warn kernel: Preamble counts: 113659, 89173, 0,
109589, 0, 0
Fri Jan 8 12:33:27 2021 kern.warn kernel: STBC rate counts (0..9): 238, 187,
51, 49, 23, 0, 1, 22, 0, 0
Fri Jan 8 12:33:27 2021 kern.warn kernel: LDPC Counts: 197725
Fri Jan 8 12:33:27 2021 kern.warn kernel: RSSI (data, mgmt): 33, 22
Fri Jan 8 12:33:27 2021 kern.warn kernel: RSSI Chain 0 (0x80 0x80 0x80 0x20)
Fri Jan 8 12:33:27 2021 kern.warn kernel: RSSI Chain 1 (0x80 0x80 0x80 0x1c)
Fri Jan 8 12:33:27 2021 kern.warn kernel: RSSI Chain 2 (0x00 0x00 0x00 0x00)
Fri Jan 8 12:33:27 2021 kern.warn kernel: RSSI Chain 3 (0x00 0x00 0x00 0x00)
Fri Jan 8 12:33:27 2021 kern.warn kernel: RSSI (comb_ht): 33
Fri Jan 8 12:33:28 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:33:28 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:33:28 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:33:28 2021 user.notice led_function: led check timeout
elapsed:46794 duration:180
Fri Jan 8 12:33:28 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:33:28 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:33:28 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:33:28 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:33:28 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:33:28 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:33:28 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:33:28 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:28 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:33:28 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:28 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:28 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:33:28 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1337 duration:170
Fri Jan 8 12:33:28 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:33:28 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:33:28 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
```

keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:28 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:28 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:28 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyRX Rate Info:
Fri Jan 8 12:33:28 2021 kern.warn kernel: MCS counts (0..9): 4586, 0, 0, 0, 77,
20188, 68397, 129938, 501811, 27607
Fri Jan 8 12:33:28 2021 kern.warn kernel: SGI counts (0..9): 0, 0, 0, 0, 76,
20070, 66924, 126215, 498615, 15530
Fri Jan 8 12:33:28 2021 kern.warn kernel: NSS counts: 1x1 4580, 2x2 1557, 3x3
552329, 4x4 194138
Fri Jan 8 12:33:28 2021 kern.warn kernel: NSTS count: 0
Fri Jan 8 12:33:28 2021 kern.warn kernel: BW counts: 20MHz 29, 40MHz 56, 80MHz
757477, 160MHz 0
Fri Jan 8 12:33:28 2021 kern.warn kernel: Preamble counts: 135383, 56, 0,
757506, 0, 5271
Fri Jan 8 12:33:28 2021 kern.warn kernel: STBC rate counts (0..9): 0, 0, 0, 0,
0, 0, 0, 0, 0, 0
Fri Jan 8 12:33:28 2021 kern.warn kernel: LDPC Counts: 748012
Fri Jan 8 12:33:28 2021 kern.warn kernel: RSSI (data, mgmt): 40, 18
Fri Jan 8 12:33:28 2021 kern.warn kernel: RSSI Chain 0 (0x80 0x25 0x21 0x24)
Fri Jan 8 12:33:28 2021 kern.warn kernel: RSSI Chain 1 (0x80 0x21 0x1e 0x22)
Fri Jan 8 12:33:28 2021 kern.warn kernel: RSSI Chain 2 (0x80 0x24 0x21 0x20)
Fri Jan 8 12:33:28 2021 kern.warn kernel: RSSI Chain 3 (0x80 0x1f 0x22 0x24)
Fri Jan 8 12:33:28 2021 kern.warn kernel: RSSI (comb_ht): 41
Fri Jan 8 12:33:29 2021 kern.warn kernel: TX Rate Info:
Fri Jan 8 12:33:29 2021 kern.warn kernel: MCS counts (0..9): 562, 704, 1316,
1625, 8547, 49155, 88763, 127675, 48447, 22270
Fri Jan 8 12:33:29 2021 kern.warn kernel: MCS counts SU (0..9): 562, 704, 1316,
1625, 8547, 49155, 88763, 127675, 48447, 22270
Fri Jan 8 12:33:29 2021 kern.warn kernel: MCS counts MU (0..9): 0, 0, 0, 0, 0,
0, 0, 0, 0, 0
Fri Jan 8 12:33:29 2021 kern.warn kernel: SGI counts (0..9): 0, 0, 0, 0, 4949,
20910, 33097, 102174, 38553, 16570
Fri Jan 8 12:33:29 2021 kern.warn kernel: NSS counts: 1x1 152324, 2x2 196740,
3x3 0 4x4 0
Fri Jan 8 12:33:29 2021 kern.warn kernel: BW counts: 20MHz 349064, 40MHz 0,
80MHz 0, 160MHz 0
Fri Jan 8 12:33:29 2021 kern.warn kernel: Preamble (O C H V) counts: 0, 13120,
143104, 206928
Fri Jan 8 12:33:29 2021 kern.warn kernel: STBC rate counts (0..9): 562, 672,
1181, 1496, 1737, 10581, 33052, 50289, 0, 0
Fri Jan 8 12:33:29 2021 kern.warn kernel: LDPC Counts: 205960
Fri Jan 8 12:33:29 2021 kern.warn kernel: RTS Counts: 27273
Fri Jan 8 12:33:29 2021 kern.warn kernel: Ack RSSI: 33
Fri Jan 8 12:33:30 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:33:30 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:30 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:30 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:33:30 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id

41205 event 0 reason 0
Fri Jan 8 12:33:30 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:33:30 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:33:30 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:33:30 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan 8 12:33:30 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:33:30 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyTX Rate Info:
Fri Jan 8 12:33:30 2021 kern.warn kernel: MCS counts (0..9): 0, 0, 0, 0, 0,
8324, 125481, 166019, 365434, 217694
Fri Jan 8 12:33:30 2021 kern.warn kernel: MCS counts SU (0..9): 0, 0, 0, 0, 0,
8324, 125481, 166019, 365434, 217694
Fri Jan 8 12:33:30 2021 kern.warn kernel: MCS counts MU (0..9): 0, 0, 0, 0, 0,
0, 0, 0, 0, 0
Fri Jan 8 12:33:30 2021 kern.warn kernel: SGI counts (0..9): 0, 0, 0, 0, 0,
8294, 124427, 149841, 319175, 185317
Fri Jan 8 12:33:30 2021 kern.warn kernel: NSS counts: 1x1 0, 2x2 332, 3x3
545719 4x4 336901
Fri Jan 8 12:33:31 2021 kern.warn kernel: BW counts: 20MHz 391, 40MHz 0, 80MHz
882561, 160MHz 0
Fri Jan 8 12:33:31 2021 kern.warn kernel: Preamble (O C H V) counts: 2, 0, 0,
882952
Fri Jan 8 12:33:31 2021 kern.warn kernel: STBC rate counts (0..9): 0, 0, 0, 0,
0, 0, 0, 0, 0
Fri Jan 8 12:33:31 2021 kern.warn kernel: LDPC Counts: 882952
Fri Jan 8 12:33:31 2021 kern.warn kernel: RTS Counts: 814
Fri Jan 8 12:33:31 2021 kern.warn kernel: Ack RSSI: 36
Fri Jan 8 12:33:31 2021 kern.warn kernel: [wifi2] FWLOG: [48005648] WAL channel
change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:31 2021 kern.warn kernel: [wifi2] FWLOG: [48005786]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:33:31 2021 kern.warn kernel: [wifi2] FWLOG: [48005962] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:31 2021 kern.warn kernel: [wifi2] FWLOG: [48006099]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:33:31 2021 kern.warn kernel: [wifi2] FWLOG: [48006275] WAL channel
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:31 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:33:31 2021 kern.warn kernel: [wifi2] FWLOG: [48006588] WAL channel
change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:32 2021 kern.warn kernel: [wifi2] FWLOG: [48006902] WAL channel
change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:32 2021 kern.warn kernel: [wifi2] FWLOG: [48007039]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:33:32 2021 kern.warn kernel: [wifi2] FWLOG: [48007215] WAL channel
change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:32 2021 kern.warn kernel: [wifi2] FWLOG: [48007528] WAL channel
change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1

Fri Jan 8 12:33:32 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:32 2021 kern.warn kernel: vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41205 event 1 reason 1
Fri Jan 8 12:33:32 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:33:32 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state transition SCAN -> INIT
Fri Jan 8 12:33:32 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0 (c9e36000)
Fri Jan 8 12:33:32 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_END[3]
Fri Jan 8 12:33:32 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3 not handled in state INIT
Fri Jan 8 12:33:32 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:33:32 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:33:32 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:32 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:32 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:33:32 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:32 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:32 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 ::: force_down_5g:0
Fri Jan 8 12:33:32 2021 user.debug repacd.wifimon: repacd check timeout elapsed:1341 duration:170
Fri Jan 8 12:33:32 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:33:32 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:33:32 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:32 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:32 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:33 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key[wifi2] FWLOG: [48007869] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:33:33 2021 kern.warn kernel: [wifi2] FWLOG: [48007869] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:33:33 2021 user.notice led_function: RSSI24G -63
Fri Jan 8 12:33:33 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:33:34 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:33:34 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:33:34 2021 user.notice led_function: led check timeout elapsed:46800 duration:180
Fri Jan 8 12:33:34 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:33:34 2021 user.notice led_function: CUR_STATE: RE_LocationSuitable
Fri Jan 8 12:33:35 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key

Fri Jan 8 12:33:35 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:33:36 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:33:36 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:33:36 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:36 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:36 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:33:36 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:33:37 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:33:37 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:33:37 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:37 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:33:37 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:37 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:37 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:33:37 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1345 duration:170
Fri Jan 8 12:33:37 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:33:37 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:33:37 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:37 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
2, off 0, len 1
Fri Jan 8 12:33:37 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:37 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:37 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:37 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:33:37 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41206 event 0 reason 0
Fri Jan 8 12:33:37 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:33:37 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:33:37 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:33:37 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan 8 12:33:37 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:33:38 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:33:38 2021 kern.warn kernel: [wifi2] FWLOG: [48012996] WAL channel

change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:38 2021 kern.warn kernel: [wifi2] FWLOG: [48013133]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:33:38 2021 kern.warn kernel: [wifi2] FWLOG: [48013309] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:38 2021 kern.warn kernel: [wifi2] FWLOG: [48013447]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:33:38 2021 kern.warn kernel: [wifi2] FWLOG: [48013622] WAL channel
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:39 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:33:39 2021 kern.warn kernel: [wifi2] FWLOG: [48013936] WAL channel
change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:39 2021 kern.warn kernel: [wifi2] FWLOG: [48014249] WAL channel
change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:39 2021 kern.warn kernel: [wifi2] FWLOG: [48014387]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:33:39 2021 kern.warn kernel: [wifi2] FWLOG: [48014562] WAL channel
change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:39 2021 user.notice led_function: RSSI24G -63
Fri Jan 8 12:33:39 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:33:39 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41206 event 1 reason 1
Fri Jan 8 12:33:39 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:33:39 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition SCAN -> INIT
Fri Jan 8 12:33:39 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0
(c9e36000)
Fri Jan 8 12:33:39 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_END[3]
Fri Jan 8 12:33:39 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3
not handled in state INIT
Fri Jan 8 12:33:39 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:33:40 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:33:40 2021 kern.warn kernel: [wifi2] FWLOG: [48014876] WAL channel
change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:40 2021 kern.warn kernel: [wifi2] FWLOG: [48015216]
RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:33:40 2021 kern.warn kernel: [wifi2] FWLOG: [48015216]
RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:33:40 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:33:40 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:33:40 2021 user.notice led_function: led check timeout
elapsed:46807 duration:180
Fri Jan 8 12:33:40 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:33:40 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:33:40 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1

Fri Jan 8 12:33:40 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:40 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:40 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:33:41 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:33:41 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:33:41 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:41 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:33:41 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:41 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:33:41 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:41 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:41 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:33:41 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 ::: force_down_5g:0
Fri Jan 8 12:33:41 2021 user.debug repacd.wifimon: repacd check timeout elapsed:1350 duration:170
Fri Jan 8 12:33:41 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:33:41 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:33:41 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:41 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:41 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:42 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:33:42 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:33:42 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:43 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:44 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:44 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:33:44 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41207 event 0 reason 0
Fri Jan 8 12:33:44 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:33:44 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state transition INIT -> SCAN
Fri Jan 8 12:33:44 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_START[9]
Fri Jan 8 12:33:44 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9

not handled in state INIT
Fri Jan 8 12:33:45 2021 kern.warn kernel: [wifi2] FWLOG: [48020340] WAL channel
change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:45 2021 kern.warn kernel: [wifi2] FWLOG: [48020477]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:33:45 2021 kern.warn kernel: [wifi2] FWLOG: [48020653] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:45 2021 kern.warn kernel: [wifi2] FWLOG: [48020791]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:33:45 2021 user.notice led_function: RSSI24G -64
Fri Jan 8 12:33:45 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:33:45 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:33:45 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:33:45 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:33:45 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:45 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:33:45 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:45 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:45 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:33:46 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1354 duration:170
Fri Jan 8 12:33:46 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:33:46 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:33:46 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:46 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:46 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
2, off 0, len 1
Fri Jan 8 12:33:46 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:33:46 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
key[wifi2] FWLOG: [48020967] WAL channel change freq=5620, mode=0 flags=0
rx_ok=1 tx_ok=1
Fri Jan 8 12:33:46 2021 kern.warn kernel: [wifi2] FWLOG: [48021280] WAL channel
change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:46 2021 kern.warn kernel: [wifi2] FWLOG: [48021594] WAL channel
change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:46 2021 kern.warn kernel: [wifi2] FWLOG: [48021907] WAL channel
change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:46 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:33:46 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:33:46 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:33:46 2021 user.notice led_function: led check timeout
elapsed:46813 duration:180
Fri Jan 8 12:33:46 2021 user.notice led_function: SELECTION LOOP CONTINUE

Fri Jan 8 12:33:46 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:33:46 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:33:46 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41207 event 1 reason 1
Fri Jan 8 12:33:46 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:33:46 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition SCAN -> INIT
Fri Jan 8 12:33:46 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0
(c9e36000)
Fri Jan 8 12:33:46 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_END[3]
Fri Jan 8 12:33:46 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3
not handled in state INIT
Fri Jan 8 12:33:46 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:33:47 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:33:47 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:33:47 2021 kern.warn kernel: [wifi2] FWLOG: [48022220] WAL channel
change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:47 2021 kern.warn kernel: [wifi2] FWLOG: [48022561]
RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:33:47 2021 kern.warn kernel: [wifi2] FWLOG: [48022561]
RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:33:47 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:33:47 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:47 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:33:47 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:33:48 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:33:48 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:33:48 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:33:48 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:48 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:33:48 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:33:48 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
1, off 0, len 1
Fri Jan 8 12:33:49 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:33:49 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1

Fri Jan 8 12:33:49 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:33:50 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:33:50 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:33:50 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:33:50 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:50 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:50 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:33:50 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:50 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:33:50 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1359 duration:170
Fri Jan 8 12:33:50 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:50 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:33:50 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:33:50 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:50 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:50 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:51 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:51 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
2, off 0, len 1
Fri Jan 8 12:33:51 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:33:51 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:33:51 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41208 event 0 reason 0
Fri Jan 8 12:33:51 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:33:51 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:33:51 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:33:51 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan 8 12:33:51 2021 user.notice led_function: RSSI24G -64
Fri Jan 8 12:33:51 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:33:52 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:33:52 2021 kern.warn kernel: [wifi2] FWLOG: [48027690] WAL channel
change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:52 2021 kern.warn kernel: [wifi2] FWLOG: [48027827]
WHAL_ERROR_RESET_OFFSETCAL ()

```
Fri Jan 8 12:33:52 2021 kern.warn kernel: [wifi2] FWLOG: [48028003] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:52 2021 kern.warn kernel: [wifi2] FWLOG: [48028141]
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan 8 12:33:52 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:33:52 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:33:52 2021 user.notice led_function: led check timeout
elapsed:46819 duration:180
Fri Jan 8 12:33:52 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:33:52 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:33:53 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:33:53 2021 kern.warn kernel: [wifi2] FWLOG: [48028317] WAL channel
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:53 2021 kern.warn kernel: [wifi2] FWLOG: [48028454]
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan 8 12:33:53 2021 kern.warn kernel: [wifi2] FWLOG: [48028630] WAL channel
change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:53 2021 kern.warn kernel: [wifi2] FWLOG: [48028944] WAL channel
change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:53 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:53 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41208 event 1 reason 1
Fri Jan 8 12:33:53 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:33:53 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition SCAN -> INIT
Fri Jan 8 12:33:53 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0
(c9e36000)
Fri Jan 8 12:33:53 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_END[3]
Fri Jan 8 12:33:53 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3
not handled in state INIT
Fri Jan 8 12:33:54 2021 kern.warn kernel: [wifi2] FWLOG: [48029257] WAL channel
change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:54 2021 kern.warn kernel: [wifi2] FWLOG: [48029570] WAL channel
change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:54 2021 kern.warn kernel: [wifi2] FWLOG: [48029708]
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan 8 12:33:54 2021 kern.warn kernel: [wifi2] FWLOG: [48029911]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan 8 12:33:54 2021 kern.warn kernel: [wifi2] FWLOG: [48029911]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan 8 12:33:54 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:33:54 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:33:54 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:33:54 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:54 2021 user.notice led_function: =====LOOP END=====
```

Fri Jan 8 12:33:54 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:54 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:33:55 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:55 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:55 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:33:55 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1363 duration:170
Fri Jan 8 12:33:55 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:55 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:33:55 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:33:55 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:55 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:56 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:56 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):[a6:c9:eb:1a:a6:a1] send null data frame on channel 13, pwr mgt
dis
Fri Jan 8 12:33:56 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:33:57 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:33:57 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:33:57 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:33:57 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:33:58 2021 user.notice led_function: RSSI24G -64
Fri Jan 8 12:33:58 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:33:58 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:33:58 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:33:58 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41209 event 0 reason 0
Fri Jan 8 12:33:58 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:33:58 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:33:58 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:33:58 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan 8 12:33:59 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:33:59 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:33:59 2021 user.notice led_function: led check timeout

elapsed:46825 duration:180
Fri Jan 8 12:33:59 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:33:59 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:33:59 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:33:59 2021 kern.warn kernel: [wifi2] FWLOG: [48035035] WAL channel
change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:33:59 2021 kern.warn kernel: [wifi2] FWLOG: [48035173]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:33:59 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:33:59 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:33:59 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:59 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:59 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:33:59 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:33:59 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:33:59 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1368 duration:170
Fri Jan 8 12:33:59 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:59 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:33:59 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:33:59 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:59 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:33:59 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:00 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
1, off 0, len 1
Fri Jan 8 12:34:00 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:34:00 2021 kern.warn kernel: [wifi2] FWLOG: [48035349] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:00 2021 kern.warn kernel: [wifi2] FWLOG: [48035486]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:34:00 2021 kern.warn kernel: [wifi2] FWLOG: [48035662] WAL channel
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:00 2021 kern.warn kernel: [wifi2] FWLOG: [48035975] WAL channel
change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:00 2021 kern.warn kernel: [wifi2] FWLOG: [48036289] WAL channel
change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:01 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41209 event 1 reason 1
Fri Jan 8 12:34:01 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:34:01 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:

VAP state transition SCAN -> INIT
Fri Jan 8 12:34:01 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0 (c9e36000)
Fri Jan 8 12:34:01 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_END[3]
Fri Jan 8 12:34:01 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3 not handled in state INIT
Fri Jan 8 12:34:01 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:34:01 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:01 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:01 2021 kern.warn kernel: [wifi2] FWLOG: [48036602] WAL channel change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:01 2021 kern.warn kernel: [wifi2] FWLOG: [48036916] WAL channel change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:01 2021 kern.warn kernel: [wifi2] FWLOG: [48037256] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:34:01 2021 kern.warn kernel: [wifi2] FWLOG: [48037256] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:34:01 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:01 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:34:02 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:34:03 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:03 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:03 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:34:03 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:34:03 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:03 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:03 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:34:03 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:04 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:04 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 ::: force_down_5g:0
Fri Jan 8 12:34:04 2021 user.debug repacd.wifimon: repacd check timeout elapsed:1372 duration:170
Fri Jan 8 12:34:04 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:34:04 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:34:04 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:04 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:04 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:04 2021 user.notice led_function: RSSI24G -64
Fri Jan 8 12:34:04 2021 user.notice led_function: PING IS WELL

Fri Jan 8 12:34:05 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:34:05 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:34:05 2021 user.notice led_function: led check timeout
elapsed:46831 duration:180
Fri Jan 8 12:34:05 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:34:05 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:34:06 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:06 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:34:06 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41210 event 0 reason 0
Fri Jan 8 12:34:06 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:34:06 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:34:06 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:34:06 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan 8 12:34:06 2021 kern.warn kernel: [wifi2] FWLOG: [48042387] WAL channel
change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:06 2021 kern.warn kernel: [wifi2] FWLOG: [48042524]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:34:07 2021 kern.warn kernel: Printing wds entries [No. of
entries:0]
Fri Jan 8 12:34:07 2021 kern.warn kernel: DA Next Hop
flags
Fri Jan 8 12:34:07 2021 kern.warn kernel:
Fri Jan 8 12:34:07 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:34:07 2021 kern.warn kernel: [wifi2] FWLOG: [48042700] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:07 2021 kern.warn kernel: [wifi2] FWLOG: [48042837]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:34:07 2021 kern.warn kernel: [wifi2] FWLOG: [48043013] WAL channel
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:07 2021 kern.warn kernel: [wifi2] FWLOG: [48043327] WAL channel
change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:07 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:34:07 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:07 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid keyvap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:34:08 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:34:08 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:34:08 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:34:08 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:08 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key[wifi2] FWLOG: [48043640] WAL channel change freq=5660, mode=0 flags=0

```
rx_ok=1 tx_ok=1
Fri Jan 8 12:34:08 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41210 event 1 reason 1
Fri Jan 8 12:34:08 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:08 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:34:08 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition SCAN -> INIT
Fri Jan 8 12:34:08 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0
(c9e36000)
Fri Jan 8 12:34:08 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:34:08 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_END[3]
Fri Jan 8 12:34:08 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3
not handled in state INIT
Fri Jan 8 12:34:08 2021 kern.warn kernel: [wifi2] FWLOG: [48043953] WAL channel
change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:08 2021 kern.warn kernel: [wifi2] FWLOG: [48044267] WAL channel
change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:08 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:08 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:08 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:34:08 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1377 duration:170
Fri Jan 8 12:34:08 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:34:08 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:34:08 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:08 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:08 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:09 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyPrinting wds entries [No. of entries:0]
Fri Jan 8 12:34:09 2021 kern.warn kernel:          DA          Next Hop
flags
Fri Jan 8 12:34:09 2021 kern.warn kernel:
Fri Jan 8 12:34:09 2021 kern.warn kernel: [wifi2] FWLOG: [48044613]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan 8 12:34:09 2021 kern.warn kernel: [wifi2] FWLOG: [48044613]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan 8 12:34:10 2021 user.notice led_function: RSSI24G -63
Fri Jan 8 12:34:10 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:34:11 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:34:11 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:34:11 2021 user.notice led_function: led check timeout
elapsed:46838 duration:180
Fri Jan 8 12:34:11 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:34:11 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
```

Fri Jan 8 12:34:11 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:11 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:34:11 2021 kern.warn kernel: Inst RSSI value of node-08:c5:e1:c2:a4:0c: 43
Fri Jan 8 12:34:11 2021 kern.warn kernel: Inst RSSI value of node-08:c5:e1:c2:a4:0c: 43
Fri Jan 8 12:34:11 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:12 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:34:12 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:34:12 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:34:12 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:12 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:12 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:34:12 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:12 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:12 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 ::: force_down_5g:0
Fri Jan 8 12:34:12 2021 user.debug repacd.wifimon: repacd check timeout elapsed:1381 duration:170
Fri Jan 8 12:34:12 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:34:12 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:34:12 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:12 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:12 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:13 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:34:13 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:34:13 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:34:13 2021 kern.warn kernel: vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41211 event 0 reason 0
Fri Jan 8 12:34:13 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:34:13 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state transition INIT -> SCAN
Fri Jan 8 12:34:13 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_START[9]
Fri Jan 8 12:34:13 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9 not handled in state INIT

```
Fri Jan 8 12:34:13 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:34:13 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:14 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:14 2021 kern.warn kernel: [wifi2] FWLOG: [48049765] WAL channel
change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:14 2021 kern.warn kernel: [wifi2] FWLOG: [48049902]
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan 8 12:34:14 2021 kern.warn kernel: [wifi2] FWLOG: [48050078] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:14 2021 kern.warn kernel: [wifi2] FWLOG: [48050215]
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan 8 12:34:14 2021 kern.warn kernel: [wifi2] FWLOG: [48050391] WAL channel
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:14 2021 kern.warn kernel: [wifi2] FWLOG: [48050705] WAL channel
change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:15 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:34:15 2021 kern.warn kernel: [wifi2] FWLOG: [48051018] WAL channel
change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:15 2021 kern.warn kernel: [wifi2] FWLOG: [48051331] WAL channel
change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:15 2021 kern.warn kernel: [wifi2] FWLOG: [48051645] WAL channel
change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:15 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41211 event 1 reason 1
Fri Jan 8 12:34:15 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:34:15 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition SCAN -> INIT
Fri Jan 8 12:34:15 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0
(c9e36000)
Fri Jan 8 12:34:15 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_END[3]
Fri Jan 8 12:34:15 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3
not handled in state INIT
Fri Jan 8 12:34:16 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:34:16 2021 kern.warn kernel: [wifi2] FWLOG: [48051985]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan 8 12:34:16 2021 kern.warn kernel: [wifi2] FWLOG: [48051985]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan 8 12:34:16 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:34:16 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:34:16 2021 user.notice led_function: RSSI24G -62
Fri Jan 8 12:34:16 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:34:16 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:34:17 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:34:17 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:34:17 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
```

```
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:17 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:34:17 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:17 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:17 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:34:17 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
2, off 0, len 1
Fri Jan 8 12:34:17 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1385 duration:170
Fri Jan 8 12:34:17 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:34:17 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:34:17 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:17 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:17 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:17 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
0, off 0, len 1
Fri Jan 8 12:34:17 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:34:17 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:34:17 2021 user.notice led_function: led check timeout
elapsed:46844 duration:180
Fri Jan 8 12:34:17 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:34:17 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:34:17 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:34:18 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:34:18 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:34:18 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:34:18 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:34:19 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:34:19 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:19 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:19 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:34:20 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:34:20 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:34:20 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41212 event 0 reason 0
Fri Jan 8 12:34:20 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
```

VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:34:20 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:34:20 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:34:20 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan 8 12:34:20 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:34:20 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:34:20 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:34:21 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:34:21 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:34:21 2021 kern.warn kernel: [wifi2] FWLOG: [48057110] WAL channel
change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:21 2021 kern.warn kernel: [wifi2] FWLOG: [48057247]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:34:21 2021 kern.warn kernel: [wifi2] FWLOG: [48057423] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:21 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:34:21 2021 kern.warn kernel: [wifi2] FWLOG: [48057561]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:34:21 2021 kern.warn kernel: [wifi2] FWLOG: [48057737] WAL channel
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:21 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:34:21 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:34:21 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:21 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:34:21 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:21 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:21 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:34:21 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1390 duration:170
Fri Jan 8 12:34:21 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:34:21 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:34:21 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:21 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:21 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:21 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:34:21 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:21 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid

keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:34:22 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:22 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key[wifi2] FWLOG: [48058050] WAL channel change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:22 2021 kern.warn kernel: [wifi2] FWLOG: [48058363] WAL channel change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:22 2021 kern.warn kernel: [wifi2] FWLOG: [48058677] WAL channel change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:22 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:22 2021 kern.warn kernel: vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41212 event 1 reason 1
Fri Jan 8 12:34:22 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:34:22 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state transition SCAN -> INIT
Fri Jan 8 12:34:22 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0 (c9e36000)
Fri Jan 8 12:34:22 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_END[3]
Fri Jan 8 12:34:22 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3 not handled in state INIT
Fri Jan 8 12:34:22 2021 user.notice led_function: RSSI24G -62
Fri Jan 8 12:34:22 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:34:22 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:34:23 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:34:23 2021 kern.warn kernel: [wifi2] FWLOG: [48058990] WAL channel change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:23 2021 kern.warn kernel: [wifi2] FWLOG: [48059331] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:34:23 2021 kern.warn kernel: [wifi2] FWLOG: [48059331] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:34:23 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:34:23 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:34:23 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:34:23 2021 user.notice led_function: wps_inprocess wps_process_logged wps_1st_finish 0
Fri Jan 8 12:34:23 2021 user.notice led_function: led check timeout elapsed:46850 duration:180
Fri Jan 8 12:34:23 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:34:23 2021 user.notice led_function: CUR_STATE: RE_LocationSuitable
Fri Jan 8 12:34:23 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:34:24 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:34:25 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:

Fri Jan 8 12:34:25 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:34:25 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:25 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:25 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:34:25 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:25 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:34:25 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:25 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:26 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:26 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:34:26 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 ::: force_down_5g:0
Fri Jan 8 12:34:26 2021 user.debug repacd.wifimon: repacd check timeout elapsed:1394 duration:170
Fri Jan 8 12:34:26 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:26 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:34:26 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:34:26 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:26 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:26 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:26 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:34:27 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:27 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:34:27 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:34:27 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:34:27 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41213 event 0 reason 0
Fri Jan 8 12:34:27 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:34:27 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state transition INIT -> SCAN
Fri Jan 8 12:34:27 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_START[9]
Fri Jan 8 12:34:27 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9 not handled in state INIT
Fri Jan 8 12:34:28 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:28 2021 kern.warn kernel: [wifi2] FWLOG: [48064453] WAL channel

change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:28 2021 kern.warn kernel: [wifi2] FWLOG: [48064591]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:34:28 2021 kern.warn kernel: [wifi2] FWLOG: [48064767] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:28 2021 kern.warn kernel: [wifi2] FWLOG: [48064904]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:34:28 2021 kern.warn kernel: RX Rate Info:
Fri Jan 8 12:34:28 2021 kern.warn kernel: MCS counts (0..9): 665, 1501, 3938,
15184, 39311, 43729, 54442, 35098, 3573, 866
Fri Jan 8 12:34:28 2021 kern.warn kernel: SGI counts (0..9): 240, 689, 1658,
7518, 13540, 16995, 28067, 17339, 1664, 472
Fri Jan 8 12:34:28 2021 kern.warn kernel: NSS counts: 1x1 126470, 2x2 71837,
3x3 0, 4x4 0
Fri Jan 8 12:34:28 2021 kern.warn kernel: NSTS count: 571
Fri Jan 8 12:34:28 2021 kern.warn kernel: BW counts: 20MHz 199246, 40MHz 0,
80MHz 0, 160MHz 0
Fri Jan 8 12:34:28 2021 kern.warn kernel: Preamble counts: 113927, 89173, 0,
110073, 0, 0
Fri Jan 8 12:34:28 2021 kern.warn kernel: STBC rate counts (0..9): 238, 187,
51, 49, 23, 0, 1, 22, 0, 0
Fri Jan 8 12:34:28 2021 kern.warn kernel: LDPC Counts: 198204
Fri Jan 8 12:34:28 2021 kern.warn kernel: RSSI (data, mgmt): 32, 34
Fri Jan 8 12:34:28 2021 kern.warn kernel: RSSI Chain 0 (0x80 0x80 0x80 0x1f)
Fri Jan 8 12:34:28 2021 kern.warn kernel: RSSI Chain 1 (0x80 0x80 0x80 0x1a)
Fri Jan 8 12:34:28 2021 kern.warn kernel: RSSI Chain 2 (0x00 0x00 0x00 0x00)
Fri Jan 8 12:34:28 2021 kern.warn kernel: RSSI Chain 3 (0x00 0x00 0x00 0x00)
Fri Jan 8 12:34:28 2021 kern.warn kernel: RSSI (comb_ht): 32
Fri Jan 8 12:34:28 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:34:28 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:34:28 2021 user.notice led_function: RSSI24G -63
Fri Jan 8 12:34:29 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:34:29 2021 kern.warn kernel: [wifi2] FWLOG: [48065080] WAL channel
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:29 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:34:29 2021 kern.warn kernel: [wifi2] FWLOG: [48065218]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:34:29 2021 kern.warn kernel: [wifi2] FWLOG: [48065394] WAL channel
change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:29 2021 kern.warn kernel: [wifi2] FWLOG: [48065707] WAL channel
change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:29 2021 kern.warn kernel: [wifi2] FWLOG: [48066020] WAL channel
change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:29 2021 kern.warn kernel: RX Rate Info:
Fri Jan 8 12:34:29 2021 kern.warn kernel: MCS counts (0..9): 4586, 0, 0, 0, 77,
20188, 68397, 129938, 501811, 27607
Fri Jan 8 12:34:29 2021 kern.warn kernel: SGI counts (0..9): 0, 0, 0, 0, 76,
20070, 66924, 126215, 498615, 15530
Fri Jan 8 12:34:29 2021 kern.warn kernel: NSS counts: 1x1 4580, 2x2 1557, 3x3
552329, 4x4 194138
Fri Jan 8 12:34:29 2021 kern.warn kernel: NSTS count: 0

```
Fri Jan 8 12:34:29 2021 kern.warn kernel: BW counts: 20MHz 29, 40MHz 56, 80MHz
757477, 160MHz 0
Fri Jan 8 12:34:29 2021 kern.warn kernel: Preamble counts: 135383, 56, 0,
757506, 0, 5271
Fri Jan 8 12:34:29 2021 kern.warn kernel: STBC rate counts (0..9): 0, 0, 0, 0,
0, 0, 0, 0, 0, 0
Fri Jan 8 12:34:29 2021 kern.warn kernel: LDPC Counts: 748012
Fri Jan 8 12:34:29 2021 kern.warn kernel: RSSI (data, mgmt): 40, 18
Fri Jan 8 12:34:29 2021 kern.warn kernel: RSSI Chain 0 (0x80 0x25 0x21 0x24)
Fri Jan 8 12:34:29 2021 kern.warn kernel: RSSI Chain 1 (0x80 0x21 0x1e 0x22)
Fri Jan 8 12:34:29 2021 kern.warn kernel: RSSI Chain 2 (0x80 0x24 0x21 0x20)
Fri Jan 8 12:34:29 2021 kern.warn kernel: RSSI Chain 3 (0x80 0x1f 0x22 0x24)
Fri Jan 8 12:34:29 2021 kern.warn kernel: RSSI (comb_ht): 41
Fri Jan 8 12:34:29 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:34:29 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41213 event 1 reason 1
Fri Jan 8 12:34:29 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:34:29 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition SCAN -> INIT
Fri Jan 8 12:34:29 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0
(c9e36000)
Fri Jan 8 12:34:29 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_END[3]
Fri Jan 8 12:34:29 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3
not handled in state INIT
Fri Jan 8 12:34:30 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:34:30 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:34:30 2021 user.notice led_function: led check timeout
elapsed:46856 duration:180
Fri Jan 8 12:34:30 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:34:30 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:34:30 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:34:30 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:34:30 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:34:30 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:30 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:34:30 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:30 2021 kern.warn kernel: [wifi2] FWLOG: [48066334] WAL channel
change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:30 2021 kern.warn kernel: [wifi2] FWLOG: [48066471]
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan 8 12:34:30 2021 kern.warn kernel: [wifi2] FWLOG: [48066674]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan 8 12:34:30 2021 kern.warn kernel: [wifi2] FWLOG: [48066674]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan 8 12:34:30 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
```

Fri Jan 8 12:34:30 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:30 2021 kern.warn kernel: TX Rate Info:
Fri Jan 8 12:34:30 2021 kern.warn kernel: MCS counts (0..9): 562, 704, 1316, 1625, 8547, 49469, 89282, 127814, 48449, 22355
Fri Jan 8 12:34:30 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 ::: force_down_5g:0
Fri Jan 8 12:34:30 2021 kern.warn kernel: MCS counts SU (0..9): 562, 704, 1316, 1625, 8547, 49469, 89282, 127814, 48449, 22355
Fri Jan 8 12:34:30 2021 kern.warn kernel: MCS counts MU (0..9): 0, 0, 0, 0, 0, 0, 0, 0, 0, 0
Fri Jan 8 12:34:30 2021 kern.warn kernel: SGI counts (0..9): 0, 0, 0, 0, 4949, 21196, 33570, 102247, 38553, 16655
Fri Jan 8 12:34:30 2021 kern.warn kernel: NSS counts: 1x1 152409, 2x2 197714, 3x3 0 4x4 0
Fri Jan 8 12:34:30 2021 kern.warn kernel: BW counts: 20MHz 350123, 40MHz 0, 80MHz 0, 160MHz 0
Fri Jan 8 12:34:30 2021 kern.warn kernel: Preamble (O C H V) counts: 0, 13120, 143104, 207987
Fri Jan 8 12:34:30 2021 kern.warn kernel: STBC rate counts (0..9): 562, 672, 1181, 1496, 1737, 10581, 33052, 50289, 0, 0
Fri Jan 8 12:34:30 2021 user.debug repacd.wifimon: repacd check timeout elapsed:1398 duration:170
Fri Jan 8 12:34:30 2021 kern.warn kernel: LDPC Counts: 207019
Fri Jan 8 12:34:30 2021 kern.warn kernel: RTS Counts:
Fri Jan 8 12:34:30 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key27351
Fri Jan 8 12:34:30 2021 kern.warn kernel: Ack RSSI: 32
Fri Jan 8 12:34:30 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:34:30 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:34:30 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:30 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:30 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:30 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:34:31 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:34:31 2021 kern.warn kernel: TX Rate Info:
Fri Jan 8 12:34:31 2021 kern.warn kernel: MCS counts (0..9): 0, 0, 0, 0, 0, 8324, 125481, 166019, 365434, 217694
Fri Jan 8 12:34:31 2021 kern.warn kernel: MCS counts SU (0..9): 0, 0, 0, 0, 0, 8324, 125481, 166019, 365434, 217694
Fri Jan 8 12:34:31 2021 kern.warn kernel: MCS counts MU (0..9): 0, 0, 0, 0, 0, 0, 0, 0, 0, 0
Fri Jan 8 12:34:31 2021 kern.warn kernel: SGI counts (0..9): 0, 0, 0, 0, 0, 8294, 124427, 149841, 319175, 185317
Fri Jan 8 12:34:31 2021 kern.warn kernel: NSS counts: 1x1 0, 2x2 332, 3x3 545719 4x4 336901
Fri Jan 8 12:34:31 2021 kern.warn kernel: BW counts: 20MHz 391, 40MHz 0, 80MHz 882561, 160MHz 0

Fri Jan 8 12:34:31 2021 kern.warn kernel: Preamble (O C H V) counts: 2, 0, 0, 882952
Fri Jan 8 12:34:31 2021 kern.warn kernel: STBC rate counts (0..9): 0, 0, 0, 0, 0, 0, 0, 0, 0, 0
Fri Jan 8 12:34:31 2021 kern.warn kernel: LDPC Counts: 882952
Fri Jan 8 12:34:31 2021 kern.warn kernel: RTS Counts: 814
Fri Jan 8 12:34:31 2021 kern.warn kernel: Ack RSSI: 36
Fri Jan 8 12:34:32 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:34:32 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:32 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:33 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:34 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:34:34 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:34:34 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:34 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:34 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:34 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:34:34 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:34 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 ::: force_down_5g:0
Fri Jan 8 12:34:34 2021 user.debug repacd.wifimon: repacd check timeout elapsed:1403 duration:170
Fri Jan 8 12:34:34 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:34 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:34:34 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid keySending SCAN START cmd
Fri Jan 8 12:34:34 2021 kern.warn kernel: vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41214 event 0 reason 0
Fri Jan 8 12:34:34 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:34:34 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state transition INIT -> SCAN
Fri Jan 8 12:34:34 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_START[9]
Fri Jan 8 12:34:34 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9 not handled in state INIT
Fri Jan 8 12:34:34 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:34:34 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:34 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:35 2021 user.notice led_function: RSSI24G -64
Fri Jan 8 12:34:35 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:34:35 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:35 2021 kern.warn kernel: [wifi2] FWLOG: [48071811] WAL channel

change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:35 2021 kern.warn kernel: [wifi2] FWLOG: [48071948]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:34:35 2021 kern.warn kernel: [wifi2] FWLOG: [48072124] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:35 2021 kern.warn kernel: [wifi2] FWLOG: [48072261]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:34:36 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:34:36 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:34:36 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:34:36 2021 user.notice led_function: led check timeout
elapsed:46862 duration:180
Fri Jan 8 12:34:36 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:34:36 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:34:36 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:34:36 2021 kern.warn kernel: [wifi2] FWLOG: [48072438] WAL channel
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:36 2021 kern.warn kernel: [wifi2] FWLOG: [48072575]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:34:36 2021 kern.warn kernel: [wifi2] FWLOG: [48072751] WAL channel
change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:36 2021 kern.warn kernel: [wifi2] FWLOG: [48073064] WAL channel
change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:36 2021 kern.warn kernel: vap-2(ath01):[a6:c9:eb:1a:a6:a1] send
null data frame on channel 13, pwr mgt dis
Fri Jan 8 12:34:37 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:34:37 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41214 event 1 reason 1
Fri Jan 8 12:34:37 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:34:37 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition SCAN -> INIT
Fri Jan 8 12:34:37 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0
(c9e36000)
Fri Jan 8 12:34:37 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_END[3]
Fri Jan 8 12:34:37 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3
not handled in state INIT
Fri Jan 8 12:34:37 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:34:37 2021 kern.warn kernel: [wifi2] FWLOG: [48073378] WAL channel
change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:37 2021 kern.warn kernel: [wifi2] FWLOG: [48073691] WAL channel
change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:37 2021 kern.warn kernel: [wifi2] FWLOG: [48074032]
RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:34:37 2021 kern.warn kernel: [wifi2] FWLOG: [48074032]
RESMGR_OCS_GEN_PERIODIC_NOA (0x0)

Fri Jan 8 12:34:37 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:34:37 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:34:38 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:34:38 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:34:38 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:38 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:34:38 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:38 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:34:39 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:34:39 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:34:39 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:39 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:34:39 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:39 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:34:39 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:39 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:34:39 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1407 duration:170
Fri Jan 8 12:34:39 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:39 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:34:39 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:34:39 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:39 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:39 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:39 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
1, off 0, len 1
Fri Jan 8 12:34:40 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:34:40 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:34:40 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:34:40 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:34:41 2021 user.notice led_function: RSSI24G -64
Fri Jan 8 12:34:41 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:34:42 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:34:42 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id

41215 event 0 reason 0
Fri Jan 8 12:34:42 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:34:42 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:34:42 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:34:42 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan 8 12:34:42 2021 kern.warn kernel: [wifi2] FWLOG: [48079156] WAL channel
change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:42 2021 kern.warn kernel: [wifi2] FWLOG: [48079293]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:34:42 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:34:42 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:34:42 2021 user.notice led_function: led check timeout
elapsed:46868 duration:180
Fri Jan 8 12:34:42 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:34:42 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:34:43 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:34:43 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:34:43 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:43 2021 kern.warn kernel: [wifi2] FWLOG: [48079469] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:43 2021 kern.warn kernel: [wifi2] FWLOG: [48079606]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:34:43 2021 kern.warn kernel: [wifi2] FWLOG: [48079782] WAL channel
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:43 2021 kern.warn kernel: [wifi2] FWLOG: [48080096] WAL channel
change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:43 2021 kern.warn kernel: [wifi2] FWLOG: [48080409] WAL channel
change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:43 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:34:43 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:34:43 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:43 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:34:43 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:43 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:43 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:34:43 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1412 duration:170
Fri Jan 8 12:34:43 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:34:43 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:34:43 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key

Fri Jan 8 12:34:43 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:43 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:43 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:43 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:34:43 2021 kern.warn kernel: Inst RSSI value of node-08:c5:e1:c2:a4:0c: 38
Fri Jan 8 12:34:43 2021 kern.warn kernel: Inst RSSI value of node-08:c5:e1:c2:a4:0c: 38
Fri Jan 8 12:34:44 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:34:44 2021 kern.warn kernel: vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41215 event 1 reason 1
Fri Jan 8 12:34:44 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:34:44 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state transition SCAN -> INIT
Fri Jan 8 12:34:44 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0 (c9e36000)
Fri Jan 8 12:34:44 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_END[3]
Fri Jan 8 12:34:44 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3 not handled in state INIT
Fri Jan 8 12:34:44 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:34:44 2021 kern.warn kernel: [wifi2] FWLOG: [48080722] WAL channel change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:44 2021 kern.warn kernel: [wifi2] FWLOG: [48080860] WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:34:44 2021 kern.warn kernel: [wifi2] FWLOG: [48081036] WAL channel change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:44 2021 kern.warn kernel: [wifi2] FWLOG: [48081376] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:34:44 2021 kern.warn kernel: [wifi2] FWLOG: [48081376] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:34:44 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:34:44 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:44 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:34:44 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:44 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:34:45 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:34:45 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:34:45 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1

[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:34:46 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:34:46 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:34:46 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:34:47 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:34:47 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:34:47 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:34:47 2021 user.notice led_function: RSSI24G -64
Fri Jan 8 12:34:47 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:34:47 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:34:47 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:34:47 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:34:47 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:47 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:34:48 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:48 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:48 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:34:48 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1416 duration:170
Fri Jan 8 12:34:48 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:34:48 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:34:48 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:48 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:48 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:48 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:34:48 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:34:48 2021 user.notice led_function: led check timeout
elapsed:46875 duration:180
Fri Jan 8 12:34:48 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:34:48 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:34:49 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:49 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:34:49 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41216 event 0 reason 0
Fri Jan 8 12:34:49 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0

Fri Jan 8 12:34:49 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:34:49 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:34:49 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan 8 12:34:49 2021 kern.warn kernel: [wifi2] FWLOG: [48086500] WAL channel
change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:49 2021 kern.warn kernel: [wifi2] FWLOG: [48086637]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:34:50 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:50 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:34:50 2021 kern.warn kernel: [wifi2] FWLOG: [48086814] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:50 2021 kern.warn kernel: [wifi2] FWLOG: [48086951]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:34:50 2021 kern.warn kernel: [wifi2] FWLOG: [48087127] WAL channel
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:50 2021 kern.warn kernel: [wifi2] FWLOG: [48087440]
Fri Jan 8 12:34:50 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:34:50 2021 kern.warn kernel: WAL channel change freq=5640, mode=0
flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:50 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:34:50 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:51 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:51 2021 kern.warn kernel: [wifi2] FWLOG: [48087754] WAL channel
change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:51 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41216 event 1 reason 1
Fri Jan 8 12:34:51 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:34:51 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition SCAN -> INIT
Fri Jan 8 12:34:51 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0
(c9e36000)
Fri Jan 8 12:34:51 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_END[3]
Fri Jan 8 12:34:51 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3
not handled in state INIT
Fri Jan 8 12:34:51 2021 kern.warn kernel: [wifi2] FWLOG: [48088067] WAL channel
change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:51 2021 kern.warn kernel: [wifi2] FWLOG: [48088380] WAL channel
change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:52 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:34:52 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:34:52 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:34:52 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key

Fri Jan 8 12:34:52 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:52 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:34:52 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
[wifi2] FWLOG: [48088722] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:34:52 2021 kern.warn kernel: [wifi2] FWLOG: [48088722] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:34:52 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:52 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 ::: force_down_5g:0
Fri Jan 8 12:34:52 2021 user.debug repacd.wifimon: repacd check timeout elapsed:1421 duration:170
Fri Jan 8 12:34:52 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:52 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:34:52 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:34:52 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:52 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:52 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:52 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:34:53 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:34:53 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:53 2021 user.notice led_function: RSSI24G -64
Fri Jan 8 12:34:53 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:34:54 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:34:54 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:34:54 2021 user.notice led_function: led check timeout elapsed:46881 duration:180
Fri Jan 8 12:34:54 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:34:54 2021 user.notice led_function: CUR_STATE: RE_LocationSuitable
Fri Jan 8 12:34:55 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:34:55 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:55 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:34:55 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:34:55 2021 kern.warn kernel: Inst RSSI value of node-08:c5:e1:c2:a4:0c: 35
Fri Jan 8 12:34:55 2021 kern.warn kernel: Inst RSSI value of node-08:c5:e1:c2:a4:0c: 35
Fri Jan 8 12:34:55 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

```
Fri Jan 8 12:34:56 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:56 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:34:56 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:34:56 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41217 event 0 reason 0
Fri Jan 8 12:34:56 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:34:56 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:34:56 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:34:56 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan 8 12:34:56 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:34:56 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:34:56 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:34:56 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:56 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:34:56 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:56 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
0, off 0, len 1
Fri Jan 8 12:34:56 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:56 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:34:56 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1425 duration:170
Fri Jan 8 12:34:56 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:34:56 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:34:56 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:34:56 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:56 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:56 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:56 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:57 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:34:57 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:34:57 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:34:57 2021 kern.warn kernel: [wifi2] FWLOG: [48093874] WAL channel
change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:57 2021 kern.warn kernel: [wifi2] FWLOG: [48094012]
WHAL_ERROR_RESET_OFFSETCAL ( )
```

Fri Jan 8 12:34:57 2021 kern.warn kernel: [wifi2] FWLOG: [48094188] WAL channel change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:57 2021 kern.warn kernel: [wifi2] FWLOG: [48094325] WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:34:57 2021 kern.warn kernel: [wifi2] FWLOG: [48094501] WAL channel change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:57 2021 kern.warn kernel: [wifi2] FWLOG: [48094814] WAL channel change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:57 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:34:57 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:34:57 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:57 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:34:58 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:34:58 2021 kern.warn kernel: [wifi2] FWLOG: [48095128] WAL channel change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:58 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:34:58 2021 kern.warn kernel: [wifi2] FWLOG: [48095265] WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:34:58 2021 kern.warn kernel: [wifi2] FWLOG: [48095441] WAL channel change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:58 2021 kern.warn kernel: [wifi2] FWLOG: [48095754] WAL channel change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:34:58 2021 kern.warn kernel: vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41217 event 1 reason 1
Fri Jan 8 12:34:58 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:34:58 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state transition SCAN -> INIT
Fri Jan 8 12:34:58 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0 (c9e36000)
Fri Jan 8 12:34:58 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_END[3]
Fri Jan 8 12:34:58 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3 not handled in state INIT
Fri Jan 8 12:34:59 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:34:59 2021 kern.warn kernel: [wifi2] FWLOG: [48096095] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:34:59 2021 kern.warn kernel: [wifi2] FWLOG: [48096095] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:34:59 2021 user.notice led_function: RSSI24G -63
Fri Jan 8 12:34:59 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:35:00 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:35:00 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:35:00 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:

```
Fri Jan 8 12:35:00 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:35:00 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:35:00 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:35:00 2021 user.notice led_function: led check timeout
elapsed:46887 duration:180
Fri Jan 8 12:35:00 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:35:00 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:35:01 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:35:01 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:01 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
1, off 0, len 1
Fri Jan 8 12:35:01 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:35:01 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:01 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:01 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:35:01 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1429 duration:170
Fri Jan 8 12:35:01 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:35:01 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:35:01 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:01 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:01 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:01 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:01 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:35:03 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:35:03 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:03 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:03 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:03 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:35:03 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41218 event 0 reason 0
Fri Jan 8 12:35:03 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:35:03 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:35:03 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:35:03 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
```



```
Fri Jan 8 12:35:04 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:04 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:04 2021 kern.warn kernel: [wifi2] FWLOG: [48101218] WAL channel
change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:04 2021 kern.warn kernel: [wifi2] FWLOG: [48101355]
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan 8 12:35:04 2021 kern.warn kernel: [wifi2] FWLOG: [48101531] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:04 2021 kern.warn kernel: [wifi2] FWLOG: [48101668]
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan 8 12:35:04 2021 kern.warn kernel: [wifi2] FWLOG: [48101845] WAL channel
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:04 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:35:04 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:35:05 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:35:05 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:35:05 2021 kern.warn kernel: [wifi2] FWLOG: [48102158] WAL channel
change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:05 2021 kern.warn kernel: [wifi2] FWLOG: [48102471] WAL channel
change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:05 2021 kern.warn kernel: [wifi2] FWLOG: [48102785] WAL channel
change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:05 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:35:05 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:35:05 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:05 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:35:05 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:05 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:05 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:35:05 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1434 duration:170
Fri Jan 8 12:35:05 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:35:05 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:35:05 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:05 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:05 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:05 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41218 event 1 reason 1
Fri Jan 8 12:35:05 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:35:05 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
```

VAP state transition SCAN -> INIT
Fri Jan 8 12:35:05 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0 (c9e36000)
Fri Jan 8 12:35:05 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_END[3]
Fri Jan 8 12:35:05 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3 not handled in state INIT
Fri Jan 8 12:35:06 2021 user.notice led_function: RSSI24G -63
Fri Jan 8 12:35:06 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:35:06 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:06 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:35:06 2021 kern.warn kernel: [wifi2] FWLOG: [48103098] WAL channel change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:06 2021 kern.warn kernel: [wifi2] FWLOG: [48103439] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:35:06 2021 kern.warn kernel: [wifi2] FWLOG: [48103439] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:35:06 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:35:07 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:35:07 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:35:07 2021 user.notice led_function: led check timeout elapsed:46893 duration:180
Fri Jan 8 12:35:07 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:35:07 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:35:07 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:35:07 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:35:07 2021 kern.warn kernel: Printing wds entries [No. of entries:0]
Fri Jan 8 12:35:07 2021 kern.warn kernel: DA Next Hop flags
Fri Jan 8 12:35:07 2021 kern.warn kernel:
Fri Jan 8 12:35:09 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:35:09 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:09 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:09 2021 kern.warn kernel: Printing wds entries [No. of entries:0]
Fri Jan 8 12:35:09 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:35:09 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:35:09 2021 kern.warn kernel: DA Next Hop flags
Fri Jan 8 12:35:09 2021 kern.warn kernel:
Fri Jan 8 12:35:09 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:09 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:09 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected

Fri Jan 8 12:35:09 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:10 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 ::: force_down_5g:0
Fri Jan 8 12:35:10 2021 user.debug repacd.wifimon: repacd check timeout elapsed:1438 duration:170
Fri Jan 8 12:35:10 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:10 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:35:10 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:35:10 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:10 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:10 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:10 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Sending SCAN START cmd
Fri Jan 8 12:35:10 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41219 event 0 reason 0
Fri Jan 8 12:35:10 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:35:10 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state transition INIT -> SCAN
Fri Jan 8 12:35:10 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_START[9]
Fri Jan 8 12:35:10 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9 not handled in state INIT
Fri Jan 8 12:35:10 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:35:11 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:11 2021 kern.warn kernel: Inst RSSI value of node-08:c5:e1:c2:a4:0c: 34
Fri Jan 8 12:35:11 2021 kern.warn kernel: Inst RSSI value of node-08:c5:e1:c2:a4:0c: 34
Fri Jan 8 12:35:11 2021 kern.warn kernel: [wifi2] FWLOG: [48108563] WAL channel change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:11 2021 kern.warn kernel: [wifi2] FWLOG: [48108700] WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:35:11 2021 kern.warn kernel: [wifi2] FWLOG: [48108876] WAL channel change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:11 2021 kern.warn kernel: [wifi2] FWLOG: [48109013] WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:35:11 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:35:11 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:35:12 2021 user.notice led_function: RSSI24G -63
Fri Jan 8 12:35:12 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:35:12 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:35:12 2021 kern.warn kernel: [wifi2] FWLOG: [48109190] WAL channel

```
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan  8 12:35:12 2021 kern.warn kernel: [wifi2] FWLOG: [48109503] WAL channel
change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan  8 12:35:12 2021 kern.warn kernel: [wifi2] FWLOG: [48109816] WAL channel
change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan  8 12:35:12 2021 kern.warn kernel: [wifi2] FWLOG: [48110130] WAL channel
change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan  8 12:35:12 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41219 event 1 reason 1
Fri Jan  8 12:35:12 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan  8 12:35:12 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition SCAN -> INIT
Fri Jan  8 12:35:12 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0
(c9e36000)
Fri Jan  8 12:35:12 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_END[3]
Fri Jan  8 12:35:12 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3
not handled in state INIT
Fri Jan  8 12:35:13 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan  8 12:35:13 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan  8 12:35:13 2021 user.notice led_function: led check timeout
elapsed:46899 duration:180
Fri Jan  8 12:35:13 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan  8 12:35:13 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan  8 12:35:13 2021 kern.warn kernel: [wifi2] FWLOG: [48110443] WAL channel
change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan  8 12:35:13 2021 kern.warn kernel: [wifi2] FWLOG: [48110783]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan  8 12:35:13 2021 kern.warn kernel: [wifi2] FWLOG: [48110783]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan  8 12:35:14 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan  8 12:35:14 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan  8 12:35:14 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan  8 12:35:14 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:35:14 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan  8 12:35:14 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan  8 12:35:14 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:35:14 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan  8 12:35:14 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1442 duration:170
Fri Jan  8 12:35:14 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan  8 12:35:14 2021 user.info repacd: AssocTimeout
Fri Jan  8 12:35:14 2021 user.info repacd: Boot time count=-1
Fri Jan  8 12:35:14 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
```

```
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan  8 12:35:14 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:35:14 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan  8 12:35:15 2021 user.notice led_function: =====LOOP END=====
Fri Jan  8 12:35:15 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:35:15 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan  8 12:35:16 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan  8 12:35:16 2021 kern.warn kernel: vap-2(ath01):[a6:c9:eb:1a:a6:a1] send
null data frame on channel 13, pwr mgt dis
Fri Jan  8 12:35:16 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan  8 12:35:17 2021 kern.warn kernel: Inst RSSI value of
node-08:c5:e1:c2:a4:0c: 34
Fri Jan  8 12:35:17 2021 kern.warn kernel: Inst RSSI value of
node-08:c5:e1:c2:a4:0c: 34
Fri Jan  8 12:35:17 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan  8 12:35:17 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan  8 12:35:17 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan  8 12:35:17 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan  8 12:35:17 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41220 event 0 reason 0
Fri Jan  8 12:35:17 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan  8 12:35:17 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan  8 12:35:17 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan  8 12:35:17 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan  8 12:35:18 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan  8 12:35:18 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan  8 12:35:18 2021 kern.warn kernel: [wifi2] FWLOG: [48115906] WAL channel
change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan  8 12:35:18 2021 kern.warn kernel: [wifi2] FWLOG: [48116044]
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan  8 12:35:18 2021 kern.warn kernel: [wifi2] FWLOG: [48116220] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan  8 12:35:18 2021 kern.warn kernel: [wifi2] FWLOG: [48116357]
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan  8 12:35:18 2021 user.notice led_function: RSSI24G -63
Fri Jan  8 12:35:18 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan  8 12:35:18 2021 user.notice led_function: PING IS WELL
Fri Jan  8 12:35:18 2021 user.debug repacd.wifimon: CHECK associatd
```

Fri Jan 8 12:35:18 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:18 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:18 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:35:18 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:18 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:18 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 ::: force_down_5g:0
Fri Jan 8 12:35:18 2021 user.debug repacd.wifimon: repacd check timeout elapsed:1447 duration:170
Fri Jan 8 12:35:18 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:35:18 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:35:18 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:18 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:35:18 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:18 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:19 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:19 2021 kern.warn kernel: [wifi2] FWLOG: [48116533] WAL channel change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:19 2021 kern.warn kernel: [wifi2] FWLOG: [48116847] WAL channel change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:19 2021 kern.warn kernel: [wifi2] FWLOG: [48117160] WAL channel change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:19 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:35:19 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:35:19 2021 user.notice led_function: led check timeout elapsed:46906 duration:180
Fri Jan 8 12:35:19 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:35:19 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:35:19 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:35:20 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:35:20 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41220 event 1 reason 1
Fri Jan 8 12:35:20 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:35:20 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state transition SCAN -> INIT
Fri Jan 8 12:35:20 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0 (c9e36000)
Fri Jan 8 12:35:20 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_END[3]

Fri Jan 8 12:35:20 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3 not handled in state INIT
Fri Jan 8 12:35:20 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:20 2021 kern.warn kernel: [wifi2] FWLOG: [48117473] WAL channel change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:20 2021 kern.warn kernel: [wifi2] FWLOG: [48117611] WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:35:20 2021 kern.warn kernel: [wifi2] FWLOG: [48117787] WAL channel change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:20 2021 kern.warn kernel: [wifi2] FWLOG: [48118127] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:35:20 2021 kern.warn kernel: [wifi2] FWLOG: [48118127] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:35:20 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:35:21 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:35:21 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:22 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:22 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:35:22 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:35:22 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:23 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:23 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:35:23 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:23 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:23 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 ::: force_down_5g:0
Fri Jan 8 12:35:23 2021 user.debug repacd.wifimon: repacd check timeout elapsed:1451 duration:170
Fri Jan 8 12:35:23 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:35:23 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:35:23 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:23 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:23 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:24 2021 user.notice led_function: RSSI24G -63
Fri Jan 8 12:35:24 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:35:24 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:25 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:25 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:35:25 2021 kern.warn kernel: vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41221 event 0 reason 0
Fri Jan 8 12:35:25 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:

VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:35:25 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:35:25 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:35:25 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan 8 12:35:25 2021 kern.warn kernel: [wifi2] FWLOG: [48123252] WAL channel
change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:25 2021 kern.warn kernel: [wifi2] FWLOG: [48123389]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:35:25 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:35:25 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:35:25 2021 user.notice led_function: led check timeout
elapsed:46912 duration:180
Fri Jan 8 12:35:25 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:35:25 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:35:26 2021 kern.warn kernel: [wifi2] FWLOG: [48123565] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:26 2021 kern.warn kernel: [wifi2] FWLOG: [48123702]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:35:26 2021 kern.warn kernel: [wifi2] FWLOG: [48123878] WAL channel
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:26 2021 kern.warn kernel: [wifi2] FWLOG: [48124192] WAL channel
change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:26 2021 kern.warn kernel: [wifi2] FWLOG: [48124505] WAL channel
change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:27 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:35:27 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:35:27 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41221 event 1 reason 1
Fri Jan 8 12:35:27 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:35:27 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition SCAN -> INIT
Fri Jan 8 12:35:27 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0
(c9e36000)
Fri Jan 8 12:35:27 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:35:27 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_END[3]
Fri Jan 8 12:35:27 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3
not handled in state INIT
Fri Jan 8 12:35:27 2021 kern.warn kernel: [wifi2] FWLOG: [48124818] WAL channel
change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:27 2021 kern.warn kernel: [wifi2] FWLOG: [48124956]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:35:27 2021 kern.warn kernel: [wifi2] FWLOG: [48125132] WAL channel
change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:27 2021 kern.warn kernel: [wifi2] FWLOG: [48125472]


```
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan  8 12:35:27 2021 kern.warn kernel: [wifi2] FWLOG: [48125472]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan  8 12:35:27 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan  8 12:35:27 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan  8 12:35:27 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan  8 12:35:27 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan  8 12:35:27 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan  8 12:35:27 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:35:27 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:35:27 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan  8 12:35:27 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1456 duration:170
Fri Jan  8 12:35:27 2021 user.info repacd: AssocTimeout
Fri Jan  8 12:35:27 2021 user.info repacd: Boot time count=-1
Fri Jan  8 12:35:27 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:35:27 2021 user.notice led_function: =====LOOP END=====
Fri Jan  8 12:35:27 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:35:27 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan  8 12:35:27 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan  8 12:35:27 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan  8 12:35:27 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan  8 12:35:28 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan  8 12:35:28 2021 kern.warn kernel: RX Rate Info:
Fri Jan  8 12:35:28 2021 kern.warn kernel: MCS counts (0..9): 665, 1501, 3938,
15263, 39459, 43773, 54458, 35148, 3613, 885
Fri Jan  8 12:35:28 2021 kern.warn kernel: SGI counts (0..9): 240, 689, 1658,
7597, 13617, 17013, 28081, 17387, 1700, 483
Fri Jan  8 12:35:28 2021 kern.warn kernel: NSS counts: 1x1 126609, 2x2 72094,
3x3 0, 4x4 0
Fri Jan  8 12:35:28 2021 kern.warn kernel: NSTS count: 571
Fri Jan  8 12:35:28 2021 kern.warn kernel: BW counts: 20MHz 199643, 40MHz 0,
80MHz 0, 160MHz 0
Fri Jan  8 12:35:28 2021 kern.warn kernel: Preamble counts: 114147, 89173, 0,
110470, 0, 0
Fri Jan  8 12:35:28 2021 kern.warn kernel: STBC rate counts (0..9): 238, 187,
51, 49, 23, 0, 1, 22, 0, 0
Fri Jan  8 12:35:28 2021 kern.warn kernel: LDPC Counts: 198600
Fri Jan  8 12:35:28 2021 kern.warn kernel: RSSI (data, mgmt): 33, 34
Fri Jan  8 12:35:28 2021 kern.warn kernel: RSSI Chain 0 (0x80 0x80 0x80 0x1f)
Fri Jan  8 12:35:28 2021 kern.warn kernel: RSSI Chain 1 (0x80 0x80 0x80 0x1c)
```

Fri Jan 8 12:35:28 2021 kern.warn kernel: RSSI Chain 2 (0x00 0x00 0x00 0x00)
Fri Jan 8 12:35:28 2021 kern.warn kernel: RSSI Chain 3 (0x00 0x00 0x00 0x00)
Fri Jan 8 12:35:28 2021 kern.warn kernel: RSSI (comb_ht): 33
Fri Jan 8 12:35:29 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:35:29 2021 kern.warn kernel: RX Rate Info:
Fri Jan 8 12:35:29 2021 kern.warn kernel: MCS counts (0..9): 4586, 0, 0, 0, 77,
20188, 68397, 129938, 501811, 27607
Fri Jan 8 12:35:29 2021 kern.warn kernel: SGI counts (0..9): 0, 0, 0, 0, 76,
20070, 66924, 126215, 498615, 15530
Fri Jan 8 12:35:29 2021 kern.warn kernel: NSS counts: 1x1 4580, 2x2 1557, 3x3
552329, 4x4 194138
Fri Jan 8 12:35:29 2021 kern.warn kernel: NSTS count: 0
Fri Jan 8 12:35:29 2021 kern.warn kernel: BW counts: 20MHz 29, 40MHz 56, 80MHz
757477, 160MHz 0
Fri Jan 8 12:35:29 2021 kern.warn kernel: Preamble counts: 135383, 56, 0,
757506, 0, 5271
Fri Jan 8 12:35:29 2021 kern.warn kernel: STBC rate counts (0..9): 0, 0, 0, 0,
0, 0, 0, 0, 0, 0
Fri Jan 8 12:35:29 2021 kern.warn kernel: LDPC Counts: 748012
Fri Jan 8 12:35:29 2021 kern.warn kernel: RSSI (data, mgmt): 40, 18
Fri Jan 8 12:35:29 2021 kern.warn kernel: RSSI Chain 0 (0x80 0x25 0x21 0x24)
Fri Jan 8 12:35:29 2021 kern.warn kernel: RSSI Chain 1 (0x80 0x21 0x1e 0x22)
Fri Jan 8 12:35:29 2021 kern.warn kernel: RSSI Chain 2 (0x80 0x24 0x21 0x20)
Fri Jan 8 12:35:29 2021 kern.warn kernel: RSSI Chain 3 (0x80 0x1f 0x22 0x24)
Fri Jan 8 12:35:29 2021 kern.warn kernel: RSSI (comb_ht): 41
Fri Jan 8 12:35:29 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:35:29 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:35:30 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:35:30 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:35:30 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:35:30 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:35:30 2021 kern.warn kernel: TX Rate Info:
Fri Jan 8 12:35:30 2021 kern.warn kernel: MCS counts (0..9): 562, 704, 1316,
1625, 8547, 50005, 89625, 127828, 48449, 22355
Fri Jan 8 12:35:30 2021 kern.warn kernel: MCS counts SU (0..9): 562, 704, 1316,
1625, 8547, 50005, 89625, 127828, 48449, 22355
Fri Jan 8 12:35:30 2021 kern.warn kernel: MCS counts MU (0..9): 0, 0, 0, 0, 0,
0, 0, 0, 0, 0
Fri Jan 8 12:35:30 2021 kern.warn kernel: SGI counts (0..9): 0, 0, 0, 0, 4949,
21732, 33847, 102247, 38553, 16655
Fri Jan 8 12:35:30 2021 kern.warn kernel: NSS counts: 1x1 152409, 2x2 198607,
3x3 0 4x4 0
Fri Jan 8 12:35:30 2021 kern.warn kernel: BW counts: 20MHz 351016, 40MHz 0,
80MHz 0, 160MHz 0
Fri Jan 8 12:35:30 2021 kern.warn kernel: Preamble (O C H V) counts: 0, 13120,
143104, 208880
Fri Jan 8 12:35:30 2021 kern.warn kernel: STBC rate counts (0..9): 562, 672,

1181, 1496, 1737, 10581, 33052, 50289, 0, 0
Fri Jan 8 12:35:30 2021 kern.warn kernel: LDPC Counts: 207912
Fri Jan 8 12:35:30 2021 kern.warn kernel: RTS Counts: 27420
Fri Jan 8 12:35:30 2021 kern.warn kernel: Ack RSSI: 33
Fri Jan 8 12:35:30 2021 user.notice led_function: RSSI24G -63
Fri Jan 8 12:35:30 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:35:30 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:35:31 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:35:31 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:35:31 2021 kern.warn kernel: TX Rate Info:
Fri Jan 8 12:35:31 2021 kern.warn kernel: MCS counts (0..9): 0, 0, 0, 0, 0,
8324, 125481, 166019, 365434, 217694
Fri Jan 8 12:35:31 2021 kern.warn kernel: MCS counts SU (0..9): 0, 0, 0, 0, 0,
8324, 125481, 166019, 365434, 217694
Fri Jan 8 12:35:31 2021 kern.warn kernel: MCS counts MU (0..9): 0, 0, 0, 0, 0,
0, 0, 0, 0, 0
Fri Jan 8 12:35:31 2021 kern.warn kernel: SGI counts (0..9): 0, 0, 0, 0, 0,
8294, 124427, 149841, 319175, 185317
Fri Jan 8 12:35:31 2021 kern.warn kernel: NSS counts: 1x1 0, 2x2 332, 3x3
545719 4x4 336901
Fri Jan 8 12:35:31 2021 kern.warn kernel: BW counts: 20MHz 391, 40MHz 0, 80MHz
882561, 160MHz 0
Fri Jan 8 12:35:31 2021 kern.warn kernel: Preamble (O C H V) counts: 2, 0, 0,
882952
Fri Jan 8 12:35:31 2021 kern.warn kernel: STBC rate counts (0..9): 0, 0, 0, 0,
0, 0, 0, 0, 0, 0
Fri Jan 8 12:35:31 2021 kern.warn kernel: LDPC Counts: 882952
Fri Jan 8 12:35:31 2021 kern.warn kernel: RTS Counts: 814
Fri Jan 8 12:35:31 2021 kern.warn kernel: Ack RSSI: 36
Fri Jan 8 12:35:31 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:35:31 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:35:31 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:35:31 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:35:31 2021 user.notice led_function: led check timeout
elapsed:46918 duration:180
Fri Jan 8 12:35:31 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:35:31 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:35:31 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:31 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:35:32 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:32 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:32 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:35:32 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1460 duration:170
Fri Jan 8 12:35:32 2021 user.info repacd: AssocTimeout

Fri Jan 8 12:35:32 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:32 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:35:32 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:35:32 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:32 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:32 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:32 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:35:32 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41222 event 0 reason 0
Fri Jan 8 12:35:32 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:35:32 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:35:32 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:35:32 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan 8 12:35:32 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:35:32 2021 kern.warn kernel: [wifi2] FWLOG: [48130595] WAL channel
change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:32 2021 kern.warn kernel: [wifi2] FWLOG: [48130732]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:35:32 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:35:32 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:32 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:35:33 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:35:33 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:35:33 2021 kern.warn kernel: [wifi2] FWLOG: [48130908] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:33 2021 kern.warn kernel: [wifi2] FWLOG: [48131046]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:35:33 2021 kern.warn kernel: [wifi2] FWLOG: [48131222] WAL channel
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:33 2021 kern.warn kernel: [wifi2] FWLOG: [48131535] WAL channel
change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:33 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:35:33 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:35:33 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:34 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:34 2021 kern.warn kernel: [wifi2] FWLOG: [48131849] WAL channel

change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:34 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41222 event 1 reason 1
Fri Jan 8 12:35:34 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:35:34 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition SCAN -> INIT
Fri Jan 8 12:35:34 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0
(c9e36000)
Fri Jan 8 12:35:34 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_END[3]
Fri Jan 8 12:35:34 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3
not handled in state INIT
Fri Jan 8 12:35:34 2021 kern.warn kernel: [wifi2] FWLOG: [48132162] WAL channel
change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:34 2021 kern.warn kernel: [wifi2] FWLOG: [48132475] WAL channel
change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:35 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:35:35 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:35 2021 kern.warn kernel: [wifi2] FWLOG: [48132817]
RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:35:35 2021 kern.warn kernel: [wifi2] FWLOG: [48132817]
RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:35:36 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:35:36 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:35:36 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:35:36 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:36 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:36 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:35:36 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:36 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:35:36 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1465 duration:170
Fri Jan 8 12:35:36 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:36 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:35:36 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:35:36 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:36 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:37 2021 user.notice led_function: RSSI24G -63
Fri Jan 8 12:35:37 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:35:37 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:37 2021 kern.warn kernel: vap-0(ath1):

[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:35:37 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:35:37 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:35:38 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:35:38 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:35:38 2021 user.notice led_function: led check timeout
elapsed:46924 duration:180
Fri Jan 8 12:35:38 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:35:38 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:35:39 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:35:39 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:35:39 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41223 event 0 reason 0
Fri Jan 8 12:35:39 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:35:39 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:35:39 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:35:39 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan 8 12:35:39 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:35:40 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:35:40 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:35:40 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:40 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:40 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key[wifi2] FWLOG: [48137969] WAL channel change freq=5580, mode=0 flags=0
rx_ok=1 tx_ok=1
Fri Jan 8 12:35:40 2021 kern.warn kernel: [wifi2] FWLOG: [48138106]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:35:40 2021 kern.warn kernel: [wifi2] FWLOG: [48138282] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:40 2021 kern.warn kernel: [wifi2] FWLOG: [48138419]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:35:40 2021 kern.warn kernel: [wifi2] FWLOG: [48138596] WAL channel
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:40 2021 kern.warn kernel: [wifi2] FWLOG: [48138909] WAL channel
change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:40 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:35:40 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:35:40 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:35:40 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid

key
Fri Jan 8 12:35:40 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:40 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:35:40 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:35:40 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:35:40 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:40 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:35:40 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1469 duration:170
Fri Jan 8 12:35:40 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:40 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
0, off 0, len 1
Fri Jan 8 12:35:40 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:35:40 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:35:41 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:35:41 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:41 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:41 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key[wifi2] FWLOG: [48139223] WAL channel change freq=5660, mode=0 flags=0
rx_ok=1 tx_ok=1
Fri Jan 8 12:35:41 2021 kern.warn kernel: [wifi2] FWLOG: [48139536] WAL channel
change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:41 2021 kern.warn kernel: [wifi2] FWLOG: [48139849] WAL channel
change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:41 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:35:41 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41223 event 1 reason 1
Fri Jan 8 12:35:41 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:35:41 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition SCAN -> INIT
Fri Jan 8 12:35:41 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0
(c9e36000)
Fri Jan 8 12:35:41 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_END[3]
Fri Jan 8 12:35:41 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3
not handled in state INIT
Fri Jan 8 12:35:41 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:35:42 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:35:42 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid

key

```
Fri Jan 8 12:35:42 2021 kern.warn kernel: [wifi2] FWLOG: [48140190]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan 8 12:35:42 2021 kern.warn kernel: [wifi2] FWLOG: [48140190]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan 8 12:35:43 2021 user.notice led_function: RSSI24G -63
Fri Jan 8 12:35:43 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:35:43 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:35:43 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:35:44 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:35:44 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:35:44 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:35:44 2021 user.notice led_function: led check timeout
elapsed:46930 duration:180
Fri Jan 8 12:35:44 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:35:44 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:35:45 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:35:45 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:35:45 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:35:45 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:45 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:45 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:35:45 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:45 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:35:45 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1473 duration:170
Fri Jan 8 12:35:45 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:45 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:35:45 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:35:45 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:45 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:45 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:46 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:35:46 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:46 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:46 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:46 2021 kern.warn kernel: Sending SCAN START cmd
```


Fri Jan 8 12:35:46 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41224 event 0 reason 0
Fri Jan 8 12:35:46 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:35:46 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:35:46 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:35:46 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan 8 12:35:47 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:35:47 2021 kern.warn kernel: [wifi2] FWLOG: [48145314] WAL channel
change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:47 2021 kern.warn kernel: [wifi2] FWLOG: [48145452]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:35:47 2021 kern.warn kernel: [wifi2] FWLOG: [48145628]
Fri Jan 8 12:35:47 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyWAL channel change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:47 2021 kern.warn kernel: [wifi2] FWLOG: [48145765]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:35:47 2021 kern.warn kernel: [wifi2] FWLOG: [48145941] WAL channel
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:47 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:35:48 2021 kern.warn kernel: [wifi2] FWLOG: [48146254] WAL channel
change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:48 2021 kern.warn kernel: [wifi2] FWLOG: [48146568] WAL channel
change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:48 2021 kern.warn kernel: [wifi2] FWLOG: [48146881] WAL channel
change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:48 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:35:48 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41224 event 1 reason 1
Fri Jan 8 12:35:48 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:35:48 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition SCAN -> INIT
Fri Jan 8 12:35:48 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0
(c9e36000)
Fri Jan 8 12:35:48 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_END[3]
Fri Jan 8 12:35:48 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3
not handled in state INIT
Fri Jan 8 12:35:48 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:35:48 2021 kern.warn kernel: Inst RSSI value of
node-08:c5:e1:c2:a4:0c: 36
Fri Jan 8 12:35:48 2021 kern.warn kernel: Inst RSSI value of
node-08:c5:e1:c2:a4:0c: 36
Fri Jan 8 12:35:49 2021 kern.warn kernel: vap-0(ath1):

```
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:35:49 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:35:49 2021 kern.warn kernel: [wifi2] FWLOG: [48147194] WAL channel
change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:49 2021 kern.warn kernel: [wifi2] FWLOG: [48147535]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan 8 12:35:49 2021 kern.warn kernel: [wifi2] FWLOG: [48147535]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan 8 12:35:49 2021 user.notice led_function: RSSI24G -63
Fri Jan 8 12:35:49 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:35:49 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:35:49 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:35:49 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:49 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:35:49 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:49 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:49 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:35:49 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1478 duration:170
Fri Jan 8 12:35:49 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:35:49 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:35:49 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:49 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:49 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:50 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:35:50 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:35:50 2021 user.notice led_function: led check timeout
elapsed:46937 duration:180
Fri Jan 8 12:35:50 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:35:50 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:35:52 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:52 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:35:52 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:52 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:53 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
2, off 0, len 1
Fri Jan 8 12:35:53 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:35:53 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
```

Fri Jan 8 12:35:53 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:35:53 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41225 event 0 reason 0
Fri Jan 8 12:35:53 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:35:53 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:35:53 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:35:53 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:35:53 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan 8 12:35:54 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:35:54 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:35:54 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:54 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:35:54 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:54 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:35:54 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1482 duration:170
Fri Jan 8 12:35:54 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:54 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:35:54 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:35:54 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:54 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:54 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:54 2021 kern.warn kernel: [wifi2] FWLOG: [48152658] WAL channel
change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:54 2021 kern.warn kernel: [wifi2] FWLOG: [48152796]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:35:54 2021 kern.warn kernel: [wifi2] FWLOG: [48152972] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:54 2021 kern.warn kernel: [wifi2] FWLOG: [48153109]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:35:55 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:35:55 2021 kern.warn kernel: [wifi2] FWLOG: [48153285] WAL channel
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:55 2021 kern.warn kernel: [wifi2] FWLOG: [48153599] WAL channel
change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:55 2021 kern.warn kernel: [wifi2] FWLOG: [48153912] WAL channel
change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:55 2021 kern.warn kernel: [wifi2] FWLOG: [48154225] WAL channel
change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:55 2021 kern.warn kernel: [wifi2] FWLOG: [48154363]

```
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan 8 12:35:55 2021 user.notice led_function: RSSI24G -63
Fri Jan 8 12:35:55 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:35:56 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:35:56 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41225 event 1 reason 1
Fri Jan 8 12:35:56 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:35:56 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition SCAN -> INIT
Fri Jan 8 12:35:56 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0
(c9e36000)
Fri Jan 8 12:35:56 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_END[3]
Fri Jan 8 12:35:56 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3
not handled in state INIT
Fri Jan 8 12:35:56 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:56 2021 kern.warn kernel: [wifi2] FWLOG: [48154539] WAL channel
change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:35:56 2021 kern.warn kernel: [wifi2] FWLOG: [48154852]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan 8 12:35:56 2021 kern.warn kernel: [wifi2] FWLOG: [48154852]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan 8 12:35:56 2021 kern.warn kernel: vap-2(ath01):[a6:c9:eb:1a:a6:a1] send
null data frame on channel 13, pwr mgt dis
Fri Jan 8 12:35:56 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:35:56 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:35:56 2021 user.notice led_function: led check timeout
elapsed:46943 duration:180
Fri Jan 8 12:35:56 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:35:56 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:35:57 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:35:57 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:35:58 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:35:58 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:35:58 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:35:58 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:35:58 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:35:58 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:58 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:35:58 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:58 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
```

Fri Jan 8 12:35:58 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:35:58 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1487 duration:170
Fri Jan 8 12:35:58 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:35:58 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:35:58 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:58 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:35:58 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:35:58 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:58 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:35:59 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:00 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
2, off 0, len 1
Fri Jan 8 12:36:00 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:36:00 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:36:00 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:36:01 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:36:01 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:36:01 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41226 event 0 reason 0
Fri Jan 8 12:36:01 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:36:01 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:36:01 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:36:01 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan 8 12:36:01 2021 kern.warn kernel: [wifi2] FWLOG: [48160019] WAL channel
change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:01 2021 kern.warn kernel: [wifi2] FWLOG: [48160157]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:36:01 2021 kern.warn kernel: [wifi2] FWLOG: [48160333] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:01 2021 kern.warn kernel: [wifi2] FWLOG: [48160470]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:36:01 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:36:01 2021 user.notice led_function: RSSI24G -63
Fri Jan 8 12:36:01 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:36:02 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

```
Fri Jan 8 12:36:02 2021 kern.warn kernel: [wifi2] FWLOG: [48160646] WAL channel
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:02 2021 kern.warn kernel: [wifi2] FWLOG: [48160959] WAL channel
change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:02 2021 kern.warn kernel: [wifi2] FWLOG: [48161273] WAL channel
change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:02 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:36:02 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:36:02 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:36:02 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:36:02 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:36:02 2021 user.notice led_function: led check timeout
elapsed:46949 duration:180
Fri Jan 8 12:36:02 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:02 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:36:02 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:36:02 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:36:03 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:03 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:03 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:36:03 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1491 duration:170
Fri Jan 8 12:36:03 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:36:03 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:36:03 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:03 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:03 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000
scan_id 41226 event 1 reason 1
Fri Jan 8 12:36:03 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:36:03 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition SCAN -> INIT
Fri Jan 8 12:36:03 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:36:03 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0
(c9e36000)
Fri Jan 8 12:36:03 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_END[3]
Fri Jan 8 12:36:03 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3
not handled in state INIT
Fri Jan 8 12:36:03 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:03 2021 kern.warn kernel: [wifi2] FWLOG: [48161586] WAL channel
change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:03 2021 kern.warn kernel: [wifi2] FWLOG: [48161899] WAL channel
```

change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:03 2021 kern.warn kernel: [wifi2] FWLOG: [48162243]
RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:36:03 2021 kern.warn kernel: [wifi2] FWLOG: [48162243]
RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:36:03 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:04 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
2, off 0, len 1
Fri Jan 8 12:36:04 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:36:04 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:36:04 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:36:04 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:05 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:05 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:36:05 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:36:05 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:36:06 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:36:06 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:06 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:36:06 2021 kern.warn kernel: Inst RSSI value of
node-08:c5:e1:c2:a4:0c: 33
Fri Jan 8 12:36:06 2021 kern.warn kernel: Inst RSSI value of
node-08:c5:e1:c2:a4:0c: 33
Fri Jan 8 12:36:07 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:36:07 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:36:07 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:36:07 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:36:07 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:36:07 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:07 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:36:07 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:07 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:36:07 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:07 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:36:07 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1496 duration:170

```
Fri Jan 8 12:36:07 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:07 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:36:07 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:36:07 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:07 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:07 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:07 2021 kern.warn kernel: Printing wds entries [No. of
entries:0]
Fri Jan 8 12:36:08 2021 user.notice led_function: RSSI24G -63
Fri Jan 8 12:36:08 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:36:08 2021 kern.warn kernel:          DA                      Next Hop
flags
Fri Jan 8 12:36:08 2021 kern.warn kernel:
Fri Jan 8 12:36:08 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:36:08 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41227 event 0 reason 0
Fri Jan 8 12:36:08 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:36:08 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:36:08 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:36:08 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan 8 12:36:08 2021 kern.warn kernel: [wifi2] FWLOG: [48167368] WAL channel
change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:08 2021 kern.warn kernel: [wifi2] FWLOG: [48167505]
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan 8 12:36:09 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:36:09 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:36:09 2021 user.notice led_function: led check timeout
elapsed:46955 duration:180
Fri Jan 8 12:36:09 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:36:09 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:36:09 2021 kern.warn kernel: [wifi2] FWLOG: [48167681] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:09 2021 kern.warn kernel: [wifi2] FWLOG: [48167818]
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan 8 12:36:09 2021 kern.warn kernel: [wifi2] FWLOG: [48167994] WAL channel
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:09 2021 kern.warn kernel: [wifi2] FWLOG: [48168308] WAL channel
change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:09 2021 kern.warn kernel: [wifi2] FWLOG: [48168621] WAL channel
change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:09 2021 kern.warn kernel: [wifi2] FWLOG: [48168759]
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan 8 12:36:09 2021 kern.warn kernel: Printing wds entries [No. of
```



```
entries:0]
Fri Jan  8 12:36:10 2021 kern.warn kernel:          DA          Next Hop
flags
Fri Jan  8 12:36:10 2021 kern.warn kernel:
Fri Jan  8 12:36:10 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000
scan_id 41227 event 1 reason 1
Fri Jan  8 12:36:10 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan  8 12:36:10 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition SCAN -> INIT
Fri Jan  8 12:36:10 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0
(c9e36000)
Fri Jan  8 12:36:10 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_END[3]
Fri Jan  8 12:36:10 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3
not handled in state INIT
Fri Jan  8 12:36:10 2021 kern.warn kernel: [wifi2] FWLOG: [48168934] WAL channel
change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan  8 12:36:10 2021 kern.warn kernel: [wifi2] FWLOG: [48169248] WAL channel
change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan  8 12:36:10 2021 kern.warn kernel: [wifi2] FWLOG: [48169588]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan  8 12:36:10 2021 kern.warn kernel: [wifi2] FWLOG: [48169588]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan  8 12:36:11 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan  8 12:36:11 2021 user.notice led_function: =====LOOP END=====
Fri Jan  8 12:36:11 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:36:11 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan  8 12:36:11 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan  8 12:36:11 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan  8 12:36:11 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan  8 12:36:11 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan  8 12:36:11 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan  8 12:36:11 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan  8 12:36:11 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:36:11 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:36:11 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan  8 12:36:11 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1500 duration:170
Fri Jan  8 12:36:11 2021 user.info repacd: AssocTimeout
Fri Jan  8 12:36:11 2021 user.info repacd: Boot time count=-1
Fri Jan  8 12:36:11 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:36:11 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
```

Fri Jan 8 12:36:11 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:13 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:13 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:36:13 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:36:14 2021 user.notice led_function: RSSI24G -63
Fri Jan 8 12:36:14 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:36:15 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:36:15 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:36:15 2021 user.notice led_function: led check timeout elapsed:46961 duration:180
Fri Jan 8 12:36:15 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:36:15 2021 user.notice led_function: CUR_STATE: RE_LocationSuitable
Fri Jan 8 12:36:15 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:36:15 2021 kern.warn kernel: vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41228 event 0 reason 0
Fri Jan 8 12:36:15 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:36:15 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state transition INIT -> SCAN
Fri Jan 8 12:36:15 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_START[9]
Fri Jan 8 12:36:15 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9 not handled in state INIT
Fri Jan 8 12:36:15 2021 kern.warn kernel: [wifi2] FWLOG: [48174712] WAL channel change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:15 2021 kern.warn kernel: [wifi2] FWLOG: [48174849] WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:36:15 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:36:16 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:36:16 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:16 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:16 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:36:16 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:16 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:16 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 ::: force_down_5g:0
Fri Jan 8 12:36:16 2021 user.debug repacd.wifimon: repacd check timeout elapsed:1504 duration:170
Fri Jan 8 12:36:16 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:16 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:36:16 2021 user.info repacd: Boot time count=-1

Fri Jan 8 12:36:16 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:16 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:16 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:16 2021 kern.warn kernel: [wifi2] FWLOG: [48175025] WAL channel change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:16 2021 kern.warn kernel: [wifi2] FWLOG: [48175162] WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:36:16 2021 kern.warn kernel: [wifi2] FWLOG: [48175338] WAL channel change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:16 2021 kern.warn kernel: [wifi2] FWLOG: [48175652] WAL channel change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:16 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:17 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:36:17 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:36:17 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:17 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:17 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:36:17 2021 kern.warn kernel: vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41228 event 1 reason 1
Fri Jan 8 12:36:17 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:36:17 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state transition SCAN -> INIT
Fri Jan 8 12:36:17 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0 (c9e36000)
Fri Jan 8 12:36:17 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_END[3]
Fri Jan 8 12:36:17 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3 not handled in state INIT
Fri Jan 8 12:36:17 2021 kern.warn kernel: [wifi2] FWLOG: [48175965] WAL channel change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:17 2021 kern.warn kernel: [wifi2] FWLOG: [48176278] WAL channel change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:17 2021 kern.warn kernel: [wifi2] FWLOG: [48176416] WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:36:17 2021 kern.warn kernel: [wifi2] FWLOG: [48176592] WAL channel change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:17 2021 kern.warn kernel: [wifi2] FWLOG: [48176932] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:36:17 2021 kern.warn kernel: [wifi2] FWLOG: [48176932] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:36:17 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:36:19 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key

Fri Jan 8 12:36:19 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1

Fri Jan 8 12:36:20 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1

Fri Jan 8 12:36:20 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:

Fri Jan 8 12:36:20 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

Fri Jan 8 12:36:20 2021 user.debug repacd.wifimon: CHECK associatd

Fri Jan 8 12:36:20 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key

Fri Jan 8 12:36:20 2021 user.notice led_function: RSSI24G -63

Fri Jan 8 12:36:20 2021 user.notice led_function: PING IS WELL

Fri Jan 8 12:36:20 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key

Fri Jan 8 12:36:20 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected

Fri Jan 8 12:36:20 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-0(ath2):wlan_get_key: invalid key

Fri Jan 8 12:36:20 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid keyvap-0(ath2):wlan_get_key: invalid key

Fri Jan 8 12:36:20 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 ::: force_down_5g:0

Fri Jan 8 12:36:20 2021 user.debug repacd.wifimon: repacd check timeout elapsed:1509 duration:170

Fri Jan 8 12:36:20 2021 user.info repacd: AssocTimeout

Fri Jan 8 12:36:20 2021 user.info repacd: Boot time count=-1

Fri Jan 8 12:36:20 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-0(ath2):wlan_get_key: invalid key

Fri Jan 8 12:36:20 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-0(ath2):wlan_get_key: invalid key

Fri Jan 8 12:36:20 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key

Fri Jan 8 12:36:21 2021 user.notice led_function: WPS CHECK LOOP:1 wps:

Fri Jan 8 12:36:21 2021 user.notice led_function: wps_inprocess

wps_process_logged wps_1st_finish 0

Fri Jan 8 12:36:21 2021 user.notice led_function: led check timeout elapsed:46968 duration:180

Fri Jan 8 12:36:21 2021 user.notice led_function: SELECTION LOOP CONTINUE

Fri Jan 8 12:36:21 2021 user.notice led_function: CUR_STATE: RE_LocationSuitable

Fri Jan 8 12:36:22 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key

Fri Jan 8 12:36:22 2021 kern.warn kernel: Sending SCAN START cmd

Fri Jan 8 12:36:22 2021 kern.warn kernel: vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41229 event 0 reason 0

Fri Jan 8 12:36:22 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state event 2, cur_state=0, vap_deleted_is_set=0

Fri Jan 8 12:36:22 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state transition INIT -> SCAN

Fri Jan 8 12:36:22 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_START[9]

Fri Jan 8 12:36:22 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9 not handled in state INIT

Fri Jan 8 12:36:22 2021 kern.warn kernel: [wifi2] FWLOG: [48182055] WAL channel change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:22 2021 kern.warn kernel: [wifi2] FWLOG: [48182192] WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:36:22 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:36:22 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:36:23 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:36:23 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:23 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:36:23 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:23 2021 kern.warn kernel: [wifi2] FWLOG: [48182368] WAL channel change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:23 2021 kern.warn kernel: [wifi2] FWLOG: [48182505] WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:36:23 2021 kern.warn kernel: [wifi2] FWLOG: [48182682] WAL channel change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:23 2021 kern.warn kernel: [wifi2] FWLOG: [48182819] WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:36:23 2021 kern.warn kernel: [wifi2] FWLOG: [48182995] WAL channel change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:24 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:24 2021 kern.warn kernel: [wifi2] FWLOG: [48183308] WAL channel change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:24 2021 kern.warn kernel: vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41229 event 1 reason 1
Fri Jan 8 12:36:24 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:36:24 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state transition SCAN -> INIT
Fri Jan 8 12:36:24 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0 (c9e36000)
Fri Jan 8 12:36:24 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:36:24 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_END[3]
Fri Jan 8 12:36:24 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3 not handled in state INIT
Fri Jan 8 12:36:24 2021 kern.warn kernel: [wifi2] FWLOG: [48183622] WAL channel change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:24 2021 kern.warn kernel: [wifi2] FWLOG: [48183759] WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:36:24 2021 kern.warn kernel: [wifi2] FWLOG: [48183935] WAL channel change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:24 2021 kern.warn kernel: [wifi2] FWLOG: [48184072] WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:36:24 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:36:24 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key

Fri Jan 8 12:36:24 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:24 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:36:25 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:25 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:25 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 ::: force_down_5g:0
Fri Jan 8 12:36:25 2021 user.debug repacd.wifimon: repacd check timeout elapsed:1513 duration:170
Fri Jan 8 12:36:25 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:36:25 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:36:25 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:25 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:25 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:25 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:36:25 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:25 2021 kern.warn kernel: [wifi2] FWLOG: [48184276] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:36:25 2021 kern.warn kernel: [wifi2] FWLOG: [48184276] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:36:26 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:36:26 2021 user.notice led_function: RSSI24G -63
Fri Jan 8 12:36:26 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:36:27 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:27 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:36:27 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:36:27 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:36:27 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:36:27 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:36:27 2021 user.notice led_function: led check timeout elapsed:46974 duration:180
Fri Jan 8 12:36:27 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:36:27 2021 user.notice led_function: CUR_STATE: RE_LocationSuitable
Fri Jan 8 12:36:29 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:29 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:36:29 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:36:29 2021 kern.warn kernel: RX Rate Info:

Fri Jan 8 12:36:29 2021 kern.warn kernel: MCS counts (0..9): 665, 1501, 3938, 15344, 39567, 43803, 54483, 35185, 3651, 887
Fri Jan 8 12:36:29 2021 kern.warn kernel: SGI counts (0..9): 240, 689, 1658, 7678, 13676, 17029, 28103, 17418, 1720, 483
Fri Jan 8 12:36:29 2021 kern.warn kernel: NSS counts: 1x1 126726, 2x2 72298, 3x3 0, 4x4 0
Fri Jan 8 12:36:29 2021 kern.warn kernel: NSTS count: 571
Fri Jan 8 12:36:29 2021 kern.warn kernel: BW counts: 20MHz 199965, 40MHz 0, 80MHz 0, 160MHz 0
Fri Jan 8 12:36:29 2021 kern.warn kernel: Preamble counts: 114352, 89173, 0, 110792, 0, 0
Fri Jan 8 12:36:29 2021 kern.warn kernel: STBC rate counts (0..9): 238, 187, 51, 49, 23, 0, 1, 22, 0, 0
Fri Jan 8 12:36:29 2021 kern.warn kernel: LDPC Counts: 198921
Fri Jan 8 12:36:29 2021 kern.warn kernel: RSSI (data, mgmt): 32, 34
Fri Jan 8 12:36:29 2021 kern.warn kernel: RSSI Chain 0 (0x80 0x80 0x80 0x1e)
Fri Jan 8 12:36:29 2021 kern.warn kernel: RSSI Chain 1 (0x80 0x80 0x80 0x1b)
Fri Jan 8 12:36:29 2021 kern.warn kernel: RSSI Chain 2 (0x00 0x00 0x00 0x00)
Fri Jan 8 12:36:29 2021 kern.warn kernel: RSSI Chain 3 (0x00 0x00 0x00 0x00)
Fri Jan 8 12:36:29 2021 kern.warn kernel: RSSI (comb_ht): 32
Fri Jan 8 12:36:29 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:36:29 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:29 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:29 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:36:29 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:36:29 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:29 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:29 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 ::: force_down_5g:0
Fri Jan 8 12:36:29 2021 user.debug repacd.wifimon: repacd check timeout elapsed:1518 duration:170
Fri Jan 8 12:36:29 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:36:29 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:36:29 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:29 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:29 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:29 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:36:29 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:29 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:36:29 2021 kern.warn kernel: vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41230 event 0 reason 0
Fri Jan 8 12:36:29 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:36:29 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:

VAP state transition INIT -> SCAN
Fri Jan 8 12:36:29 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_START[9]
Fri Jan 8 12:36:29 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9 not handled in state INIT
Fri Jan 8 12:36:29 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:30 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
RX Rate Info:
Fri Jan 8 12:36:30 2021 kern.warn kernel: MCS counts (0..9): 4586, 0, 0, 0, 77, 20188, 68397, 129938, 501811, 27607
Fri Jan 8 12:36:30 2021 kern.warn kernel: SGI counts (0..9): 0, 0, 0, 0, 76, 20070, 66924, 126215, 498615, 15530
Fri Jan 8 12:36:30 2021 kern.warn kernel: NSS counts: 1x1 4580, 2x2 1557, 3x3 552329, 4x4 194138
Fri Jan 8 12:36:30 2021 kern.warn kernel: NSTS count: 0
Fri Jan 8 12:36:30 2021 kern.warn kernel: BW counts: 20MHz 29, 40MHz 56, 80MHz 757477, 160MHz 0
Fri Jan 8 12:36:30 2021 kern.warn kernel: Preamble counts: 135383, 56, 0, 757506, 0, 5271
Fri Jan 8 12:36:30 2021 kern.warn kernel: STBC rate counts (0..9): 0, 0, 0, 0, 0, 0, 0, 0, 0, 0
Fri Jan 8 12:36:30 2021 kern.warn kernel: LDPC Counts: 748012
Fri Jan 8 12:36:30 2021 kern.warn kernel: RSSI (data, mgmt): 40, 20
Fri Jan 8 12:36:30 2021 kern.warn kernel: RSSI Chain 0 (0x80 0x25 0x21 0x24)
Fri Jan 8 12:36:30 2021 kern.warn kernel: RSSI Chain 1 (0x80 0x21 0x1e 0x22)
Fri Jan 8 12:36:30 2021 kern.warn kernel: RSSI Chain 2 (0x80 0x24 0x21 0x20)
Fri Jan 8 12:36:30 2021 kern.warn kernel: RSSI Chain 3 (0x80 0x1f 0x22 0x24)
Fri Jan 8 12:36:30 2021 kern.warn kernel: RSSI (comb_ht): 41
Fri Jan 8 12:36:30 2021 kern.warn kernel: [wifi2] FWLOG: [48189442] WAL channel change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:30 2021 kern.warn kernel: [wifi2] FWLOG: [48189579]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:36:30 2021 kern.warn kernel: [wifi2] FWLOG: [48189755] WAL channel change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:30 2021 kern.warn kernel: [wifi2] FWLOG: [48189892]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:36:30 2021 kern.warn kernel: [wifi2] FWLOG: [48190068] WAL channel change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:30 2021 kern.warn kernel: [wifi2] FWLOG: [48190382] WAL channel change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:31 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
TX Rate Info:
Fri Jan 8 12:36:31 2021 kern.warn kernel: MCS counts (0..9): 562, 704, 1316, 1625, 8547, 50719, 89693, 127828, 48449, 22442
Fri Jan 8 12:36:31 2021 kern.warn kernel: MCS counts SU (0..9): 562, 704, 1316, 1625, 8547, 50719, 89693, 127828, 48449, 22442
Fri Jan 8 12:36:31 2021 kern.warn kernel: MCS counts MU (0..9): 0, 0, 0, 0, 0, 0, 0, 0, 0, 0
Fri Jan 8 12:36:31 2021 kern.warn kernel: SGI counts (0..9): 0, 0, 0, 0, 4949, 22357, 33847, 102247, 38553, 16742
Fri Jan 8 12:36:31 2021 kern.warn kernel: NSS counts: 1x1 152496, 2x2 199389, 3x3 0 4x4 0

Fri Jan 8 12:36:31 2021 kern.warn kernel: BW counts: 20MHz 351885, 40MHz 0, 80MHz 0, 160MHz 0
Fri Jan 8 12:36:31 2021 kern.warn kernel: Preamble (O C H V) counts: 0, 13120, 143104, 209749
Fri Jan 8 12:36:31 2021 kern.warn kernel: STBC rate counts (0..9): 562, 672, 1181, 1496, 1737, 10581, 33052, 50289, 0, 0
Fri Jan 8 12:36:31 2021 kern.warn kernel: LDPC Counts: 208781
Fri Jan 8 12:36:31 2021 kern.warn kernel: RTS Counts: 27480
Fri Jan 8 12:36:31 2021 kern.warn kernel: Ack RSSI: 33
Fri Jan 8 12:36:31 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:36:31 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:36:31 2021 kern.warn kernel: [wifi2] FWLOG: [48190695] WAL channel change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:31 2021 kern.warn kernel: [wifi2] FWLOG: [48191008] WAL channel change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:31 2021 kern.warn kernel: [wifi2] FWLOG: [48191322] WAL channel change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:31 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:36:31 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:31 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41230 event 1 reason 1
Fri Jan 8 12:36:31 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:36:31 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state transition SCAN -> INIT
Fri Jan 8 12:36:31 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0 (c9e36000)
Fri Jan 8 12:36:31 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_END[3]
Fri Jan 8 12:36:31 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3 not handled in state INIT
Fri Jan 8 12:36:32 2021 kern.warn kernel: TX Rate Info:
Fri Jan 8 12:36:32 2021 kern.warn kernel: MCS counts (0..9): 0, 0, 0, 0, 0, 8324, 125481, 166019, 365434, 217694
Fri Jan 8 12:36:32 2021 kern.warn kernel: MCS counts SU (0..9): 0, 0, 0, 0, 0, 8324, 125481, 166019, 365434, 217694
Fri Jan 8 12:36:32 2021 kern.warn kernel: MCS counts MU (0..9): 0, 0, 0, 0, 0, 0, 0, 0, 0, 0
Fri Jan 8 12:36:32 2021 kern.warn kernel: SGI counts (0..9): 0, 0, 0, 0, 0, 8294, 124427, 149841, 319175, 185317
Fri Jan 8 12:36:32 2021 kern.warn kernel: NSS counts: 1x1 0, 2x2 332, 3x3 545719 4x4 336901
Fri Jan 8 12:36:32 2021 kern.warn kernel: BW counts: 20MHz 391, 40MHz 0, 80MHz 882561, 160MHz 0
Fri Jan 8 12:36:32 2021 kern.warn kernel: Preamble (O C H V) counts: 2, 0, 0, 882952
Fri Jan 8 12:36:32 2021 kern.warn kernel: STBC rate counts (0..9): 0, 0, 0, 0, 0, 0, 0, 0, 0, 0
Fri Jan 8 12:36:32 2021 kern.warn kernel: LDPC Counts: 882952

```
Fri Jan 8 12:36:32 2021 kern.warn kernel: RTS Counts: 814
Fri Jan 8 12:36:32 2021 kern.warn kernel: Ack RSSI: 36
Fri Jan 8 12:36:32 2021 kern.warn kernel: [wifi2] FWLOG: [48191662]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan 8 12:36:32 2021 kern.warn kernel: [wifi2] FWLOG: [48191662]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan 8 12:36:32 2021 user.notice led_function: RSSI24G -63
Fri Jan 8 12:36:32 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:36:33 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:36:33 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:36:33 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:36:33 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:33 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:36:33 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:33 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:33 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:36:33 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1522 duration:170
Fri Jan 8 12:36:33 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:36:33 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:36:33 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:33 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:36:33 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:36:33 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:33 2021 user.notice led_function: led check timeout
elapsed:46980 duration:180
Fri Jan 8 12:36:33 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:36:33 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:36:33 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:34 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:35 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:36:36 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:36 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:36 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:36 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:36:36 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:36:36 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41231 event 0 reason 0
```

Fri Jan 8 12:36:36 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:36:36 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:36:36 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:36:36 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan 8 12:36:37 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:36:37 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:36:37 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:36:37 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
key[wifi2] FWLOG: [48196788] WAL channel change freq=5580, mode=0 flags=0
rx_ok=1 tx_ok=1
Fri Jan 8 12:36:37 2021 kern.warn kernel: [wifi2] FWLOG: [48196926]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:36:37 2021 kern.warn kernel: [wifi2] FWLOG: [48197102] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:37 2021 kern.warn kernel: [wifi2] FWLOG: [48197239]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:36:37 2021 kern.warn kernel: [wifi2] FWLOG: [48197415] WAL channel
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:37 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:36:37 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:36:37 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:36:38 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:36:38 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:38 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:38 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:36:38 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
0, off 0, len 1
Fri Jan 8 12:36:38 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:38 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:36:38 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1526 duration:170
Fri Jan 8 12:36:38 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:38 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:36:38 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:36:38 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:38 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:38 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1

Fri Jan 8 12:36:38 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:38 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:36:38 2021 kern.warn kernel: [wifi2] FWLOG: [48197728] WAL channel change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:38 2021 kern.warn kernel: [wifi2] FWLOG: [48198042] WAL channel change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:38 2021 kern.warn kernel: [wifi2] FWLOG: [48198355] WAL channel change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:39 2021 kern.warn kernel: vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41231 event 1 reason 1
Fri Jan 8 12:36:39 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:36:39 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state transition SCAN -> INIT
Fri Jan 8 12:36:39 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0 (c9e36000)
Fri Jan 8 12:36:39 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_END[3]
Fri Jan 8 12:36:39 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3 not handled in state INIT
Fri Jan 8 12:36:39 2021 user.notice led_function: RSSI24G -64
Fri Jan 8 12:36:39 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:36:39 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:36:39 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:36:39 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:36:39 2021 kern.warn kernel: [wifi2] FWLOG: [48198668] WAL channel change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:39 2021 kern.warn kernel: [wifi2] FWLOG: [48198806] WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:36:39 2021 kern.warn kernel: [wifi2] FWLOG: [48199009] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:36:39 2021 kern.warn kernel: [wifi2] FWLOG: [48199009] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:36:39 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:36:40 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:36:40 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:36:40 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:36:40 2021 user.notice led_function: led check timeout elapsed:46986 duration:180
Fri Jan 8 12:36:40 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:36:40 2021 user.notice led_function: CUR_STATE: RE_LocationSuitable
Fri Jan 8 12:36:41 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key

Fri Jan 8 12:36:41 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:36:41 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:36:41 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:36:42 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:36:42 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:36:42 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:42 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:36:42 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:42 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:36:42 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:36:42 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:36:42 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:42 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:36:42 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:42 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
0, off 0, len 1
Fri Jan 8 12:36:42 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:42 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:36:42 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1531 duration:170
Fri Jan 8 12:36:42 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:36:42 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:36:42 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:36:42 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:42 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:36:42 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:42 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:36:42 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:36:42 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:43 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:43 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:36:43 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:36:44 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:36:44 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:36:44 2021 kern.warn kernel:

vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41232 event 0 reason 0
Fri Jan 8 12:36:44 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:36:44 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state transition INIT -> SCAN
Fri Jan 8 12:36:44 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_START[9]
Fri Jan 8 12:36:44 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9 not handled in state INIT
Fri Jan 8 12:36:44 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:44 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:36:44 2021 kern.warn kernel: [wifi2] FWLOG: [48204144] WAL channel change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:44 2021 kern.warn kernel: [wifi2] FWLOG: [48204282] WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:36:44 2021 kern.warn kernel: [wifi2] FWLOG: [48204458] WAL channel change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:44 2021 kern.warn kernel: [wifi2] FWLOG: [48204595] WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:36:44 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:36:45 2021 user.notice led_function: RSSI24G -63
Fri Jan 8 12:36:45 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:36:45 2021 kern.warn kernel: [wifi2] FWLOG: [48204771] WAL channel change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:45 2021 kern.warn kernel: [wifi2] FWLOG: [48205084] WAL channel change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:45 2021 kern.warn kernel: [wifi2] FWLOG: [48205222] WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:36:45 2021 kern.warn kernel: [wifi2] FWLOG: [48205398] WAL channel change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:45 2021 kern.warn kernel: [wifi2] FWLOG: [48205711] WAL channel change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:45 2021 kern.warn kernel: [wifi2] FWLOG: [48205849] WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:36:46 2021 kern.warn kernel: vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41232 event 1 reason 1
Fri Jan 8 12:36:46 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:36:46 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state transition SCAN -> INIT
Fri Jan 8 12:36:46 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0 (c9e36000)
Fri Jan 8 12:36:46 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_END[3]
Fri Jan 8 12:36:46 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3 not handled in state INIT
Fri Jan 8 12:36:46 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:36:46 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0

Fri Jan 8 12:36:46 2021 user.notice led_function: led check timeout elapsed:46992 duration:180
Fri Jan 8 12:36:46 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:36:46 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:36:46 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:36:46 2021 kern.warn kernel: [wifi2] FWLOG: [48206025] WAL channel change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:46 2021 kern.warn kernel: [wifi2] FWLOG: [48206365] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:36:46 2021 kern.warn kernel: [wifi2] FWLOG: [48206365] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:36:46 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:36:46 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:46 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:46 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:36:47 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:47 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:47 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 ::: force_down_5g:0
Fri Jan 8 12:36:47 2021 user.debug repacd.wifimon: repacd check timeout elapsed:1535 duration:170
Fri Jan 8 12:36:47 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:36:47 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:36:47 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:47 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:47 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:47 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:36:47 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:36:47 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:48 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:36:48 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:48 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:49 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:49 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-2(ath01):[a6:c9:eb:1a:a6:a1] send null data frame on channel 13, pwr mgt dis
Fri Jan 8 12:36:51 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:36:51 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid

key
Fri Jan 8 12:36:51 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:36:51 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41233 event 0 reason 0
Fri Jan 8 12:36:51 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:36:51 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:36:51 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:36:51 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan 8 12:36:51 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:36:51 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:36:51 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:51 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:36:51 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:51 2021 user.notice led_function: RSSI24G -63
Fri Jan 8 12:36:51 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:51 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:36:51 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:36:51 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1540 duration:170
Fri Jan 8 12:36:51 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:36:51 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:36:51 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:51 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:51 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:51 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
key[wifi2] FWLOG: [48211489] WAL channel change freq=5580, mode=0 flags=0
rx_ok=1 tx_ok=1
Fri Jan 8 12:36:51 2021 kern.warn kernel: [wifi2] FWLOG: [48211627]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:36:51 2021 kern.warn kernel: [wifi2] FWLOG: [48211803] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:51 2021 kern.warn kernel: [wifi2] FWLOG: [48211940]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:36:52 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:36:52 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:36:52 2021 user.notice led_function: led check timeout
elapsed:46999 duration:180
Fri Jan 8 12:36:52 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:36:52 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable

Fri Jan 8 12:36:52 2021 kern.warn kernel: [wifi2] FWLOG: [48212116] WAL channel change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:52 2021 kern.warn kernel: [wifi2] FWLOG: [48212430] WAL channel change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:52 2021 kern.warn kernel: [wifi2] FWLOG: [48212743] WAL channel change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:53 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41233 event 1 reason 1
Fri Jan 8 12:36:53 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:36:53 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state transition SCAN -> INIT
Fri Jan 8 12:36:53 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0 (c9e36000)
Fri Jan 8 12:36:53 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_END[3]
Fri Jan 8 12:36:53 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3 not handled in state INIT
Fri Jan 8 12:36:53 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:53 2021 kern.warn kernel: [wifi2] FWLOG: [48213056] WAL channel change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:53 2021 kern.warn kernel: [wifi2] FWLOG: [48213370] WAL channel change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:53 2021 kern.warn kernel: [wifi2] FWLOG: [48213710] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:36:53 2021 kern.warn kernel: [wifi2] FWLOG: [48213710] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:36:54 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:36:54 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:55 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:36:55 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:55 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:36:55 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:55 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:55 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:36:55 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:55 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:55 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 ::: force_down_5g:0
Fri Jan 8 12:36:56 2021 user.debug repacd.wifimon: repacd check timeout elapsed:1544 duration:170
Fri Jan 8 12:36:56 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:36:56 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:36:56 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:36:56 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-0(ath2):wlan_get_key: invalid key

Fri Jan 8 12:36:56 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:56 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:36:56 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:36:56 2021 kern.warn kernel: Inst RSSI value of
node-08:c5:e1:c2:a4:0c: 34
Fri Jan 8 12:36:56 2021 kern.warn kernel: Inst RSSI value of
node-08:c5:e1:c2:a4:0c: 33
Fri Jan 8 12:36:57 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:36:57 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:36:57 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:36:57 2021 user.notice led_function: RSSI24G -63
Fri Jan 8 12:36:57 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:36:57 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:36:58 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:36:58 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
key
Fri Jan 8 12:36:58 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
keySending SCAN START cmd
Fri Jan 8 12:36:58 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41234 event 0 reason 0
Fri Jan 8 12:36:58 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:36:58 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:36:58 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:36:58 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan 8 12:36:58 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:36:58 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:36:58 2021 user.notice led_function: led check timeout
elapsed:47005 duration:180
Fri Jan 8 12:36:58 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:36:58 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:36:58 2021 kern.warn kernel: [wifi2] FWLOG: [48218834] WAL channel
change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:58 2021 kern.warn kernel: [wifi2] FWLOG: [48218971]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:36:58 2021 kern.warn kernel: [wifi2] FWLOG: [48219147] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:58 2021 kern.warn kernel: [wifi2] FWLOG: [48219285]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:36:59 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid

key

```
Fri Jan 8 12:36:59 2021 kern.warn kernel: [wifi2] FWLOG: [48219461] WAL channel
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:59 2021 kern.warn kernel: [wifi2] FWLOG: [48219774] WAL channel
change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:36:59 2021 kern.warn kernel: [wifi2] FWLOG: [48220088] WAL channel
change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:00 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:37:00 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:37:00 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:37:00 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:37:00 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:37:00 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:00 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:00 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:37:00 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:00 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:37:00 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1549 duration:170
Fri Jan 8 12:37:00 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:00 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:37:00 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:37:00 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:37:00 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:00 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:00 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:00 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000
scan_id 41234 event 1 reason 1
Fri Jan 8 12:37:00 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:37:00 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition SCAN -> INIT
Fri Jan 8 12:37:00 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:37:00 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0
(c9e36000)
Fri Jan 8 12:37:00 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_END[3]
Fri Jan 8 12:37:00 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3
not handled in state INIT
Fri Jan 8 12:37:00 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:37:00 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:00 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
```

```
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:00 2021 kern.warn kernel: [wifi2] FWLOG: [48220401] WAL channel
change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:00 2021 kern.warn kernel: [wifi2] FWLOG: [48220714] WAL channel
change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:00 2021 kern.warn kernel: [wifi2] FWLOG: [48220851]
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan 8 12:37:00 2021 kern.warn kernel: [wifi2] FWLOG: [48221063]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan 8 12:37:00 2021 kern.warn kernel: [wifi2] FWLOG: [48221063]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan 8 12:37:02 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:37:02 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:37:02 2021 kern.warn kernel: Inst RSSI value of
node-08:c5:e1:c2:a4:0c: 37
Fri Jan 8 12:37:02 2021 kern.warn kernel: Inst RSSI value of
node-08:c5:e1:c2:a4:0c: 37
Fri Jan 8 12:37:03 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:37:03 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:37:03 2021 user.notice led_function: RSSI24G -64
Fri Jan 8 12:37:03 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:37:04 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:37:04 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:37:04 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:04 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:04 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:04 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:37:04 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:04 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:37:04 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1553 duration:170
Fri Jan 8 12:37:04 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:04 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:37:04 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:37:04 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:04 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:04 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:37:04 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:37:05 2021 user.notice led_function: led check timeout
elapsed:47011 duration:180
Fri Jan 8 12:37:05 2021 user.notice led_function: SELECTION LOOP CONTINUE
```

Fri Jan 8 12:37:05 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:37:05 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:05 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:37:05 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41235 event 0 reason 0
Fri Jan 8 12:37:05 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:37:05 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:37:05 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:37:05 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan 8 12:37:05 2021 kern.warn kernel: [wifi2] FWLOG: [48226199] WAL channel
change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:05 2021 kern.warn kernel: [wifi2] FWLOG: [48226337]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:37:06 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:37:06 2021 kern.warn kernel: [wifi2] FWLOG: [48226513] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:06 2021 kern.warn kernel: [wifi2] FWLOG: [48226650]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:37:06 2021 kern.warn kernel: [wifi2] FWLOG: [48226826] WAL channel
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:06 2021 kern.warn kernel: [wifi2] FWLOG: [48227139] WAL channel
change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:06 2021 kern.warn kernel: [wifi2] FWLOG: [48227453] WAL channel
change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:07 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:37:07 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:07 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:07 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:37:07 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:37:07 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41235 event 1 reason 1
Fri Jan 8 12:37:07 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:37:07 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition SCAN -> INIT
Fri Jan 8 12:37:07 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0
(c9e36000)
Fri Jan 8 12:37:07 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_END[3]
Fri Jan 8 12:37:07 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3
not handled in state INIT
Fri Jan 8 12:37:07 2021 kern.warn kernel: [wifi2] FWLOG: [48227766] WAL channel

change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:07 2021 kern.warn kernel: [wifi2] FWLOG: [48227904]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:37:07 2021 kern.warn kernel: [wifi2] FWLOG: [48228079] WAL channel
change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:07 2021 kern.warn kernel: [wifi2] FWLOG: [48228420]
RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:37:07 2021 kern.warn kernel: [wifi2] FWLOG: [48228420]
RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:37:08 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:37:08 2021 kern.warn kernel: Printing wds entries [No. of
entries:0]
Fri Jan 8 12:37:08 2021 kern.warn kernel: DA Next Hop
flags
Fri Jan 8 12:37:08 2021 kern.warn kernel:
Fri Jan 8 12:37:08 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:37:09 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:37:09 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:09 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:09 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:09 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:37:09 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:09 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:09 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:37:09 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1557 duration:170
Fri Jan 8 12:37:09 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:37:09 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:37:09 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:09 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:09 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:10 2021 user.notice led_function: RSSI24G -64
Fri Jan 8 12:37:10 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:37:10 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyPrinting wds entries [No. of entries:0]
Fri Jan 8 12:37:11 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:37:11 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:37:11 2021 user.notice led_function: led check timeout
elapsed:47017 duration:180
Fri Jan 8 12:37:11 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:37:11 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:37:12 2021 kern.warn kernel: DA Next Hop

flags

```
Fri Jan 8 12:37:12 2021 kern.warn kernel:
Fri Jan 8 12:37:12 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keySending SCAN START cmd
Fri Jan 8 12:37:12 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41236 event 0 reason 0
Fri Jan 8 12:37:12 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:37:12 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:37:12 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:37:12 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan 8 12:37:12 2021 kern.warn kernel: [wifi2] FWLOG: [48233543] WAL channel
change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:12 2021 kern.warn kernel: [wifi2] FWLOG: [48233681]
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan 8 12:37:13 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:37:13 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:37:13 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:13 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:37:13 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:13 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:13 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:13 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:37:13 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:13 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
2, off 0, len 1
Fri Jan 8 12:37:13 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:37:13 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1562 duration:170
Fri Jan 8 12:37:13 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:37:13 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:37:13 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:37:13 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:13 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:13 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:13 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:37:13 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:37:13 2021 kern.warn kernel: Inst RSSI value of
```

node-08:c5:e1:c2:a4:0c: 38
Fri Jan 8 12:37:13 2021 kern.warn kernel: Inst RSSI value of
node-08:c5:e1:c2:a4:0c: 38
Fri Jan 8 12:37:13 2021 kern.warn kernel: [wifi2] FWLOG: [48233857] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:13 2021 kern.warn kernel: [wifi2] FWLOG: [48233994]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:37:13 2021 kern.warn kernel: [wifi2] FWLOG: [48234170] WAL channel
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:14 2021 kern.warn kernel: [wifi2] FWLOG: [48234483] WAL channel
change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:14 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:37:14 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:37:14 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:37:14 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:37:14 2021 kern.warn kernel: [wifi2] FWLOG: [48234797] WAL channel
change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:14 2021 kern.warn kernel: [wifi2]
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41236 event 1 reason 1
Fri Jan 8 12:37:14 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:37:15 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition SCAN -> INIT
Fri Jan 8 12:37:15 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0
(c9e36000)
Fri Jan 8 12:37:15 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_END[3]
Fri Jan 8 12:37:15 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3
not handled in state INIT
Fri Jan 8 12:37:15 2021 kern.warn kernel: FWLOG: [48235110] WAL channel change
freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:15 2021 kern.warn kernel: [wifi2] FWLOG: [48235248]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:37:15 2021 kern.warn kernel: [wifi2] FWLOG: [48235423] WAL channel
change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:15 2021 kern.warn kernel: [wifi2] FWLOG: [48235561]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:37:15 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:37:15 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:37:15 2021 kern.warn kernel: [wifi2] FWLOG: [48235765]
RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:37:16 2021 kern.warn kernel: [wifi2] FWLOG: [48235765]
RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:37:16 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:37:16 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1


```
Fri Jan 8 12:37:16 2021 user.notice led_function: RSSI24G -64
Fri Jan 8 12:37:16 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:37:16 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:37:16 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:37:17 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:37:17 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:37:17 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:37:17 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:37:17 2021 user.notice led_function: led check timeout
elapsed:47024 duration:180
Fri Jan 8 12:37:17 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:37:17 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:37:17 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:37:17 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:37:17 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:37:17 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:37:17 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
1, off 0, len 1
Fri Jan 8 12:37:17 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:37:17 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:37:17 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:18 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:18 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:37:18 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1566 duration:170
Fri Jan 8 12:37:18 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:18 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:37:18 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:37:18 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:37:18 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:37:18 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:18 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:19 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:19 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
```

1, off 0, len 1
Fri Jan 8 12:37:19 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:37:19 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:37:19 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:20 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:20 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:37:20 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41237 event 0 reason 0
Fri Jan 8 12:37:20 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:37:20 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:37:20 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:37:20 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan 8 12:37:20 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:37:20 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:37:20 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:37:20 2021 kern.warn kernel: [wifi2] FWLOG: [48240926] WAL channel
change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:21 2021 kern.warn kernel: [wifi2] FWLOG: [48241063]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:37:21 2021 kern.warn kernel: [wifi2] FWLOG: [48241239] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:21 2021 kern.warn kernel: [wifi2] FWLOG: [48241376]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:37:21 2021 kern.warn kernel: [wifi2] FWLOG: [48241552] WAL channel
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:21 2021 kern.warn kernel: [wifi2] FWLOG: [48241866] WAL channel
change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:21 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:37:21 2021 kern.warn kernel: [wifi2] FWLOG: [48242179] WAL channel
change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:22 2021 kern.warn kernel: [wifi2] FWLOG: [48242317]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:37:22 2021 kern.warn kernel: [wifi2] FWLOG: [48242492] WAL channel
change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:22 2021 kern.warn kernel: [wifi2] FWLOG: [48242631]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:37:22 2021 kern.warn kernel: [wifi2] FWLOG: [48242806] WAL channel
change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:22 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:37:22 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:37:22 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:37:22 2021 kern.warn kernel:

vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41237 event 1 reason 1
Fri Jan 8 12:37:22 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:37:22 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state transition SCAN -> INIT
Fri Jan 8 12:37:22 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0 (c9e36000)
Fri Jan 8 12:37:22 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_END[3]
Fri Jan 8 12:37:22 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3 not handled in state INIT
Fri Jan 8 12:37:22 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:22 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:22 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:37:22 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:22 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 ::: force_down_5g:0
Fri Jan 8 12:37:22 2021 user.debug repacd.wifimon: repacd check timeout elapsed:1571 duration:170
Fri Jan 8 12:37:22 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:22 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:37:22 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:37:22 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:22 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:22 2021 user.notice led_function: RSSI24G -64
Fri Jan 8 12:37:22 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:37:22 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:22 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:37:22 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:37:22 2021 kern.warn kernel: [wifi2] FWLOG: [48243119]
RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:37:23 2021 kern.warn kernel: [wifi2] FWLOG: [48243119]
RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:37:23 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:37:23 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:37:23 2021 user.notice led_function: led check timeout
elapsed:47030 duration:180
Fri Jan 8 12:37:23 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:37:23 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:37:23 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:37:23 2021 kern.warn kernel: Inst RSSI value of
node-08:c5:e1:c2:a4:0c: 35

Fri Jan 8 12:37:23 2021 kern.warn kernel: Inst RSSI value of node-08:c5:e1:c2:a4:0c: 35
Fri Jan 8 12:37:23 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:37:24 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:37:24 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:24 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:37:25 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:37:25 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:26 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:37:26 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:37:26 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:26 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:26 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:26 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:37:26 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:26 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:26 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 ::: force_down_5g:0
Fri Jan 8 12:37:26 2021 user.debug repacd.wifimon: repacd check timeout elapsed:1575 duration:170
Fri Jan 8 12:37:27 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:37:27 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:37:27 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:27 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:27 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:27 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
keySending SCAN START cmd
Fri Jan 8 12:37:27 2021 kern.warn kernel: vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41238 event 0 reason 0
Fri Jan 8 12:37:27 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:37:27 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state transition INIT -> SCAN
Fri Jan 8 12:37:27 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:37:27 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_START[9]
Fri Jan 8 12:37:27 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9 not handled in state INIT
Fri Jan 8 12:37:27 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

Fri Jan 8 12:37:27 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:27 2021 kern.warn kernel: [wifi2] FWLOG: [48248285] WAL channel change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:28 2021 kern.warn kernel: [wifi2] FWLOG: [48248423] WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:37:28 2021 kern.warn kernel: [wifi2] FWLOG: [48248599] WAL channel change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:28 2021 kern.warn kernel: [wifi2] FWLOG: [48248736] WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:37:28 2021 kern.warn kernel: [wifi2] FWLOG: [48248912] WAL channel change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:28 2021 user.notice led_function: RSSI24G -63
Fri Jan 8 12:37:28 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:37:28 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:37:28 2021 kern.warn kernel: [wifi2] FWLOG: [48249225] WAL channel change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:29 2021 kern.warn kernel: [wifi2] FWLOG: [48249539] WAL channel change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:29 2021 kern.warn kernel: [wifi2] FWLOG: [48249852] WAL channel change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:29 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:37:29 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:29 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41238 event 1 reason 1
Fri Jan 8 12:37:29 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:37:29 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state transition SCAN -> INIT
Fri Jan 8 12:37:29 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0 (c9e36000)
Fri Jan 8 12:37:29 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_END[3]
Fri Jan 8 12:37:29 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3 not handled in state INIT
Fri Jan 8 12:37:29 2021 kern.warn kernel: RX Rate Info:
Fri Jan 8 12:37:29 2021 kern.warn kernel: MCS counts (0..9): 665, 1511, 4028, 15571, 39685, 44089, 54746, 35236, 3682, 887
Fri Jan 8 12:37:29 2021 kern.warn kernel: SGI counts (0..9): 240, 697, 1691, 7819, 13720, 17197, 28213, 17449, 1720, 483
Fri Jan 8 12:37:29 2021 kern.warn kernel: NSS counts: 1x1 127436, 2x2 72664, 3x3 0, 4x4 0
Fri Jan 8 12:37:29 2021 kern.warn kernel: NSTS count: 577
Fri Jan 8 12:37:29 2021 kern.warn kernel: BW counts: 20MHz 201066, 40MHz 0, 80MHz 0, 160MHz 0
Fri Jan 8 12:37:29 2021 kern.warn kernel: Preamble counts: 114704, 89173, 0, 111893, 0, 0
Fri Jan 8 12:37:29 2021 kern.warn kernel: STBC rate counts (0..9): 238, 187, 51, 52, 23, 3, 1, 22, 0, 0
Fri Jan 8 12:37:29 2021 kern.warn kernel: LDPC Counts: 199997
Fri Jan 8 12:37:29 2021 kern.warn kernel: RSSI (data, mgmt): 33, 35

```
Fri Jan 8 12:37:29 2021 kern.warn kernel: RSSI Chain 0 (0x80 0x80 0x80 0x1f)
Fri Jan 8 12:37:29 2021 kern.warn kernel: RSSI Chain 1 (0x80 0x80 0x80 0x1c)
Fri Jan 8 12:37:29 2021 kern.warn kernel: RSSI Chain 2 (0x00 0x00 0x00 0x00)
Fri Jan 8 12:37:29 2021 kern.warn kernel: RSSI Chain 3 (0x00 0x00 0x00 0x00)
Fri Jan 8 12:37:29 2021 kern.warn kernel: RSSI (comb_ht): 33
Fri Jan 8 12:37:29 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:37:29 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:37:29 2021 user.notice led_function: led check timeout
elapsed:47036 duration:180
Fri Jan 8 12:37:29 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:37:29 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:37:30 2021 kern.warn kernel: [wifi2] FWLOG: [48250165] WAL channel
change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:30 2021 kern.warn kernel: [wifi2] FWLOG: [48250509]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan 8 12:37:30 2021 kern.warn kernel: [wifi2] FWLOG: [48250509]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan 8 12:37:30 2021 kern.warn kernel: RX Rate Info:
Fri Jan 8 12:37:30 2021 kern.warn kernel: MCS counts (0..9): 4586, 0, 0, 0, 77,
20188, 68397, 129938, 501811, 27607
Fri Jan 8 12:37:30 2021 kern.warn kernel: SGI counts (0..9): 0, 0, 0, 0, 76,
20070, 66924, 126215, 498615, 15530
Fri Jan 8 12:37:30 2021 kern.warn kernel: NSS counts: 1x1 4580, 2x2 1557, 3x3
552329, 4x4 194138
Fri Jan 8 12:37:30 2021 kern.warn kernel: NSTS count: 0
Fri Jan 8 12:37:30 2021 kern.warn kernel: BW counts: 20MHz 29, 40MHz 56, 80MHz
757477, 160MHz 0
Fri Jan 8 12:37:30 2021 kern.warn kernel: Preamble counts: 135383, 56, 0,
757506, 0, 5271
Fri Jan 8 12:37:30 2021 kern.warn kernel: STBC rate counts (0..9): 0, 0, 0, 0,
0, 0, 0, 0, 0, 0
Fri Jan 8 12:37:30 2021 kern.warn kernel: LDPC Counts: 748012
Fri Jan 8 12:37:30 2021 kern.warn kernel: RSSI (data, mgmt): 40, 18
Fri Jan 8 12:37:30 2021 kern.warn kernel: RSSI Chain 0 (0x80 0x25 0x21 0x24)
Fri Jan 8 12:37:30 2021 kern.warn kernel: RSSI Chain 1 (0x80 0x21 0x1e 0x22)
Fri Jan 8 12:37:30 2021 kern.warn kernel: RSSI Chain 2 (0x80 0x24 0x21 0x20)
Fri Jan 8 12:37:30 2021 kern.warn kernel: RSSI Chain 3 (0x80 0x1f 0x22 0x24)
Fri Jan 8 12:37:30 2021 kern.warn kernel: RSSI (comb_ht): 41
Fri Jan 8 12:37:30 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
2, off 0, len 1
Fri Jan 8 12:37:31 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:37:31 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:37:31 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:37:31 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:37:31 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:31 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:37:31 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
```

Fri Jan 8 12:37:31 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:31 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 ::: force_down_5g:0
Fri Jan 8 12:37:31 2021 user.debug repacd.wifimon: repacd check timeout elapsed:1580 duration:170
Fri Jan 8 12:37:31 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:37:31 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:37:31 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:31 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:37:31 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:31 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:31 2021 kern.warn kernel: TX Rate Info:
Fri Jan 8 12:37:31 2021 kern.warn kernel: MCS counts (0..9): 562, 704, 1316, 1625, 8673, 51051, 89696, 127828, 48662, 23364
Fri Jan 8 12:37:31 2021 kern.warn kernel: MCS counts SU (0..9): 562, 704, 1316, 1625, 8673, 51051, 89696, 127828, 48662, 23364
Fri Jan 8 12:37:31 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:31 2021 kern.warn kernel: MCS counts MU (0..9): 0, 0, 0, 0, 0, 0, 0, 0, 0
Fri Jan 8 12:37:31 2021 kern.warn kernel: SGI counts (0..9): 0, 0, 0, 0, 5075, 22479, 33847, 102247, 38766, 17640
Fri Jan 8 12:37:31 2021 kern.warn kernel: NSS counts: 1x1 153631, 2x2 199850, 3x3 0 4x4 0
Fri Jan 8 12:37:31 2021 kern.warn kernel: BW counts: 20MHz 353481, 40MHz 0, 80MHz 0, 160MHz 0
Fri Jan 8 12:37:31 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:31 2021 kern.warn kernel: Preamble (O C H V) counts: 0, 13120, 143104, 211347
Fri Jan 8 12:37:31 2021 kern.warn kernel: STBC rate counts (0..9): 562, 672, 1181, 1496, 1737, 10581, 33052, 50289, 0, 0
Fri Jan 8 12:37:31 2021 kern.warn kernel: LDPC Counts: 210377
Fri Jan 8 12:37:31 2021 kern.warn kernel: RTS Counts: 27704
Fri Jan 8 12:37:31 2021 kern.warn kernel: Ack RSSI: 33
Fri Jan 8 12:37:31 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:37:31 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:32 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:32 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:37:32 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:37:32 2021 kern.warn kernel: TX Rate Info:
Fri Jan 8 12:37:32 2021 kern.warn kernel: MCS counts (0..9): 0, 0, 0, 0, 0, 8324, 125481, 166019, 365434, 217694
Fri Jan 8 12:37:32 2021 kern.warn kernel: MCS counts SU (0..9): 0, 0, 0, 0, 0, 8324, 125481, 166019, 365434, 217694
Fri Jan 8 12:37:32 2021 kern.warn kernel: MCS counts MU (0..9): 0, 0, 0, 0, 0, 0, 0, 0, 0

Fri Jan 8 12:37:32 2021 kern.warn kernel: SGI counts (0..9): 0, 0, 0, 0, 0, 8294, 124427, 149841, 319175, 185317
Fri Jan 8 12:37:32 2021 kern.warn kernel: NSS counts: 1x1 0, 2x2 332, 3x3 545719 4x4 336901
Fri Jan 8 12:37:32 2021 kern.warn kernel: BW counts: 20MHz 391, 40MHz 0, 80MHz 882561, 160MHz 0
Fri Jan 8 12:37:32 2021 kern.warn kernel: Preamble (O C H V) counts: 2, 0, 0, 882952
Fri Jan 8 12:37:32 2021 kern.warn kernel: STBC rate counts (0..9): 0, 0, 0, 0, 0, 0, 0, 0, 0, 0
Fri Jan 8 12:37:32 2021 kern.warn kernel: LDPC Counts: 882952
Fri Jan 8 12:37:32 2021 kern.warn kernel: RTS Counts: 814
Fri Jan 8 12:37:32 2021 kern.warn kernel: Ack RSSI: 36
Fri Jan 8 12:37:33 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:33 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:37:33 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:37:33 2021 kern.warn kernel: Inst RSSI value of node-08:c5:e1:c2:a4:0c: 37
Fri Jan 8 12:37:33 2021 kern.warn kernel: Inst RSSI value of node-08:c5:e1:c2:a4:0c: 37
Fri Jan 8 12:37:34 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:37:34 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:34 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:37:34 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41239 event 0 reason 0
Fri Jan 8 12:37:34 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:37:34 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state transition INIT -> SCAN
Fri Jan 8 12:37:34 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_START[9]
Fri Jan 8 12:37:34 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9 not handled in state INIT
Fri Jan 8 12:37:34 2021 kern.warn kernel: [wifi2] FWLOG: [48255645] WAL channel change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:35 2021 kern.warn kernel: [wifi2] FWLOG: [48255783] WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:37:35 2021 kern.warn kernel: [wifi2] FWLOG: [48255959] WAL channel change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:35 2021 kern.warn kernel: [wifi2] FWLOG: [48256096] WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:37:35 2021 user.notice led_function: RSSI24G -63
Fri Jan 8 12:37:35 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:37:35 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:37:35 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:37:35 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

Fri Jan 8 12:37:35 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:37:35 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:35 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:35 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:37:35 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:35 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:35 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 ::: force_down_5g:0
Fri Jan 8 12:37:35 2021 user.debug repacd.wifimon: repacd check timeout elapsed:1584 duration:170
Fri Jan 8 12:37:35 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:37:35 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:37:35 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:35 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:35 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
[wifi2] FWLOG: [48256272] WAL channel change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:36 2021 kern.warn kernel: [wifi2] FWLOG: [48256585] WAL channel change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:36 2021 kern.warn kernel: [wifi2] FWLOG: [48256899] WAL channel change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:36 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:36 2021 kern.warn kernel: [wifi2] FWLOG: [48257212] WAL channel change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:36 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:37:36 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:37:36 2021 user.notice led_function: led check timeout elapsed:47042 duration:180
Fri Jan 8 12:37:36 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:37:36 2021 user.notice led_function: CUR_STATE: RE_LocationSuitable
Fri Jan 8 12:37:36 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:36 2021 kern.warn kernel: vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41239 event 1 reason 1
Fri Jan 8 12:37:36 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:37:36 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state transition SCAN -> INIT
Fri Jan 8 12:37:36 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0 (c9e36000)
Fri Jan 8 12:37:36 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_END[3]
Fri Jan 8 12:37:36 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3 not handled in state INIT
Fri Jan 8 12:37:36 2021 kern.warn kernel: [wifi2] FWLOG: [48257525] WAL channel

```
change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan  8 12:37:37 2021 kern.warn kernel: [wifi2] FWLOG: [48257866]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan  8 12:37:37 2021 kern.warn kernel: [wifi2] FWLOG: [48257866]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan  8 12:37:37 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan  8 12:37:37 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan  8 12:37:37 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan  8 12:37:38 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan  8 12:37:38 2021 user.notice led_function: =====LOOP END=====
Fri Jan  8 12:37:38 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:37:39 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan  8 12:37:39 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan  8 12:37:39 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan  8 12:37:39 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
2, off 0, len 1
Fri Jan  8 12:37:40 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan  8 12:37:40 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan  8 12:37:40 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan  8 12:37:40 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:37:40 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan  8 12:37:40 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan  8 12:37:40 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan  8 12:37:40 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:37:40 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan  8 12:37:40 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1588 duration:170
Fri Jan  8 12:37:40 2021 user.info repacd: AssocTimeout
Fri Jan  8 12:37:40 2021 user.info repacd: Boot time count=-1
Fri Jan  8 12:37:40 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:37:40 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:37:40 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan  8 12:37:40 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
1, off 0, len 1
Fri Jan  8 12:37:40 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan  8 12:37:41 2021 user.notice led_function: RSSI24G -63
```

```
Fri Jan  8 12:37:41 2021 user.notice led_function: PING IS WELL
Fri Jan  8 12:37:41 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan  8 12:37:41 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan  8 12:37:41 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41240 event 0 reason 0
Fri Jan  8 12:37:41 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan  8 12:37:41 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan  8 12:37:41 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan  8 12:37:41 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan  8 12:37:42 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan  8 12:37:42 2021 kern.warn kernel: [wifi2] FWLOG: [48262989] WAL channel
change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan  8 12:37:42 2021 kern.warn kernel: [wifi2] FWLOG: [48263126]
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan  8 12:37:42 2021 kern.warn kernel: [wifi2] FWLOG: [48263302] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan  8 12:37:42 2021 kern.warn kernel: [wifi2] FWLOG: [48263439]
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan  8 12:37:42 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan  8 12:37:42 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan  8 12:37:42 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan  8 12:37:42 2021 user.notice led_function: led check timeout
elapsed:47048 duration:180
Fri Jan  8 12:37:42 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan  8 12:37:42 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan  8 12:37:42 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan  8 12:37:42 2021 kern.warn kernel: vap-2(ath01):[a6:c9:eb:1a:a6:a1] send
null data frame on channel 13, pwr mgt dis
Fri Jan  8 12:37:42 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan  8 12:37:43 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan  8 12:37:43 2021 kern.warn kernel: [wifi2] FWLOG: [48263616] WAL channel
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan  8 12:37:43 2021 kern.warn kernel: [wifi2] FWLOG: [48263929] WAL channel
change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan  8 12:37:43 2021 kern.warn kernel: [wifi2] FWLOG: [48264242] WAL channel
change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan  8 12:37:43 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan  8 12:37:43 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan  8 12:37:43 2021 kern.warn kernel: vap-0(ath1):
```

[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:37:43 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41240 event 1 reason 1
Fri Jan 8 12:37:43 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:37:43 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition SCAN -> INIT
Fri Jan 8 12:37:43 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0
(c9e36000)
Fri Jan 8 12:37:43 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_END[3]
Fri Jan 8 12:37:43 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3
not handled in state INIT
Fri Jan 8 12:37:43 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:37:44 2021 kern.warn kernel: [wifi2] FWLOG: [48264556] WAL channel
change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:44 2021 kern.warn kernel: [wifi2] FWLOG: [48264693]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:37:44 2021 kern.warn kernel: [wifi2] FWLOG: [48264869] WAL channel
change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:44 2021 kern.warn kernel: [wifi2] FWLOG: [48265006]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:37:44 2021 kern.warn kernel: [wifi2] FWLOG: [48265210]
RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:37:44 2021 kern.warn kernel: [wifi2] FWLOG: [48265210]
RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:37:44 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:37:44 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:37:44 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:44 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:37:44 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:44 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:37:44 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:37:44 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:37:44 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:44 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:37:44 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:44 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:37:44 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:44 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:37:44 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1593 duration:170
Fri Jan 8 12:37:44 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key

```
Fri Jan 8 12:37:44 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:37:44 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:37:44 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:44 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:45 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:46 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:46 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:37:47 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:37:47 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:37:47 2021 user.notice led_function: RSSI24G -63
Fri Jan 8 12:37:47 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:37:47 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:37:47 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:37:48 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:37:48 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:37:48 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:37:48 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:37:48 2021 user.notice led_function: led check timeout
elapsed:47055 duration:180
Fri Jan 8 12:37:48 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:37:48 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:37:48 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:37:48 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:37:48 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:37:48 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41241 event 0 reason 0
Fri Jan 8 12:37:48 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:37:48 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:37:48 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:37:48 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan 8 12:37:48 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:37:48 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:37:49 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
```

```
Fri Jan 8 12:37:49 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:49 2021 kern.warn kernel: [wifi2] FWLOG: [48270346] WAL channel
change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:49 2021 kern.warn kernel: [wifi2] FWLOG: [48270483]
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan 8 12:37:49 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:37:49 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:37:49 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:49 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:49 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:37:49 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1597 duration:170
Fri Jan 8 12:37:49 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:37:49 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:37:49 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:49 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:49 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:50 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:50 2021 kern.warn kernel: [wifi2] FWLOG: [48270659] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:50 2021 kern.warn kernel: [wifi2] FWLOG: [48270796]
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan 8 12:37:50 2021 kern.warn kernel: [wifi2] FWLOG: [48270973] WAL channel
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:50 2021 kern.warn kernel: [wifi2] FWLOG: [48271286] WAL channel
change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:50 2021 kern.warn kernel: [wifi2] FWLOG: [48271599] WAL channel
change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:50 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:50 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
2, off 0, len 1
Fri Jan 8 12:37:50 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:37:50 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:50 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:50 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:37:50 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:37:50 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41241 event 1 reason 1
Fri Jan 8 12:37:50 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 3, cur_state=1, vap_deleted_is_set=0
```

Fri Jan 8 12:37:50 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition SCAN -> INIT
Fri Jan 8 12:37:50 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0
(c9e36000)
Fri Jan 8 12:37:50 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_END[3]
Fri Jan 8 12:37:50 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3
not handled in state INIT
Fri Jan 8 12:37:51 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:37:51 2021 kern.warn kernel: [wifi2] FWLOG: [48271913] WAL channel
change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:51 2021 kern.warn kernel: [wifi2] FWLOG: [48272226] WAL channel
change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:51 2021 kern.warn kernel: [wifi2] FWLOG: [48272566]
RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:37:51 2021 kern.warn kernel: [wifi2] FWLOG: [48272566]
RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:37:51 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:37:51 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:37:51 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:37:51 2021 kern.warn kernel: Inst RSSI value of
node-08:c5:e1:c2:a4:0c: 42
Fri Jan 8 12:37:51 2021 kern.warn kernel: Inst RSSI value of
node-08:c5:e1:c2:a4:0c: 42
Fri Jan 8 12:37:52 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:37:52 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:37:52 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:37:52 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:37:52 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:37:53 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:37:53 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:37:53 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:37:53 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:53 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:37:53 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:53 2021 user.notice led_function: RSSI24G -64
Fri Jan 8 12:37:53 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:37:53 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:53 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:37:53 2021 user.debug repacd.wifimon: repacd check timeout

elapsed:1602 duration:170
Fri Jan 8 12:37:53 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:37:53 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:37:53 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:53 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:53 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:54 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:37:54 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:37:54 2021 user.notice led_function: led check timeout
elapsed:47061 duration:180
Fri Jan 8 12:37:54 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:37:54 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:37:55 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:55 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keySending SCAN START cmd
Fri Jan 8 12:37:55 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41242 event 0 reason 0
Fri Jan 8 12:37:55 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:37:55 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:37:55 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:37:55 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan 8 12:37:56 2021 kern.warn kernel: [wifi2] FWLOG: [48277691] WAL channel
change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:56 2021 kern.warn kernel: [wifi2] FWLOG: [48277829]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:37:56 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:37:56 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:57 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:57 2021 kern.warn kernel: [wifi2] FWLOG: [48278005] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:57 2021 kern.warn kernel: [wifi2] FWLOG: [48278142]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:37:57 2021 kern.warn kernel: [wifi2] FWLOG: [48278318] WAL channel
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:57 2021 kern.warn kernel: [wifi2] FWLOG: [48278631] WAL channel
change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:57 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:37:57 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:37:57 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:37:57 2021 user.debug repacd.wifimon: CHECK associatd

Fri Jan 8 12:37:57 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:58 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:58 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:58 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:37:58 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
[wifi2] FWLOG: [48278945] WAL channel change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:58 2021 kern.warn kernel: vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41242 event 1 reason 1
Fri Jan 8 12:37:58 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:37:58 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state transition SCAN -> INIT
Fri Jan 8 12:37:58 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0 (c9e36000)
Fri Jan 8 12:37:58 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_END[3]
Fri Jan 8 12:37:58 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3 not handled in state INIT
Fri Jan 8 12:37:58 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:58 2021 kern.warn kernel: [wifi2] FWLOG: [48279258] WAL channel change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:58 2021 kern.warn kernel: [wifi2] FWLOG: [48279396] WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:37:58 2021 kern.warn kernel: [wifi2] FWLOG: [48279572] WAL channel change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:37:58 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:58 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 ::: force_down_5g:0
Fri Jan 8 12:37:58 2021 user.debug repacd.wifimon: repacd check timeout elapsed:1606 duration:170
Fri Jan 8 12:37:58 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:58 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:37:58 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:37:58 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:58 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:58 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:58 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:58 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:58 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:37:59 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:37:59 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:37:59 2021 kern.warn kernel: [wifi2] FWLOG: [48279913] RESMGR_OCS_GEN_PERIODIC_NOA (0x0)

```
Fri Jan 8 12:37:59 2021 kern.warn kernel: [wifi2] FWLOG: [48279913]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan 8 12:37:59 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:37:59 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:37:59 2021 user.notice led_function: RSSI24G -64
Fri Jan 8 12:37:59 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:38:00 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:38:00 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:38:00 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:38:00 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:38:00 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:38:00 2021 user.notice led_function: led check timeout
elapsed:47067 duration:180
Fri Jan 8 12:38:00 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:38:00 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:38:02 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:38:02 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:38:02 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:38:02 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:38:02 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:38:02 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:38:02 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
1, off 0, len 1
Fri Jan 8 12:38:02 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:38:02 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:38:02 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1611 duration:170
Fri Jan 8 12:38:02 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:38:02 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:38:02 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:38:02 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:38:02 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:38:02 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
0, off 0, len 1
Fri Jan 8 12:38:02 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:38:02 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:38:03 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
```

Fri Jan 8 12:38:03 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keySending SCAN START cmd

Fri Jan 8 12:38:03 2021 kern.warn kernel: vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41243 event 0 reason 0

Fri Jan 8 12:38:03 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state event 2, cur_state=0, vap_deleted_is_set=0

Fri Jan 8 12:38:03 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state transition INIT -> SCAN

Fri Jan 8 12:38:03 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_START[9]

Fri Jan 8 12:38:03 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9 not handled in state INIT

Fri Jan 8 12:38:04 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key

Fri Jan 8 12:38:04 2021 kern.warn kernel: [wifi2] FWLOG: [48285075] WAL channel change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1

Fri Jan 8 12:38:04 2021 kern.warn kernel: [wifi2] FWLOG: [48285213] WHAL_ERROR_RESET_OFFSETCAL ()

Fri Jan 8 12:38:04 2021 kern.warn kernel: [wifi2] FWLOG: [48285389] WAL channel change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1

Fri Jan 8 12:38:04 2021 kern.warn kernel: [wifi2] FWLOG: [48285526] WHAL_ERROR_RESET_OFFSETCAL ()

Fri Jan 8 12:38:04 2021 kern.warn kernel: [wifi2] FWLOG: [48285702] WAL channel change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1

Fri Jan 8 12:38:04 2021 kern.warn kernel: [wifi2] FWLOG: [48285840] WHAL_ERROR_RESET_OFFSETCAL ()

Fri Jan 8 12:38:04 2021 kern.warn kernel: [wifi2] FWLOG: [48286015] WAL channel change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1

Fri Jan 8 12:38:05 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key

Fri Jan 8 12:38:05 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key[wifi2] FWLOG: [48286329] WAL channel change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1

Fri Jan 8 12:38:05 2021 kern.warn kernel: vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1

Fri Jan 8 12:38:05 2021 kern.warn kernel: [wifi2] FWLOG: [48286642] WAL channel change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1

Fri Jan 8 12:38:05 2021 kern.warn kernel: [wifi2] FWLOG: [48286780] WHAL_ERROR_RESET_OFFSETCAL ()

Fri Jan 8 12:38:05 2021 kern.warn kernel: [wifi2] FWLOG: [48286956] WAL channel change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1

Fri Jan 8 12:38:05 2021 kern.warn kernel: [wifi2] FWLOG: [48287093] WHAL_ERROR_RESET_OFFSETCAL ()

Fri Jan 8 12:38:05 2021 kern.warn kernel: vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41243 event 1 reason 1

Fri Jan 8 12:38:05 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state event 3, cur_state=1, vap_deleted_is_set=0

Fri Jan 8 12:38:05 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state transition SCAN -> INIT

Fri Jan 8 12:38:05 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0 (c9e36000)

Fri Jan 8 12:38:05 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current

```
state INIT event SCAN_END[3]
Fri Jan  8 12:38:05 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3
not handled in state INIT
Fri Jan  8 12:38:05 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan  8 12:38:06 2021 user.notice led_function: RSSI24G -63
Fri Jan  8 12:38:06 2021 user.notice led_function: PING IS WELL
Fri Jan  8 12:38:06 2021 kern.warn kernel: [wifi2] FWLOG: [48287296]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan  8 12:38:06 2021 kern.warn kernel: [wifi2] FWLOG: [48287296]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan  8 12:38:06 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan  8 12:38:06 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan  8 12:38:06 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan  8 12:38:06 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan  8 12:38:06 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan  8 12:38:06 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan  8 12:38:06 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan  8 12:38:07 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:38:07 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:38:07 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan  8 12:38:07 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1615 duration:170
Fri Jan  8 12:38:07 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan  8 12:38:07 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan  8 12:38:07 2021 user.info repacd: AssocTimeout
Fri Jan  8 12:38:07 2021 user.info repacd: Boot time count=-1
Fri Jan  8 12:38:07 2021 user.notice led_function: led check timeout
elapsed:47073 duration:180
Fri Jan  8 12:38:07 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan  8 12:38:07 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:38:07 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan  8 12:38:07 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:38:07 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan  8 12:38:07 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
2, off 0, len 1
Fri Jan  8 12:38:07 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan  8 12:38:08 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan  8 12:38:08 2021 kern.warn kernel: Printing wds entries [No. of
```

```

entries:0]
Fri Jan  8 12:38:09 2021 kern.warn kernel:          DA          Next Hop
flags
Fri Jan  8 12:38:09 2021 kern.warn kernel:
Fri Jan  8 12:38:09 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan  8 12:38:09 2021 user.notice led_function: =====LOOP END=====
Fri Jan  8 12:38:09 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:38:09 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan  8 12:38:09 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan  8 12:38:10 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan  8 12:38:10 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan  8 12:38:10 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41244 event 0 reason 0
Fri Jan  8 12:38:10 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan  8 12:38:10 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan  8 12:38:10 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan  8 12:38:10 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan  8 12:38:10 2021 kern.warn kernel: Printing wds entries [No. of
entries:0]
Fri Jan  8 12:38:10 2021 kern.warn kernel:          DA          Next Hop
flags
Fri Jan  8 12:38:10 2021 kern.warn kernel:
Fri Jan  8 12:38:10 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan  8 12:38:11 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:38:11 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan  8 12:38:11 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key[wifi2] FWLOG: [48292420] WAL channel change freq=5580, mode=0 flags=0
rx_ok=1 tx_ok=1
Fri Jan  8 12:38:11 2021 kern.warn kernel: [wifi2] FWLOG: [48292557]
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan  8 12:38:11 2021 kern.warn kernel: [wifi2] FWLOG: [48292733] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan  8 12:38:11 2021 kern.warn kernel: [wifi2] FWLOG: [48292870]
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan  8 12:38:11 2021 kern.warn kernel: [wifi2] FWLOG: [48293047] WAL channel
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan  8 12:38:11 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan  8 12:38:11 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan  8 12:38:11 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:38:11 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyInst RSSI value of node-08:c5:e1:c2:a4:0c: 43
Fri Jan  8 12:38:11 2021 kern.warn kernel: Inst RSSI value of

```

node-08:c5:e1:c2:a4:0c: 43
Fri Jan 8 12:38:11 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:38:11 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:38:11 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:38:11 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:38:11 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:38:11 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:38:11 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1620 duration:170
Fri Jan 8 12:38:11 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:38:11 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:38:11 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:38:11 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:38:11 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:38:12 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
key[wifi2] FWLOG: [48293360] WAL channel change freq=5640, mode=0 flags=0
rx_ok=1 tx_ok=1
Fri Jan 8 12:38:12 2021 kern.warn kernel: [wifi2] FWLOG: [48293673] WAL channel
change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:38:12 2021 kern.warn kernel: [wifi2] FWLOG: [48293987] WAL channel
change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:38:12 2021 user.notice led_function: RSSI24G -63
Fri Jan 8 12:38:12 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:38:12 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41244 event 1 reason 1
Fri Jan 8 12:38:12 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:38:12 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition SCAN -> INIT
Fri Jan 8 12:38:12 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0
(c9e36000)
Fri Jan 8 12:38:12 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_END[3]
Fri Jan 8 12:38:12 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3
not handled in state INIT
Fri Jan 8 12:38:13 2021 kern.warn kernel: [wifi2] FWLOG: [48294300] WAL channel
change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:38:13 2021 kern.warn kernel: [wifi2] FWLOG: [48294641]
RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:38:13 2021 kern.warn kernel: [wifi2] FWLOG: [48294641]
RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:38:13 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:38:13 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:38:13 2021 user.notice led_function: led check timeout
elapsed:47079 duration:180

Fri Jan 8 12:38:13 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:38:13 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:38:13 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:38:13 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:38:14 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:38:14 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:38:14 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:38:15 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:38:15 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:38:15 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:38:15 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:38:15 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:38:15 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:38:15 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:38:15 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:38:15 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
0, off 0, len 1
Fri Jan 8 12:38:15 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:38:15 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:38:15 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1624 duration:170
Fri Jan 8 12:38:15 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:38:15 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:38:15 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:38:15 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:38:15 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:38:16 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:38:16 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
1, off 0, len 1
Fri Jan 8 12:38:17 2021 kern.warn kernel: Inst RSSI value of
node-08:c5:e1:c2:a4:0c: 44
Fri Jan 8 12:38:17 2021 kern.warn kernel: Inst RSSI value of
node-08:c5:e1:c2:a4:0c: 43
Fri Jan 8 12:38:17 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:38:17 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:38:17 2021 kern.warn kernel: Sending SCAN START cmd

Fri Jan 8 12:38:17 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41245 event 0 reason 0
Fri Jan 8 12:38:17 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:38:17 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:38:17 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:38:17 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan 8 12:38:17 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:38:18 2021 kern.warn kernel: [wifi2] FWLOG: [48299766] WAL channel
change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:38:18 2021 kern.warn kernel: [wifi2] FWLOG: [48299904]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:38:18 2021 kern.warn kernel: [wifi2] FWLOG: [48300080] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:38:18 2021 kern.warn kernel: [wifi2] FWLOG: [48300217]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:38:18 2021 kern.warn kernel: [wifi2] FWLOG: [48300393] WAL channel
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:38:18 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:38:18 2021 user.notice led_function: RSSI24G -63
Fri Jan 8 12:38:18 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:38:19 2021 kern.warn kernel: [wifi2] FWLOG: [48300706] WAL channel
change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:38:19 2021 kern.warn kernel: [wifi2] FWLOG: [48301020] WAL channel
change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:38:19 2021 kern.warn kernel: [wifi2] FWLOG: [48301333] WAL channel
change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:38:19 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:38:19 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:38:19 2021 user.notice led_function: led check timeout
elapsed:47086 duration:180
Fri Jan 8 12:38:19 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:38:19 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:38:19 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41245 event 1 reason 1
Fri Jan 8 12:38:19 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:38:19 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition SCAN -> INIT
Fri Jan 8 12:38:19 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0
(c9e36000)
Fri Jan 8 12:38:19 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_END[3]
Fri Jan 8 12:38:19 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3
not handled in state INIT

Fri Jan 8 12:38:19 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:38:19 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:38:20 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:38:20 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:38:20 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:38:20 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:38:20 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:38:20 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:38:20 2021 kern.warn kernel: [wifi2] FWLOG: [48301646] WAL channel
change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:38:20 2021 kern.warn kernel: [wifi2] FWLOG: [48301784]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:38:20 2021 kern.warn kernel: [wifi2] FWLOG: [48301987]
RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:38:20 2021 kern.warn kernel: [wifi2] FWLOG: [48301987]
RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:38:20 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:38:20 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:38:20 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1628 duration:170
Fri Jan 8 12:38:20 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:38:20 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:38:20 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:38:20 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:38:20 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:38:20 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:38:20 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:38:20 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:38:20 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:38:21 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:38:21 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:38:21 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:38:22 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:38:22 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
2, off 0, len 1
Fri Jan 8 12:38:22 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:38:22 2021 kern.warn kernel: Inst RSSI value of

node-08:c5:e1:c2:a4:0c: 44
Fri Jan 8 12:38:22 2021 kern.warn kernel: Inst RSSI value of
node-08:c5:e1:c2:a4:0c: 43
Fri Jan 8 12:38:23 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:38:23 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:38:24 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:38:24 2021 user.info syslog: [admin login] from source
192.168.1.44,
Fri Jan 8 12:38:24 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:38:24 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:38:24 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:38:24 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:38:24 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:38:24 2021 user.notice led_function: RSSI24G -63
Fri Jan 8 12:38:24 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:38:24 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:38:24 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:38:24 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41246 event 0 reason 0
Fri Jan 8 12:38:24 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:38:24 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:38:24 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition INIT -> SCAN
Fri Jan 8 12:38:24 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:38:24 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_START[9]
Fri Jan 8 12:38:24 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9
not handled in state INIT
Fri Jan 8 12:38:24 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:38:24 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1633 duration:170
Fri Jan 8 12:38:24 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:38:24 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:38:24 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:38:24 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:38:24 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:38:25 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
2, off 0, len 1
Fri Jan 8 12:38:25 2021 kern.warn kernel: [wifi2] FWLOG: [48307111] WAL channel
change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:38:25 2021 kern.warn kernel: [wifi2] FWLOG: [48307249]

```
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan 8 12:38:25 2021 kern.warn kernel: [wifi2] FWLOG: [48307425] WAL channel
change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:38:25 2021 kern.warn kernel: [wifi2] FWLOG: [48307562]
WHAL_ERROR_RESET_OFFSETCAL ( )
Fri Jan 8 12:38:25 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:38:25 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:38:25 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:38:25 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:38:25 2021 user.notice led_function: led check timeout
elapsed:47092 duration:180
Fri Jan 8 12:38:25 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:38:25 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:38:26 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:38:26 2021 kern.warn kernel: [wifi2] FWLOG: [48307738] WAL channel
change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:38:26 2021 kern.warn kernel: [wifi2] FWLOG: [48308052] WAL channel
change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:38:26 2021 kern.warn kernel: [wifi2] FWLOG: [48308365] WAL channel
change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:38:26 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:38:26 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41246 event 1 reason 1
Fri Jan 8 12:38:26 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:38:26 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition SCAN -> INIT
Fri Jan 8 12:38:26 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0
(c9e36000)
Fri Jan 8 12:38:26 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_END[3]
Fri Jan 8 12:38:26 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3
not handled in state INIT
Fri Jan 8 12:38:27 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:38:27 2021 kern.warn kernel: [wifi2] FWLOG: [48308678] WAL channel
change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:38:27 2021 kern.warn kernel: [wifi2] FWLOG: [48308992] WAL channel
change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:38:27 2021 kern.warn kernel: [wifi2] FWLOG: [48309332]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan 8 12:38:27 2021 kern.warn kernel: [wifi2] FWLOG: [48309332]
RESMGR_OCS_GEN_PERIODIC_NOA ( 0x0 )
Fri Jan 8 12:38:27 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:38:27 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
```

```
Fri Jan 8 12:38:27 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:38:27 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:38:28 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:38:28 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:38:28 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:38:28 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:38:28 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:38:29 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:38:29 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:38:29 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected
Fri Jan 8 12:38:29 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:38:29 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:38:29 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1637 duration:170
Fri Jan 8 12:38:29 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:38:29 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:38:29 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:38:29 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:38:29 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:38:29 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:38:29 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyRX Rate Info:
Fri Jan 8 12:38:29 2021 kern.warn kernel: MCS counts (0..9): 665, 1530, 4101,
15711, 39749, 44143, 54749, 35236, 3682, 887
Fri Jan 8 12:38:30 2021 kern.warn kernel: SGI counts (0..9): 240, 716, 1748,
7921, 13730, 17234, 28213, 17449, 1720, 483
Fri Jan 8 12:38:30 2021 kern.warn kernel: NSS counts: 1x1 127525, 2x2 72928,
3x3 0, 4x4 0
Fri Jan 8 12:38:30 2021 kern.warn kernel: NSTS count: 577
Fri Jan 8 12:38:30 2021 kern.warn kernel: BW counts: 20MHz 201421, 40MHz 0,
80MHz 0, 160MHz 0
Fri Jan 8 12:38:30 2021 kern.warn kernel: Preamble counts: 114921, 89173, 0,
112248, 0, 0
Fri Jan 8 12:38:30 2021 kern.warn kernel: STBC rate counts (0..9): 238, 187,
51, 52, 23, 3, 1, 22, 0, 0
Fri Jan 8 12:38:30 2021 kern.warn kernel: LDPC Counts: 200350
Fri Jan 8 12:38:30 2021 kern.warn kernel: RSSI (data, mgmt): 31, 23
Fri Jan 8 12:38:30 2021 kern.warn kernel: RSSI Chain 0 (0x80 0x80 0x80 0x1d)
Fri Jan 8 12:38:30 2021 kern.warn kernel: RSSI Chain 1 (0x80 0x80 0x80 0x1a)
Fri Jan 8 12:38:30 2021 kern.warn kernel: RSSI Chain 2 (0x00 0x00 0x00 0x00)
Fri Jan 8 12:38:30 2021 kern.warn kernel: RSSI Chain 3 (0x00 0x00 0x00 0x00)
Fri Jan 8 12:38:30 2021 kern.warn kernel: RSSI (comb_ht): 31
Fri Jan 8 12:38:30 2021 user.notice led_function: RSSI24G -64
```

Fri Jan 8 12:38:30 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:38:31 2021 kern.warn kernel: RX Rate Info:
Fri Jan 8 12:38:31 2021 kern.warn kernel: MCS counts (0..9): 4586, 0, 0, 0, 77, 20188, 68397, 129938, 501811, 27607
Fri Jan 8 12:38:31 2021 kern.warn kernel: SGI counts (0..9): 0, 0, 0, 0, 76, 20070, 66924, 126215, 498615, 15530
Fri Jan 8 12:38:31 2021 kern.warn kernel: NSS counts: 1x1 4580, 2x2 1557, 3x3 552329, 4x4 194138
Fri Jan 8 12:38:31 2021 kern.warn kernel: NSTS count: 0
Fri Jan 8 12:38:31 2021 kern.warn kernel: BW counts: 20MHz 29, 40MHz 56, 80MHz 757477, 160MHz 0
Fri Jan 8 12:38:31 2021 kern.warn kernel: Preamble counts: 135383, 56, 0, 757506, 0, 5271
Fri Jan 8 12:38:31 2021 kern.warn kernel: STBC rate counts (0..9): 0, 0, 0, 0, 0, 0, 0, 0, 0, 0
Fri Jan 8 12:38:31 2021 kern.warn kernel: LDPC Counts: 748012
Fri Jan 8 12:38:31 2021 kern.warn kernel: RSSI (data, mgmt): 40, 18
Fri Jan 8 12:38:31 2021 kern.warn kernel: RSSI Chain 0 (0x80 0x25 0x21 0x24)
Fri Jan 8 12:38:31 2021 kern.warn kernel: RSSI Chain 1 (0x80 0x21 0x1e 0x22)
Fri Jan 8 12:38:31 2021 kern.warn kernel: RSSI Chain 2 (0x80 0x24 0x21 0x20)
Fri Jan 8 12:38:31 2021 kern.warn kernel: RSSI Chain 3 (0x80 0x1f 0x22 0x24)
Fri Jan 8 12:38:31 2021 kern.warn kernel: RSSI (comb_ht): 41
Fri Jan 8 12:38:31 2021 kern.warn kernel: Sending SCAN START cmd
Fri Jan 8 12:38:31 2021 kern.warn kernel: vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id 41247 event 0 reason 0
Fri Jan 8 12:38:31 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state event 2, cur_state=0, vap_deleted_is_set=0
Fri Jan 8 12:38:31 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event: VAP state transition INIT -> SCAN
Fri Jan 8 12:38:31 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current state INIT event SCAN_START[9]
Fri Jan 8 12:38:31 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 9 not handled in state INIT
Fri Jan 8 12:38:31 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:38:31 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:38:31 2021 user.notice led_function: led check timeout elapsed:47098 duration:180
Fri Jan 8 12:38:31 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:38:32 2021 user.notice led_function: CUR_STATE: RE_LocationSuitable
Fri Jan 8 12:38:32 2021 kern.warn kernel: TX Rate Info:
Fri Jan 8 12:38:32 2021 kern.warn kernel: MCS counts (0..9): 562, 704, 1316, 1625, 9111, 51527, 89714, 127828, 48662, 23369
Fri Jan 8 12:38:32 2021 kern.warn kernel: MCS counts SU (0..9): 562, 704, 1316, 1625, 9111, 51527, 89714, 127828, 48662, 23369
Fri Jan 8 12:38:32 2021 kern.warn kernel: MCS counts MU (0..9): 0, 0, 0, 0, 0, 0, 0, 0, 0, 0
Fri Jan 8 12:38:32 2021 kern.warn kernel: SGI counts (0..9):
Fri Jan 8 12:38:32 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key0, 0, 0, 0, 5513, 22776, 33847, 102247, 38766, 17640
Fri Jan 8 12:38:32 2021 kern.warn kernel: NSS counts: 1x1 153636, 2x2 200782, 3x3 0 4x4 0

Fri Jan 8 12:38:32 2021 kern.warn kernel: BW counts: 20MHz 354418, 40MHz 0, 80MHz 0, 160MHz 0
Fri Jan 8 12:38:32 2021 kern.warn kernel: Preamble (O C H V) counts: 0, 13120, 143104, 212284
Fri Jan 8 12:38:32 2021 kern.warn kernel: STBC rate counts (0..9): 562, 672, 1181, 1496, 1737, 10581, 33052, 50289, 0, 0
Fri Jan 8 12:38:32 2021 kern.warn kernel: LDPC Counts: 211314
Fri Jan 8 12:38:32 2021 kern.warn kernel: RTS Counts: 27845
Fri Jan 8 12:38:32 2021 kern.warn kernel: Ack RSSI: 32
Fri Jan 8 12:38:32 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:38:32 2021 kern.warn kernel: [wifi2] FWLOG: [48314455] WAL channel change freq=5580, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:38:32 2021 kern.warn kernel: [wifi2] FWLOG: [48314593] WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:38:33 2021 kern.warn kernel: TX Rate Info:
Fri Jan 8 12:38:33 2021 kern.warn kernel: MCS counts (0..9): 0, 0, 0, 0, 0, 8324, 125481, 166019, 365434, 217694
Fri Jan 8 12:38:33 2021 kern.warn kernel: MCS counts SU (0..9): 0, 0, 0, 0, 0, 8324, 125481, 166019, 365434, 217694
Fri Jan 8 12:38:33 2021 kern.warn kernel: MCS counts MU (0..9): 0, 0, 0, 0, 0, 0, 0, 0, 0, 0
Fri Jan 8 12:38:33 2021 kern.warn kernel: SGI counts (0..9): 0, 0, 0, 0, 0, 8294, 124427, 149841, 319175, 185317
Fri Jan 8 12:38:33 2021 kern.warn kernel: NSS counts: 1x1 0, 2x2 332, 3x3 545719 4x4 336901
Fri Jan 8 12:38:33 2021 kern.warn kernel: BW counts: 20MHz 391, 40MHz 0, 80MHz 882561, 160MHz 0
Fri Jan 8 12:38:33 2021 kern.warn kernel: Preamble (O C H V) counts: 2, 0, 0, 882952
Fri Jan 8 12:38:33 2021 kern.warn kernel: STBC rate counts (0..9): 0, 0, 0, 0, 0, 0, 0, 0, 0, 0
Fri Jan 8 12:38:33 2021 kern.warn kernel: LDPC Counts: 882952
Fri Jan 8 12:38:33 2021 kern.warn kernel: RTS Counts: 814
Fri Jan 8 12:38:33 2021 kern.warn kernel: Ack RSSI: 36
Fri Jan 8 12:38:33 2021 kern.warn kernel: [wifi2] FWLOG: [48314769] WAL channel change freq=5600, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:38:33 2021 kern.warn kernel: [wifi2] FWLOG: [48314906] WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:38:33 2021 kern.warn kernel: [wifi2] FWLOG: [48315082] WAL channel change freq=5620, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:38:33 2021 kern.warn kernel: [wifi2] FWLOG: [48315395] WAL channel change freq=5640, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:38:33 2021 kern.warn kernel: [wifi2] FWLOG: [48315709] WAL channel change freq=5660, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:38:33 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:38:33 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:38:33 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:38:33 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:38:33 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:38:33 2021 user.debug repacd.wifimon: Only 2.4g backhaul connected

Fri Jan 8 12:38:33 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:38:33 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:38:33 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:38:33 2021 user.debug repacd.wifimon: sta_iface_24g:ath01 :::
force_down_5g:0
Fri Jan 8 12:38:33 2021 user.debug repacd.wifimon: repacd check timeout
elapsed:1642 duration:170
Fri Jan 8 12:38:33 2021 user.info repacd: AssocTimeout
Fri Jan 8 12:38:33 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:38:33 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:38:33 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:38:33 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:38:33 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
0, off 0, len 1
Fri Jan 8 12:38:34 2021 kern.warn kernel:
vap-0(ath2):ieee80211_vap_scan_event_handler: orig=c8b70000 vap=c8b70000 scan_id
41247 event 1 reason 1
Fri Jan 8 12:38:34 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state event 3, cur_state=1, vap_deleted_is_set=0
Fri Jan 8 12:38:34 2021 kern.warn kernel: vap-0(ath2):ieee80211_state_event:
VAP state transition SCAN -> INIT
Fri Jan 8 12:38:34 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:38:34 2021 kern.warn kernel: send_vdev_down_cmd_non_tlv for vap 0
(c9e36000)
Fri Jan 8 12:38:34 2021 kern.warn kernel: vap-0(ath2):HSM: connection :current
state INIT event SCAN_END[3]
Fri Jan 8 12:38:34 2021 kern.warn kernel: vap-0(ath2):HSM: connection : event 3
not handled in state INIT
Fri Jan 8 12:38:34 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:38:34 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:38:34 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:38:34 2021 kern.warn kernel: [wifi2] FWLOG: [48316022] WAL channel
change freq=5680, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:38:34 2021 kern.warn kernel: [wifi2] FWLOG: [48316335] WAL channel
change freq=5700, mode=0 flags=0 rx_ok=1 tx_ok=1
Fri Jan 8 12:38:34 2021 kern.warn kernel: [wifi2] FWLOG: [48316473]
WHAL_ERROR_RESET_OFFSETCAL ()
Fri Jan 8 12:38:34 2021 kern.warn kernel: [wifi2] FWLOG: [48316676]
RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:38:34 2021 kern.warn kernel: [wifi2] FWLOG: [48316676]
RESMGR_OCS_GEN_PERIODIC_NOA (0x0)
Fri Jan 8 12:38:35 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:38:35 2021 kern.warn kernel: vap-2(ath01):[a6:c9:eb:1a:a6:a1] send
null data frame on channel 13, pwr mgt dis