

```
Fri Jan 8 12:45:08 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:45:08 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:45:09 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:45:09 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:45:09 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:45:09 2021 user.debug repacd.wifimon: All backhaul connected
Fri Jan 8 12:45:09 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:45:09 2021 user.debug repacd.wifimon: [repacd]Network associated
Fri Jan 8 12:45:09 2021 user.info repacd: RE_LocationSuitable
Fri Jan 8 12:45:09 2021 user.info repacd: LED SOLID TIMES--59
Fri Jan 8 12:45:09 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:45:09 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:45:09 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:45:09 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:45:09 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:45:10 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:45:10 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:45:10 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:45:10 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:45:10 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:45:11 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:45:11 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:45:12 2021 user.notice led_function: RSSI5G -58
Fri Jan 8 12:45:12 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:45:12 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:45:12 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
1, off 0, len 1
Fri Jan 8 12:45:12 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:45:12 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:45:13 2021 kern.warn kernel: Printing wds entries [No. of
entries:0]
Fri Jan 8 12:45:13 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:45:13 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:45:13 2021 user.notice led_function: led check timeout
elapsed:47499 duration:180
Fri Jan 8 12:45:13 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:45:13 2021 user.notice led_function: CUR_STATE:
```

RE_LocationSuitable

```
Fri Jan  8 12:45:13 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan  8 12:45:13 2021 kern.warn kernel:      DA      Next Hop
flags
Fri Jan  8 12:45:13 2021 kern.warn kernel:
Fri Jan  8 12:45:13 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan  8 12:45:13 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan  8 12:45:13 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan  8 12:45:13 2021 user.debug repacd.wifimon: All backhaul connected
Fri Jan  8 12:45:13 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
0, off 0, len 1
Fri Jan  8 12:45:13 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:45:13 2021 user.debug repacd.wifimon: [repacd]Network associated
Fri Jan  8 12:45:13 2021 user.info repacd: RE_LocationSuitable
Fri Jan  8 12:45:13 2021 user.info repacd: LED SOLID TIMES--58
Fri Jan  8 12:45:13 2021 user.info repacd: Boot time count=-1
Fri Jan  8 12:45:13 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan  8 12:45:15 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyPrinting wds entries [No. of entries:0]
Fri Jan  8 12:45:15 2021 user.notice led_function: =====LOOP END=====
Fri Jan  8 12:45:15 2021 kern.warn kernel:      DA      Next Hop
flags
Fri Jan  8 12:45:15 2021 kern.warn kernel:
Fri Jan  8 12:45:15 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:45:16 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan  8 12:45:16 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
1, off 0, len 1
Fri Jan  8 12:45:16 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan  8 12:45:17 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan  8 12:45:17 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan  8 12:45:17 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:45:17 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan  8 12:45:17 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan  8 12:45:17 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan  8 12:45:17 2021 user.debug repacd.wifimon: All backhaul connected
Fri Jan  8 12:45:17 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:45:17 2021 user.debug repacd.wifimon: [repacd]Network associated
Fri Jan  8 12:45:17 2021 user.info repacd: RE_LocationSuitable
Fri Jan  8 12:45:17 2021 user.info repacd: LED SOLID TIMES--57
Fri Jan  8 12:45:17 2021 user.info repacd: Boot time count=-1
Fri Jan  8 12:45:17 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
```

keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:45:17 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:45:18 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:45:18 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:45:18 2021 user.notice led_function: RSSI5G -57
Fri Jan 8 12:45:18 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:45:18 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:45:18 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:45:18 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:45:19 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:45:19 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:45:19 2021 user.notice led_function: led check timeout
elapsed:47505 duration:180
Fri Jan 8 12:45:19 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:45:19 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:45:19 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:45:19 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:45:19 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:45:20 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:45:20 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:45:20 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:45:21 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:45:21 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:45:21 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:45:21 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:45:21 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:45:22 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:45:22 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:45:22 2021 user.debug repacd.wifimon: All backhaul connected
Fri Jan 8 12:45:22 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:45:22 2021 user.debug repacd.wifimon: [repacd]Network associated
Fri Jan 8 12:45:22 2021 user.info repacd: RE_LocationSuitable

Fri Jan 8 12:45:22 2021 user.info repacd: LED SOLID TIMES--56
Fri Jan 8 12:45:22 2021 user.info repacd: Boot time count--1
Fri Jan 8 12:45:22 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:45:22 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:45:23 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:45:24 2021 user.notice led_function: RSSI5G -59
Fri Jan 8 12:45:24 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:45:24 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:45:25 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:45:25 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:45:25 2021 user.notice led_function: led check timeout
elapsed:47512 duration:180
Fri Jan 8 12:45:25 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:45:25 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:45:26 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:45:26 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:45:26 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:45:26 2021 user.debug repacd.wifimon: All backhaul connected
Fri Jan 8 12:45:26 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:45:26 2021 user.debug repacd.wifimon: [repacd]Network associated
Fri Jan 8 12:45:26 2021 user.info repacd: RE_LocationSuitable
Fri Jan 8 12:45:26 2021 user.info repacd: LED SOLID TIMES--55
Fri Jan 8 12:45:26 2021 user.info repacd: Boot time count--1
Fri Jan 8 12:45:26 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:45:27 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:45:27 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:45:27 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:45:27 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
1, off 0, len 1
Fri Jan 8 12:45:27 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:45:28 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:45:28 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:45:29 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:45:29 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
1, off 0, len 1
Fri Jan 8 12:45:30 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:45:30 2021 kern.warn kernel: vap-0(ath1):

```
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:45:30 2021 user.notice led_function: RSSI5G -59
Fri Jan 8 12:45:30 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:45:30 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:45:30 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:45:30 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:45:30 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:45:31 2021 user.debug repacd.wifimon: All backhaul connected
Fri Jan 8 12:45:31 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:45:31 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:45:31 2021 user.debug repacd.wifimon: [repacd]Network associated
Fri Jan 8 12:45:31 2021 user.info repacd: RE_LocationSuitable
Fri Jan 8 12:45:31 2021 user.info repacd: LED SOLID TIMES--54
Fri Jan 8 12:45:31 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:45:31 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:45:31 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:45:31 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:45:31 2021 user.notice led_function: led check timeout
elapsed:47518 duration:180
Fri Jan 8 12:45:31 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:45:31 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:45:32 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
2, off 0, len 1
Fri Jan 8 12:45:33 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:45:33 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:45:33 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:45:33 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:45:33 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:45:34 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyRX Rate Info:
Fri Jan 8 12:45:34 2021 kern.warn kernel: MCS counts (0..9): 665, 1530, 4139,
16058, 40027, 44467, 55064, 35404, 3843, 939
Fri Jan 8 12:45:34 2021 kern.warn kernel: SGI counts (0..9): 240, 716, 1786,
8235, 13884, 17511, 28470, 17578, 1845, 505
Fri Jan 8 12:45:34 2021 kern.warn kernel: NSS counts: 1x1 128498, 2x2 73638,
3x3 0, 4x4 0
Fri Jan 8 12:45:34 2021 kern.warn kernel: NSTS count: 577
Fri Jan 8 12:45:34 2021 kern.warn kernel: BW counts: 20MHz 203113, 40MHz 0,
80MHz 0, 160MHz 0
Fri Jan 8 12:45:34 2021 kern.warn kernel: Preamble counts: 116387, 89173, 0,
113940, 0, 0
Fri Jan 8 12:45:34 2021 kern.warn kernel: STBC rate counts (0..9): 238, 187,
51, 52, 23, 3, 1, 22, 0, 0
```

Fri Jan 8 12:45:34 2021 kern.warn kernel: LDPC Counts: 202033
Fri Jan 8 12:45:34 2021 kern.warn kernel: RSSI (data, mgmt): 32, 23
Fri Jan 8 12:45:34 2021 kern.warn kernel: RSSI Chain 0 (0x80 0x80 0x80 0x1e)
Fri Jan 8 12:45:34 2021 kern.warn kernel: RSSI Chain 1 (0x80 0x80 0x80 0x1c)
Fri Jan 8 12:45:34 2021 kern.warn kernel: RSSI Chain 2 (0x00 0x00 0x00 0x00)
Fri Jan 8 12:45:34 2021 kern.warn kernel: RSSI Chain 3 (0x00 0x00 0x00 0x00)
Fri Jan 8 12:45:34 2021 kern.warn kernel: RSSI (comb_ht): 32
Fri Jan 8 12:45:35 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:45:35 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:45:35 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:45:35 2021 user.debug repacd.wifimon: All backhaul connected
Fri Jan 8 12:45:35 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:45:35 2021 kern.warn kernel: RX Rate Info:
Fri Jan 8 12:45:35 2021 kern.warn kernel: MCS counts (0..9): 4586, 0, 0, 0, 77,
20222, 69185, 132015, 501932, 27622
Fri Jan 8 12:45:35 2021 kern.warn kernel: SGI counts (0..9): 0, 0, 0, 0, 76,
20104, 67712, 128222, 498736, 15536
Fri Jan 8 12:45:35 2021 kern.warn kernel: NSS counts: 1x1 4580, 2x2 1557, 3x3
552473, 4x4 197029
Fri Jan 8 12:45:35 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:45:35 2021 kern.warn kernel: NSTS count: 0
Fri Jan 8 12:45:35 2021 kern.warn kernel: BW counts: 20MHz 29, 40MHz 56, 80MHz
760528, 160MHz 0
Fri Jan 8 12:45:35 2021 kern.warn kernel: Preamble counts: 136401, 56, 0,
760557, 0, 5278
Fri Jan 8 12:45:35 2021 kern.warn kernel: STBC rate counts (0..9):
Fri Jan 8 12:45:35 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key0, 0, 0, 0, 0, 0, 0, 0, 0, 0
Fri Jan 8 12:45:35 2021 kern.warn kernel: LDPC Counts: 751047
Fri Jan 8 12:45:35 2021 kern.warn kernel: RSSI (data, mgmt): 39, 34
Fri Jan 8 12:45:35 2021 kern.warn kernel: RSSI Chain 0 (0x80 0x22 0x20 0x22)
Fri Jan 8 12:45:35 2021 kern.warn kernel: RSSI Chain 1 (0x80 0x1f 0x1b 0x20)
Fri Jan 8 12:45:35 2021 kern.warn kernel: RSSI Chain 2 (0x80 0x21 0x1f 0x1e)
Fri Jan 8 12:45:35 2021 kern.warn kernel: RSSI Chain 3 (0x80 0x1e 0x21 0x21)
Fri Jan 8 12:45:35 2021 kern.warn kernel: RSSI (comb_ht): 39
Fri Jan 8 12:45:35 2021 user.debug repacd.wifimon: [repacd]Network associated
Fri Jan 8 12:45:35 2021 user.info repacd: RE_LocationSuitable
Fri Jan 8 12:45:35 2021 user.info repacd: LED SOLID TIMES--53
Fri Jan 8 12:45:35 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:45:35 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:45:36 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:45:36 2021 kern.warn kernel: TX Rate Info:
Fri Jan 8 12:45:36 2021 kern.warn kernel: MCS counts (0..9): 562, 704, 1316,
1625, 9416, 54370, 90746, 127892, 48662, 23374
Fri Jan 8 12:45:36 2021 kern.warn kernel: MCS counts SU (0..9): 562, 704, 1316,
1625, 9416, 54370, 90746, 127892, 48662, 23374
Fri Jan 8 12:45:36 2021 kern.warn kernel: MCS counts MU (0..9): 0, 0, 0, 0, 0,
0, 0, 0, 0, 0
Fri Jan 8 12:45:36 2021 kern.warn kernel: SGI counts (0..9): 0, 0, 0, 0, 5818,
25071, 34622, 102247, 38766, 17643
Fri Jan 8 12:45:36 2021 kern.warn kernel: NSS counts: 1x1 153641, 2x2 205026,

3x3 0 4x4 0
Fri Jan 8 12:45:36 2021 kern.warn kernel: BW counts: 20MHz 358667, 40MHz 0, 80MHz 0, 160MHz 0
Fri Jan 8 12:45:36 2021 kern.warn kernel: Preamble (O C H V) counts: 0, 13120, 143104, 216533
Fri Jan 8 12:45:36 2021 kern.warn kernel: STBC rate counts (0..9): 562, 672, 1181, 1496, 1737, 10581, 33052, 50289, 0, 0
Fri Jan 8 12:45:36 2021 kern.warn kernel: LDPC Counts: 215563
Fri Jan 8 12:45:36 2021 kern.warn kernel: RTS Counts: 28232
Fri Jan 8 12:45:36 2021 kern.warn kernel: Ack RSSI: 33
Fri Jan 8 12:45:36 2021 user.notice led_function: RSSI5G -59
Fri Jan 8 12:45:36 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:45:37 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:45:37 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
vap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:45:37 2021 kern.warn kernel: TX Rate Info:
Fri Jan 8 12:45:37 2021 kern.warn kernel: MCS counts (0..9): 0, 0, 0, 0, 0, 8329, 125486, 168146, 365684, 217694
Fri Jan 8 12:45:37 2021 kern.warn kernel: MCS counts SU (0..9): 0, 0, 0, 0, 0, 8329, 125486, 168146, 365684, 217694
Fri Jan 8 12:45:37 2021 kern.warn kernel: MCS counts MU (0..9): 0, 0, 0, 0, 0, 0, 0, 0, 0, 0
Fri Jan 8 12:45:37 2021 kern.warn kernel: SGI counts (0..9): 0, 0, 0, 0, 0, 8299, 124432, 151968, 319425, 185317
Fri Jan 8 12:45:37 2021 kern.warn kernel: NSS counts: 1x1 0, 2x2 332, 3x3 545719 4x4 339288
Fri Jan 8 12:45:37 2021 kern.warn kernel: BW counts: 20MHz 392, 40MHz 0, 80MHz 884947, 160MHz 0
Fri Jan 8 12:45:37 2021 kern.warn kernel: Preamble (O C H V) counts: 4, 0, 0, 885339
Fri Jan 8 12:45:37 2021 kern.warn kernel: STBC rate counts (0..9): 0, 0, 0, 0, 0, 0, 0, 0, 0, 0
Fri Jan 8 12:45:37 2021 kern.warn kernel: LDPC Counts: 885339
Fri Jan 8 12:45:37 2021 kern.warn kernel: RTS Counts: 814
Fri Jan 8 12:45:37 2021 kern.warn kernel: Ack RSSI: 35
Fri Jan 8 12:45:37 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:45:37 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:45:37 2021 kern.warn kernel: Inst RSSI value of node-08:c5:e1:c2:a4:0c: 40
Fri Jan 8 12:45:37 2021 kern.warn kernel: Inst RSSI value of node-08:c5:e1:c2:a4:0c: 41
Fri Jan 8 12:45:37 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:45:37 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:45:37 2021 user.notice led_function: led check timeout elapsed:47524 duration:180
Fri Jan 8 12:45:37 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:45:37 2021 user.notice led_function: CUR_STATE: RE_LocationSuitable
Fri Jan 8 12:45:37 2021 kern.warn kernel: vap-0(ath1):

```
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan  8 12:45:38 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan  8 12:45:38 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan  8 12:45:38 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
0, off 0, len 1
Fri Jan  8 12:45:39 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan  8 12:45:39 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan  8 12:45:39 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan  8 12:45:39 2021 user.debug repacd.wifimon: All backhaul connected
Fri Jan  8 12:45:39 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:45:39 2021 user.debug repacd.wifimon: [repacd]Network associated
Fri Jan  8 12:45:39 2021 user.info repacd: RE_LocationSuitable
Fri Jan  8 12:45:39 2021 user.info repacd: LED SOLID TIMES--52
Fri Jan  8 12:45:39 2021 user.info repacd: Boot time count=-1
Fri Jan  8 12:45:39 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan  8 12:45:39 2021 user.notice led_function: =====LOOP END=====
Fri Jan  8 12:45:40 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:45:40 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
2, off 0, len 1
Fri Jan  8 12:45:41 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:45:41 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan  8 12:45:43 2021 user.notice led_function: RSSI5G -58
Fri Jan  8 12:45:43 2021 user.notice led_function: PING IS WELL
Fri Jan  8 12:45:43 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:45:43 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan  8 12:45:43 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan  8 12:45:43 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:45:43 2021 user.debug repacd.wifimon: All backhaul connected
Fri Jan  8 12:45:43 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan  8 12:45:43 2021 user.debug repacd.wifimon: [repacd]Network associated
Fri Jan  8 12:45:43 2021 user.info repacd: RE_LocationSuitable
Fri Jan  8 12:45:43 2021 user.info repacd: LED SOLID TIMES--51
Fri Jan  8 12:45:43 2021 user.info repacd: Boot time count=-1
Fri Jan  8 12:45:43 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan  8 12:45:44 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan  8 12:45:44 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan  8 12:45:44 2021 user.notice led_function: led check timeout
elapsed:47530 duration:180
Fri Jan  8 12:45:44 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan  8 12:45:44 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
```

```
Fri Jan 8 12:45:45 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:45:45 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:45:45 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:45:46 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:45:46 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:45:47 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:45:47 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:45:47 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:45:47 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:45:47 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:45:48 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:45:48 2021 user.debug repacd.wifimon: All backhaul connected
Fri Jan 8 12:45:48 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:45:48 2021 user.debug repacd.wifimon: [repacd]Network associated
Fri Jan 8 12:45:48 2021 user.info repacd: RE_LocationSuitable
Fri Jan 8 12:45:48 2021 user.info repacd: LED SOLID TIMES--50
Fri Jan 8 12:45:48 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:45:48 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:45:48 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:45:49 2021 user.notice led_function: RSSI5G -58
Fri Jan 8 12:45:49 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:45:49 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:45:49 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:45:49 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:45:49 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:45:50 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:45:50 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:45:50 2021 user.notice led_function: led check timeout
elapsed:47536 duration:180
Fri Jan 8 12:45:50 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:45:50 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:45:52 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:45:52 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
2, off 0, len 1
Fri Jan 8 12:45:52 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:45:52 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
```

```
Fri Jan 8 12:45:52 2021 user.debug repacd.wifimon: All backhaul connected
Fri Jan 8 12:45:52 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:45:52 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:45:52 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:45:52 2021 user.debug repacd.wifimon: [repacd]Network associated
Fri Jan 8 12:45:52 2021 user.info repacd: RE_LocationSuitable
Fri Jan 8 12:45:52 2021 user.info repacd: LED SOLID TIMES--49
Fri Jan 8 12:45:52 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
0, off 0, len 1
Fri Jan 8 12:45:52 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:45:52 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:45:52 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
2, off 0, len 1
Fri Jan 8 12:45:52 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:45:53 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 1, off 0, len 1
Fri Jan 8 12:45:53 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:45:54 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:45:54 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
2, off 0, len 1
Fri Jan 8 12:45:54 2021 kern.warn kernel: vap-2(ath01):[a6:c9:eb:1a:a6:a1] send
null data frame on channel 13, pwr mgt dis
Fri Jan 8 12:45:54 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:45:54 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 2, off 0, len 1
Fri Jan 8 12:45:55 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:45:55 2021 user.notice led_function: RSSI5G -57
Fri Jan 8 12:45:55 2021 user.notice led_function: PING IS WELL
Fri Jan 8 12:45:56 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
key
Fri Jan 8 12:45:56 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):[9c:c9:eb:1a:a6:a4] send null data frame on channel 112, pwr mgt
dis
Fri Jan 8 12:45:56 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:45:56 2021 user.notice led_function: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:45:56 2021 user.notice led_function: wps_inprocess
wps_process_logged wps_1st_finish 0
Fri Jan 8 12:45:56 2021 user.notice led_function: led check timeout
elapsed:47543 duration:180
Fri Jan 8 12:45:56 2021 user.notice led_function: SELECTION LOOP CONTINUE
Fri Jan 8 12:45:56 2021 user.notice led_function: CUR_STATE:
RE_LocationSuitable
Fri Jan 8 12:45:56 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:45:56 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
```

key

```
Fri Jan 8 12:45:56 2021 user.debug repacd.wifimon: All backhaul connected
Fri Jan 8 12:45:56 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:45:56 2021 user.debug repacd.wifimon: [repacd]Network associated
Fri Jan 8 12:45:56 2021 user.info repacd: RE_LocationSuitable
Fri Jan 8 12:45:56 2021 user.info repacd: LED SOLID TIMES--48
Fri Jan 8 12:45:56 2021 user.info repacd: Boot time count=-1
Fri Jan 8 12:45:56 2021 kern.warn kernel: vap-2(ath01):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:45:57 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath1): [9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending
2, off 0, len 1
Fri Jan 8 12:45:57 2021 kern.warn kernel: Inst RSSI value of
node-08:c5:e1:c2:a4:0c: 40
Fri Jan 8 12:45:57 2021 kern.warn kernel: Inst RSSI value of
node-08:c5:e1:c2:a4:0c: 40
Fri Jan 8 12:45:57 2021 kern.warn kernel: vap-0(ath1):
[9c:c9:eb:19:92:7d]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Fri Jan 8 12:45:58 2021 user.notice led_function: =====LOOP END=====
Fri Jan 8 12:45:58 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:45:59 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-2(ath01):wlan_get_key: invalid key
Fri Jan 8 12:46:00 2021 kern.warn kernel: vap-0(ath2):wlan_get_key: invalid
keyvap-0(ath2):wlan_get_key: invalid key
Fri Jan 8 12:46:00 2021 user.debug repacd.wifimon: WPS CHECK LOOP:1 wps:
Fri Jan 8 12:46:00 2021 user.debug repacd.wifimon: CHECK associatd
Fri Jan 8 12:46:00 2021 user.debug repacd.wifimon: All backhaul connected
Fri Jan 8 12:46:01 2021 user.debug repacd.wifimon: [repacd]Network associated
Fri Jan 8 12:46:01 2021 user.info repacd: RE_LocationSuitable
Fri Jan 8 12:46:01 2021 user.info repacd: LED SOLID TIMES--47
Fri Jan 8 12:46:01 2021 user.info repacd: Boot time count=-1
```