

```

May 23 13:27:24 XR1000 local1.notice CEVENT_APP[16072]: 1653312444844 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:27:24 XR1000 local1.notice CEVENT_APP[16072]: 1653312444844 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312444844] 243
May 23 13:27:24 XR1000 local1.notice CEVENT_APP[16072]: 1653312444904 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC/7 163
May 23 13:27:24 XR1000 local1.notice CEVENT_APP[16072]: 1653312444904 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX ASSOC_RX [CE: 1
24 1/0x0001/CE_D2C 24 7/0x0007/ASSOC_RX 0x40000000 1653312444904] 243
May 23 13:27:24 XR1000 local1.notice CEVENT_APP[16072]: 1653312444904 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX ASSOC_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 1/0x0001/ASSOC_TX 0x80000000 1653312444904] 243
May 23 13:27:24 XR1000 local1.notice CEVENT_APP[16072]: 1653312444905 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC_IND/8 163
May 23 13:27:24 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
associated 100
May 23 13:27:25 XR1000 local1.notice CEVENT_APP[16072]: 1653312445020 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312445020] 243
May 23 13:27:25 XR1000 local1.notice CEVENT_APP[16072]: 1653312445202 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC/7 163
May 23 13:27:25 XR1000 local1.notice CEVENT_APP[16072]: 1653312445202 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX ASSOC_RX [CE: 1
24 1/0x0001/CE_D2C 24 7/0x0007/ASSOC_RX 0x40000000 1653312445202] 243
May 23 13:27:25 XR1000 local1.notice CEVENT_APP[16072]: 1653312445203 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX ASSOC_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 1/0x0001/ASSOC_TX 0x80000000 1653312445203] 243
May 23 13:27:25 XR1000 local1.notice CEVENT_APP[16072]: 1653312445204 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC_IND/8 163
May 23 13:27:25 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
associated 100
May 23 13:27:25 XR1000 local1.notice CEVENT_APP[16072]: 1653312445228 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312445228] 243
May 23 13:27:25 XR1000 local1.notice CEVENT_APP[16072]: 1653312445502 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312445502] 243
May 23 13:27:25 XR1000 local1.notice CEVENT_APP[16072]: 1653312445509 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312445509] 243
May 23 13:27:25 XR1000 local1.notice CEVENT_APP[16072]: 1653312445509 wl0
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M2_RX [CE: 1
159 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312445509] 243
May 23 13:27:26 XR1000 local1.notice CEVENT_APP[16072]: 1653312446026 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312446026] 243
May 23 13:27:26 XR1000 local1.notice CEVENT_APP[16072]: 1653312446231 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312446231] 243

```

```

May 23 13:27:26 XR1000 local1.notice CEVENT_APP[16072]: 1653312446499 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312446499] 243
May 23 13:27:26 XR1000 local1.notice CEVENT_APP[16072]: 1653312446504 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312446504] 243
May 23 13:27:26 XR1000 local1.notice CEVENT_APP[16072]: 1653312446504 w10
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M2_RX [CE: 1
159 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312446504] 243
May 23 13:27:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312447029 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312447029] 243
May 23 13:27:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312447234 w10
80:9F:9B:5A:F7:DB 0 0000 0002 0000 Driver TX DEAUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 4/0x0004/DEAUTH_TX 0x80000000 1653312447234] 244
May 23 13:27:29 XR1000 local1.notice CEVENT_APP[16072]: 1653312449083 w10
80:9F:9B:5A:F7:DB 0 0000 0003 0000 Driver -- E_DEAUTH/5 163
May 23 13:27:29 XR1000 local1.notice CEVENT_APP[16072]: 1653312449456 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_FAIL [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000002 1653312449456] 243
May 23 13:27:29 XR1000 local1.notice CEVENT_APP[16072]: 1653312449457 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_FAIL [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000002 1653312449457] 243
May 23 13:27:29 XR1000 local1.notice CEVENT_APP[16072]: 1653312449457 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_FAIL [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000002 1653312449457] 243
May 23 13:27:32 XR1000 daemon.info hostapd: w10: STA 80:9f:9b:5a:f7:db IEEE 802.11:
deauthenticated due to local death request 133
May 23 13:27:39 XR1000 local1.notice CEVENT_APP[16072]: 1653312459426 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312459426] 243
May 23 13:27:39 XR1000 local1.notice CEVENT_APP[16072]: 1653312459428 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:27:39 XR1000 local1.notice CEVENT_APP[16072]: 1653312459430 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312459430] 243
May 23 13:27:39 XR1000 local1.notice CEVENT_APP[16072]: 1653312459431 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312459431] 243
May 23 13:27:39 XR1000 local1.notice CEVENT_APP[16072]: 1653312459432 w10
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:27:39 XR1000 local1.notice CEVENT_APP[16072]: 1653312459432 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:27:39 XR1000 local1.notice CEVENT_APP[16072]: 1653312459431 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312459431] 243
May 23 13:27:39 XR1000 daemon.info hostapd: w10: STA 80:9f:9b:5a:f7:db IEEE 802.11:
associated 100
May 23 13:27:39 XR1000 local1.notice CEVENT_APP[16072]: 1653312459477 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC/7 163

```

```

May 23 13:27:39 XR1000 local1.notice CEVENT_APP[16072]: 1653312459477 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX ASSOC_RX [CE: 1
24 1/0x0001/CE_D2C 24 7/0x0007/ASSOC_RX 0x40000000 1653312459477] 243
May 23 13:27:39 XR1000 local1.notice CEVENT_APP[16072]: 1653312459477 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX ASSOC_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 1/0x0001/ASSOC_TX 0x80000000 1653312459477] 243
May 23 13:27:39 XR1000 local1.notice CEVENT_APP[16072]: 1653312459478 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC_IND/8 163
May 23 13:27:39 XR1000 local1.notice CEVENT_APP[16072]: 1653312459498 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312459498] 243
May 23 13:27:39 XR1000 local1.notice CEVENT_APP[16072]: 1653312459503 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312459503] 243
May 23 13:27:40 XR1000 local1.notice CEVENT_APP[16072]: 1653312460501 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312460501] 243
May 23 13:27:41 XR1000 local1.notice CEVENT_APP[16072]: 1653312461206 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312461206] 243
May 23 13:27:41 XR1000 local1.notice CEVENT_APP[16072]: 1653312461210 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312461210] 243
May 23 13:27:41 XR1000 local1.notice CEVENT_APP[16072]: 1653312461211 w10
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M2_RX [CE: 1
159 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312461211] 243
May 23 13:27:41 XR1000 local1.notice CEVENT_APP[16072]: 1653312461211 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312461211] 243
May 23 13:27:42 XR1000 local1.notice CEVENT_APP[16072]: 1653312462215 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312462215] 243
May 23 13:27:43 XR1000 local1.notice CEVENT_APP[16072]: 1653312463217 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312463217] 243
May 23 13:27:44 XR1000 local1.notice CEVENT_APP[16072]: 1653312464121 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312464121] 243
May 23 13:27:44 XR1000 local1.notice CEVENT_APP[16072]: 1653312464126 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312464126] 243
May 23 13:27:44 XR1000 local1.notice CEVENT_APP[16072]: 1653312464127 w10
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M4_RX [CE: 1
137 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312464127] 243
May 23 13:27:44 XR1000 daemon.info hostapd: w10: STA 80:9f:9b:5a:f7:db RADIUS:
starting accounting session 09369DE52E784FAC 129
May 23 13:27:44 XR1000 daemon.info hostapd: w10: STA 80:9f:9b:5a:f7:db WPA: pairwise
key handshake completed (RSN) 120
May 23 13:27:44 XR1000 local1.notice CEVENT_APP[16072]: 1653312464129 w10
80:9F:9B:5A:F7:DB 0 0136 0000 0000 Driver -- E_AUTHORIZED/136 163

```

```

May 23 13:27:44 XR1000 local1.notice CEVENT_APP[16072]: 1653312464522 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312464522] 243
May 23 13:27:44 XR1000 local1.notice CEVENT_APP[16072]: 1653312464526 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312464526] 243
May 23 13:27:44 XR1000 local1.notice CEVENT_APP[16072]: 1653312464527 wl0
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M4_RX [CE: 1
137 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312464527] 243
May 23 13:27:44 XR1000 local1.notice CEVENT_APP[16072]: 1653312464726 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312464726] 243
May 23 13:27:44 XR1000 local1.notice CEVENT_APP[16072]: 1653312464730 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312464730] 243
May 23 13:27:44 XR1000 local1.notice CEVENT_APP[16072]: 1653312464731 wl0
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M4_RX [CE: 1
137 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312464731] 243
May 23 13:27:51 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
disassociated 103
May 23 13:27:51 XR1000 local1.notice CEVENT_APP[16072]: 1653312471910 wl0
80:9F:9B:5A:F7:DB 0 0000 0003 0000 Driver -- E_DEAUTH_IND/6 163
May 23 13:27:51 XR1000 local1.notice CEVENT_APP[16072]: 1653312471910 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX DEAUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 10/0x000A/DEAUTH_RX 0x40000000 1653312471910] 244
May 23 13:27:51 XR1000 local1.notice CEVENT_APP[16072]: 1653312471920 wl0
80:9F:9B:5A:F7:DB 24 0000 0000 0000 Driver RX DEAUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 10/0x000A/DEAUTH_RX 0x40000000 1653312471920] 244
May 23 13:27:51 XR1000 local1.notice CEVENT_APP[16072]: 1653312471943 wl0
80:9F:9B:5A:F7:DB 0 0000 0007 0000 Driver -- E_DEAUTH/5 163
May 23 13:27:51 XR1000 local1.notice CEVENT_APP[16072]: 1653312471976 wl0
80:9F:9B:5A:F7:DB 0 0000 0007 0000 Driver -- E_DEAUTH/5 163
May 23 13:27:54 XR1000 local1.notice CEVENT_APP[16072]: 1653312474662 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312474662] 243
May 23 13:27:54 XR1000 local1.notice CEVENT_APP[16072]: 1653312474663 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:27:54 XR1000 local1.notice CEVENT_APP[16072]: 1653312474663 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312474663] 243
May 23 13:27:54 XR1000 local1.notice CEVENT_APP[16072]: 1653312474964 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312474964] 243
May 23 13:27:54 XR1000 local1.notice CEVENT_APP[16072]: 1653312474966 wl0
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:27:54 XR1000 local1.notice CEVENT_APP[16072]: 1653312474966 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:27:54 XR1000 local1.notice CEVENT_APP[16072]: 1653312474966 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312474966] 243

```

```

May 23 13:27:55 XR1000 local1.notice CEVENT_APP[16072]: 1653312475264 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312475264] 243
May 23 13:27:55 XR1000 local1.notice CEVENT_APP[16072]: 1653312475265 wl0
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:27:55 XR1000 local1.notice CEVENT_APP[16072]: 1653312475265 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:27:55 XR1000 local1.notice CEVENT_APP[16072]: 1653312475265 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312475265] 243
May 23 13:27:55 XR1000 local1.notice CEVENT_APP[16072]: 1653312475566 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312475566] 243
May 23 13:27:55 XR1000 local1.notice CEVENT_APP[16072]: 1653312475566 wl0
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:27:55 XR1000 local1.notice CEVENT_APP[16072]: 1653312475567 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:27:55 XR1000 local1.notice CEVENT_APP[16072]: 1653312475567 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312475567] 243
May 23 13:27:55 XR1000 local1.notice CEVENT_APP[16072]: 1653312475864 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312475864] 243
May 23 13:27:55 XR1000 local1.notice CEVENT_APP[16072]: 1653312475865 wl0
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:27:55 XR1000 local1.notice CEVENT_APP[16072]: 1653312475866 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:27:55 XR1000 local1.notice CEVENT_APP[16072]: 1653312475866 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312475866] 243
May 23 13:27:56 XR1000 local1.notice CEVENT_APP[16072]: 1653312476100 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC/7 163
May 23 13:27:56 XR1000 local1.notice CEVENT_APP[16072]: 1653312476100 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX ASSOC_RX [CE: 1
24 1/0x0001/CE_D2C 24 7/0x0007/ASSOC_RX 0x40000000 1653312476100] 243
May 23 13:27:56 XR1000 local1.notice CEVENT_APP[16072]: 1653312476103 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX ASSOC_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 1/0x0001/ASSOC_TX 0x80000000 1653312476103] 243
May 23 13:27:56 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
associated 100
May 23 13:27:56 XR1000 local1.notice CEVENT_APP[16072]: 1653312476111 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC_IND/8 163
May 23 13:27:56 XR1000 local1.notice CEVENT_APP[16072]: 1653312476118 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312476118] 243
May 23 13:27:56 XR1000 local1.notice CEVENT_APP[16072]: 1653312476394 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC/7 163
May 23 13:27:56 XR1000 local1.notice CEVENT_APP[16072]: 1653312476394 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX ASSOC_RX [CE: 1
24 1/0x0001/CE_D2C 24 7/0x0007/ASSOC_RX 0x40000000 1653312476394] 243

```

```

May 23 13:27:56 XR1000 local1.notice CEVENT_APP[16072]: 1653312476394 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX ASSOC_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 1/0x0001/ASSOC_TX 0x80000000 1653312476394] 243
May 23 13:27:56 XR1000 daemon.info hostapd: w10: STA 80:9f:9b:5a:f7:db IEEE 802.11:
associated 100
May 23 13:27:56 XR1000 local1.notice CEVENT_APP[16072]: 1653312476401 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC_IND/8 163
May 23 13:27:56 XR1000 local1.notice CEVENT_APP[16072]: 1653312476412 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312476412] 243
May 23 13:27:56 XR1000 daemon.info hostapd: w10: STA 80:9f:9b:5a:f7:db IEEE 802.11:
associated 100
May 23 13:27:56 XR1000 local1.notice CEVENT_APP[16072]: 1653312476694 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC/7 163
May 23 13:27:56 XR1000 local1.notice CEVENT_APP[16072]: 1653312476694 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX ASSOC_RX [CE: 1
24 1/0x0001/CE_D2C 24 7/0x0007/ASSOC_RX 0x40000000 1653312476694] 243
May 23 13:27:56 XR1000 local1.notice CEVENT_APP[16072]: 1653312476694 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX ASSOC_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 1/0x0001/ASSOC_TX 0x80000000 1653312476694] 243
May 23 13:27:56 XR1000 local1.notice CEVENT_APP[16072]: 1653312476696 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC_IND/8 163
May 23 13:27:56 XR1000 local1.notice CEVENT_APP[16072]: 1653312476708 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312476708] 243
May 23 13:27:57 XR1000 local1.notice CEVENT_APP[16072]: 1653312477121 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312477121] 243
May 23 13:27:57 XR1000 local1.notice CEVENT_APP[16072]: 1653312477415 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312477415] 243
May 23 13:27:57 XR1000 local1.notice CEVENT_APP[16072]: 1653312477672 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312477672] 243
May 23 13:27:57 XR1000 local1.notice CEVENT_APP[16072]: 1653312477678 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312477678] 243
May 23 13:27:57 XR1000 local1.notice CEVENT_APP[16072]: 1653312477679 w10
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M2_RX [CE: 1
159 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312477679] 243
May 23 13:27:57 XR1000 local1.notice CEVENT_APP[16072]: 1653312477709 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312477709] 243
May 23 13:27:58 XR1000 local1.notice CEVENT_APP[16072]: 1653312478123 w10
80:9F:9B:5A:F7:DB 0 0000 0002 0000 Driver TX DEAUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 4/0x0004/DEAUTH_TX 0x80000000 1653312478123] 244
May 23 13:27:59 XR1000 local1.notice CEVENT_APP[16072]: 1653312479199 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312479199] 243
May 23 13:27:59 XR1000 local1.notice CEVENT_APP[16072]: 1653312479200 w10

```

```

80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
 24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312479200] 243
May 23 13:27:59 XR1000 local1.notice CEVENT_APP[16072]: 1653312479202 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
 24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312479202] 243
May 23 13:27:59 XR1000 local1.notice CEVENT_APP[16072]: 1653312479206 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
 24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312479206] 243
May 23 13:27:59 XR1000 local1.notice CEVENT_APP[16072]: 1653312479207 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
 24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312479207] 243
May 23 13:27:59 XR1000 local1.notice CEVENT_APP[16072]: 1653312479207 wl0
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M2_RX [CE: 1
159 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312479207] 243
May 23 13:27:59 XR1000 local1.notice CEVENT_APP[16072]: 1653312479211 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
 24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312479211] 243
May 23 13:27:59 XR1000 local1.notice CEVENT_APP[16072]: 1653312479212 wl0
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M2_RX [CE: 1
159 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312479212] 243
May 23 13:27:59 XR1000 local1.notice CEVENT_APP[16072]: 1653312479213 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
 24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312479213] 243
May 23 13:27:59 XR1000 local1.notice CEVENT_APP[16072]: 1653312479213 wl0
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M2_RX [CE: 1
159 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312479213] 243
May 23 13:27:59 XR1000 local1.notice CEVENT_APP[16072]: 1653312479220 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
 24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312479220] 243
May 23 13:27:59 XR1000 local1.notice CEVENT_APP[16072]: 1653312479221 wl0
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M2_RX [CE: 1
159 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312479221] 243
May 23 13:28:00 XR1000 local1.notice CEVENT_APP[16072]: 1653312480454 wl0
80:9F:9B:5A:F7:DB 0 0000 0003 0000 Driver -- E_DEAUTH/5 163
May 23 13:28:02 XR1000 local1.notice CEVENT_APP[16072]: 1653312482594 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
 24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312482594] 243
May 23 13:28:02 XR1000 local1.notice CEVENT_APP[16072]: 1653312482602 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
 24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312482602] 243
May 23 13:28:02 XR1000 local1.notice CEVENT_APP[16072]: 1653312482603 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:28:02 XR1000 local1.notice CEVENT_APP[16072]: 1653312482603 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
 24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312482603] 243
May 23 13:28:02 XR1000 local1.notice CEVENT_APP[16072]: 1653312482603 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
 24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312482603] 243
May 23 13:28:02 XR1000 local1.notice CEVENT_APP[16072]: 1653312482604 wl0
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163

```

```

May 23 13:28:02 XR1000 local1.notice CEVENT_APP[16072]: 1653312482604 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:28:02 XR1000 local1.notice CEVENT_APP[16072]: 1653312482603 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312482603] 243
May 23 13:28:02 XR1000 local1.notice CEVENT_APP[16072]: 1653312482900 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312482900] 243
May 23 13:28:02 XR1000 local1.notice CEVENT_APP[16072]: 1653312482901 wl0
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:28:02 XR1000 local1.notice CEVENT_APP[16072]: 1653312482902 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:28:02 XR1000 local1.notice CEVENT_APP[16072]: 1653312482901 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312482901] 243
May 23 13:28:03 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
deauthenticated due to local death request 133
May 23 13:28:03 XR1000 local1.notice CEVENT_APP[16072]: 1653312483126 wl0
80:9F:9B:5A:F7:DB 0 0000 0002 0000 Driver TX DEAUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 4/0x0004/DEAUTH_TX 0x80000000 1653312483126] 244
May 23 13:28:03 XR1000 local1.notice CEVENT_APP[16072]: 1653312483200 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312483200] 243
May 23 13:28:03 XR1000 local1.notice CEVENT_APP[16072]: 1653312483201 wl0
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:28:03 XR1000 local1.notice CEVENT_APP[16072]: 1653312483201 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:28:03 XR1000 local1.notice CEVENT_APP[16072]: 1653312483201 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312483201] 243
May 23 13:28:03 XR1000 local1.notice CEVENT_APP[16072]: 1653312483500 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312483500] 243
May 23 13:28:03 XR1000 local1.notice CEVENT_APP[16072]: 1653312483501 wl0
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:28:03 XR1000 local1.notice CEVENT_APP[16072]: 1653312483501 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:28:03 XR1000 local1.notice CEVENT_APP[16072]: 1653312483501 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312483501] 243
May 23 13:28:03 XR1000 local1.notice CEVENT_APP[16072]: 1653312483800 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312483800] 243
May 23 13:28:03 XR1000 local1.notice CEVENT_APP[16072]: 1653312483802 wl0
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:28:03 XR1000 local1.notice CEVENT_APP[16072]: 1653312483802 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:28:03 XR1000 local1.notice CEVENT_APP[16072]: 1653312483801 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312483801] 243

```



```

May 23 13:28:06 XR1000 local1.notice CEVENT_APP[16072]: 1653312486031 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312486031] 243
May 23 13:28:06 XR1000 local1.notice CEVENT_APP[16072]: 1653312486032 wl0
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:28:06 XR1000 local1.notice CEVENT_APP[16072]: 1653312486032 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:28:06 XR1000 local1.notice CEVENT_APP[16072]: 1653312486032 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312486032] 243
May 23 13:28:06 XR1000 local1.notice CEVENT_APP[16072]: 1653312486328 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312486328] 243
May 23 13:28:06 XR1000 local1.notice CEVENT_APP[16072]: 1653312486329 wl0
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:28:06 XR1000 local1.notice CEVENT_APP[16072]: 1653312486329 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:28:06 XR1000 local1.notice CEVENT_APP[16072]: 1653312486329 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312486329] 243
May 23 13:28:06 XR1000 local1.notice CEVENT_APP[16072]: 1653312486409 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC/7 163
May 23 13:28:06 XR1000 local1.notice CEVENT_APP[16072]: 1653312486409 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX ASSOC_RX [CE: 1
24 1/0x0001/CE_D2C 24 7/0x0007/ASSOC_RX 0x40000000 1653312486409] 243
May 23 13:28:06 XR1000 local1.notice CEVENT_APP[16072]: 1653312486409 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX ASSOC_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 1/0x0001/ASSOC_TX 0x80000000 1653312486409] 243
May 23 13:28:06 XR1000 local1.notice CEVENT_APP[16072]: 1653312486411 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC_IND/8 163
May 23 13:28:06 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
associated 100
May 23 13:28:06 XR1000 local1.notice CEVENT_APP[16072]: 1653312486488 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312486488] 243
May 23 13:28:06 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
associated 100
May 23 13:28:06 XR1000 local1.notice CEVENT_APP[16072]: 1653312486707 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC/7 163
May 23 13:28:06 XR1000 local1.notice CEVENT_APP[16072]: 1653312486707 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX ASSOC_RX [CE: 1
24 1/0x0001/CE_D2C 24 7/0x0007/ASSOC_RX 0x40000000 1653312486707] 243
May 23 13:28:06 XR1000 local1.notice CEVENT_APP[16072]: 1653312486707 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX ASSOC_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 1/0x0001/ASSOC_TX 0x80000000 1653312486707] 243
May 23 13:28:06 XR1000 local1.notice CEVENT_APP[16072]: 1653312486715 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC_IND/8 163
May 23 13:28:06 XR1000 local1.notice CEVENT_APP[16072]: 1653312486724 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312486724] 243

```

```

May 23 13:28:07 XR1000 local1.notice CEVENT_APP[16072]: 1653312487046 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312487046] 243
May 23 13:28:07 XR1000 local1.notice CEVENT_APP[16072]: 1653312487051 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312487051] 243
May 23 13:28:07 XR1000 local1.notice CEVENT_APP[16072]: 1653312487051 wl0
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M2_RX [CE: 1
159 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312487051] 243
May 23 13:28:07 XR1000 local1.notice CEVENT_APP[16072]: 1653312487053 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312487053] 243
May 23 13:28:07 XR1000 local1.notice CEVENT_APP[16072]: 1653312487056 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312487056] 243
May 23 13:28:07 XR1000 local1.notice CEVENT_APP[16072]: 1653312487056 wl0
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M2_RX [CE: 1
159 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312487056] 243
May 23 13:28:07 XR1000 local1.notice CEVENT_APP[16072]: 1653312487493 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312487493] 243
May 23 13:28:07 XR1000 local1.notice CEVENT_APP[16072]: 1653312487664 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312487664] 243
May 23 13:28:07 XR1000 local1.notice CEVENT_APP[16072]: 1653312487668 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312487668] 243
May 23 13:28:07 XR1000 local1.notice CEVENT_APP[16072]: 1653312487669 wl0
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M2_RX [CE: 1
159 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312487669] 243
May 23 13:28:07 XR1000 local1.notice CEVENT_APP[16072]: 1653312487669 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312487669] 243
May 23 13:28:07 XR1000 local1.notice CEVENT_APP[16072]: 1653312487684 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312487684] 243
May 23 13:28:07 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db RADIUS:
starting accounting session 3E3EF1DA8D0513D1 129
May 23 13:28:07 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db WPA: pairwise
key handshake completed (RSN) 120
May 23 13:28:07 XR1000 local1.notice CEVENT_APP[16072]: 1653312487691 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312487691] 243
May 23 13:28:07 XR1000 local1.notice CEVENT_APP[16072]: 1653312487691 wl0
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M4_RX [CE: 1
137 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312487691] 243
May 23 13:28:07 XR1000 local1.notice CEVENT_APP[16072]: 1653312487693 wl0
80:9F:9B:5A:F7:DB 0 0136 0000 0000 Driver -- E_AUTHORIZED/136 163
May 23 13:28:19 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
disassociated 103

```

```

May 23 13:28:19 XR1000 local1.notice CEVENT_APP[16072]: 1653312499420 wl0
80:9F:9B:5A:F7:DB 0 0000 0003 0000 Driver -- E_DEAUTH_IND/6 163
May 23 13:28:19 XR1000 local1.notice CEVENT_APP[16072]: 1653312499419 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX DEAUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 10/0x000A/DEAUTH_RX 0x40000000 1653312499419] 244
May 23 13:28:19 XR1000 local1.notice CEVENT_APP[16072]: 1653312499439 wl0
80:9F:9B:5A:F7:DB 0 0000 0007 0000 Driver -- E_DEAUTH/5 163
May 23 13:28:19 XR1000 local1.notice CEVENT_APP[16072]: 1653312499443 wl0
80:9F:9B:5A:F7:DB 0 0000 0007 0000 Driver -- E_DEAUTH/5 163
May 23 13:28:19 XR1000 local1.notice CEVENT_APP[16072]: 1653312499463 wl0
80:9F:9B:5A:F7:DB 0 0000 0007 0000 Driver -- E_DEAUTH/5 163
May 23 13:28:37 XR1000 local1.notice CEVENT_APP[16072]: 1653312517656 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312517656] 243
May 23 13:28:37 XR1000 local1.notice CEVENT_APP[16072]: 1653312517657 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:28:37 XR1000 local1.notice CEVENT_APP[16072]: 1653312517657 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312517657] 243
May 23 13:28:37 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
associated 100
May 23 13:28:37 XR1000 local1.notice CEVENT_APP[16072]: 1653312517675 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC/7 163
May 23 13:28:37 XR1000 local1.notice CEVENT_APP[16072]: 1653312517675 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX ASSOC_RX [CE: 1
24 1/0x0001/CE_D2C 24 7/0x0007/ASSOC_RX 0x40000000 1653312517675] 243
May 23 13:28:37 XR1000 local1.notice CEVENT_APP[16072]: 1653312517675 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX ASSOC_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 1/0x0001/ASSOC_TX 0x80000000 1653312517675] 243
May 23 13:28:37 XR1000 local1.notice CEVENT_APP[16072]: 1653312517676 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC_IND/8 163
May 23 13:28:37 XR1000 local1.notice CEVENT_APP[16072]: 1653312517689 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312517689] 243
May 23 13:28:37 XR1000 local1.notice CEVENT_APP[16072]: 1653312517690 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312517690] 243
May 23 13:28:37 XR1000 local1.notice CEVENT_APP[16072]: 1653312517705 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312517705] 243
May 23 13:28:37 XR1000 local1.notice CEVENT_APP[16072]: 1653312517706 wl0
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M2_RX [CE: 1
159 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312517706] 243
May 23 13:28:37 XR1000 local1.notice CEVENT_APP[16072]: 1653312517707 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312517707] 243
May 23 13:28:37 XR1000 local1.notice CEVENT_APP[16072]: 1653312517946 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312517946] 243
May 23 13:28:37 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db RADIUS:

```

```

starting accounting session F6E8385C5E8556AC 129
May 23 13:28:37 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db WPA: pairwise
key handshake completed (RSN) 120
May 23 13:28:37 XR1000 local1.notice CEVENT_APP[16072]: 1653312517950 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312517950] 243
May 23 13:28:37 XR1000 local1.notice CEVENT_APP[16072]: 1653312517950 wl0
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M4_RX [CE: 1
137 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312517950] 243
May 23 13:28:37 XR1000 local1.notice CEVENT_APP[16072]: 1653312517951 wl0
80:9F:9B:5A:F7:DB 0 0136 0000 0000 Driver -- E_AUTHORIZED/136 163
May 23 08:28:38 XR1000 user.warn com.netdumasoftware.procmanager: Rapp
com.netdumasoftware.pingheatmap has not responded to watchdog 138
May 23 13:28:44 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
disassociated 103
May 23 13:28:44 XR1000 local1.notice CEVENT_APP[16072]: 1653312524309 wl0
80:9F:9B:5A:F7:DB 0 0000 0003 0000 Driver -- E_DEAUTH_IND/6 163
May 23 13:28:44 XR1000 local1.notice CEVENT_APP[16072]: 1653312524309 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX DEAUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 10/0x000A/DEAUTH_RX 0x40000000 1653312524309] 244
May 23 13:28:44 XR1000 local1.notice CEVENT_APP[16072]: 1653312524328 wl0
80:9F:9B:5A:F7:DB 0 0000 0007 0000 Driver -- E_DEAUTH/5 163
May 23 13:28:44 XR1000 local1.notice CEVENT_APP[16072]: 1653312524335 wl0
80:9F:9B:5A:F7:DB 0 0000 0007 0000 Driver -- E_DEAUTH/5 163
May 23 13:28:46 XR1000 local1.notice CEVENT_APP[16072]: 1653312526956 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312526956] 243
May 23 13:28:46 XR1000 local1.notice CEVENT_APP[16072]: 1653312526956 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:28:46 XR1000 local1.notice CEVENT_APP[16072]: 1653312526956 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312526956] 243
May 23 13:28:47 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
associated 100
May 23 13:28:47 XR1000 local1.notice CEVENT_APP[16072]: 1653312527117 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC/7 163
May 23 13:28:47 XR1000 local1.notice CEVENT_APP[16072]: 1653312527116 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX ASSOC_RX [CE: 1
24 1/0x0001/CE_D2C 24 7/0x0007/ASSOC_RX 0x40000000 1653312527116] 243
May 23 13:28:47 XR1000 local1.notice CEVENT_APP[16072]: 1653312527117 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX ASSOC_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 1/0x0001/ASSOC_TX 0x80000000 1653312527117] 243
May 23 13:28:47 XR1000 local1.notice CEVENT_APP[16072]: 1653312527118 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC_IND/8 163
May 23 13:28:47 XR1000 local1.notice CEVENT_APP[16072]: 1653312527131 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312527131] 243
May 23 13:28:47 XR1000 local1.notice CEVENT_APP[16072]: 1653312527623 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312527623] 243

```

```

May 23 13:28:47 XR1000 local1.notice CEVENT_APP[16072]: 1653312527627 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312527627] 243
May 23 13:28:47 XR1000 local1.notice CEVENT_APP[16072]: 1653312527628 wl0
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M2_RX [CE: 1
159 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312527628] 243
May 23 13:28:47 XR1000 local1.notice CEVENT_APP[16072]: 1653312527629 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312527629] 243
May 23 13:28:47 XR1000 local1.notice CEVENT_APP[16072]: 1653312527804 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312527804] 243
May 23 13:28:47 XR1000 local1.notice CEVENT_APP[16072]: 1653312527809 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312527809] 243
May 23 13:28:47 XR1000 local1.notice CEVENT_APP[16072]: 1653312527810 wl0
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M4_RX [CE: 1
137 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312527810] 243
May 23 13:28:47 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db RADIUS:
starting accounting session 5DCB78E854DEAEEC 129
May 23 13:28:47 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db WPA: pairwise
key handshake completed (RSN) 120
May 23 13:28:47 XR1000 local1.notice CEVENT_APP[16072]: 1653312527814 wl0
80:9F:9B:5A:F7:DB 0 0136 0000 0000 Driver -- E_AUTHORIZED/136 163
May 23 08:28:52 XR1000 user.info com.netdumasoftware.neighwatch: DHCP new event. 86
May 23 08:28:52 XR1000 user.info com.netdumasoftware.neighwatch: DHCP lease change.
89
May 23 08:28:55 XR1000 user.info com.netdumasoftware.neighwatch: DHCP new event. 86
May 23 08:28:55 XR1000 user.info com.netdumasoftware.neighwatch: DHCP lease change.
89
May 23 08:28:58 XR1000 user.info com.netdumasoftware.neighwatch: DHCP new event. 86
May 23 08:28:58 XR1000 user.info com.netdumasoftware.neighwatch: DHCP lease change.
89
May 23 13:29:20 XR1000 local1.notice CEVENT_APP[16072]: 1653312560814 wl0
80:9F:9B:5A:F7:DB 0 0000 0003 0000 Driver -- E_DEAUTH_IND/6 163
May 23 13:29:20 XR1000 local1.notice CEVENT_APP[16072]: 1653312560814 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX DEAUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 10/0x000A/DEAUTH_RX 0x40000000 1653312560814] 244
May 23 13:29:20 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
disassociated 103
May 23 13:29:20 XR1000 local1.notice CEVENT_APP[16072]: 1653312560824 wl0
80:9F:9B:5A:F7:DB 24 0000 0000 0000 Driver RX DEAUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 10/0x000A/DEAUTH_RX 0x40000000 1653312560824] 244
May 23 13:29:22 XR1000 local1.notice CEVENT_APP[16072]: 1653312562692 wl0
34:9F:7B:2C:D8:6E 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312562692] 243
May 23 13:29:22 XR1000 local1.notice CEVENT_APP[16072]: 1653312562697 wl0
34:9F:7B:2C:D8:6E 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:29:22 XR1000 local1.notice CEVENT_APP[16072]: 1653312562698 wl0
34:9F:7B:2C:D8:6E 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163

```

```

May 23 13:29:22 XR1000 local1.notice CEVENT_APP[16072]: 1653312562698 wl0
34:9F:7B:2C:D8:6E 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312562698] 243
May 23 13:29:22 XR1000 local1.notice CEVENT_APP[16072]: 1653312562820 wl0
34:9F:7B:2C:D8:6E 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312562820] 243
May 23 13:29:22 XR1000 local1.notice CEVENT_APP[16072]: 1653312562821 wl0
34:9F:7B:2C:D8:6E 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:29:22 XR1000 local1.notice CEVENT_APP[16072]: 1653312562821 wl0
34:9F:7B:2C:D8:6E 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:29:22 XR1000 local1.notice CEVENT_APP[16072]: 1653312562821 wl0
34:9F:7B:2C:D8:6E 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312562821] 243
May 23 13:29:23 XR1000 local1.notice CEVENT_APP[16072]: 1653312563445 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312563445] 243
May 23 13:29:23 XR1000 local1.notice CEVENT_APP[16072]: 1653312563445 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:29:23 XR1000 local1.notice CEVENT_APP[16072]: 1653312563445 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312563445] 243
May 23 13:29:23 XR1000 local1.notice CEVENT_APP[16072]: 1653312563626 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC/7 163
May 23 13:29:23 XR1000 local1.notice CEVENT_APP[16072]: 1653312563626 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX ASSOC_RX [CE: 1
24 1/0x0001/CE_D2C 24 7/0x0007/ASSOC_RX 0x40000000 1653312563626] 243
May 23 13:29:23 XR1000 local1.notice CEVENT_APP[16072]: 1653312563626 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX ASSOC_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 1/0x0001/ASSOC_TX 0x80000000 1653312563626] 243
May 23 13:29:23 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
associated 100
May 23 13:29:23 XR1000 local1.notice CEVENT_APP[16072]: 1653312563633 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC_IND/8 163
May 23 13:29:23 XR1000 local1.notice CEVENT_APP[16072]: 1653312563642 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312563642] 243
May 23 13:29:23 XR1000 local1.notice CEVENT_APP[16072]: 1653312563645 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312563645] 243
May 23 13:29:24 XR1000 local1.notice CEVENT_APP[16072]: 1653312564646 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312564646] 243
May 23 13:29:25 XR1000 local1.notice CEVENT_APP[16072]: 1653312565095 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_FAIL [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000002 1653312565095] 243
May 23 13:29:25 XR1000 local1.notice CEVENT_APP[16072]: 1653312565245 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312565245] 243
May 23 13:29:25 XR1000 local1.notice CEVENT_APP[16072]: 1653312565250 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1

```

```

24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312565250] 243
May 23 13:29:25 XR1000 local1.notice CEVENT_APP[16072]: 1653312565251 wl0
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M2_RX [CE: 1
159 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312565251] 243
May 23 13:29:25 XR1000 local1.notice CEVENT_APP[16072]: 1653312565251 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312565251] 243
May 23 13:29:25 XR1000 local1.notice CEVENT_APP[16072]: 1653312565392 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312565392] 243
May 23 13:29:25 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db RADIUS:
starting accounting session C9050FEE7E1AB666 129
May 23 13:29:25 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db WPA: pairwise
key handshake completed (RSN) 120
May 23 13:29:25 XR1000 local1.notice CEVENT_APP[16072]: 1653312565403 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312565403] 243
May 23 13:29:25 XR1000 local1.notice CEVENT_APP[16072]: 1653312565404 wl0
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M4_RX [CE: 1
137 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312565404] 243
May 23 13:29:25 XR1000 local1.notice CEVENT_APP[16072]: 1653312565404 wl0
80:9F:9B:5A:F7:DB 0 0136 0000 0000 Driver -- E_AUTHORIZED/136 163
May 23 08:29:31 XR1000 user.info com.netdumasoftware.neighwatch: DHCP new event. 86
May 23 08:29:31 XR1000 user.info com.netdumasoftware.neighwatch: DHCP lease change.
89
May 23 08:29:34 XR1000 user.info com.netdumasoftware.neighwatch: DHCP new event. 86
May 23 08:29:34 XR1000 user.info com.netdumasoftware.neighwatch: DHCP lease change.
89
May 23 08:29:37 XR1000 user.info com.netdumasoftware.neighwatch: DHCP new event. 86
May 23 08:29:37 XR1000 user.info com.netdumasoftware.neighwatch: DHCP lease change.
89
May 23 13:29:51 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
disassociated 103
May 23 13:29:51 XR1000 local1.notice CEVENT_APP[16072]: 1653312591343 wl0
80:9F:9B:5A:F7:DB 0 0000 0003 0000 Driver -- E_DEAUTH_IND/6 163
May 23 13:29:51 XR1000 local1.notice CEVENT_APP[16072]: 1653312591343 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX DEAUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 10/0x000A/DEAUTH_RX 0x40000000 1653312591343] 244
May 23 13:29:51 XR1000 local1.notice CEVENT_APP[16072]: 1653312591354 wl0
80:9F:9B:5A:F7:DB 24 0000 0000 0000 Driver RX DEAUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 10/0x000A/DEAUTH_RX 0x40000000 1653312591354] 244
May 23 13:29:51 XR1000 local1.notice CEVENT_APP[16072]: 1653312591372 wl0
80:9F:9B:5A:F7:DB 0 0000 0007 0000 Driver -- E_DEAUTH/5 163
May 23 13:29:51 XR1000 local1.notice CEVENT_APP[16072]: 1653312591403 wl0
80:9F:9B:5A:F7:DB 0 0000 0007 0000 Driver -- E_DEAUTH/5 163
May 23 13:29:54 XR1000 local1.notice CEVENT_APP[16072]: 1653312594165 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312594165] 243
May 23 13:29:54 XR1000 local1.notice CEVENT_APP[16072]: 1653312594166 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163

```

```

May 23 13:29:54 XR1000 local1.notice CEVENT_APP[16072]: 1653312594166 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312594166] 243
May 23 13:29:54 XR1000 local1.notice CEVENT_APP[16072]: 1653312594465 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312594465] 243
May 23 13:29:54 XR1000 local1.notice CEVENT_APP[16072]: 1653312594466 w10
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:29:54 XR1000 local1.notice CEVENT_APP[16072]: 1653312594466 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:29:54 XR1000 local1.notice CEVENT_APP[16072]: 1653312594466 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312594466] 243
May 23 13:29:54 XR1000 local1.notice CEVENT_APP[16072]: 1653312594765 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312594765] 243
May 23 13:29:54 XR1000 local1.notice CEVENT_APP[16072]: 1653312594766 w10
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:29:54 XR1000 local1.notice CEVENT_APP[16072]: 1653312594767 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:29:54 XR1000 local1.notice CEVENT_APP[16072]: 1653312594767 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312594767] 243
May 23 13:30:01 XR1000 local1.notice CEVENT_APP[16072]: 1653312601546 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312601546] 243
May 23 13:30:01 XR1000 local1.notice CEVENT_APP[16072]: 1653312601546 w10
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:30:01 XR1000 local1.notice CEVENT_APP[16072]: 1653312601548 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:30:01 XR1000 local1.notice CEVENT_APP[16072]: 1653312601547 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312601547] 243
May 23 13:30:01 XR1000 local1.notice CEVENT_APP[16072]: 1653312601841 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312601841] 243
May 23 13:30:01 XR1000 local1.notice CEVENT_APP[16072]: 1653312601847 w10
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:30:01 XR1000 local1.notice CEVENT_APP[16072]: 1653312601847 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:30:01 XR1000 local1.notice CEVENT_APP[16072]: 1653312601849 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312601849] 243
May 23 13:30:02 XR1000 local1.notice CEVENT_APP[16072]: 1653312602142 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312602142] 243
May 23 13:30:02 XR1000 local1.notice CEVENT_APP[16072]: 1653312602143 w10
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:30:02 XR1000 local1.notice CEVENT_APP[16072]: 1653312602143 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163

```



```

May 23 13:30:02 XR1000 local1.notice CEVENT_APP[16072]: 1653312602143 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312602143] 243
May 23 13:30:02 XR1000 local1.notice CEVENT_APP[16072]: 1653312602445 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312602445] 243
May 23 13:30:02 XR1000 local1.notice CEVENT_APP[16072]: 1653312602446 w10
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:30:02 XR1000 local1.notice CEVENT_APP[16072]: 1653312602446 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:30:02 XR1000 local1.notice CEVENT_APP[16072]: 1653312602446 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312602446] 243
May 23 13:30:02 XR1000 local1.notice CEVENT_APP[16072]: 1653312602741 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312602741] 243
May 23 13:30:02 XR1000 local1.notice CEVENT_APP[16072]: 1653312602743 w10
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:30:02 XR1000 local1.notice CEVENT_APP[16072]: 1653312602743 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:30:02 XR1000 local1.notice CEVENT_APP[16072]: 1653312602742 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312602742] 243
May 23 13:30:05 XR1000 local1.notice CEVENT_APP[16072]: 1653312605227 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312605227] 243
May 23 13:30:05 XR1000 local1.notice CEVENT_APP[16072]: 1653312605228 w10
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:30:05 XR1000 local1.notice CEVENT_APP[16072]: 1653312605228 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:30:05 XR1000 local1.notice CEVENT_APP[16072]: 1653312605227 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312605227] 243
May 23 13:30:05 XR1000 local1.notice CEVENT_APP[16072]: 1653312605525 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312605525] 243
May 23 13:30:05 XR1000 local1.notice CEVENT_APP[16072]: 1653312605527 w10
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:30:05 XR1000 local1.notice CEVENT_APP[16072]: 1653312605528 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:30:05 XR1000 local1.notice CEVENT_APP[16072]: 1653312605527 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312605527] 243
May 23 13:30:05 XR1000 local1.notice CEVENT_APP[16072]: 1653312605826 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312605826] 243
May 23 13:30:05 XR1000 local1.notice CEVENT_APP[16072]: 1653312605827 w10
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:30:05 XR1000 local1.notice CEVENT_APP[16072]: 1653312605827 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163

```

```

May 23 13:30:05 XR1000 local1.notice CEVENT_APP[16072]: 1653312605827 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312605827] 243
May 23 13:30:06 XR1000 local1.notice CEVENT_APP[16072]: 1653312606128 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312606128] 243
May 23 13:30:06 XR1000 local1.notice CEVENT_APP[16072]: 1653312606129 wl0
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:30:06 XR1000 local1.notice CEVENT_APP[16072]: 1653312606129 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:30:06 XR1000 local1.notice CEVENT_APP[16072]: 1653312606129 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312606129] 243
May 23 13:30:06 XR1000 local1.notice CEVENT_APP[16072]: 1653312606426 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312606426] 243
May 23 13:30:06 XR1000 local1.notice CEVENT_APP[16072]: 1653312606428 wl0
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:30:06 XR1000 local1.notice CEVENT_APP[16072]: 1653312606428 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:30:06 XR1000 local1.notice CEVENT_APP[16072]: 1653312606427 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312606427] 243
May 23 13:30:08 XR1000 local1.notice CEVENT_APP[16072]: 1653312608678 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312608678] 243
May 23 13:30:08 XR1000 local1.notice CEVENT_APP[16072]: 1653312608679 wl0
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:30:08 XR1000 local1.notice CEVENT_APP[16072]: 1653312608683 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:30:08 XR1000 local1.notice CEVENT_APP[16072]: 1653312608683 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312608683] 243
May 23 13:30:08 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
associated 100
May 23 13:30:08 XR1000 local1.notice CEVENT_APP[16072]: 1653312608729 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC/7 163
May 23 13:30:08 XR1000 local1.notice CEVENT_APP[16072]: 1653312608729 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX ASSOC_RX [CE: 1
24 1/0x0001/CE_D2C 24 7/0x0007/ASSOC_RX 0x40000000 1653312608729] 243
May 23 13:30:08 XR1000 local1.notice CEVENT_APP[16072]: 1653312608729 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX ASSOC_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 1/0x0001/ASSOC_TX 0x80000000 1653312608729] 243
May 23 13:30:08 XR1000 local1.notice CEVENT_APP[16072]: 1653312608730 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC_IND/8 163
May 23 13:30:08 XR1000 local1.notice CEVENT_APP[16072]: 1653312608744 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312608744] 243
May 23 13:30:09 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
associated 100

```

```

May 23 13:30:09 XR1000 local1.notice CEVENT_APP[16072]: 1653312609028 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC/7 163
May 23 13:30:09 XR1000 local1.notice CEVENT_APP[16072]: 1653312609028 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX ASSOC_RX [CE: 1
24 1/0x0001/CE_D2C 24 7/0x0007/ASSOC_RX 0x40000000 1653312609028] 243
May 23 13:30:09 XR1000 local1.notice CEVENT_APP[16072]: 1653312609028 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX ASSOC_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 1/0x0001/ASSOC_TX 0x80000000 1653312609028] 243
May 23 13:30:09 XR1000 local1.notice CEVENT_APP[16072]: 1653312609034 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC_IND/8 163
May 23 13:30:09 XR1000 local1.notice CEVENT_APP[16072]: 1653312609041 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312609041] 243
May 23 13:30:09 XR1000 local1.notice CEVENT_APP[16072]: 1653312609236 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312609236] 243
May 23 13:30:09 XR1000 local1.notice CEVENT_APP[16072]: 1653312609241 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312609241] 243
May 23 13:30:09 XR1000 local1.notice CEVENT_APP[16072]: 1653312609242 w10
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M2_RX [CE: 1
159 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312609242] 243
May 23 13:30:09 XR1000 local1.notice CEVENT_APP[16072]: 1653312609747 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312609747] 243
May 23 13:30:10 XR1000 local1.notice CEVENT_APP[16072]: 1653312610044 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312610044] 243
May 23 13:30:10 XR1000 local1.notice CEVENT_APP[16072]: 1653312610228 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312610228] 243
May 23 13:30:10 XR1000 local1.notice CEVENT_APP[16072]: 1653312610232 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312610232] 243
May 23 13:30:10 XR1000 local1.notice CEVENT_APP[16072]: 1653312610233 w10
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M2_RX [CE: 1
159 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312610233] 243
May 23 13:30:10 XR1000 local1.notice CEVENT_APP[16072]: 1653312610557 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312610557] 243
May 23 13:30:10 XR1000 local1.notice CEVENT_APP[16072]: 1653312610559 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312610559] 243
May 23 13:30:10 XR1000 local1.notice CEVENT_APP[16072]: 1653312610565 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312610565] 243
May 23 13:30:10 XR1000 local1.notice CEVENT_APP[16072]: 1653312610565 w10
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M2_RX [CE: 1
159 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312610565] 243
May 23 13:30:10 XR1000 local1.notice CEVENT_APP[16072]: 1653312610566 w10

```

```

80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
 24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312610566] 243
May 23 13:30:10 XR1000 local1.notice CEVENT_APP[16072]: 1653312610566 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
 24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312610566] 243
May 23 13:30:10 XR1000 local1.notice CEVENT_APP[16072]: 1653312610567 wl0
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M2_RX [CE: 1
159 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312610567] 243
May 23 13:30:11 XR1000 local1.notice CEVENT_APP[16072]: 1653312611158 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
 24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312611158] 243
May 23 13:30:11 XR1000 local1.notice CEVENT_APP[16072]: 1653312611158 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
 24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312611158] 243
May 23 13:30:11 XR1000 local1.notice CEVENT_APP[16072]: 1653312611158 wl0
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M4_RX [CE: 1
137 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312611158] 243
May 23 13:30:11 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db RADIUS:
starting accounting session C0640057F49B34D0 129
May 23 13:30:11 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db WPA: pairwise
key handshake completed (RSN) 120
May 23 13:30:11 XR1000 local1.notice CEVENT_APP[16072]: 1653312611161 wl0
80:9F:9B:5A:F7:DB 0 0136 0000 0000 Driver -- E_AUTHORIZED/136 163
May 23 13:30:19 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
disassociated 103
May 23 13:30:19 XR1000 local1.notice CEVENT_APP[16072]: 1653312619502 wl0
80:9F:9B:5A:F7:DB 0 0000 0003 0000 Driver -- E_DEAUTH_IND/6 163
May 23 13:30:19 XR1000 local1.notice CEVENT_APP[16072]: 1653312619502 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX DEAUTH_RX [CE: 1
 24 1/0x0001/CE_D2C 24 10/0x000A/DEAUTH_RX 0x40000000 1653312619502] 244
May 23 13:30:19 XR1000 local1.notice CEVENT_APP[16072]: 1653312619509 wl0
80:9F:9B:5A:F7:DB 24 0000 0000 0000 Driver RX DEAUTH_RX [CE: 1
 24 1/0x0001/CE_D2C 24 10/0x000A/DEAUTH_RX 0x40000000 1653312619509] 244
May 23 13:30:19 XR1000 local1.notice CEVENT_APP[16072]: 1653312619535 wl0
80:9F:9B:5A:F7:DB 0 0000 0007 0000 Driver -- E_DEAUTH/5 163
May 23 13:30:22 XR1000 local1.notice CEVENT_APP[16072]: 1653312622325 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
 24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312622325] 243
May 23 13:30:22 XR1000 local1.notice CEVENT_APP[16072]: 1653312622326 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:30:22 XR1000 local1.notice CEVENT_APP[16072]: 1653312622325 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
 24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312622325] 243
May 23 13:30:22 XR1000 local1.notice CEVENT_APP[16072]: 1653312622625 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
 24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312622625] 243
May 23 13:30:22 XR1000 local1.notice CEVENT_APP[16072]: 1653312622627 wl0
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:30:22 XR1000 local1.notice CEVENT_APP[16072]: 1653312622627 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163

```

```

May 23 13:30:22 XR1000 local1.notice CEVENT_APP[16072]: 1653312622626 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312622626] 243
May 23 13:30:22 XR1000 local1.notice CEVENT_APP[16072]: 1653312622651 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC/7 163
May 23 13:30:22 XR1000 local1.notice CEVENT_APP[16072]: 1653312622651 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX ASSOC_RX [CE: 1
24 1/0x0001/CE_D2C 24 7/0x0007/ASSOC_RX 0x40000000 1653312622651] 243
May 23 13:30:22 XR1000 local1.notice CEVENT_APP[16072]: 1653312622651 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX ASSOC_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 1/0x0001/ASSOC_TX 0x80000000 1653312622651] 243
May 23 13:30:22 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
associated 100
May 23 13:30:22 XR1000 local1.notice CEVENT_APP[16072]: 1653312622652 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC_IND/8 163
May 23 13:30:22 XR1000 local1.notice CEVENT_APP[16072]: 1653312622673 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312622673] 243
May 23 13:30:22 XR1000 local1.notice CEVENT_APP[16072]: 1653312622958 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312622958] 243
May 23 13:30:22 XR1000 local1.notice CEVENT_APP[16072]: 1653312622963 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312622963] 243
May 23 13:30:22 XR1000 local1.notice CEVENT_APP[16072]: 1653312622964 wl0
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M2_RX [CE: 1
159 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312622964] 243
May 23 13:30:22 XR1000 local1.notice CEVENT_APP[16072]: 1653312622965 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312622965] 243
May 23 13:30:23 XR1000 local1.notice CEVENT_APP[16072]: 1653312623145 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312623145] 243
May 23 13:30:23 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db RADIUS:
starting accounting session 5930B02A0B1DD38E 129
May 23 13:30:23 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db WPA: pairwise
key handshake completed (RSN) 120
May 23 13:30:23 XR1000 local1.notice CEVENT_APP[16072]: 1653312623150 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312623150] 243
May 23 13:30:23 XR1000 local1.notice CEVENT_APP[16072]: 1653312623151 wl0
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M4_RX [CE: 1
137 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312623151] 243
May 23 13:30:23 XR1000 local1.notice CEVENT_APP[16072]: 1653312623151 wl0
80:9F:9B:5A:F7:DB 0 0136 0000 0000 Driver -- E_AUTHORIZED/136 163
May 23 08:30:26 XR1000 user.info com.netdumasoftware.neighwatch: DHCP new event. 86
May 23 08:30:26 XR1000 user.info com.netdumasoftware.neighwatch: DHCP lease change.
89
May 23 08:30:29 XR1000 user.info com.netdumasoftware.neighwatch: DHCP new event. 86
May 23 08:30:29 XR1000 user.info com.netdumasoftware.neighwatch: DHCP lease change.

```

89

```
May 23 13:30:30 XR1000 local1.notice CEVENT_APP[16072]: 1653312630194 wl0
34:9F:7B:2C:D8:6E 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312630194] 243
May 23 13:30:30 XR1000 local1.notice CEVENT_APP[16072]: 1653312630195 wl0
34:9F:7B:2C:D8:6E 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:30:30 XR1000 local1.notice CEVENT_APP[16072]: 1653312630195 wl0
34:9F:7B:2C:D8:6E 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:30:30 XR1000 local1.notice CEVENT_APP[16072]: 1653312630195 wl0
34:9F:7B:2C:D8:6E 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312630195] 243
May 23 08:30:32 XR1000 user.info com.netdumasoftware.neighwatch: DHCP new event. 86
May 23 08:30:32 XR1000 user.info com.netdumasoftware.neighwatch: DHCP lease change.
89
May 23 08:30:38 XR1000 user.warn com.netdumasoftware.procmanager: Rapp
com.netdumasoftware.pingheatmap has not responded to watchdog 138
May 23 13:30:48 XR1000 local1.notice CEVENT_APP[16072]: 1653312648659 wl0
34:9F:7B:2C:D8:6E 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312648659] 243
May 23 13:30:48 XR1000 local1.notice CEVENT_APP[16072]: 1653312648660 wl0
34:9F:7B:2C:D8:6E 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:30:48 XR1000 local1.notice CEVENT_APP[16072]: 1653312648661 wl0
34:9F:7B:2C:D8:6E 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:30:48 XR1000 local1.notice CEVENT_APP[16072]: 1653312648660 wl0
34:9F:7B:2C:D8:6E 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312648660] 243
May 23 13:31:08 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
disassociated 103
May 23 13:31:08 XR1000 local1.notice CEVENT_APP[16072]: 1653312668054 wl0
80:9F:9B:5A:F7:DB 0 0000 0003 0000 Driver -- E_DEAUTH_IND/6 163
May 23 13:31:08 XR1000 local1.notice CEVENT_APP[16072]: 1653312668054 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX DEAUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 10/0x000A/DEAUTH_RX 0x40000000 1653312668054] 244
May 23 13:31:08 XR1000 local1.notice CEVENT_APP[16072]: 1653312668073 wl0
80:9F:9B:5A:F7:DB 0 0000 0007 0000 Driver -- E_DEAUTH/5 163
May 23 13:31:08 XR1000 local1.notice CEVENT_APP[16072]: 1653312668078 wl0
80:9F:9B:5A:F7:DB 0 0000 0007 0000 Driver -- E_DEAUTH/5 163
May 23 13:31:10 XR1000 local1.notice CEVENT_APP[16072]: 1653312670763 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312670763] 243
May 23 13:31:10 XR1000 local1.notice CEVENT_APP[16072]: 1653312670764 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:31:10 XR1000 local1.notice CEVENT_APP[16072]: 1653312670763 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312670763] 243
May 23 13:31:11 XR1000 local1.notice CEVENT_APP[16072]: 1653312671067 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312671067] 243
May 23 13:31:11 XR1000 local1.notice CEVENT_APP[16072]: 1653312671068 wl0
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
```

```

May 23 13:31:11 XR1000 local1.notice CEVENT_APP[16072]: 1653312671068 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:31:11 XR1000 local1.notice CEVENT_APP[16072]: 1653312671067 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312671067] 243
May 23 13:31:11 XR1000 local1.notice CEVENT_APP[16072]: 1653312671362 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312671362] 243
May 23 13:31:11 XR1000 local1.notice CEVENT_APP[16072]: 1653312671365 w10
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:31:11 XR1000 local1.notice CEVENT_APP[16072]: 1653312671369 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:31:11 XR1000 local1.notice CEVENT_APP[16072]: 1653312671369 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312671369] 243
May 23 13:31:11 XR1000 local1.notice CEVENT_APP[16072]: 1653312671662 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312671662] 243
May 23 13:31:11 XR1000 local1.notice CEVENT_APP[16072]: 1653312671668 w10
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:31:11 XR1000 local1.notice CEVENT_APP[16072]: 1653312671673 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:31:11 XR1000 local1.notice CEVENT_APP[16072]: 1653312671673 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312671673] 243
May 23 13:31:11 XR1000 local1.notice CEVENT_APP[16072]: 1653312671962 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312671962] 243
May 23 13:31:11 XR1000 local1.notice CEVENT_APP[16072]: 1653312671963 w10
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:31:11 XR1000 local1.notice CEVENT_APP[16072]: 1653312671963 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:31:11 XR1000 local1.notice CEVENT_APP[16072]: 1653312671963 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312671963] 243
May 23 13:31:15 XR1000 local1.notice CEVENT_APP[16072]: 1653312675268 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312675268] 243
May 23 13:31:15 XR1000 local1.notice CEVENT_APP[16072]: 1653312675269 w10
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:31:15 XR1000 local1.notice CEVENT_APP[16072]: 1653312675269 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:31:15 XR1000 local1.notice CEVENT_APP[16072]: 1653312675269 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312675269] 243
May 23 13:31:15 XR1000 local1.notice CEVENT_APP[16072]: 1653312675424 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC/7 163
May 23 13:31:15 XR1000 local1.notice CEVENT_APP[16072]: 1653312675425 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX ASSOC_RX [CE: 1
24 1/0x0001/CE_D2C 24 7/0x0007/ASSOC_RX 0x40000000 1653312675425] 243

```

```

May 23 13:31:15 XR1000 local1.notice CEVENT_APP[16072]: 1653312675425 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX ASSOC_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 1/0x0001/ASSOC_TX 0x80000000 1653312675425] 243
May 23 13:31:15 XR1000 local1.notice CEVENT_APP[16072]: 1653312675429 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC_IND/8 163
May 23 13:31:15 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
associated 100
May 23 13:31:15 XR1000 local1.notice CEVENT_APP[16072]: 1653312675445 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312675445] 243
May 23 13:31:16 XR1000 local1.notice CEVENT_APP[16072]: 1653312676282 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312676282] 243
May 23 13:31:16 XR1000 local1.notice CEVENT_APP[16072]: 1653312676308 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312676308] 243
May 23 13:31:16 XR1000 local1.notice CEVENT_APP[16072]: 1653312676308 wl0
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M2_RX [CE: 1
159 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312676308] 243
May 23 13:31:16 XR1000 local1.notice CEVENT_APP[16072]: 1653312676308 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312676308] 243
May 23 13:31:16 XR1000 local1.notice CEVENT_APP[16072]: 1653312676593 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312676593] 243
May 23 13:31:16 XR1000 local1.notice CEVENT_APP[16072]: 1653312676608 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312676608] 243
May 23 13:31:16 XR1000 local1.notice CEVENT_APP[16072]: 1653312676609 wl0
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M4_RX [CE: 1
137 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312676609] 243
May 23 13:31:16 XR1000 local1.notice CEVENT_APP[16072]: 1653312676612 wl0
80:9F:9B:5A:F7:DB 0 0136 0000 0000 Driver -- E_AUTHORIZED/136 163
May 23 13:31:16 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db RADIUS:
starting accounting session 1D979572AAD8D223 129
May 23 13:31:16 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db WPA: pairwise
key handshake completed (RSN) 120
May 23 13:31:21 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
disassociated 103
May 23 13:31:21 XR1000 local1.notice CEVENT_APP[16072]: 1653312681046 wl0
80:9F:9B:5A:F7:DB 0 0000 0003 0000 Driver -- E_DEAUTH_IND/6 163
May 23 13:31:21 XR1000 local1.notice CEVENT_APP[16072]: 1653312681046 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX DEAUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 10/0x000A/DEAUTH_RX 0x40000000 1653312681046] 244
May 23 13:31:21 XR1000 local1.notice CEVENT_APP[16072]: 1653312681057 wl0
80:9F:9B:5A:F7:DB 24 0000 0000 0000 Driver RX DEAUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 10/0x000A/DEAUTH_RX 0x40000000 1653312681057] 244
May 23 13:31:23 XR1000 local1.notice CEVENT_APP[16072]: 1653312683970 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312683970] 243

```



```

May 23 13:31:23 XR1000 local1.notice CEVENT_APP[16072]: 1653312683971 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:31:23 XR1000 local1.notice CEVENT_APP[16072]: 1653312683971 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312683971] 243
May 23 13:31:24 XR1000 local1.notice CEVENT_APP[16072]: 1653312684270 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312684270] 243
May 23 13:31:24 XR1000 local1.notice CEVENT_APP[16072]: 1653312684275 w10
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:31:24 XR1000 local1.notice CEVENT_APP[16072]: 1653312684275 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:31:24 XR1000 local1.notice CEVENT_APP[16072]: 1653312684271 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312684271] 243
May 23 13:31:24 XR1000 local1.notice CEVENT_APP[16072]: 1653312684278 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC/7 163
May 23 13:31:24 XR1000 local1.notice CEVENT_APP[16072]: 1653312684278 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX ASSOC_RX [CE: 1
24 1/0x0001/CE_D2C 24 7/0x0007/ASSOC_RX 0x40000000 1653312684278] 243
May 23 13:31:24 XR1000 local1.notice CEVENT_APP[16072]: 1653312684280 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX ASSOC_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 1/0x0001/ASSOC_TX 0x80000000 1653312684280] 243
May 23 13:31:24 XR1000 local1.notice CEVENT_APP[16072]: 1653312684282 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC_IND/8 163
May 23 13:31:24 XR1000 daemon.info hostapd: w10: STA 80:9f:9b:5a:f7:db IEEE 802.11:
associated 100
May 23 13:31:24 XR1000 local1.notice CEVENT_APP[16072]: 1653312684299 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312684299] 243
May 23 13:31:24 XR1000 local1.notice CEVENT_APP[16072]: 1653312684580 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312684580] 243
May 23 13:31:24 XR1000 local1.notice CEVENT_APP[16072]: 1653312684586 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312684586] 243
May 23 13:31:24 XR1000 local1.notice CEVENT_APP[16072]: 1653312684587 w10
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M2_RX [CE: 1
159 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312684587] 243
May 23 13:31:24 XR1000 local1.notice CEVENT_APP[16072]: 1653312684587 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312684587] 243
May 23 13:31:25 XR1000 local1.notice CEVENT_APP[16072]: 1653312685273 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312685273] 243
May 23 13:31:25 XR1000 local1.notice CEVENT_APP[16072]: 1653312685276 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312685276] 243
May 23 13:31:25 XR1000 local1.notice CEVENT_APP[16072]: 1653312685277 w10
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M4_RX [CE: 1

```

137 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312685277] 243
May 23 13:31:25 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db RADIUS:
starting accounting session AA48E140B2DF5B4F 129
May 23 13:31:25 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db WPA: pairwise
key handshake completed (RSN) 120
May 23 13:31:25 XR1000 local1.notice CEVENT_APP[16072]: 1653312685280 wl0
80:9F:9B:5A:F7:DB 0 0136 0000 0000 Driver -- E_AUTHORIZED/136 163
May 23 08:31:27 XR1000 user.info com.netdumasoftware.neighwatch: DHCP new event. 86
May 23 08:31:27 XR1000 user.info com.netdumasoftware.neighwatch: DHCP lease change.
89
May 23 13:31:28 XR1000 local1.notice CEVENT_APP[16072]: 1653312688808 wl0
34:9F:7B:2C:D8:6E 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312688808] 243
May 23 13:31:28 XR1000 local1.notice CEVENT_APP[16072]: 1653312688810 wl0
34:9F:7B:2C:D8:6E 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:31:28 XR1000 local1.notice CEVENT_APP[16072]: 1653312688810 wl0
34:9F:7B:2C:D8:6E 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:31:28 XR1000 local1.notice CEVENT_APP[16072]: 1653312688809 wl0
34:9F:7B:2C:D8:6E 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312688809] 243
May 23 08:31:30 XR1000 user.info com.netdumasoftware.neighwatch: DHCP new event. 86
May 23 08:31:30 XR1000 user.info com.netdumasoftware.neighwatch: DHCP lease change.
89
May 23 13:31:51 XR1000 local1.notice CEVENT_APP[16072]: 1653312711731 wl0
80:9F:9B:5A:F7:DB 0 0000 0003 0000 Driver -- E_DEAUTH_IND/6 163
May 23 13:31:51 XR1000 local1.notice CEVENT_APP[16072]: 1653312711731 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX DEAUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 10/0x000A/DEAUTH_RX 0x40000000 1653312711731] 244
May 23 13:31:51 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
disassociated 103
May 23 13:31:51 XR1000 local1.notice CEVENT_APP[16072]: 1653312711750 wl0
80:9F:9B:5A:F7:DB 0 0000 0007 0000 Driver -- E_DEAUTH/5 163
May 23 13:31:51 XR1000 local1.notice CEVENT_APP[16072]: 1653312711786 wl0
80:9F:9B:5A:F7:DB 0 0000 0007 0000 Driver -- E_DEAUTH/5 163
May 23 13:31:54 XR1000 local1.notice CEVENT_APP[16072]: 1653312714363 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312714363] 243
May 23 13:31:54 XR1000 local1.notice CEVENT_APP[16072]: 1653312714364 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:31:54 XR1000 local1.notice CEVENT_APP[16072]: 1653312714364 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312714364] 243
May 23 13:31:54 XR1000 local1.notice CEVENT_APP[16072]: 1653312714663 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312714663] 243
May 23 13:31:54 XR1000 local1.notice CEVENT_APP[16072]: 1653312714664 wl0
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:31:54 XR1000 local1.notice CEVENT_APP[16072]: 1653312714664 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:31:54 XR1000 local1.notice CEVENT_APP[16072]: 1653312714664 wl0

```

80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312714664] 243
May 23 13:31:54 XR1000 local1.notice CEVENT_APP[16072]: 1653312714962 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312714962] 243
May 23 13:31:54 XR1000 local1.notice CEVENT_APP[16072]: 1653312714964 wl0
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:31:54 XR1000 local1.notice CEVENT_APP[16072]: 1653312714964 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:31:54 XR1000 local1.notice CEVENT_APP[16072]: 1653312714963 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312714963] 243
May 23 13:31:55 XR1000 local1.notice CEVENT_APP[16072]: 1653312715263 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312715263] 243
May 23 13:31:55 XR1000 local1.notice CEVENT_APP[16072]: 1653312715264 wl0
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:31:55 XR1000 local1.notice CEVENT_APP[16072]: 1653312715264 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:31:55 XR1000 local1.notice CEVENT_APP[16072]: 1653312715264 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312715264] 243
May 23 13:31:55 XR1000 local1.notice CEVENT_APP[16072]: 1653312715307 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC/7 163
May 23 13:31:55 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
associated 100
May 23 13:31:55 XR1000 local1.notice CEVENT_APP[16072]: 1653312715307 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX ASSOC_RX [CE: 1
24 1/0x0001/CE_D2C 24 7/0x0007/ASSOC_RX 0x40000000 1653312715307] 243
May 23 13:31:55 XR1000 local1.notice CEVENT_APP[16072]: 1653312715308 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX ASSOC_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 1/0x0001/ASSOC_TX 0x80000000 1653312715308] 243
May 23 13:31:55 XR1000 local1.notice CEVENT_APP[16072]: 1653312715309 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC_IND/8 163
May 23 13:31:55 XR1000 local1.notice CEVENT_APP[16072]: 1653312715323 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312715323] 243
May 23 13:31:55 XR1000 local1.notice CEVENT_APP[16072]: 1653312715445 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312715445] 243
May 23 13:31:55 XR1000 local1.notice CEVENT_APP[16072]: 1653312715450 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312715450] 243
May 23 13:31:55 XR1000 local1.notice CEVENT_APP[16072]: 1653312715451 wl0
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M2_RX [CE: 1
159 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312715451] 243
May 23 13:31:55 XR1000 local1.notice CEVENT_APP[16072]: 1653312715452 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312715452] 243
May 23 13:31:55 XR1000 local1.notice CEVENT_APP[16072]: 1653312715817 wl0

```

```

80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
 24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312715817] 243
May 23 13:31:55 XR1000 local1.notice CEVENT_APP[16072]: 1653312715823 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
 24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312715823] 243
May 23 13:31:55 XR1000 local1.notice CEVENT_APP[16072]: 1653312715824 wl0
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M4_RX [CE: 1
137 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312715824] 243
May 23 13:31:55 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db RADIUS:
starting accounting session 3CC555E2B872D926 129
May 23 13:31:55 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db WPA: pairwise
key handshake completed (RSN) 120
May 23 13:31:55 XR1000 local1.notice CEVENT_APP[16072]: 1653312715954 wl0
80:9F:9B:5A:F7:DB 0 0136 0000 0000 Driver -- E_AUTHORIZED/136 163
May 23 13:32:22 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
disassociated 103
May 23 13:32:22 XR1000 local1.notice CEVENT_APP[16072]: 1653312742319 wl0
80:9F:9B:5A:F7:DB 0 0000 0003 0000 Driver -- E_DEAUTH_IND/6 163
May 23 13:32:22 XR1000 local1.notice CEVENT_APP[16072]: 1653312742319 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX DEAUTH_RX [CE: 1
 24 1/0x0001/CE_D2C 24 10/0x000A/DEAUTH_RX 0x40000000 1653312742319] 244
May 23 13:32:25 XR1000 local1.notice CEVENT_APP[16072]: 1653312745709 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
 24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312745709] 243
May 23 13:32:25 XR1000 local1.notice CEVENT_APP[16072]: 1653312745710 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:32:25 XR1000 local1.notice CEVENT_APP[16072]: 1653312745709 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
 24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312745709] 243
May 23 13:32:25 XR1000 local1.notice CEVENT_APP[16072]: 1653312745773 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC/7 163
May 23 13:32:25 XR1000 local1.notice CEVENT_APP[16072]: 1653312745773 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX ASSOC_RX [CE: 1
 24 1/0x0001/CE_D2C 24 7/0x0007/ASSOC_RX 0x40000000 1653312745773] 243
May 23 13:32:25 XR1000 local1.notice CEVENT_APP[16072]: 1653312745773 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX ASSOC_TX_QUEUED [CE: 1
 24 1/0x0001/CE_D2C 24 1/0x0001/ASSOC_TX 0x80000000 1653312745773] 243
May 23 13:32:25 XR1000 local1.notice CEVENT_APP[16072]: 1653312745774 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC_IND/8 163
May 23 13:32:25 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
associated 100
May 23 13:32:25 XR1000 local1.notice CEVENT_APP[16072]: 1653312745794 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
 24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312745794] 243
May 23 13:32:25 XR1000 local1.notice CEVENT_APP[16072]: 1653312745887 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
 24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312745887] 243
May 23 13:32:26 XR1000 local1.notice CEVENT_APP[16072]: 1653312746798 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
 24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312746798] 243

```

```

May 23 13:32:26 XR1000 local1.notice CEVENT_APP[16072]: 1653312746845 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312746845] 243
May 23 13:32:26 XR1000 local1.notice CEVENT_APP[16072]: 1653312746849 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312746849] 243
May 23 13:32:26 XR1000 local1.notice CEVENT_APP[16072]: 1653312746849 wl0
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M2_RX [CE: 1
159 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312746849] 243
May 23 13:32:26 XR1000 local1.notice CEVENT_APP[16072]: 1653312746850 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312746850] 243
May 23 13:32:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312747148 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312747148] 243
May 23 13:32:27 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db RADIUS:
starting accounting session A5AE438BE14B4EB9 129
May 23 13:32:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312747162 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312747162] 243
May 23 13:32:27 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db WPA: pairwise
key handshake completed (RSN) 120
May 23 13:32:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312747163 wl0
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M4_RX [CE: 1
137 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312747163] 243
May 23 13:32:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312747163 wl0
80:9F:9B:5A:F7:DB 0 0136 0000 0000 Driver -- E_AUTHORIZED/136 163
May 23 08:32:29 XR1000 user.info com.netdumasoftware.neighwatch: DHCP new event. 86
May 23 08:32:29 XR1000 user.info com.netdumasoftware.neighwatch: DHCP lease change.
89
May 23 08:32:32 XR1000 user.info com.netdumasoftware.neighwatch: DHCP new event. 86
May 23 08:32:32 XR1000 user.info com.netdumasoftware.neighwatch: DHCP lease change.
89
May 23 08:32:38 XR1000 user.warn com.netdumasoftware.procmanager: Rapp
com.netdumasoftware.pingheatmap has not responded to watchdog 138
May 23 13:33:20 XR1000 local1.notice CEVENT_APP[16072]: 1653312800201 wl0
80:9F:9B:5A:F7:DB 0 0000 0003 0000 Driver -- E_DEAUTH_IND/6 163
May 23 13:33:20 XR1000 local1.notice CEVENT_APP[16072]: 1653312800201 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX DEAUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 10/0x000A/DEAUTH_RX 0x40000000 1653312800201] 244
May 23 13:33:20 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
disassociated 103
May 23 13:33:20 XR1000 local1.notice CEVENT_APP[16072]: 1653312800206 wl0
80:9F:9B:5A:F7:DB 24 0000 0000 0000 Driver RX DEAUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 10/0x000A/DEAUTH_RX 0x40000000 1653312800206] 244
May 23 13:33:22 XR1000 local1.notice CEVENT_APP[16072]: 1653312802853 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312802853] 243
May 23 13:33:22 XR1000 local1.notice CEVENT_APP[16072]: 1653312802854 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163

```

```

May 23 13:33:22 XR1000 local1.notice CEVENT_APP[16072]: 1653312802854 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312802854] 243
May 23 13:33:23 XR1000 local1.notice CEVENT_APP[16072]: 1653312803152 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312803152] 243
May 23 13:33:23 XR1000 local1.notice CEVENT_APP[16072]: 1653312803153 wl0
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:33:23 XR1000 local1.notice CEVENT_APP[16072]: 1653312803153 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:33:23 XR1000 local1.notice CEVENT_APP[16072]: 1653312803152 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312803152] 243
May 23 13:33:23 XR1000 local1.notice CEVENT_APP[16072]: 1653312803455 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312803455] 243
May 23 13:33:23 XR1000 local1.notice CEVENT_APP[16072]: 1653312803457 wl0
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:33:23 XR1000 local1.notice CEVENT_APP[16072]: 1653312803457 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:33:23 XR1000 local1.notice CEVENT_APP[16072]: 1653312803456 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312803456] 243
May 23 13:33:23 XR1000 local1.notice CEVENT_APP[16072]: 1653312803752 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312803752] 243
May 23 13:33:23 XR1000 local1.notice CEVENT_APP[16072]: 1653312803753 wl0
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:33:23 XR1000 local1.notice CEVENT_APP[16072]: 1653312803753 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:33:23 XR1000 local1.notice CEVENT_APP[16072]: 1653312803754 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312803754] 243
May 23 13:33:23 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
associated 100
May 23 13:33:23 XR1000 local1.notice CEVENT_APP[16072]: 1653312803997 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC/7 163
May 23 13:33:23 XR1000 local1.notice CEVENT_APP[16072]: 1653312803997 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX ASSOC_RX [CE: 1
24 1/0x0001/CE_D2C 24 7/0x0007/ASSOC_RX 0x40000000 1653312803997] 243
May 23 13:33:23 XR1000 local1.notice CEVENT_APP[16072]: 1653312803997 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX ASSOC_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 1/0x0001/ASSOC_TX 0x80000000 1653312803997] 243
May 23 13:33:23 XR1000 local1.notice CEVENT_APP[16072]: 1653312803998 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC_IND/8 163
May 23 13:33:24 XR1000 local1.notice CEVENT_APP[16072]: 1653312804015 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312804015] 243
May 23 13:33:24 XR1000 local1.notice CEVENT_APP[16072]: 1653312804299 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1

```

```

24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312804299] 243
May 23 13:33:24 XR1000 local1.notice CEVENT_APP[16072]: 1653312804303 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312804303] 243
May 23 13:33:24 XR1000 local1.notice CEVENT_APP[16072]: 1653312804304 wl0
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M2_RX [CE: 1
159 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312804304] 243
May 23 13:33:24 XR1000 local1.notice CEVENT_APP[16072]: 1653312804305 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312804305] 243
May 23 13:33:24 XR1000 local1.notice CEVENT_APP[16072]: 1653312804321 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312804321] 243
May 23 13:33:24 XR1000 local1.notice CEVENT_APP[16072]: 1653312804325 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312804325] 243
May 23 13:33:24 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db RADIUS:
starting accounting session 24CE334D664B2BCF 129
May 23 13:33:24 XR1000 local1.notice CEVENT_APP[16072]: 1653312804325 wl0
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M4_RX [CE: 1
137 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312804325] 243
May 23 13:33:24 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db WPA: pairwise
key handshake completed (RSN) 120
May 23 13:33:24 XR1000 local1.notice CEVENT_APP[16072]: 1653312804327 wl0
80:9F:9B:5A:F7:DB 0 0136 0000 0000 Driver -- E_AUTHORIZED/136 163
May 23 08:33:27 XR1000 user.info com.netdumasoftware.neighwatch: DHCP new event. 86
May 23 08:33:27 XR1000 user.info com.netdumasoftware.neighwatch: DHCP lease change.
89
May 23 08:33:30 XR1000 user.info com.netdumasoftware.neighwatch: DHCP new event. 86
May 23 08:33:30 XR1000 user.info com.netdumasoftware.neighwatch: DHCP lease change.
89
May 23 08:33:33 XR1000 user.info com.netdumasoftware.neighwatch: DHCP new event. 86
May 23 08:33:33 XR1000 user.info com.netdumasoftware.neighwatch: DHCP lease change.
89
May 23 13:33:50 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
disassociated 103
May 23 13:33:50 XR1000 local1.notice CEVENT_APP[16072]: 1653312830865 wl0
80:9F:9B:5A:F7:DB 0 0000 0003 0000 Driver -- E_DEAUTH_IND/6 163
May 23 13:33:50 XR1000 local1.notice CEVENT_APP[16072]: 1653312830865 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX DEAUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 10/0x000A/DEAUTH_RX 0x40000000 1653312830865] 244
May 23 13:33:50 XR1000 local1.notice CEVENT_APP[16072]: 1653312830885 wl0
80:9F:9B:5A:F7:DB 0 0000 0007 0000 Driver -- E_DEAUTH/5 163
May 23 13:33:50 XR1000 local1.notice CEVENT_APP[16072]: 1653312830889 wl0
80:9F:9B:5A:F7:DB 0 0000 0007 0000 Driver -- E_DEAUTH/5 163
May 23 13:33:53 XR1000 local1.notice CEVENT_APP[16072]: 1653312833680 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312833680] 243
May 23 13:33:53 XR1000 local1.notice CEVENT_APP[16072]: 1653312833685 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163

```

```

May 23 13:33:53 XR1000 local1.notice CEVENT_APP[16072]: 1653312833681 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312833681] 243
May 23 13:33:53 XR1000 local1.notice CEVENT_APP[16072]: 1653312833980 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312833980] 243
May 23 13:33:53 XR1000 local1.notice CEVENT_APP[16072]: 1653312833981 w10
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:33:53 XR1000 local1.notice CEVENT_APP[16072]: 1653312833981 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:33:53 XR1000 local1.notice CEVENT_APP[16072]: 1653312833981 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312833981] 243
May 23 13:33:54 XR1000 local1.notice CEVENT_APP[16072]: 1653312834280 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312834280] 243
May 23 13:33:54 XR1000 local1.notice CEVENT_APP[16072]: 1653312834281 w10
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:33:54 XR1000 local1.notice CEVENT_APP[16072]: 1653312834281 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:33:54 XR1000 local1.notice CEVENT_APP[16072]: 1653312834281 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312834281] 243
May 23 13:33:54 XR1000 local1.notice CEVENT_APP[16072]: 1653312834580 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312834580] 243
May 23 13:33:54 XR1000 local1.notice CEVENT_APP[16072]: 1653312834581 w10
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:33:54 XR1000 local1.notice CEVENT_APP[16072]: 1653312834581 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:33:54 XR1000 local1.notice CEVENT_APP[16072]: 1653312834581 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312834581] 243
May 23 13:33:54 XR1000 local1.notice CEVENT_APP[16072]: 1653312834880 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312834880] 243
May 23 13:33:54 XR1000 local1.notice CEVENT_APP[16072]: 1653312834882 w10
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:33:54 XR1000 local1.notice CEVENT_APP[16072]: 1653312834882 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:33:54 XR1000 local1.notice CEVENT_APP[16072]: 1653312834881 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312834881] 243
May 23 13:33:57 XR1000 local1.notice CEVENT_APP[16072]: 1653312837185 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312837185] 243
May 23 13:33:57 XR1000 local1.notice CEVENT_APP[16072]: 1653312837187 w10
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:33:57 XR1000 local1.notice CEVENT_APP[16072]: 1653312837187 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163

```



```

May 23 13:33:57 XR1000 local1.notice CEVENT_APP[16072]: 1653312837186 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312837186] 243
May 23 13:33:57 XR1000 local1.notice CEVENT_APP[16072]: 1653312837484 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312837484] 243
May 23 13:33:57 XR1000 local1.notice CEVENT_APP[16072]: 1653312837485 wl0
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:33:57 XR1000 local1.notice CEVENT_APP[16072]: 1653312837485 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:33:57 XR1000 local1.notice CEVENT_APP[16072]: 1653312837485 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312837485] 243
May 23 13:33:57 XR1000 local1.notice CEVENT_APP[16072]: 1653312837784 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312837784] 243
May 23 13:33:57 XR1000 local1.notice CEVENT_APP[16072]: 1653312837786 wl0
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:33:57 XR1000 local1.notice CEVENT_APP[16072]: 1653312837786 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:33:57 XR1000 local1.notice CEVENT_APP[16072]: 1653312837785 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312837785] 243
May 23 13:33:58 XR1000 local1.notice CEVENT_APP[16072]: 1653312838088 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312838088] 243
May 23 13:33:58 XR1000 local1.notice CEVENT_APP[16072]: 1653312838089 wl0
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:33:58 XR1000 local1.notice CEVENT_APP[16072]: 1653312838089 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:33:58 XR1000 local1.notice CEVENT_APP[16072]: 1653312838089 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312838089] 243
May 23 13:33:58 XR1000 local1.notice CEVENT_APP[16072]: 1653312838189 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC/7 163
May 23 13:33:58 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
associated 100
May 23 13:33:58 XR1000 local1.notice CEVENT_APP[16072]: 1653312838190 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX ASSOC_RX [CE: 1
24 1/0x0001/CE_D2C 24 7/0x0007/ASSOC_RX 0x40000000 1653312838190] 243
May 23 13:33:58 XR1000 local1.notice CEVENT_APP[16072]: 1653312838190 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX ASSOC_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 1/0x0001/ASSOC_TX 0x80000000 1653312838190] 243
May 23 13:33:58 XR1000 local1.notice CEVENT_APP[16072]: 1653312838197 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC_IND/8 163
May 23 13:33:58 XR1000 local1.notice CEVENT_APP[16072]: 1653312838204 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312838204] 243
May 23 13:33:58 XR1000 local1.notice CEVENT_APP[16072]: 1653312838317 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1

```

```

24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312838317] 243
May 23 13:33:58 XR1000 local1.notice CEVENT_APP[16072]: 1653312838322 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312838322] 243
May 23 13:33:58 XR1000 local1.notice CEVENT_APP[16072]: 1653312838323 wl0
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M2_RX [CE: 1
159 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312838323] 243
May 23 13:33:58 XR1000 local1.notice CEVENT_APP[16072]: 1653312838323 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312838323] 243
May 23 13:33:58 XR1000 local1.notice CEVENT_APP[16072]: 1653312838390 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312838390] 243
May 23 13:33:58 XR1000 local1.notice CEVENT_APP[16072]: 1653312838393 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312838393] 243
May 23 13:33:58 XR1000 local1.notice CEVENT_APP[16072]: 1653312838394 wl0
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M4_RX [CE: 1
137 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312838394] 243
May 23 13:33:58 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db RADIUS:
starting accounting session 6687D3C364800B37 129
May 23 13:33:58 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db WPA: pairwise
key handshake completed (RSN) 120
May 23 13:33:58 XR1000 local1.notice CEVENT_APP[16072]: 1653312838396 wl0
80:9F:9B:5A:F7:DB 0 0136 0000 0000 Driver -- E_AUTHORIZED/136 163
May 23 08:34:04 XR1000 user.info com.netdumasoftware.neighwatch: DHCP new event. 86
May 23 08:34:04 XR1000 user.info com.netdumasoftware.neighwatch: DHCP lease change.
89
May 23 13:34:21 XR1000 local1.notice CEVENT_APP[16072]: 1653312861491 wl0
80:9F:9B:5A:F7:DB 0 0000 0003 0000 Driver -- E_DEAUTH_IND/6 163
May 23 13:34:21 XR1000 local1.notice CEVENT_APP[16072]: 1653312861491 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX DEAUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 10/0x000A/DEAUTH_RX 0x40000000 1653312861491] 244
May 23 13:34:21 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
disassociated 103
May 23 13:34:21 XR1000 local1.notice CEVENT_APP[16072]: 1653312861510 wl0
80:9F:9B:5A:F7:DB 0 0000 0007 0000 Driver -- E_DEAUTH/5 163
May 23 13:34:21 XR1000 local1.notice CEVENT_APP[16072]: 1653312861525 wl0
80:9F:9B:5A:F7:DB 0 0000 0007 0000 Driver -- E_DEAUTH/5 163
May 23 13:34:24 XR1000 local1.notice CEVENT_APP[16072]: 1653312864344 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312864344] 243
May 23 13:34:24 XR1000 local1.notice CEVENT_APP[16072]: 1653312864345 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:34:24 XR1000 local1.notice CEVENT_APP[16072]: 1653312864345 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312864345] 243
May 23 13:34:26 XR1000 local1.notice CEVENT_APP[16072]: 1653312866247 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312866247] 243

```

```

May 23 13:34:26 XR1000 local1.notice CEVENT_APP[16072]: 1653312866248 wl0
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:34:26 XR1000 local1.notice CEVENT_APP[16072]: 1653312866248 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:34:26 XR1000 local1.notice CEVENT_APP[16072]: 1653312866248 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312866248] 243
May 23 13:34:26 XR1000 local1.notice CEVENT_APP[16072]: 1653312866360 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC/7 163
May 23 13:34:26 XR1000 local1.notice CEVENT_APP[16072]: 1653312866362 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX ASSOC_RX [CE: 1
24 1/0x0001/CE_D2C 24 7/0x0007/ASSOC_RX 0x40000000 1653312866362] 243
May 23 13:34:26 XR1000 local1.notice CEVENT_APP[16072]: 1653312866364 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX ASSOC_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 1/0x0001/ASSOC_TX 0x80000000 1653312866364] 243
May 23 13:34:26 XR1000 local1.notice CEVENT_APP[16072]: 1653312866365 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC_IND/8 163
May 23 13:34:26 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
associated 100
May 23 13:34:26 XR1000 local1.notice CEVENT_APP[16072]: 1653312866384 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312866384] 243
May 23 13:34:26 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
associated 100
May 23 13:34:26 XR1000 local1.notice CEVENT_APP[16072]: 1653312866660 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC/7 163
May 23 13:34:26 XR1000 local1.notice CEVENT_APP[16072]: 1653312866659 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX ASSOC_RX [CE: 1
24 1/0x0001/CE_D2C 24 7/0x0007/ASSOC_RX 0x40000000 1653312866659] 243
May 23 13:34:26 XR1000 local1.notice CEVENT_APP[16072]: 1653312866659 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX ASSOC_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 1/0x0001/ASSOC_TX 0x80000000 1653312866659] 243
May 23 13:34:26 XR1000 local1.notice CEVENT_APP[16072]: 1653312866660 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC_IND/8 163
May 23 13:34:26 XR1000 local1.notice CEVENT_APP[16072]: 1653312866673 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312866673] 243
May 23 13:34:26 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
associated 100
May 23 13:34:26 XR1000 local1.notice CEVENT_APP[16072]: 1653312866961 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC/7 163
May 23 13:34:26 XR1000 local1.notice CEVENT_APP[16072]: 1653312866960 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX ASSOC_RX [CE: 1
24 1/0x0001/CE_D2C 24 7/0x0007/ASSOC_RX 0x40000000 1653312866960] 243
May 23 13:34:26 XR1000 local1.notice CEVENT_APP[16072]: 1653312866960 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX ASSOC_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 1/0x0001/ASSOC_TX 0x80000000 1653312866960] 243
May 23 13:34:26 XR1000 local1.notice CEVENT_APP[16072]: 1653312866961 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC_IND/8 163
May 23 13:34:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312867038 wl0

```

```

80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
 24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312867038] 243
May 23 13:34:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312867260 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
 24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312867260] 243
May 23 13:34:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312867264 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
 24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312867264] 243
May 23 13:34:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312867274 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
 24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312867274] 243
May 23 13:34:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312867327 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
 24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312867327] 243
May 23 13:34:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312867328 w10
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M2_RX [CE: 1
159 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312867328] 243
May 23 13:34:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312867329 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
 24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312867329] 243
May 23 13:34:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312867330 w10
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M2_RX [CE: 1
159 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312867330] 243
May 23 13:34:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312867331 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
 24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312867331] 243
May 23 13:34:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312867332 w10
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M2_RX [CE: 1
159 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312867332] 243
May 23 13:34:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312867386 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
 24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312867386] 243
May 23 13:34:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312867675 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
 24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312867675] 243
May 23 13:34:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312867872 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
 24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312867872] 243
May 23 13:34:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312867875 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
 24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312867875] 243
May 23 13:34:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312867876 w10
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M2_RX [CE: 1
159 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312867876] 243
May 23 13:34:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312867876 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
 24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312867876] 243
May 23 13:34:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312867886 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
 24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312867886] 243

```

```

May 23 13:34:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312867887 wl0
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M2_RX [CE: 1
159 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312867887] 243
May 23 13:34:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312867932 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312867932] 243
May 23 13:34:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312867934 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312867934] 243
May 23 13:34:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312867938 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312867938] 243
May 23 13:34:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312867939 wl0
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M4_RX [CE: 1
137 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312867939] 243
May 23 13:34:27 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db RADIUS:
starting accounting session F82E544F79F48DCF 129
May 23 13:34:27 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db WPA: pairwise
key handshake completed (RSN) 120
May 23 13:34:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312867940 wl0
80:9F:9B:5A:F7:DB 0 0136 0000 0000 Driver -- E_AUTHORIZED/136 163
May 23 08:34:38 XR1000 user.warn com.netdumasoftware.procmanager: Rapp
com.netdumasoftware.pingheatmap has not responded to watchdog 138
May 23 08:34:54 XR1000 user.info com.netdumasoftware.neighwatch: DHCP new event. 86
May 23 08:34:54 XR1000 user.info com.netdumasoftware.neighwatch: DHCP lease change.
89
May 23 08:34:57 XR1000 user.info com.netdumasoftware.neighwatch: DHCP new event. 86
May 23 08:34:57 XR1000 user.info com.netdumasoftware.neighwatch: DHCP lease change.
89
May 23 08:35:00 XR1000 user.info com.netdumasoftware.neighwatch: DHCP new event. 86
May 23 08:35:00 XR1000 user.info com.netdumasoftware.neighwatch: DHCP lease change.
89
May 23 13:35:22 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
disassociated 103
May 23 13:35:22 XR1000 local1.notice CEVENT_APP[16072]: 1653312922071 wl0
80:9F:9B:5A:F7:DB 0 0000 0003 0000 Driver -- E_DEAUTH_IND/6 163
May 23 13:35:22 XR1000 local1.notice CEVENT_APP[16072]: 1653312922071 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX DEAUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 10/0x000A/DEAUTH_RX 0x40000000 1653312922071] 244
May 23 13:35:22 XR1000 local1.notice CEVENT_APP[16072]: 1653312922081 wl0
80:9F:9B:5A:F7:DB 24 0000 0000 0000 Driver RX DEAUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 10/0x000A/DEAUTH_RX 0x40000000 1653312922081] 244
May 23 13:35:22 XR1000 local1.notice CEVENT_APP[16072]: 1653312922105 wl0
80:9F:9B:5A:F7:DB 0 0000 0007 0000 Driver -- E_DEAUTH/5 163
May 23 13:35:42 XR1000 local1.notice CEVENT_APP[16072]: 1653312942635 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312942635] 243
May 23 13:35:42 XR1000 local1.notice CEVENT_APP[16072]: 1653312942636 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:35:42 XR1000 local1.notice CEVENT_APP[16072]: 1653312942635 wl0

```

```

80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
 24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312942635] 243
May 23 13:35:42 XR1000 local1.notice CEVENT_APP[16072]: 1653312942645 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC/7 163
May 23 13:35:42 XR1000 local1.notice CEVENT_APP[16072]: 1653312942645 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX ASSOC_RX [CE: 1
 24 1/0x0001/CE_D2C 24 7/0x0007/ASSOC_RX 0x40000000 1653312942645] 243
May 23 13:35:42 XR1000 local1.notice CEVENT_APP[16072]: 1653312942645 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX ASSOC_TX_QUEUED [CE: 1
 24 1/0x0001/CE_D2C 24 1/0x0001/ASSOC_TX 0x80000000 1653312942645] 243
May 23 13:35:42 XR1000 local1.notice CEVENT_APP[16072]: 1653312942645 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC_IND/8 163
May 23 13:35:42 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
associated 100
May 23 13:35:42 XR1000 local1.notice CEVENT_APP[16072]: 1653312942660 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
 24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312942660] 243
May 23 13:35:42 XR1000 local1.notice CEVENT_APP[16072]: 1653312942839 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
 24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312942839] 243
May 23 13:35:42 XR1000 local1.notice CEVENT_APP[16072]: 1653312942843 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
 24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312942843] 243
May 23 13:35:42 XR1000 local1.notice CEVENT_APP[16072]: 1653312942844 wl0
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M2_RX [CE: 1
159 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312942844] 243
May 23 13:35:42 XR1000 local1.notice CEVENT_APP[16072]: 1653312942847 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
 24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312942847] 243
May 23 13:35:42 XR1000 local1.notice CEVENT_APP[16072]: 1653312942849 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
 24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312942849] 243
May 23 13:35:42 XR1000 local1.notice CEVENT_APP[16072]: 1653312942853 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
 24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312942853] 243
May 23 13:35:42 XR1000 local1.notice CEVENT_APP[16072]: 1653312942854 wl0
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M4_RX [CE: 1
137 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312942854] 243
May 23 13:35:42 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db RADIUS:
starting accounting session 2DC3AC80E637018C 129
May 23 13:35:42 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db WPA: pairwise
key handshake completed (RSN) 120
May 23 13:35:42 XR1000 local1.notice CEVENT_APP[16072]: 1653312942858 wl0
80:9F:9B:5A:F7:DB 0 0136 0000 0000 Driver -- E_AUTHORIZED/136 163
May 23 13:35:53 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
disassociated 103
May 23 13:35:53 XR1000 local1.notice CEVENT_APP[16072]: 1653312953167 wl0
80:9F:9B:5A:F7:DB 0 0000 0003 0000 Driver -- E_DEAUTH_IND/6 163
May 23 13:35:53 XR1000 local1.notice CEVENT_APP[16072]: 1653312953166 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX DEAUTH_RX [CE: 1

```

```

24 1/0x0001/CE_D2C 24 10/0x000A/DEAUTH_RX 0x40000000 1653312953166] 244
May 23 13:35:53 XR1000 local1.notice CEVENT_APP[16072]: 1653312953186 wl0
80:9F:9B:5A:F7:DB 0 0000 0007 0000 Driver -- E_DEAUTH/5 163
May 23 13:35:53 XR1000 local1.notice CEVENT_APP[16072]: 1653312953196 wl0
80:9F:9B:5A:F7:DB 0 0000 0007 0000 Driver -- E_DEAUTH/5 163
May 23 13:35:55 XR1000 local1.notice CEVENT_APP[16072]: 1653312955801 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312955801] 243
May 23 13:35:55 XR1000 local1.notice CEVENT_APP[16072]: 1653312955802 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:35:55 XR1000 local1.notice CEVENT_APP[16072]: 1653312955802 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312955802] 243
May 23 13:35:55 XR1000 local1.notice CEVENT_APP[16072]: 1653312955826 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC/7 163
May 23 13:35:55 XR1000 local1.notice CEVENT_APP[16072]: 1653312955826 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX ASSOC_RX [CE: 1
24 1/0x0001/CE_D2C 24 7/0x0007/ASSOC_RX 0x40000000 1653312955826] 243
May 23 13:35:55 XR1000 local1.notice CEVENT_APP[16072]: 1653312955826 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX ASSOC_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 1/0x0001/ASSOC_TX 0x80000000 1653312955826] 243
May 23 13:35:55 XR1000 local1.notice CEVENT_APP[16072]: 1653312955827 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC_IND/8 163
May 23 13:35:55 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
associated 100
May 23 13:35:55 XR1000 local1.notice CEVENT_APP[16072]: 1653312955844 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312955844] 243
May 23 13:35:56 XR1000 local1.notice CEVENT_APP[16072]: 1653312956455 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312956455] 243
May 23 13:35:56 XR1000 local1.notice CEVENT_APP[16072]: 1653312956461 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312956461] 243
May 23 13:35:56 XR1000 local1.notice CEVENT_APP[16072]: 1653312956462 wl0
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M2_RX [CE: 1
159 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312956462] 243
May 23 13:35:56 XR1000 local1.notice CEVENT_APP[16072]: 1653312956462 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312956462] 243
May 23 13:35:57 XR1000 local1.notice CEVENT_APP[16072]: 1653312957062 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312957062] 243
May 23 13:35:57 XR1000 local1.notice CEVENT_APP[16072]: 1653312957074 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312957074] 243
May 23 13:35:57 XR1000 local1.notice CEVENT_APP[16072]: 1653312957075 wl0
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M4_RX [CE: 1
137 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312957075] 243
May 23 13:35:57 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db RADIUS:

```

```

starting accounting session 8D95642E0064740B 129
May 23 13:35:57 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db WPA: pairwise
key handshake completed (RSN) 120
May 23 13:35:57 XR1000 local1.notice CEVENT_APP[16072]: 1653312957080 wl0
80:9F:9B:5A:F7:DB      0 0136 0000 0000 Driver  -- E_AUTHORIZED/136          163
May 23 13:36:23 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
disassociated 103
May 23 13:36:23 XR1000 local1.notice CEVENT_APP[16072]: 1653312983747 wl0
80:9F:9B:5A:F7:DB      0 0000 0003 0000 Driver  -- E_DEAUTH_IND/6          163
May 23 13:36:23 XR1000 local1.notice CEVENT_APP[16072]: 1653312983747 wl0
80:9F:9B:5A:F7:DB      0 0000 0000 0000 Driver  RX DEAUTH_RX          [CE: 1
24 1/0x0001/CE_D2C 24 10/0x000A/DEAUTH_RX 0x40000000 1653312983747] 244
May 23 13:36:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312987217 wl0
80:9F:9B:5A:F7:DB      0 0000 0000 0000 Driver  RX AUTH_RX          [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312987217] 243
May 23 13:36:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312987218 wl0
80:9F:9B:5A:F7:DB      0 0000 0000 0000 Driver  -- E_AUTH_IND/4          163
May 23 13:36:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312987217 wl0
80:9F:9B:5A:F7:DB      0 0000 0000 0000 Driver  TX AUTH_TX_QUEUED    [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312987217] 243
May 23 13:36:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312987518 wl0
80:9F:9B:5A:F7:DB      0 0000 0000 0000 Driver  RX AUTH_RX          [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312987518] 243
May 23 13:36:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312987520 wl0
80:9F:9B:5A:F7:DB      0 0000 0001 0000 Driver  -- E_DEAUTH/5          163
May 23 13:36:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312987520 wl0
80:9F:9B:5A:F7:DB      0 0000 0000 0000 Driver  -- E_AUTH_IND/4          163
May 23 13:36:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312987519 wl0
80:9F:9B:5A:F7:DB      0 0000 0000 0000 Driver  TX AUTH_TX_QUEUED    [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312987519] 243
May 23 13:36:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312987818 wl0
80:9F:9B:5A:F7:DB      0 0000 0000 0000 Driver  RX AUTH_RX          [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653312987818] 243
May 23 13:36:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312987819 wl0
80:9F:9B:5A:F7:DB      0 0000 0001 0000 Driver  -- E_DEAUTH/5          163
May 23 13:36:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312987819 wl0
80:9F:9B:5A:F7:DB      0 0000 0000 0000 Driver  -- E_AUTH_IND/4          163
May 23 13:36:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312987819 wl0
80:9F:9B:5A:F7:DB      0 0000 0000 0000 Driver  TX AUTH_TX_QUEUED    [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653312987819] 243
May 23 13:36:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312987834 wl0
80:9F:9B:5A:F7:DB      0 0000 0000 0000 Driver  -- E_ASSOC/7          163
May 23 13:36:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312987834 wl0
80:9F:9B:5A:F7:DB      0 0000 0000 0000 Driver  RX ASSOC_RX          [CE: 1
24 1/0x0001/CE_D2C 24 7/0x0007/ASSOC_RX 0x40000000 1653312987834] 243
May 23 13:36:27 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
associated 100
May 23 13:36:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312987835 wl0
80:9F:9B:5A:F7:DB      0 0000 0000 0000 Driver  TX ASSOC_TX_QUEUED    [CE: 1
24 1/0x0001/CE_D2C 24 1/0x0001/ASSOC_TX 0x80000000 1653312987835] 243

```



```

May 23 13:36:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312987835 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC_IND/8 163
May 23 13:36:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312987850 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312987850] 243
May 23 13:36:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312987921 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312987921] 243
May 23 13:36:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312987926 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312987926] 243
May 23 13:36:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312987927 wl0
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M2_RX [CE: 1
159 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312987927] 243
May 23 13:36:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312987929 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653312987929] 243
May 23 13:36:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312987940 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653312987940] 243
May 23 13:36:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312987943 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653312987943] 243
May 23 13:36:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312987944 wl0
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M4_RX [CE: 1
137 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653312987944] 243
May 23 13:36:27 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db RADIUS:
starting accounting session 6452F6F06CE97A65 129
May 23 13:36:27 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db WPA: pairwise
key handshake completed (RSN) 120
May 23 13:36:27 XR1000 local1.notice CEVENT_APP[16072]: 1653312987946 wl0
80:9F:9B:5A:F7:DB 0 0136 0000 0000 Driver -- E_AUTHORIZED/136 163
May 23 08:36:39 XR1000 user.warn com.netdumasoftware.procmanager: Rapp
com.netdumasoftware.pingheatmap has not responded to watchdog 138
May 23 13:36:45 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
disassociated 103
May 23 13:36:45 XR1000 local1.notice CEVENT_APP[16072]: 1653313005239 wl0
80:9F:9B:5A:F7:DB 0 0000 0003 0000 Driver -- E_DEAUTH_IND/6 163
May 23 13:36:45 XR1000 local1.notice CEVENT_APP[16072]: 1653313005238 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX DEAUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 10/0x000A/DEAUTH_RX 0x40000000 1653313005238] 244
May 23 13:36:45 XR1000 local1.notice CEVENT_APP[16072]: 1653313005259 wl0
80:9F:9B:5A:F7:DB 0 0000 0007 0000 Driver -- E_DEAUTH/5 163
May 23 13:36:45 XR1000 local1.notice CEVENT_APP[16072]: 1653313005296 wl0
80:9F:9B:5A:F7:DB 0 0000 0007 0000 Driver -- E_DEAUTH/5 163
May 23 13:36:48 XR1000 local1.notice CEVENT_APP[16072]: 1653313008295 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653313008295] 243
May 23 13:36:48 XR1000 local1.notice CEVENT_APP[16072]: 1653313008296 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163

```

```

May 23 13:36:48 XR1000 local1.notice CEVENT_APP[16072]: 1653313008295 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653313008295] 243
May 23 13:36:48 XR1000 local1.notice CEVENT_APP[16072]: 1653313008595 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653313008595] 243
May 23 13:36:48 XR1000 local1.notice CEVENT_APP[16072]: 1653313008596 w10
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:36:48 XR1000 local1.notice CEVENT_APP[16072]: 1653313008596 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:36:48 XR1000 local1.notice CEVENT_APP[16072]: 1653313008596 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653313008596] 243
May 23 13:36:48 XR1000 local1.notice CEVENT_APP[16072]: 1653313008894 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653313008894] 243
May 23 13:36:48 XR1000 local1.notice CEVENT_APP[16072]: 1653313008897 w10
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:36:48 XR1000 local1.notice CEVENT_APP[16072]: 1653313008898 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:36:48 XR1000 local1.notice CEVENT_APP[16072]: 1653313008898 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653313008898] 243
May 23 13:36:49 XR1000 daemon.info hostapd: w10: STA 80:9f:9b:5a:f7:db IEEE 802.11:
associated 100
May 23 13:36:49 XR1000 local1.notice CEVENT_APP[16072]: 1653313009130 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC/7 163
May 23 13:36:49 XR1000 local1.notice CEVENT_APP[16072]: 1653313009129 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX ASSOC_RX [CE: 1
24 1/0x0001/CE_D2C 24 7/0x0007/ASSOC_RX 0x40000000 1653313009129] 243
May 23 13:36:49 XR1000 local1.notice CEVENT_APP[16072]: 1653313009129 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX ASSOC_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 1/0x0001/ASSOC_TX 0x80000000 1653313009129] 243
May 23 13:36:49 XR1000 local1.notice CEVENT_APP[16072]: 1653313009130 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC_IND/8 163
May 23 13:36:49 XR1000 local1.notice CEVENT_APP[16072]: 1653313009143 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653313009143] 243
May 23 13:36:49 XR1000 local1.notice CEVENT_APP[16072]: 1653313009152 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653313009152] 243
May 23 13:36:49 XR1000 local1.notice CEVENT_APP[16072]: 1653313009156 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653313009156] 243
May 23 13:36:49 XR1000 local1.notice CEVENT_APP[16072]: 1653313009157 w10
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M2_RX [CE: 1
159 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653313009157] 243
May 23 13:36:49 XR1000 local1.notice CEVENT_APP[16072]: 1653313009159 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653313009159] 243

```

May 23 13:36:49 XR1000 local1.notice CEVENT_APP[16072]: 1653313009604 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653313009604] 243
May 23 13:36:49 XR1000 local1.notice CEVENT_APP[16072]: 1653313009608 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653313009608] 243
May 23 13:36:49 XR1000 local1.notice CEVENT_APP[16072]: 1653313009608 wl0
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M4_RX [CE: 1
137 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653313009608] 243
May 23 13:36:49 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db RADIUS:
starting accounting session 00746CA190337677 129
May 23 13:36:49 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db WPA: pairwise
key handshake completed (RSN) 120
May 23 13:36:49 XR1000 local1.notice CEVENT_APP[16072]: 1653313009719 wl0
80:9F:9B:5A:F7:DB 0 0136 0000 0000 Driver -- E_AUTHORIZED/136 163
May 23 08:36:52 XR1000 user.info com.netdumasoftware.neighwatch: DHCP new event. 86
May 23 08:36:52 XR1000 user.info com.netdumasoftware.neighwatch: DHCP lease change.
89
May 23 08:36:55 XR1000 user.info com.netdumasoftware.neighwatch: DHCP new event. 86
May 23 08:36:55 XR1000 user.info com.netdumasoftware.neighwatch: DHCP lease change.
89
May 23 08:36:58 XR1000 user.info com.netdumasoftware.neighwatch: DHCP new event. 86
May 23 08:36:58 XR1000 user.info com.netdumasoftware.neighwatch: DHCP lease change.
89
May 23 13:37:21 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
disassociated 103
May 23 13:37:21 XR1000 local1.notice CEVENT_APP[16072]: 1653313041767 wl0
80:9F:9B:5A:F7:DB 0 0000 0003 0000 Driver -- E_DEAUTH_IND/6 163
May 23 13:37:21 XR1000 local1.notice CEVENT_APP[16072]: 1653313041766 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX DEAUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 10/0x000A/DEAUTH_RX 0x40000000 1653313041766] 244
May 23 13:37:25 XR1000 local1.notice CEVENT_APP[16072]: 1653313045213 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653313045213] 243
May 23 13:37:25 XR1000 local1.notice CEVENT_APP[16072]: 1653313045214 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:37:25 XR1000 local1.notice CEVENT_APP[16072]: 1653313045214 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653313045214] 243
May 23 13:37:25 XR1000 local1.notice CEVENT_APP[16072]: 1653313045514 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653313045514] 243
May 23 13:37:25 XR1000 local1.notice CEVENT_APP[16072]: 1653313045516 wl0
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:37:25 XR1000 local1.notice CEVENT_APP[16072]: 1653313045516 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:37:25 XR1000 local1.notice CEVENT_APP[16072]: 1653313045515 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653313045515] 243
May 23 13:37:25 XR1000 local1.notice CEVENT_APP[16072]: 1653313045814 wl0

```

80:9F:9B:5A:F7:DB    0 0000 0000 0000 Driver  RX  AUTH_RX                [CE: 1
 24 1/0x0001/CE_D2C  24 6/0x0006/AUTH_RX 0x40000000 1653313045814] 243
May 23 13:37:25 XR1000 local1.notice CEVENT_APP[16072]: 1653313045815 w10
80:9F:9B:5A:F7:DB    0 0000 0001 0000 Driver  --  E_DEAUTH/5                163
May 23 13:37:25 XR1000 local1.notice CEVENT_APP[16072]: 1653313045815 w10
80:9F:9B:5A:F7:DB    0 0000 0000 0000 Driver  --  E_AUTH_IND/4              163
May 23 13:37:25 XR1000 local1.notice CEVENT_APP[16072]: 1653313045815 w10
80:9F:9B:5A:F7:DB    0 0000 0000 0000 Driver  TX  AUTH_TX_QUEUED          [CE: 1
 24 1/0x0001/CE_D2C  24 0/0x0000/AUTH_TX 0x80000000 1653313045815] 243
May 23 13:37:26 XR1000 local1.notice CEVENT_APP[16072]: 1653313046115 w10
80:9F:9B:5A:F7:DB    0 0000 0000 0000 Driver  RX  AUTH_RX                [CE: 1
 24 1/0x0001/CE_D2C  24 6/0x0006/AUTH_RX 0x40000000 1653313046115] 243
May 23 13:37:26 XR1000 local1.notice CEVENT_APP[16072]: 1653313046116 w10
80:9F:9B:5A:F7:DB    0 0000 0001 0000 Driver  --  E_DEAUTH/5                163
May 23 13:37:26 XR1000 local1.notice CEVENT_APP[16072]: 1653313046118 w10
80:9F:9B:5A:F7:DB    0 0000 0000 0000 Driver  --  E_AUTH_IND/4              163
May 23 13:37:26 XR1000 local1.notice CEVENT_APP[16072]: 1653313046116 w10
80:9F:9B:5A:F7:DB    0 0000 0000 0000 Driver  TX  AUTH_TX_QUEUED          [CE: 1
 24 1/0x0001/CE_D2C  24 0/0x0000/AUTH_TX 0x80000000 1653313046116] 243
May 23 13:37:26 XR1000 local1.notice CEVENT_APP[16072]: 1653313046414 w10
80:9F:9B:5A:F7:DB    0 0000 0000 0000 Driver  RX  AUTH_RX                [CE: 1
 24 1/0x0001/CE_D2C  24 6/0x0006/AUTH_RX 0x40000000 1653313046414] 243
May 23 13:37:26 XR1000 local1.notice CEVENT_APP[16072]: 1653313046415 w10
80:9F:9B:5A:F7:DB    0 0000 0001 0000 Driver  --  E_DEAUTH/5                163
May 23 13:37:26 XR1000 local1.notice CEVENT_APP[16072]: 1653313046416 w10
80:9F:9B:5A:F7:DB    0 0000 0000 0000 Driver  --  E_AUTH_IND/4              163
May 23 13:37:26 XR1000 local1.notice CEVENT_APP[16072]: 1653313046416 w10
80:9F:9B:5A:F7:DB    0 0000 0000 0000 Driver  TX  AUTH_TX_QUEUED          [CE: 1
 24 1/0x0001/CE_D2C  24 0/0x0000/AUTH_TX 0x80000000 1653313046416] 243
May 23 13:37:29 XR1000 local1.notice CEVENT_APP[16072]: 1653313049740 w10
80:9F:9B:5A:F7:DB    0 0000 0000 0000 Driver  RX  AUTH_RX                [CE: 1
 24 1/0x0001/CE_D2C  24 6/0x0006/AUTH_RX 0x40000000 1653313049740] 243
May 23 13:37:29 XR1000 local1.notice CEVENT_APP[16072]: 1653313049742 w10
80:9F:9B:5A:F7:DB    0 0000 0001 0000 Driver  --  E_DEAUTH/5                163
May 23 13:37:29 XR1000 local1.notice CEVENT_APP[16072]: 1653313049742 w10
80:9F:9B:5A:F7:DB    0 0000 0000 0000 Driver  --  E_AUTH_IND/4              163
May 23 13:37:29 XR1000 local1.notice CEVENT_APP[16072]: 1653313049742 w10
80:9F:9B:5A:F7:DB    0 0000 0000 0000 Driver  TX  AUTH_TX_QUEUED          [CE: 1
 24 1/0x0001/CE_D2C  24 0/0x0000/AUTH_TX 0x80000000 1653313049742] 243
May 23 13:37:30 XR1000 local1.notice CEVENT_APP[16072]: 1653313050038 w10
80:9F:9B:5A:F7:DB    0 0000 0000 0000 Driver  RX  AUTH_RX                [CE: 1
 24 1/0x0001/CE_D2C  24 6/0x0006/AUTH_RX 0x40000000 1653313050038] 243
May 23 13:37:30 XR1000 local1.notice CEVENT_APP[16072]: 1653313050038 w10
80:9F:9B:5A:F7:DB    0 0000 0001 0000 Driver  --  E_DEAUTH/5                163
May 23 13:37:30 XR1000 local1.notice CEVENT_APP[16072]: 1653313050039 w10
80:9F:9B:5A:F7:DB    0 0000 0000 0000 Driver  --  E_AUTH_IND/4              163
May 23 13:37:30 XR1000 local1.notice CEVENT_APP[16072]: 1653313050042 w10
80:9F:9B:5A:F7:DB    0 0000 0000 0000 Driver  TX  AUTH_TX_QUEUED          [CE: 1
 24 1/0x0001/CE_D2C  24 0/0x0000/AUTH_TX 0x80000000 1653313050042] 243
May 23 13:37:30 XR1000 local1.notice CEVENT_APP[16072]: 1653313050342 w10

```

```

80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653313050342] 243
May 23 13:37:30 XR1000 local1.notice CEVENT_APP[16072]: 1653313050343 wl0
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:37:30 XR1000 local1.notice CEVENT_APP[16072]: 1653313050343 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:37:30 XR1000 local1.notice CEVENT_APP[16072]: 1653313050343 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653313050343] 243
May 23 13:37:30 XR1000 local1.notice CEVENT_APP[16072]: 1653313050358 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC/7 163
May 23 13:37:30 XR1000 local1.notice CEVENT_APP[16072]: 1653313050359 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX ASSOC_RX [CE: 1
24 1/0x0001/CE_D2C 24 7/0x0007/ASSOC_RX 0x40000000 1653313050359] 243
May 23 13:37:30 XR1000 local1.notice CEVENT_APP[16072]: 1653313050361 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX ASSOC_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 1/0x0001/ASSOC_TX 0x80000000 1653313050361] 243
May 23 13:37:30 XR1000 local1.notice CEVENT_APP[16072]: 1653313050362 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC_IND/8 163
May 23 13:37:30 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
associated 100
May 23 13:37:30 XR1000 local1.notice CEVENT_APP[16072]: 1653313050379 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653313050379] 243
May 23 13:37:30 XR1000 local1.notice CEVENT_APP[16072]: 1653313050382 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653313050382] 243
May 23 13:37:30 XR1000 local1.notice CEVENT_APP[16072]: 1653313050390 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653313050390] 243
May 23 13:37:30 XR1000 local1.notice CEVENT_APP[16072]: 1653313050391 wl0
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M2_RX [CE: 1
159 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653313050391] 243
May 23 13:37:30 XR1000 local1.notice CEVENT_APP[16072]: 1653313050393 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653313050393] 243
May 23 13:37:30 XR1000 local1.notice CEVENT_APP[16072]: 1653313050588 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653313050588] 243
May 23 13:37:30 XR1000 local1.notice CEVENT_APP[16072]: 1653313050594 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653313050594] 243
May 23 13:37:30 XR1000 local1.notice CEVENT_APP[16072]: 1653313050594 wl0
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M4_RX [CE: 1
137 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653313050594] 243
May 23 13:37:30 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db RADIUS:
starting accounting session 4E9DE5E72F2D45DC 129
May 23 13:37:30 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db WPA: pairwise
key handshake completed (RSN) 120
May 23 13:37:30 XR1000 local1.notice CEVENT_APP[16072]: 1653313050730 wl0

```

```

80:9F:9B:5A:F7:DB      0 0136 0000 0000 Driver  -- E_AUTHORIZED/136          163
May 23 13:37:52 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
disassociated 103
May 23 13:37:52 XR1000 local1.notice CEVENT_APP[16072]: 1653313072306 wl0
80:9F:9B:5A:F7:DB      0 0000 0003 0000 Driver  -- E_DEAUTH_IND/6          163
May 23 13:37:52 XR1000 local1.notice CEVENT_APP[16072]: 1653313072306 wl0
80:9F:9B:5A:F7:DB      0 0000 0000 0000 Driver  RX  DEAUTH_RX              [CE: 1
24 1/0x0001/CE_D2C      24 10/0x000A/DEAUTH_RX 0x40000000 1653313072306] 244
May 23 13:37:52 XR1000 local1.notice CEVENT_APP[16072]: 1653313072326 wl0
80:9F:9B:5A:F7:DB      0 0000 0007 0000 Driver  -- E_DEAUTH/5            163
May 23 13:37:52 XR1000 local1.notice CEVENT_APP[16072]: 1653313072338 wl0
80:9F:9B:5A:F7:DB      0 0000 0007 0000 Driver  -- E_DEAUTH/5            163
May 23 13:37:55 XR1000 local1.notice CEVENT_APP[16072]: 1653313075860 wl0
80:9F:9B:5A:F7:DB      0 0000 0000 0000 Driver  RX  AUTH_RX              [CE: 1
24 1/0x0001/CE_D2C      24 6/0x0006/AUTH_RX   0x40000000 1653313075860] 243
May 23 13:37:55 XR1000 local1.notice CEVENT_APP[16072]: 1653313075861 wl0
80:9F:9B:5A:F7:DB      0 0000 0000 0000 Driver  -- E_AUTH_IND/4          163
May 23 13:37:55 XR1000 local1.notice CEVENT_APP[16072]: 1653313075861 wl0
80:9F:9B:5A:F7:DB      0 0000 0000 0000 Driver  TX  AUTH_TX_QUEUED       [CE: 1
24 1/0x0001/CE_D2C      24 0/0x0000/AUTH_TX   0x80000000 1653313075861] 243
May 23 13:37:55 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
associated 100
May 23 13:37:55 XR1000 local1.notice CEVENT_APP[16072]: 1653313075887 wl0
80:9F:9B:5A:F7:DB      0 0000 0000 0000 Driver  -- E_ASSOC/7            163
May 23 13:37:55 XR1000 local1.notice CEVENT_APP[16072]: 1653313075887 wl0
80:9F:9B:5A:F7:DB      0 0000 0000 0000 Driver  RX  ASSOC_RX             [CE: 1
24 1/0x0001/CE_D2C      24 7/0x0007/ASSOC_RX 0x40000000 1653313075887] 243
May 23 13:37:55 XR1000 local1.notice CEVENT_APP[16072]: 1653313075888 wl0
80:9F:9B:5A:F7:DB      0 0000 0000 0000 Driver  TX  ASSOC_TX_QUEUED     [CE: 1
24 1/0x0001/CE_D2C      24 1/0x0001/ASSOC_TX 0x80000000 1653313075888] 243
May 23 13:37:55 XR1000 local1.notice CEVENT_APP[16072]: 1653313075888 wl0
80:9F:9B:5A:F7:DB      0 0000 0000 0000 Driver  -- E_ASSOC_IND/8        163
May 23 13:37:55 XR1000 local1.notice CEVENT_APP[16072]: 1653313075898 wl0
80:9F:9B:5A:F7:DB      0 0000 0000 0000 Driver  TX  EAP_TX_QUEUED       [CE: 1
24 1/0x0001/CE_D2C      24 2/0x0002/EAP_TX   0x80000000 1653313075898] 243
May 23 13:37:55 XR1000 local1.notice CEVENT_APP[16072]: 1653313075957 wl0
80:9F:9B:5A:F7:DB      0 0000 0000 0000 Driver  TX  EAP_TX_SUCCESS       [CE: 1
24 1/0x0001/CE_D2C      24 2/0x0002/EAP_TX   0x80000001 1653313075957] 243
May 23 13:37:55 XR1000 local1.notice CEVENT_APP[16072]: 1653313075960 wl0
80:9F:9B:5A:F7:DB      0 0000 0000 0000 Driver  RX  EAP_RX              [CE: 1
24 1/0x0001/CE_D2C      24 8/0x0008/EAP_RX   0x40000000 1653313075960] 243
May 23 13:37:55 XR1000 local1.notice CEVENT_APP[16072]: 1653313075961 wl0
80:9F:9B:5A:F7:DB      6144 0000 0000 0000 EAPD    RX  M2_RX              [CE: 1
159 4/0x0004/CE_D2A      24 2/0x0002/--        0x40000001 1653313075961] 243
May 23 13:37:55 XR1000 local1.notice CEVENT_APP[16072]: 1653313075963 wl0
80:9F:9B:5A:F7:DB      0 0000 0000 0000 Driver  TX  EAP_TX_QUEUED       [CE: 1
24 1/0x0001/CE_D2C      24 2/0x0002/EAP_TX   0x80000000 1653313075963] 243
May 23 13:37:56 XR1000 local1.notice CEVENT_APP[16072]: 1653313076070 wl0
80:9F:9B:5A:F7:DB      0 0000 0000 0000 Driver  TX  EAP_TX_SUCCESS       [CE: 1
24 1/0x0001/CE_D2C      24 2/0x0002/EAP_TX   0x80000001 1653313076070] 243

```

```

May 23 13:37:56 XR1000 local1.notice CEVENT_APP[16072]: 1653313076072 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653313076072] 243
May 23 13:37:56 XR1000 local1.notice CEVENT_APP[16072]: 1653313076073 wl0
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M4_RX [CE: 1
137 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653313076073] 243
May 23 13:37:56 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db RADIUS:
starting accounting session 04052E8326AA49C1 129
May 23 13:37:56 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db WPA: pairwise
key handshake completed (RSN) 120
May 23 13:37:56 XR1000 local1.notice CEVENT_APP[16072]: 1653313076075 wl0
80:9F:9B:5A:F7:DB 0 0136 0000 0000 Driver -- E_AUTHORIZED/136 163
May 23 13:37:58 XR1000 local1.notice CEVENT_APP[16072]: 1653313078848 wl0
80:9F:9B:5A:F7:DB 0 0000 0003 0000 Driver -- E_DEAUTH_IND/6 163
May 23 13:37:58 XR1000 local1.notice CEVENT_APP[16072]: 1653313078848 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX DEAUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 10/0x000A/DEAUTH_RX 0x40000000 1653313078848] 244
May 23 13:37:58 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
disassociated 103
May 23 13:37:58 XR1000 local1.notice CEVENT_APP[16072]: 1653313078852 wl0
80:9F:9B:5A:F7:DB 24 0000 0000 0000 Driver RX DEAUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 10/0x000A/DEAUTH_RX 0x40000000 1653313078852] 244
May 23 13:38:02 XR1000 local1.notice CEVENT_APP[16072]: 1653313082188 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653313082188] 243
May 23 13:38:02 XR1000 local1.notice CEVENT_APP[16072]: 1653313082189 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:38:02 XR1000 local1.notice CEVENT_APP[16072]: 1653313082189 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653313082189] 243
May 23 13:38:02 XR1000 local1.notice CEVENT_APP[16072]: 1653313082212 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC/7 163
May 23 13:38:02 XR1000 local1.notice CEVENT_APP[16072]: 1653313082211 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX ASSOC_RX [CE: 1
24 1/0x0001/CE_D2C 24 7/0x0007/ASSOC_RX 0x40000000 1653313082211] 243
May 23 13:38:02 XR1000 local1.notice CEVENT_APP[16072]: 1653313082211 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX ASSOC_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 1/0x0001/ASSOC_TX 0x80000000 1653313082211] 243
May 23 13:38:02 XR1000 local1.notice CEVENT_APP[16072]: 1653313082215 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC_IND/8 163
May 23 13:38:02 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
associated 100
May 23 13:38:02 XR1000 local1.notice CEVENT_APP[16072]: 1653313082237 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653313082237] 243
May 23 13:38:02 XR1000 local1.notice CEVENT_APP[16072]: 1653313082519 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653313082519] 243
May 23 13:38:02 XR1000 local1.notice CEVENT_APP[16072]: 1653313082525 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1

```

```

24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653313082525] 243
May 23 13:38:02 XR1000 local1.notice CEVENT_APP[16072]: 1653313082526 w10
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M2_RX [CE: 1
159 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653313082526] 243
May 23 13:38:02 XR1000 local1.notice CEVENT_APP[16072]: 1653313082526 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653313082526] 243
May 23 13:38:02 XR1000 local1.notice CEVENT_APP[16072]: 1653313082794 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653313082794] 243
May 23 13:38:02 XR1000 daemon.info hostapd: w10: STA 80:9f:9b:5a:f7:db RADIUS:
starting accounting session CEE93221D0BD483E 129
May 23 13:38:02 XR1000 daemon.info hostapd: w10: STA 80:9f:9b:5a:f7:db WPA: pairwise
key handshake completed (RSN) 120
May 23 13:38:02 XR1000 local1.notice CEVENT_APP[16072]: 1653313082803 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653313082803] 243
May 23 13:38:02 XR1000 local1.notice CEVENT_APP[16072]: 1653313082804 w10
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M4_RX [CE: 1
137 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653313082804] 243
May 23 13:38:02 XR1000 local1.notice CEVENT_APP[16072]: 1653313082804 w10
80:9F:9B:5A:F7:DB 0 0136 0000 0000 Driver -- E_AUTHORIZED/136 163
May 23 13:38:23 XR1000 daemon.info hostapd: w10: STA 80:9f:9b:5a:f7:db IEEE 802.11:
disassociated 103
May 23 13:38:23 XR1000 local1.notice CEVENT_APP[16072]: 1653313103408 w10
80:9F:9B:5A:F7:DB 0 0000 0003 0000 Driver -- E_DEAUTH_IND/6 163
May 23 13:38:23 XR1000 local1.notice CEVENT_APP[16072]: 1653313103408 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX DEAUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 10/0x000A/DEAUTH_RX 0x40000000 1653313103408] 244
May 23 13:38:34 XR1000 local1.notice CEVENT_APP[16072]: 1653313114559 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653313114559] 243
May 23 13:38:34 XR1000 local1.notice CEVENT_APP[16072]: 1653313114560 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:38:34 XR1000 local1.notice CEVENT_APP[16072]: 1653313114560 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653313114560] 243
May 23 13:38:34 XR1000 local1.notice CEVENT_APP[16072]: 1653313114859 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653313114859] 243
May 23 13:38:34 XR1000 local1.notice CEVENT_APP[16072]: 1653313114859 w10
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:38:34 XR1000 local1.notice CEVENT_APP[16072]: 1653313114864 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:38:34 XR1000 local1.notice CEVENT_APP[16072]: 1653313114859 w10
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653313114859] 243
May 23 13:38:34 XR1000 daemon.info hostapd: w10: STA 80:9f:9b:5a:f7:db IEEE 802.11:
associated 100
May 23 13:38:34 XR1000 local1.notice CEVENT_APP[16072]: 1653313114895 w10

```



```

80:9F:9B:5A:F7:DB      0 0000 0000 0000 Driver  -- E_ASSOC/7                      163
May 23 13:38:34 XR1000 local1.notice CEVENT_APP[16072]: 1653313114896 wl0
80:9F:9B:5A:F7:DB      0 0000 0000 0000 Driver  RX ASSOC_RX                      [CE: 1
 24 1/0x0001/CE_D2C    24 7/0x0007/ASSOC_RX 0x40000000 1653313114896] 243
May 23 13:38:34 XR1000 local1.notice CEVENT_APP[16072]: 1653313114896 wl0
80:9F:9B:5A:F7:DB      0 0000 0000 0000 Driver  TX ASSOC_TX_QUEUED             [CE: 1
 24 1/0x0001/CE_D2C    24 1/0x0001/ASSOC_TX 0x80000000 1653313114896] 243
May 23 13:38:34 XR1000 local1.notice CEVENT_APP[16072]: 1653313114902 wl0
80:9F:9B:5A:F7:DB      0 0000 0000 0000 Driver  -- E_ASSOC_IND/8                163
May 23 13:38:34 XR1000 local1.notice CEVENT_APP[16072]: 1653313114909 wl0
80:9F:9B:5A:F7:DB      0 0000 0000 0000 Driver  TX EAP_TX_QUEUED              [CE: 1
 24 1/0x0001/CE_D2C    24 2/0x0002/EAP_TX 0x80000000 1653313114909] 243
May 23 13:38:35 XR1000 local1.notice CEVENT_APP[16072]: 1653313115666 wl0
80:9F:9B:5A:F7:DB      0 0000 0000 0000 Driver  TX EAP_TX_SUCCESS             [CE: 1
 24 1/0x0001/CE_D2C    24 2/0x0002/EAP_TX 0x80000001 1653313115666] 243
May 23 13:38:35 XR1000 local1.notice CEVENT_APP[16072]: 1653313115670 wl0
80:9F:9B:5A:F7:DB      0 0000 0000 0000 Driver  RX EAP_RX                      [CE: 1
 24 1/0x0001/CE_D2C    24 8/0x0008/EAP_RX 0x40000000 1653313115670] 243
May 23 13:38:35 XR1000 local1.notice CEVENT_APP[16072]: 1653313115671 wl0
80:9F:9B:5A:F7:DB      6144 0000 0000 0000 EAPD    RX M2_RX                       [CE: 1
159 4/0x0004/CE_D2A    24 2/0x0002/--          0x40000001 1653313115671] 243
May 23 13:38:35 XR1000 local1.notice CEVENT_APP[16072]: 1653313115671 wl0
80:9F:9B:5A:F7:DB      0 0000 0000 0000 Driver  TX EAP_TX_QUEUED             [CE: 1
 24 1/0x0001/CE_D2C    24 2/0x0002/EAP_TX 0x80000000 1653313115671] 243
May 23 13:38:36 XR1000 local1.notice CEVENT_APP[16072]: 1653313116002 wl1
E4:B3:18:14:CF:08      0 0000 0001 0000 Driver  -- E_DEAUTH_IND/6              163
May 23 13:38:36 XR1000 local1.notice CEVENT_APP[16072]: 1653313116001 wl1
E4:B3:18:14:CF:08      0 0000 0000 0000 Driver  RX DEAUTH_RX                  [CE: 1
 24 1/0x0001/CE_D2C    24 10/0x000A/DEAUTH_RX 0x40000000 1653313116001] 244
May 23 13:38:36 XR1000 local1.notice CEVENT_APP[16072]: 1653313116001 wl0
80:9F:9B:5A:F7:DB      0 0000 0000 0000 Driver  TX EAP_TX_SUCCESS             [CE: 1
 24 1/0x0001/CE_D2C    24 2/0x0002/EAP_TX 0x80000001 1653313116001] 243
May 23 13:38:36 XR1000 daemon.info hostapd: wl1: STA e4:b3:18:14:cf:08 IEEE 802.11:
disassociated 103
May 23 13:38:36 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db RADIUS:
starting accounting session D33E3833EAF82850 129
May 23 13:38:36 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db WPA: pairwise
key handshake completed (RSN) 120
May 23 13:38:36 XR1000 local1.notice CEVENT_APP[16072]: 1653313116005 wl0
80:9F:9B:5A:F7:DB      0 0000 0000 0000 Driver  RX EAP_RX                      [CE: 1
 24 1/0x0001/CE_D2C    24 8/0x0008/EAP_RX 0x40000000 1653313116005] 243
May 23 13:38:36 XR1000 local1.notice CEVENT_APP[16072]: 1653313116006 wl0
80:9F:9B:5A:F7:DB      6144 0000 0000 0000 EAPD    RX M4_RX                       [CE: 1
137 4/0x0004/CE_D2A    24 2/0x0002/--          0x40000001 1653313116006] 243
May 23 13:38:36 XR1000 local1.notice CEVENT_APP[16072]: 1653313116006 wl0
80:9F:9B:5A:F7:DB      0 0136 0000 0000 Driver  -- E_AUTHORIZED/136            163
May 23 08:38:39 XR1000 user.warn com.netdumasoftware.procmanager: Rapp
com.netdumasoftware.pingheatmap has not responded to watchdog 138
May 23 13:39:08 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
disassociated 103

```

```

May 23 13:39:08 XR1000 local1.notice CEVENT_APP[16072]: 1653313148965 wl0
80:9F:9B:5A:F7:DB 0 0000 0003 0000 Driver -- E_DEAUTH_IND/6 163
May 23 13:39:08 XR1000 local1.notice CEVENT_APP[16072]: 1653313148965 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX DEAUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 10/0x000A/DEAUTH_RX 0x40000000 1653313148965] 244
May 23 13:39:11 XR1000 local1.notice CEVENT_APP[16072]: 1653313151639 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653313151639] 243
May 23 13:39:11 XR1000 local1.notice CEVENT_APP[16072]: 1653313151640 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:39:11 XR1000 local1.notice CEVENT_APP[16072]: 1653313151640 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653313151640] 243
May 23 13:39:11 XR1000 local1.notice CEVENT_APP[16072]: 1653313151645 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653313151645] 243
May 23 13:39:11 XR1000 local1.notice CEVENT_APP[16072]: 1653313151651 wl0
80:9F:9B:5A:F7:DB 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:39:11 XR1000 local1.notice CEVENT_APP[16072]: 1653313151651 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:39:11 XR1000 local1.notice CEVENT_APP[16072]: 1653313151651 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653313151651] 243
May 23 13:39:11 XR1000 local1.notice CEVENT_APP[16072]: 1653313151654 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC/7 163
May 23 13:39:11 XR1000 local1.notice CEVENT_APP[16072]: 1653313151654 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX ASSOC_RX [CE: 1
24 1/0x0001/CE_D2C 24 7/0x0007/ASSOC_RX 0x40000000 1653313151654] 243
May 23 13:39:11 XR1000 local1.notice CEVENT_APP[16072]: 1653313151656 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX ASSOC_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 1/0x0001/ASSOC_TX 0x80000000 1653313151656] 243
May 23 13:39:11 XR1000 local1.notice CEVENT_APP[16072]: 1653313151658 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver -- E_ASSOC_IND/8 163
May 23 13:39:11 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
associated 100
May 23 13:39:11 XR1000 local1.notice CEVENT_APP[16072]: 1653313151668 wl0
34:9F:7B:2C:D8:6E 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653313151668] 243
May 23 13:39:11 XR1000 local1.notice CEVENT_APP[16072]: 1653313151669 wl0
34:9F:7B:2C:D8:6E 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:39:11 XR1000 local1.notice CEVENT_APP[16072]: 1653313151670 wl0
34:9F:7B:2C:D8:6E 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:39:11 XR1000 local1.notice CEVENT_APP[16072]: 1653313151674 wl0
34:9F:7B:2C:D8:6E 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653313151674] 243
May 23 13:39:11 XR1000 local1.notice CEVENT_APP[16072]: 1653313151674 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653313151674] 243
May 23 13:39:11 XR1000 local1.notice CEVENT_APP[16072]: 1653313151775 wl0
34:9F:7B:2C:D8:6E 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1

```

```

24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653313151775] 243
May 23 13:39:11 XR1000 local1.notice CEVENT_APP[16072]: 1653313151776 wl0
34:9F:7B:2C:D8:6E 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:39:11 XR1000 local1.notice CEVENT_APP[16072]: 1653313151777 wl0
34:9F:7B:2C:D8:6E 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:39:11 XR1000 local1.notice CEVENT_APP[16072]: 1653313151778 wl0
34:9F:7B:2C:D8:6E 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653313151778] 243
May 23 13:39:12 XR1000 local1.notice CEVENT_APP[16072]: 1653313152350 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653313152350] 243
May 23 13:39:12 XR1000 local1.notice CEVENT_APP[16072]: 1653313152356 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653313152356] 243
May 23 13:39:12 XR1000 local1.notice CEVENT_APP[16072]: 1653313152357 wl0
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M2_RX [CE: 1
159 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653313152357] 243
May 23 13:39:12 XR1000 local1.notice CEVENT_APP[16072]: 1653313152358 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653313152358] 243
May 23 13:39:13 XR1000 local1.notice CEVENT_APP[16072]: 1653313153362 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653313153362] 243
May 23 13:39:14 XR1000 local1.notice CEVENT_APP[16072]: 1653313154366 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653313154366] 243
May 23 13:39:15 XR1000 local1.notice CEVENT_APP[16072]: 1653313155370 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000000 1653313155370] 243
May 23 13:39:16 XR1000 local1.notice CEVENT_APP[16072]: 1653313156374 wl0
80:9F:9B:5A:F7:DB 0 0000 0002 0000 Driver TX DEAUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 4/0x0004/DEAUTH_TX 0x80000000 1653313156374] 244
May 23 13:39:19 XR1000 local1.notice CEVENT_APP[16072]: 1653313159484 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver TX EAP_TX_SUCCESS [CE: 1
24 1/0x0001/CE_D2C 24 2/0x0002/EAP_TX 0x80000001 1653313159484] 243
May 23 13:39:19 XR1000 local1.notice CEVENT_APP[16072]: 1653313159489 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX EAP_RX [CE: 1
24 1/0x0001/CE_D2C 24 8/0x0008/EAP_RX 0x40000000 1653313159489] 243
May 23 13:39:19 XR1000 local1.notice CEVENT_APP[16072]: 1653313159489 wl0
80:9F:9B:5A:F7:DB 6144 0000 0000 0000 EAPD RX M4_RX [CE: 1
137 4/0x0004/CE_D2A 24 2/0x0002/-- 0x40000001 1653313159489] 243
May 23 13:39:21 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
deauthenticated due to local deauth request 133
May 23 13:39:21 XR1000 daemon.info hostapd: wl0: STA 80:9f:9b:5a:f7:db IEEE 802.11:
disassociated 103
May 23 13:39:21 XR1000 local1.notice CEVENT_APP[16072]: 1653313161495 wl0
80:9F:9B:5A:F7:DB 0 0000 0003 0000 Driver -- E_DEAUTH_IND/6 163
May 23 13:39:21 XR1000 local1.notice CEVENT_APP[16072]: 1653313161494 wl0
80:9F:9B:5A:F7:DB 0 0000 0000 0000 Driver RX DEAUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 10/0x000A/DEAUTH_RX 0x40000000 1653313161494] 244

```

```

May 23 13:39:21 XR1000 local1.notice CEVENT_APP[16072]: 1653313161767 wl0
34:9F:7B:2C:D8:6E 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653313161767] 243
May 23 13:39:21 XR1000 local1.notice CEVENT_APP[16072]: 1653313161768 wl0
34:9F:7B:2C:D8:6E 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:39:21 XR1000 local1.notice CEVENT_APP[16072]: 1653313161768 wl0
34:9F:7B:2C:D8:6E 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:39:21 XR1000 local1.notice CEVENT_APP[16072]: 1653313161768 wl0
34:9F:7B:2C:D8:6E 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653313161768] 243
May 23 13:39:21 XR1000 local1.notice CEVENT_APP[16072]: 1653313161991 wl0
34:9F:7B:2C:D8:6E 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653313161991] 243
May 23 13:39:21 XR1000 local1.notice CEVENT_APP[16072]: 1653313161993 wl0
34:9F:7B:2C:D8:6E 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:39:21 XR1000 local1.notice CEVENT_APP[16072]: 1653313161993 wl0
34:9F:7B:2C:D8:6E 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:39:21 XR1000 local1.notice CEVENT_APP[16072]: 1653313161992 wl0
34:9F:7B:2C:D8:6E 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653313161992] 243
May 23 13:39:22 XR1000 local1.notice CEVENT_APP[16072]: 1653313162110 wl0
34:9F:7B:2C:D8:6E 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653313162110] 243
May 23 13:39:22 XR1000 local1.notice CEVENT_APP[16072]: 1653313162113 wl0
34:9F:7B:2C:D8:6E 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:39:22 XR1000 local1.notice CEVENT_APP[16072]: 1653313162113 wl0
34:9F:7B:2C:D8:6E 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:39:22 XR1000 local1.notice CEVENT_APP[16072]: 1653313162112 wl0
34:9F:7B:2C:D8:6E 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653313162112] 243
May 23 13:39:27 XR1000 local1.notice CEVENT_APP[16072]: 1653313167272 wl0
34:9F:7B:2C:D8:6E 0 0000 0000 0000 Driver RX AUTH_RX [CE: 1
24 1/0x0001/CE_D2C 24 6/0x0006/AUTH_RX 0x40000000 1653313167272] 243
May 23 13:39:27 XR1000 local1.notice CEVENT_APP[16072]: 1653313167273 wl0
34:9F:7B:2C:D8:6E 0 0000 0001 0000 Driver -- E_DEAUTH/5 163
May 23 13:39:27 XR1000 local1.notice CEVENT_APP[16072]: 1653313167273 wl0
34:9F:7B:2C:D8:6E 0 0000 0000 0000 Driver -- E_AUTH_IND/4 163
May 23 13:39:27 XR1000 local1.notice CEVENT_APP[16072]: 1653313167273 wl0
34:9F:7B:2C:D8:6E 0 0000 0000 0000 Driver TX AUTH_TX_QUEUED [CE: 1
24 1/0x0001/CE_D2C 24 0/0x0000/AUTH_TX 0x80000000 1653313167273] 243

```