

Event Log

Clear Log

Refresh

Time	Category	Message
2020-07-01, 21:18:14	Warning (5)	QOS=1.1,CM-VER=3.1;
2020-07-01, 21:18:09	Notice (6)	DS profile assignment change. DS Chan ID: 32; Previous Profile: ; New Profile: 1 2 3 ;CM-MAC=3c:37:86:e7:e1:88;CMTS-MAC=2c:0b:e9:14:80:7d;CM-QOS=1.1,CM-VER=3.1;
2020-07-01, 21:18:00	Notice (6)	TLV-11 - unrecognized Oid.CM-MAC=3c:37:86:e7:e1:88;CMTS-MAC=2c:0b:e9:14:80:7d;CM-QOS=1.1,CM-VER=3.1;
2020-07-01, 21:18:00	Error (4)	Missing BP Configuration Setting TLV Type: 17.9,CM-MAC=3c:37:86:e7:e1:88;CMTS-MAC=2c:0b:e9:14:80:7d;CM-QOS=1.1,CM-VER=3.1;
2020-07-01, 21:18:00	Error (4)	Missing BP Configuration Setting TLV Type: 17.8,CM-MAC=3c:37:86:e7:e1:88;CMTS-MAC=2c:0b:e9:14:80:7d;CM-QOS=1.1,CM-VER=3.1;
2020-07-01, 21:18:00	Error (4)	Missing BP Configuration Setting TLV Type: 17.7,CM-MAC=3c:37:86:e7:e1:88;CMTS-MAC=2c:0b:e9:14:80:7d;CM-QOS=1.1,CM-VER=3.1;
2020-07-01, 21:18:00	Error (4)	Missing BP Configuration Setting TLV Type: 17.6,CM-MAC=3c:37:86:e7:e1:88;CMTS-MAC=2c:0b:e9:14:80:7d;CM-QOS=1.1,CM-VER=3.1;
2020-07-01, 21:18:00	Error (4)	Missing BP Configuration Setting TLV Type: 17.5,CM-MAC=3c:37:86:e7:e1:88;CMTS-MAC=2c:0b:e9:14:80:7d;CM-QOS=1.1,CM-VER=3.1;
2020-07-01, 21:18:00	Error (4)	Missing BP Configuration Setting TLV Type: 17.4,CM-MAC=3c:37:86:e7:e1:88;CMTS-MAC=2c:0b:e9:14:80:7d;CM-QOS=1.1,CM-VER=3.1;
2020-07-01, 21:18:00	Error (4)	Missing BP Configuration Setting TLV Type: 17.3,CM-MAC=3c:37:86:e7:e1:88;CMTS-MAC=2c:0b:e9:14:80:7d;CM-QOS=1.1,CM-VER=3.1;
2020-07-01, 21:18:00	Error (4)	Missing BP Configuration Setting TLV Type: 17.2,CM-MAC=3c:37:86:e7:e1:88;CMTS-MAC=2c:0b:e9:14:80:7d;CM-QOS=1.1,CM-VER=3.1;
2020-07-01, 21:18:00	Error (4)	Missing BP Configuration Setting TLV Type: 17.1,CM-MAC=3c:37:86:e7:e1:88;CMTS-MAC=2c:0b:e9:14:80:7d;CM-QOS=1.1,CM-VER=3.1;
Time Not Established	Warning (5)	DHCP WARNING - Non-critical field invalid in response ,CM-MAC=3c:37:86:e7:e1:88;CMTS-MAC=2c:0b:e9:14:80:7d;CM-QOS=1.1,CM-VER=3.1;
Time Not Established	Notice (6)	Honoring MDD: IP provisioning mode = IPv4
Time Not Established	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing ,CM-MAC=3c:37:86:e7:e1:88;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.1,CM-VER=3.1;
Time Not Established	Critical (3)	No Ranging Response received - T3 time-out,CM-MAC=3c:37:86:e7:e1:88;CMTS-MAC=2c:0b:e9:14:80:7d;CM-QOS=1.1,CM-VER=3.1;
Time Not Established	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing ,CM-MAC=3c:37:86:e7:e1:88;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.1,CM-VER=3.1;
2020-07-01, 19:12:43	Critical (3)	Resetting the cable modem due to docsDevResetNow
Time Not Established	Critical (3)	No Ranging Response received - T3 time-out,CM-MAC=3c:37:86:e7:e1:88;CMTS-MAC=2c:0b:e9:14:80:7d;CM-QOS=1.1,CM-VER=3.1;
Time Not Established	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing ,CM-MAC=3c:37:86:e7:e1:88;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.1,CM-VER=3.1;
Time Not Established	Critical (3)	No Ranging Response received - T3 time-out,CM-MAC=3c:37:86:e7:e1:88;CMTS-MAC=2c:0b:e9:14:80:7d;CM-QOS=1.1,CM-VER=3.1;
Time Not Established	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing ,CM-MAC=3c:37:86:e7:e1:88;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.1,CM-VER=3.1;
Time Not Established	Critical (3)	No Ranging Response received - T3 time-out,CM-MAC=3c:37:86:e7:e1:88;CMTS-MAC=2c:0b:e9:14:80:7d;CM-QOS=1.1,CM-VER=3.1;
Time Not Established	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing ,CM-MAC=3c:37:86:e7:e1:88;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.1,CM-VER=3.1;
2020-07-01, 18:28:11	Critical (3)	Resetting the cable modem due to docsDevResetNow
Time Not Established	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing ,CM-MAC=3c:37:86:e7:e1:88;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.1,CM-VER=3.1;
Time Not Established	Critical (3)	No Ranging Response received - T3 time-out,CM-MAC=3c:37:86:e7:e1:88;CMTS-MAC=2c:0b:e9:14:80:7d;CM-QOS=1.1,CM-VER=3.1;
Time Not Established	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing ,CM-MAC=3c:37:86:e7:e1:88;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.1,CM-VER=3.1;
Time Not Established	Critical (3)	No Ranging Response received - T3 time-out,CM-MAC=3c:37:86:e7:e1:88;CMTS-MAC=2c:0b:e9:14:80:7d;CM-QOS=1.1,CM-VER=3.1;
Time Not Established	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing ,CM-MAC=3c:37:86:e7:e1:88;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.1,CM-VER=3.1;
2020-06-27, 22:37:10	Critical (3)	Resetting the cable modem due to docsDevResetNow
Time Not Established	Critical (3)	No Ranging Response received - T3 time-out,CM-MAC=3c:37:86:e7:e1:88;CMTS-MAC=2c:0b:e9:14:80:7d;CM-QOS=1.1,CM-VER=3.1;
Time Not Established	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing ,CM-MAC=3c:37:86:e7:e1:88;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.1,CM-VER=3.1;
Time Not Established	Critical (3)	No Ranging Response received - T3 time-out,CM-MAC=3c:37:86:e7:e1:88;CMTS-MAC=2c:0b:e9:14:80:7d;CM-QOS=1.1,CM-VER=3.1;
Time Not Established	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing ,CM-MAC=3c:37:86:e7:e1:88;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.1,CM-VER=3.1;
Time Not Established	Critical (3)	No Ranging Response received - T3 time-out,CM-MAC=3c:37:86:e7:e1:88;CMTS-MAC=2c:0b:e9:14:80:7d;CM-QOS=1.1,CM-VER=3.1;