

Clear Log

Refresh

Time	Priority	Description
2020-07-06 17:19:41	Warning (5)	REG-RSP-MP Mismatch Between Calculated Value for P1 6hi Compared to CCAP Provided Value:CM-MAC=3c:37:86:e7:e1:88:CMTS-MAC=2c:0b:e9:14:80:7d:CM-QOS=1.1:CM-VER=3.1;
2020-07-06 17:19:29	Notice (6)	TLV-T1 - unrecognized OID:CM-MAC=3c:37:86:e7:e1:88:CMTS-MAC=2c:0b:e9:14:80:7d:CM-QOS=1.1:CM-VER=3.1;
2020-07-06 17:19:29	Error (4)	Missing BP Configuration Setting TLV Type: 17.9:CM-MAC=3c:37:86:e7:e1:88:CMTS-MAC=2c:0b:e9:14:80:7d:CM-QOS=1.1:CM-VER=3.1;
2020-07-06 17:19:29	Error (4)	Missing BP Configuration Setting TLV Type: 17.8:CM-MAC=3c:37:86:e7:e1:88:CMTS-MAC=2c:0b:e9:14:80:7d:CM-QOS=1.1:CM-VER=3.1;
2020-07-06 17:19:29	Error (4)	Missing BP Configuration Setting TLV Type: 17.7:CM-MAC=3c:37:86:e7:e1:88:CMTS-MAC=2c:0b:e9:14:80:7d:CM-QOS=1.1:CM-VER=3.1;
2020-07-06 17:19:29	Error (4)	Missing BP Configuration Setting TLV Type: 17.6:CM-MAC=3c:37:86:e7:e1:88:CMTS-MAC=2c:0b:e9:14:80:7d:CM-QOS=1.1:CM-VER=3.1;
2020-07-06 17:19:29	Error (4)	Missing BP Configuration Setting TLV Type: 17.5:CM-MAC=3c:37:86:e7:e1:88:CMTS-MAC=2c:0b:e9:14:80:7d:CM-QOS=1.1:CM-VER=3.1;
2020-07-06 17:19:29	Error (4)	Missing BP Configuration Setting TLV Type: 17.4:CM-MAC=3c:37:86:e7:e1:88:CMTS-MAC=2c:0b:e9:14:80:7d:CM-QOS=1.1:CM-VER=3.1;
2020-07-06 17:19:29	Error (4)	Missing BP Configuration Setting TLV Type: 17.3:CM-MAC=3c:37:86:e7:e1:88:CMTS-MAC=2c:0b:e9:14:80:7d:CM-QOS=1.1:CM-VER=3.1;
2020-07-06 17:19:29	Error (4)	Missing BP Configuration Setting TLV Type: 17.2:CM-MAC=3c:37:86:e7:e1:88:CMTS-MAC=2c:0b:e9:14:80:7d:CM-QOS=1.1:CM-VER=3.1;
2020-07-06 17:19:29	Error (4)	Missing BP Configuration Setting TLV Type: 17.1:CM-MAC=3c:37:86:e7:e1:88:CMTS-MAC=2c:0b:e9:14:80:7d:CM-QOS=1.1:CM-VER=3.1;
Time Not Established	Warning (5)	DHCP WARNING - Non-critical field invalid in response :CM-MAC=3c:37:86:e7:e1:88:CMTS-MAC=2c:0b:e9:14:80:7d:CM-QOS=1.1:CM-VER=3.1;
Time Not Established	Notice (6)	Honoring MDD: IP provisioning mode = IPv4
Time Not Established	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing:CM-MAC=3c:37:86:e7:e1:88:CMTS-MAC=00:00:00:00:00:00:CM-QOS=1.1:CM-VER=3.1;
Time Not Established	Critical (3)	No Ranging Response received - T3 time-out:CM-MAC=3c:37:86:e7:e1:88:CMTS-MAC=2c:0b:e9:14:80:7d:CM-QOS=1.1:CM-VER=3.1;
Time Not Established	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing:CM-MAC=3c:37:86:e7:e1:88:CMTS-MAC=00:00:00:00:00:00:CM-QOS=1.1:CM-VER=3.1;
Time Not Established	Critical (3)	No Ranging Response received - T3 time-out:CM-MAC=3c:37:86:e7:e1:88:CMTS-MAC=2c:0b:e9:14:80:7d:CM-QOS=1.1:CM-VER=3.1;
Time Not Established	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing:CM-MAC=3c:37:86:e7:e1:88:CMTS-MAC=00:00:00:00:00:00:CM-QOS=1.1:CM-VER=3.1;
Time Not Established	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing:CM-MAC=3c:37:86:e7:e1:88:CMTS-MAC=00:00:00:00:00:00:CM-QOS=1.1:CM-VER=3.1;
Time Not Established	Critical (3)	No Ranging Response received - T3 time-out:CM-MAC=3c:37:86:e7:e1:88:CMTS-MAC=2c:0b:e9:14:80:7d:CM-QOS=1.1:CM-VER=3.1;
Time Not Established	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing:CM-MAC=3c:37:86:e7:e1:88:CMTS-MAC=00:00:00:00:00:00:CM-QOS=1.1:CM-VER=3.1;
Time Not Established	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing:CM-MAC=3c:37:86:e7:e1:88:CMTS-MAC=00:00:00:00:00:00:CM-QOS=1.1:CM-VER=3.1;
Time Not Established	Critical (3)	No Ranging Response received - T3 time-out:CM-MAC=3c:37:86:e7:e1:88:CMTS-MAC=2c:0b:e9:14:80:7d:CM-QOS=1.1:CM-VER=3.1;
Time Not Established	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing:CM-MAC=3c:37:86:e7:e1:88:CMTS-MAC=00:00:00:00:00:00:CM-QOS=1.1:CM-VER=3.1;
Time Not Established	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing:CM-MAC=3c:37:86:e7:e1:88:CMTS-MAC=00:00:00:00:00:00:CM-QOS=1.1:CM-VER=3.1;
2020-07-05 20:04:05	Critical (3)	Started Unicast Maintenance Ranging - No Response received - T3 time-out:CM-MAC=3c:37:86:e7:e1:88:CMTS-MAC=2c:0b:e9:14:80:7d:CM-QOS=1.1:CM-VER=3.1;
Time Not Established	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing:CM-MAC=3c:37:86:e7:e1:88:CMTS-MAC=00:00:00:00:00:00:CM-QOS=1.1:CM-VER=3.1;