

ADVANCED

✓ **Cable Information**

Hardware Version	2.02
Firmware Version	V3.01.04
Cable Modem Serial Number	4L0477W102A3E
CM certificate	Installed
CM MAC	b0:39:56:4b:b8:68

Time	Priority	Description
2017-12-23, 13:29:07	Notice (6)	CM-STATUS message sent. Event Type Code: 4; Chan ID: 22 ; DSID: N/A; MAC Addr: N/A; OFDM/OFDMA Profile ID: N/A.;CM-MAC=b0:39:56:4b:b8:68;CMTS-MAC=00:01:5c:a7:12:4e;CM-QOS=1.1;CM-VER=3.1;
2017-12-23, 13:28:29	Warning (5)	MDD message timeout;CM-MAC=b0:39:56:4b:b8:68;CMTS-MAC=00:01:5c:a7:12:4e;CM-QOS=1.1;CM-VER=3.1;
2017-12-23, 13:27:53	Notice (6)	CM-STATUS message sent. Event Type Code: 4; Chan ID: 22 ; DSID: N/A; MAC Addr: N/A; OFDM/OFDMA Profile ID: N/A.;CM-MAC=b0:39:56:4b:b8:68;CMTS-MAC=00:01:5c:a7:12:4e;CM-QOS=1.1;CM-VER=3.1;
2017-12-23, 13:27:35	Warning (5)	MDD message timeout;CM-MAC=b0:39:56:4b:b8:68;CMTS-MAC=00:01:5c:a7:12:4e;CM-QOS=1.1;CM-VER=3.1;
2017-12-23, 13:26:42	Notice (6)	CM-STATUS message sent. Event Type Code: 4; Chan ID: 22 ; DSID: N/A; MAC Addr: N/A; OFDM/OFDMA Profile ID: N/A.;CM-MAC=b0:39:56:4b:b8:68;CMTS-MAC=00:01:5c:a7:12:4e;CM-QOS=1.1;CM-VER=3.1;
2017-12-23, 13:26:23	Warning (5)	MDD message timeout;CM-MAC=b0:39:56:4b:b8:68;CMTS-MAC=00:01:5c:a7:12:4e;CM-QOS=1.1;CM-VER=3.1;
2017-12-23, 13:25:11	Notice (6)	CM-STATUS message sent. Event Type Code: 4; Chan ID: 22 ; DSID: N/A; MAC Addr: N/A; OFDM/OFDMA Profile ID: N/A.;CM-MAC=b0:39:56:4b:b8:68;CMTS-MAC=00:01:5c:a7:12:4e;CM-QOS=1.1;CM-VER=3.1;
2017-12-23, 13:24:41	Warning (5)	MDD message timeout;CM-MAC=b0:39:56:4b:b8:68;CMTS-MAC=00:01:5c:a7:12:4e;CM-QOS=1.1;CM-VER=3.1;
2017-12-23, 13:24:24	Notice (6)	CM-STATUS message sent. Event Type Code: 4; Chan ID: 22 ; DSID: N/A; MAC Addr: N/A; OFDM/OFDMA Profile ID: N/A.;CM-MAC=b0:39:56:4b:b8:68;CMTS-MAC=00:01:5c:a7:12:4e;CM-QOS=1.1;CM-VER=3.1;
2017-12-23, 13:23:57	Warning (5)	MDD message timeout;CM-MAC=b0:39:56:4b:b8:68;CMTS-MAC=00:01:5c:a7:12:4e;CM-QOS=1.1;CM-VER=3.1;
2017-12-23, 13:22:57	Notice (6)	CM-STATUS message sent. Event Type Code: 4; Chan ID: 22 ; DSID: N/A; MAC Addr: N/A; OFDM/OFDMA Profile ID: N/A.;CM-MAC=b0:39:56:4b:b8:68;CMTS-MAC=00:01:5c:a7:12:4e;CM-QOS=1.1;CM-VER=3.1;
2017-12-23, 13:22:29	Warning (5)	MDD message timeout;CM-MAC=b0:39:56:4b:b8:68;CMTS-MAC=00:01:5c:a7:12:4e;CM-QOS=1.1;CM-VER=3.1;
2017-12-23, 13:20:58	Notice (6)	CM-STATUS message sent. Event Type Code: 4; Chan ID: 22 ; DSID:

		N/A; MAC Addr: N/A; OFDM/OFDMA Profile ID: N/A.;CM-MAC=b0:39:56:4b:b8:68;CMTS-MAC=00:01:5c:a7:12:4e;CM-QOS=1.1;CM-VER=3.1;
2017-12-23, 13:20:35	Warning (5)	MDD message timeout;CM-MAC=b0:39:56:4b:b8:68;CMTS-MAC=00:01:5c:a7:12:4e;CM-QOS=1.1;CM-VER=3.1;
2017-12-23, 13:18:51	Notice (6)	CM-STATUS message sent. Event Type Code: 4; Chan ID: 22 ; DSID: N/A; MAC Addr: N/A; OFDM/OFDMA Profile ID: N/A.;CM-MAC=b0:39:56:4b:b8:68;CMTS-MAC=00:01:5c:a7:12:4e;CM-QOS=1.1;CM-VER=3.1;
2017-12-23, 13:18:35	Warning (5)	MDD message timeout;CM-MAC=b0:39:56:4b:b8:68;CMTS-MAC=00:01:5c:a7:12:4e;CM-QOS=1.1;CM-VER=3.1;
2017-12-23, 13:17:20	Notice (6)	CM-STATUS message sent. Event Type Code: 4; Chan ID: 22 ; DSID: N/A; MAC Addr: N/A; OFDM/OFDMA Profile ID: N/A.;CM-MAC=b0:39:56:4b:b8:68;CMTS-MAC=00:01:5c:a7:12:4e;CM-QOS=1.1;CM-VER=3.1;
2017-12-23, 13:17:01	Warning (5)	MDD message timeout;CM-MAC=b0:39:56:4b:b8:68;CMTS-MAC=00:01:5c:a7:12:4e;CM-QOS=1.1;CM-VER=3.1;
2017-12-23, 13:15:48	Notice (6)	CM-STATUS message sent. Event Type Code: 4; Chan ID: 22 ; DSID: N/A; MAC Addr: N/A; OFDM/OFDMA Profile ID: N/A.;CM-MAC=b0:39:56:4b:b8:68;CMTS-MAC=00:01:5c:a7:12:4e;CM-QOS=1.1;CM-VER=3.1;
2017-12-23, 13:15:27	Warning (5)	MDD message timeout;CM-MAC=b0:39:56:4b:b8:68;CMTS-MAC=00:01:5c:a7:12:4e;CM-QOS=1.1;CM-VER=3.1;
2017-12-23, 13:13:57	Notice (6)	CM-STATUS message sent. Event Type Code: 4; Chan ID: 22 ; DSID: N/A; MAC Addr: N/A; OFDM/OFDMA Profile ID: N/A.;CM-MAC=b0:39:56:4b:b8:68;CMTS-MAC=00:01:5c:a7:12:4e;CM-QOS=1.1;CM-VER=3.1;
2017-12-23, 13:13:51	Warning (5)	MDD message timeout;CM-MAC=b0:39:56:4b:b8:68;CMTS-MAC=00:01:5c:a7:12:4e;CM-QOS=1.1;CM-VER=3.1;
2017-12-23, 13:13:08	Notice (6)	CM-STATUS message sent. Event Type Code: 4; Chan ID: 22 ; DSID: N/A; MAC Addr: N/A; OFDM/OFDMA Profile ID: N/A.;CM-MAC=b0:39:56:4b:b8:68;CMTS-MAC=00:01:5c:a7:12:4e;CM-QOS=1.1;CM-VER=3.1;
2017-12-23, 13:12:53	Warning (5)	MDD message timeout;CM-MAC=b0:39:56:4b:b8:68;CMTS-MAC=00:01:5c:a7:12:4e;CM-QOS=1.1;CM-VER=3.1;
2017-12-23, 13:12:11	Notice (6)	CM-STATUS message sent. Event Type Code: 4; Chan ID: 22 ; DSID: N/A; MAC Addr: N/A; OFDM/OFDMA Profile ID: N/A.;CM-MAC=b0:39:56:4b:b8:68;CMTS-MAC=00:01:5c:a7:12:4e;CM-QOS=1.1;CM-VER=3.1;
2017-12-23, 13:12:09	Warning (5)	MDD message timeout;CM-MAC=b0:39:56:4b:b8:68;CMTS-MAC=00:01:5c:a7:12:4e;CM-QOS=1.1;CM-VER=3.1;
2017-12-23, 13:11:47	Notice (6)	CM-STATUS message sent. Event Type Code: 4; Chan ID: 22 ; DSID: N/A; MAC Addr: N/A; OFDM/OFDMA Profile ID: N/A.;CM-MAC=b0:39:56:4b:b8:68;CMTS-MAC=00:01:5c:a7:12:4e;CM-QOS=1.1;CM-VER=3.1;
2017-12-23, 13:11:19	Warning (5)	MDD message timeout;CM-MAC=b0:39:56:4b:b8:68;CMTS-MAC=00:01:5c:a7:12:4e;CM-QOS=1.1;CM-VER=3.1;
2017-12-23, 13:07:56	Notice (6)	CM-STATUS message sent. Event Type Code: 4; Chan ID: 22 ; DSID: N/A; MAC Addr: N/A; OFDM/OFDMA Profile ID: N/A.;CM-MAC=b0:39:56:4b:b8:68;CMTS-MAC=00:01:5c:a7:12:4e;CM-QOS=1.1;CM-VER=3.1;
2017-12-23, 13:07:41	Warning (5)	MDD message timeout;CM-MAC=b0:39:56:4b:b8:68;CMTS-MAC=00:01:5c:a7:12:4e;CM-QOS=1.1;CM-VER=3.1;
2017-12-23, 13:06:54	Notice (6)	CM-STATUS message sent. Event Type Code: 4; Chan ID: 22 ; DSID: N/A; MAC Addr: N/A; OFDM/OFDMA Profile ID: N/A.;CM-MAC=b0:39:56:4b:b8:68;CMTS-MAC=00:01:5c:a7:12:4e;CM-QOS=1.1;CM-VER=3.1;
2017-12-23, 13:06:49	Warning (5)	MDD message timeout;CM-MAC=b0:39:56:4b:b8:68;CMTS-MAC=00:01:5c:a7:12:4e;CM-QOS=1.1;CM-VER=3.1;

2017-12-23, 13:05:33	Notice (6)	CM-STATUS message sent. Event Type Code: 4; Chan ID: 22 ; DSID: N/A; MAC Addr: N/A; OFDM/OFDMA Profile ID: N/A.;CM-MAC=b0:39:56:4b:b8:68;CMTS-MAC=00:01:5c:a7:12:4e;CM-QOS=1.1;CM-VER=3.1;
2017-12-23, 13:05:29	Warning (5)	MDD message timeout;CM-MAC=b0:39:56:4b:b8:68;CMTS-MAC=00:01:5c:a7:12:4e;CM-QOS=1.1;CM-VER=3.1;
2017-12-23, 13:03:20	Notice (6)	CM-STATUS message sent. Event Type Code: 4; Chan ID: 22 ; DSID: N/A; MAC Addr: N/A; OFDM/OFDMA Profile ID: N/A.;CM-MAC=b0:39:56:4b:b8:68;CMTS-MAC=00:01:5c:a7:12:4e;CM-QOS=1.1;CM-VER=3.1;
2017-12-23, 13:02:57	Warning (5)	MDD message timeout;CM-MAC=b0:39:56:4b:b8:68;CMTS-MAC=00:01:5c:a7:12:4e;CM-QOS=1.1;CM-VER=3.1;
2017-12-23, 13:00:53	Notice (6)	DS profile assignment change. DS Chan ID: 32; Previous Profile: ; New Profile: 1 .;CM-MAC=b0:39:56:4b:b8:68;CMTS-MAC=00:01:5c:a7:12:4e;CM-QOS=1.1;CM-VER=3.1;
Time Not Established	Notice (6)	Honoring MDD; IP provisioning mode = IPv6
Time Not Established	Critical (3)	No Ranging Response received - T3 time-out;CM-MAC=b0:39:56:4b:b8:68;CMTS-MAC=00:01:5c:a7:12:4e;CM-QOS=1.1;CM-VER=3.1;
Time Not Established	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;CM-MAC=b0:39:56:4b:b8:68;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.1;CM-VER=3.1;