

Time	Priority	Description
2018-6-19, 10:20:54	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;;CM-MAC=a0:63:91:54:2a:88;CMTS-MAC=00:01:5c:77:44:4e;CM-QOS=1.0;CM-VER=3.0;
2018-6-19, 10:21:00	Critical (3)	No Ranging Response received - T3 time-out;CM-MAC=a0:63:91:54:2a:88;CMTS-MAC=00:01:5c:77:44:4e;CM-QOS=1.0;CM-VER=3.0;
2018-6-19, 10:21:06	Notice (6)	Overriding MDD IP initialization parameters; IP provisioning mode = IPv6
2018-6-19, 10:21:15	Error (4)	Missing BP Configuration Setting TLV Type: 17.8;CM-MAC=a0:63:91:54:2a:88;CMTS-MAC=00:01:5c:77:44:4e;CM-QOS=1.1;CM-VER=3.0;
2018-6-19, 10:21:15	Error (4)	Missing BP Configuration Setting TLV Type: 17.9;CM-MAC=a0:63:91:54:2a:88;CMTS-MAC=00:01:5c:77:44:4e;CM-QOS=1.1;CM-VER=3.0;

2018-6-19, 10:21:19	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/ QPSK symbol timing;;CM- MAC=a0:63:91:54:2a: 88;CMTS- MAC=00:01:5c: 77:44:4e;CM- QOS=1.0;CM-VER=3.0;
2018-6-19, 10:21:25	Critical (3)	No Ranging Response received - T3 time- out;CM- MAC=a0:63:91:54:2a: 88;CMTS- MAC=00:01:5c: 77:44:4e;CM- QOS=1.0;CM-VER=3.0;
2018-6-19, 10:21:32	Notice (6)	Overriding MDD IP initialization parameters; IP provisioning mode = IPv6
2018-6-19, 10:21:47	Error (4)	Missing BP Configuration Setting TLV Type: 17.8;CM- MAC=a0:63:91:54:2a: 88;CMTS- MAC=00:01:5c: 77:44:4e;CM- QOS=1.1;CM-VER=3.0;
2018-6-19, 10:21:47	Error (4)	Missing BP Configuration Setting TLV Type: 17.9;CM- MAC=a0:63:91:54:2a: 88;CMTS- MAC=00:01:5c: 77:44:4e;CM- QOS=1.1;CM-VER=3.0;

2018-6-19, 10:21:51	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire FEC framing;CM- MAC=a0:63:91:54:2a: 88;CMTS- MAC=00:01:5c: 77:44:4e;CM- QOS=1.0;CM-VER=3.0;
2018-6-19, 10:21:57	Critical (3)	No Ranging Response received - T3 time- out;CM- MAC=a0:63:91:54:2a: 88;CMTS- MAC=00:01:5c: 77:44:4e;CM- QOS=1.0;CM-VER=3.0;
2018-6-19, 10:22:07	Notice (6)	Overriding MDD IP initialization parameters; IP provisioning mode = IPv6
2018-6-19, 10:22:18	Error (4)	Missing BP Configuration Setting TLV Type: 17.8;CM- MAC=a0:63:91:54:2a: 88;CMTS- MAC=00:01:5c: 77:44:4e;CM- QOS=1.1;CM-VER=3.0;
2018-6-19, 10:22:18	Error (4)	Missing BP Configuration Setting TLV Type: 17.9;CM- MAC=a0:63:91:54:2a: 88;CMTS- MAC=00:01:5c: 77:44:4e;CM- QOS=1.1;CM-VER=3.0;

2018-6-19, 10:22:22	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/ QPSK symbol timing;;CM- MAC=a0:63:91:54:2a: 88;CMTS- MAC=00:01:5c: 77:44:4e;CM- QOS=1.0;CM-VER=3.0;
2018-6-19, 10:22:27	Critical (3)	No Ranging Response received - T3 time- out;CM- MAC=a0:63:91:54:2a: 88;CMTS- MAC=00:01:5c: 77:44:4e;CM- QOS=1.0;CM-VER=3.0;
2018-6-19, 10:22:34	Notice (6)	Overriding MDD IP initialization parameters; IP provisioning mode = IPv6
2018-6-19, 10:22:47	Error (4)	Missing BP Configuration Setting TLV Type: 17.8;CM- MAC=a0:63:91:54:2a: 88;CMTS- MAC=00:01:5c: 77:44:4e;CM- QOS=1.1;CM-VER=3.0;
2018-6-19, 10:22:47	Error (4)	Missing BP Configuration Setting TLV Type: 17.9;CM- MAC=a0:63:91:54:2a: 88;CMTS- MAC=00:01:5c: 77:44:4e;CM- QOS=1.1;CM-VER=3.0;

2018-6-19, 10:22:52	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire FEC framing;CM- MAC=a0:63:91:54:2a: 88;CMTS- MAC=00:01:5c: 77:44:4e;CM- QOS=1.0;CM-VER=3.0;
2018-6-19, 10:22:58	Critical (3)	No Ranging Response received - T3 time- out;CM- MAC=a0:63:91:54:2a: 88;CMTS- MAC=00:01:5c: 77:44:4e;CM- QOS=1.0;CM-VER=3.0;
2018-6-19, 10:23:07	Notice (6)	Overriding MDD IP initialization parameters; IP provisioning mode = IPv6
2018-6-19, 10:23:16	Error (4)	Missing BP Configuration Setting TLV Type: 17.8;CM- MAC=a0:63:91:54:2a: 88;CMTS- MAC=00:01:5c: 77:44:4e;CM- QOS=1.1;CM-VER=3.0;
2018-6-19, 10:23:16	Error (4)	Missing BP Configuration Setting TLV Type: 17.9;CM- MAC=a0:63:91:54:2a: 88;CMTS- MAC=00:01:5c: 77:44:4e;CM- QOS=1.1;CM-VER=3.0;

2018-6-19, 10:23:20	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire FEC framing;CM- MAC=a0:63:91:54:2a: 88;CMTS- MAC=00:01:5c: 77:44:4e;CM- QOS=1.0;CM-VER=3.0;
2018-6-19, 10:23:27	Critical (3)	No Ranging Response received - T3 time- out;CM- MAC=a0:63:91:54:2a: 88;CMTS- MAC=00:01:5c: 77:44:4e;CM- QOS=1.0;CM-VER=3.0;
2018-6-19, 10:23:35	Notice (6)	Overriding MDD IP initialization parameters; IP provisioning mode = IPv6
2018-6-19, 10:23:50	Error (4)	Missing BP Configuration Setting TLV Type: 17.8;CM- MAC=a0:63:91:54:2a: 88;CMTS- MAC=00:01:5c: 77:44:4e;CM- QOS=1.1;CM-VER=3.0;
2018-6-19, 10:23:50	Error (4)	Missing BP Configuration Setting TLV Type: 17.9;CM- MAC=a0:63:91:54:2a: 88;CMTS- MAC=00:01:5c: 77:44:4e;CM- QOS=1.1;CM-VER=3.0;

2018-6-19, 10:23:54	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire FEC framing;CM- MAC=a0:63:91:54:2a: 88;CMTS- MAC=00:01:5c: 77:44:4e;CM- QOS=1.0;CM-VER=3.0;
2018-6-19, 10:23:59	Critical (3)	No Ranging Response received - T3 time- out;CM- MAC=a0:63:91:54:2a: 88;CMTS- MAC=00:01:5c: 77:44:4e;CM- QOS=1.0;CM-VER=3.0;
2018-6-19, 10:24:10	Notice (6)	Overriding MDD IP initialization parameters; IP provisioning mode = IPv6
2018-6-19, 10:24:24	Error (4)	Missing BP Configuration Setting TLV Type: 17.8;CM- MAC=a0:63:91:54:2a: 88;CMTS- MAC=00:01:5c: 77:44:4e;CM- QOS=1.1;CM-VER=3.0;
2018-6-19, 10:24:24	Error (4)	Missing BP Configuration Setting TLV Type: 17.9;CM- MAC=a0:63:91:54:2a: 88;CMTS- MAC=00:01:5c: 77:44:4e;CM- QOS=1.1;CM-VER=3.0;

2018-6-19, 10:24:28	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/ QPSK symbol timing;;CM- MAC=a0:63:91:54:2a: 88;CMTS- MAC=00:01:5c: 77:44:4e;CM- QOS=1.0;CM-VER=3.0;
2018-6-19, 10:24:33	Critical (3)	No Ranging Response received - T3 time- out;CM- MAC=a0:63:91:54:2a: 88;CMTS- MAC=00:01:5c: 77:44:4e;CM- QOS=1.0;CM-VER=3.0;
2018-6-19, 10:24:37	Notice (6)	Overriding MDD IP initialization parameters; IP provisioning mode = IPv6
2018-6-19, 10:24:47	Error (4)	Missing BP Configuration Setting TLV Type: 17.8;CM- MAC=a0:63:91:54:2a: 88;CMTS- MAC=00:01:5c: 77:44:4e;CM- QOS=1.1;CM-VER=3.0;
2018-6-19, 10:24:47	Error (4)	Missing BP Configuration Setting TLV Type: 17.9;CM- MAC=a0:63:91:54:2a: 88;CMTS- MAC=00:01:5c: 77:44:4e;CM- QOS=1.1;CM-VER=3.0;