



Logout

Firmware Version
V2.01.18

ADVANCED

Event Log

Clear Log

Refresh

Time	Priority	Description
Aug 07 2020 16:40:11	Notice (6)	TLV-11 - unrecognized OID
Aug 07 2020 16:40:11	Warning (5)	MIMO Event MIMO: Stored MIMO=-1 post cfg file MIMO=-1
Aug 07 2020 16:26:24	Notice (6)	TLV-11 - unrecognized OID
Aug 07 2020 16:26:23	Warning (5)	MIMO Event MIMO: Stored MIMO=-1 post cfg file MIMO=-1
Aug 07 2020 16:22:57	Warning (5)	RCS Partial Service
Aug 07 2020 16:22:56	Notice (6)	TLV-11 - unrecognized OID
Aug 07 2020 16:22:56	Warning (5)	MIMO Event MIMO: Stored MIMO=-1 post cfg file MIMO=-1
Aug 06 2020 03:27:13	Critical (3)	No Ranging Response received - T3 time-out
Aug 06 2020 02:04:24	Notice (6)	TLV-11 - unrecognized OID
Aug 06 2020 02:04:24	Warning (5)	MIMO Event MIMO: Stored MIMO=-1 post cfg file MIMO=-1
Aug 06 2020 01:47:57	Notice (6)	TLV-11 - unrecognized OID
Aug 06 2020 01:47:57	Warning (5)	MIMO Event MIMO: Stored MIMO=-1 post cfg file MIMO=-1
Aug 05 2020 16:37:40	Notice (6)	TLV-11 - unrecognized OID
Aug 05 2020 16:37:40	Warning (5)	MIMO Event MIMO: Stored MIMO=-1 post cfg file MIMO=-1
Aug 05 2020 16:24:19	Warning (5)	RCS Partial Service
Aug 05 2020 16:24:18	Notice (6)	TLV-11 - unrecognized OID
Aug 05 2020 16:24:18	Warning (5)	MIMO Event MIMO: Stored MIMO=-1 post cfg file MIMO=-1
Aug 05 2020 15:56:39	Notice (6)	TLV-11 - unrecognized OID
Aug 05 2020 15:56:39	Warning (5)	MIMO Event MIMO: Stored MIMO=-1 post cfg file MIMO=-1
Aug 05 2020 15:53:47	Notice (6)	TLV-11 - unrecognized OID
Aug 05 2020 15:53:47	Warning (5)	MIMO Event MIMO: Stored MIMO=-1 post cfg file MIMO=-1
Aug 05 2020 15:51:07	Notice (6)	TLV-11 - unrecognized OID
Aug 05 2020 15:51:07	Warning (5)	MIMO Event MIMO: Stored MIMO=-1 post cfg file MIMO=-1
Aug 05 2020 15:45:56	Warning (5)	RCS Partial Service
Aug 05 2020 15:45:55	Notice (6)	TLV-11 - unrecognized OID
Aug 05 2020 15:45:55	Warning (5)	MIMO Event MIMO: Stored MIMO=-1 post cfg file MIMO=-1
Aug 05 2020 15:42:46	Notice (6)	TLV-11 - unrecognized OID
Aug 05 2020 15:42:46	Warning (5)	MIMO Event MIMO: Stored MIMO=-1 post cfg file MIMO=-1
Aug 05 2020 15:39:33	Warning (5)	RCS Partial Service
Aug 05 2020 15:39:32	Notice (6)	TLV-11 - unrecognized OID
Aug 05 2020 15:39:32	Warning (5)	MIMO Event MIMO: Stored MIMO=-1 post cfg file MIMO=-1
Aug 05 2020 15:36:08	Notice (6)	TLV-11 - unrecognized OID
Aug 05 2020 15:36:08	Warning (5)	MIMO Event MIMO: Stored MIMO=-1 post cfg file MIMO=-1
Aug 05 2020 15:33:24	Notice (6)	TLV-11 - unrecognized OID
Aug 05 2020 15:33:24	Warning (5)	MIMO Event MIMO: Stored MIMO=-1 post cfg file MIMO=-1
Aug 05 2020 15:29:53	Warning (5)	RCS Partial Service
Aug 05 2020 15:29:53	Notice (6)	TLV-11 - unrecognized OID
Aug 05 2020 15:29:53	Warning (5)	MIMO Event MIMO: Stored MIMO=-1 post cfg file MIMO=-1
Aug 05 2020 15:27:11	Notice (6)	TLV-11 - unrecognized OID
Aug 05 2020 15:27:10	Warning (5)	MIMO Event MIMO: Stored MIMO=-1 post cfg file MIMO=-1
Aug 05 2020 15:27:10	Warning (5)	MIMO Event MIMO: Stored MIMO=-1 post cfg file MIMO=-1
Aug 05 2020 15:27:10	Warning (5)	MIMO Event MIMO: Stored MIMO=-1 post cfg file MIMO=-1

ADVANCED
✓ Cable Information

Hardware Version	V4.0
Firmware Version	V2.01.18
Cable Modem Serial Number	4NH16971A1D6A
CM certificate	Installed
LAN Port	
MAC Address	a0:04:60:f6:9a:1a
IP Address/Mask	192.168.0.1/24, 2604:2d80:ef87:d800:a204:60ff:fe6:9a1a/64
DHCP	On

[Factory Reset](#)
[Reboot](#)
✓ Internet Port

MAC Address	a0:04:60:f6:9a:19
IP Address/Mask	50.81.249.9/23, 2604:2d80:cc05:0:fdd1:cd61:27c0:6a06/128
Connection	DHCP Client
Default Gateway	50.81.248.1
Domain Name Server	108.166.149.2, 108.166.149.3, 2607:fdc8:c::2, 2607:fdc8:c::3

[Show Statistics](#)
[Connection Status](#)
✓ Wireless Settings (2.4GHz)

Name (SSID)	tRc-2G
Region	United States
Channel	1 (1)
Mode	Up to 450 Mbps
Wireless AP	On
Broadcast Name	On
Wi-Fi Protected Setup	Configured

✓ Wireless Settings (5GHz)

Name (SSID)	tRc-5G
Region	United States
Channel	153 (149,153,157,161)
Mode	Up to 1.3 Gbps
Wireless AP	On
Broadcast Name	On
Wi-Fi Protected Setup	Configured

✗ Guest Network (2.4 GHz)

Name (SSID)	Netgear-Guest
Wireless AP	Off
Broadcast Name	Off
Allow guests to see each other and access my local network	Off

✗ Guest Network (5 GHz)

Name (SSID)	Netgear-5G-Guest
Wireless AP	Off
Broadcast Name	Off
Allow guests to see each other and access my local network	Off

Show Statistics

System Up Time 00:12:43

Port	Status	TxPkts	RxPkts	Collisions	Tx B/s	Rx B/s	Up Time
WAN	Link Up	2145	8629	0	675	1657	00:09:00
LAN1	1000M/Full	4123	7366	0	1435	1651	00:10:54
LAN2	Link Down						--
LAN3	Link Down						--
LAN4	Link Down						--
WLAN/2.4G	216.7 Mb/s	4280	2355	0	1305	846	00:11:45
WLAN/5G	1.3 Gb/s	31946	30002	0	5559	3388	00:11:46

Poll Interval : (secs)

Set Interval

Stop

Connection Status

IP Address	50.81.249.9, 2604:2d80:cc05:0:fdd1:cd61:27c0:6a06
Subnet Mask	255.255.254.0, /128
Default Gateway	50.81.248.1
DHCP Server	68.66.66.114
DNS Server	108.166.149.2, 108.166.149.3, 2607:fdc8:c::2, 2607:fdc8:c::3
Lease Obtained	4 Days,0 Hours,0 Minutes
Lease Expires	3 Days,23 Hours,50 Minutes

Release

Renew

Close Window

Description	Count	Last Occurrence	Target	Source
[DHCP IP: (192.168.0.46)] to MAC address 02:0f:b5:d7:74:b7	23	Friday, 07 Aug 2020 22:44:15	0.0.0.0	0.0.0.0
[WLAN access denied] from MAC: 02:0f:b5:d7:74:b7	2	Friday, 07 Aug 2020 22:43:20	0.0.0.0	0.0.0.0
[admin login] from source 192.168.0.20	1	Friday, 07 Aug 2020 22:38:26	0.0.0.0	192.168.0.20
[DHCP IP: (192.168.0.46)] to MAC address 02:0f:b5:d7:74:b7	1	Friday, 07 Aug 2020 22:33:12	0.0.0.0	0.0.0.0
[WLAN access denied] from MAC: 02:0f:b5:d7:74:b7	2	Friday, 07 Aug 2020 22:33:03	0.0.0.0	0.0.0.0
[DoS attack] ICMP Flood from 46.234.125.89	1	Friday, 07 Aug 2020 22:30:27	50.81.249.9	46.234.125.89
[DoS attack] ICMP Flood from 103.204.79.174	1	Friday, 07 Aug 2020 22:28:50	50.81.249.9	103.204.79.174
[DHCP IP: (192.168.0.59)] to MAC address 02:0f:b5:65:e5:82	8	Friday, 07 Aug 2020 22:23:17	0.0.0.0	0.0.0.0
[DHCP IP: (192.168.0.46)] to MAC address 02:0f:b5:d7:74:b7	1	Friday, 07 Aug 2020 22:22:56	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:65:e5:82	2	Friday, 07 Aug 2020 22:22:45	0.0.0.0	0.0.0.0
[WLAN access denied] from MAC: 02:0f:b5:d7:74:b7	2	Friday, 07 Aug 2020 22:22:42	0.0.0.0	0.0.0.0
[DoS attack] ICMP Flood from 5.188.168.41	1	Friday, 07 Aug 2020 22:02:36	50.81.249.9	5.188.168.41
[DHCP IP: (192.168.0.46)] to MAC address 02:0f:b5:d7:74:b7	1	Friday, 07 Aug 2020 21:44:47	0.0.0.0	0.0.0.0
[WLAN access denied] from MAC: 02:0f:b5:d7:74:b7	2	Friday, 07 Aug 2020 21:44:45	0.0.0.0	0.0.0.0
[DHCP IP: (192.168.0.58)] to MAC address 02:0f:b5:77:b6:bb	11	Friday, 07 Aug 2020 21:31:22	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:77:b6:bb	4	Friday, 07 Aug 2020 21:31:08	0.0.0.0	0.0.0.0
[DHCP IP: (192.168.0.53)] to MAC address 02:0f:b5:81:90:f4	1	Friday, 07 Aug 2020 21:27:40	0.0.0.0	0.0.0.0
[WLAN access denied] from MAC: 02:0f:b5:81:90:f4	2	Friday, 07 Aug 2020 21:27:32	0.0.0.0	0.0.0.0
[DHCP IP: (192.168.0.58)] to MAC address 02:0f:b5:77:b6:bb	11	Friday, 07 Aug 2020 21:17:13	0.0.0.0	0.0.0.0
[DHCP IP: (192.168.0.59)] to MAC address 02:0f:b5:65:e5:82	5	Friday, 07 Aug 2020 21:17:01	0.0.0.0	0.0.0.0
[DHCP IP: (192.168.0.58)] to MAC address 02:0f:b5:77:b6:bb	1	Friday, 07 Aug 2020 21:16:40	0.0.0.0	0.0.0.0
[DHCP IP: (192.168.0.59)] to MAC address 02:0f:b5:65:e5:82	1	Friday, 07 Aug 2020 21:16:38	0.0.0.0	0.0.0.0

[WLAN access allowed] from MAC: 02:0f:b5:77:b6:bb	2	Friday, 07 Aug 2020 21:16:36	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:65:e5:82	2	Friday, 07 Aug 2020 21:16:34	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:77:b6:bb	2	Friday, 07 Aug 2020 21:16:30	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:65:e5:82	2	Friday, 07 Aug 2020 21:16:22	0.0.0.0	0.0.0.0
[WLAN access denied] from MAC: 02:0f:b5:81:90:f4	4	Friday, 07 Aug 2020 21:13:45	0.0.0.0	0.0.0.0
[DHCP IP: (192.168.0.37)] to MAC address 40:16:3b:f0:29:ec	1	Friday, 07 Aug 2020 21:06:01	0.0.0.0	0.0.0.0
[WLAN access denied] from MAC: 40:16:3b:f0:29:ec	2	Friday, 07 Aug 2020 21:05:58	0.0.0.0	0.0.0.0
[DHCP IP: (192.168.0.58)] to MAC address 02:0f:b5:77:b6:bb	5	Friday, 07 Aug 2020 21:01:35	0.0.0.0	0.0.0.0
[DHCP IP: (192.168.0.59)] to MAC address 02:0f:b5:65:e5:82	6	Friday, 07 Aug 2020 21:01:30	0.0.0.0	0.0.0.0
[DHCP IP: (192.168.0.58)] to MAC address 02:0f:b5:77:b6:bb	2	Friday, 07 Aug 2020 21:01:22	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:77:b6:bb	2	Friday, 07 Aug 2020 21:01:19	0.0.0.0	0.0.0.0
[DHCP IP: (192.168.0.59)] to MAC address 02:0f:b5:65:e5:82	1	Friday, 07 Aug 2020 21:01:14	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:65:e5:82	2	Friday, 07 Aug 2020 21:01:12	0.0.0.0	0.0.0.0
[DHCP IP: (192.168.0.33)] to MAC address 02:0f:b5:25:4f:b3	1	Friday, 07 Aug 2020 21:01:09	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:25:4f:b3	2	Friday, 07 Aug 2020 21:01:07	0.0.0.0	0.0.0.0
[DHCP IP: (192.168.0.32)] to MAC address 02:0f:b5:25:51:fd	1	Friday, 07 Aug 2020 21:00:48	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:25:4f:b3	2	Friday, 07 Aug 2020 21:00:47	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:25:51:fd	2	Friday, 07 Aug 2020 21:00:44	0.0.0.0	0.0.0.0
[DHCP IP: (192.168.0.33)] to MAC address 02:0f:b5:25:4f:b3	1	Friday, 07 Aug 2020 21:00:41	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:25:4f:b3	2	Friday, 07 Aug 2020 21:00:40	0.0.0.0	0.0.0.0
[DHCP IP: (192.168.0.35)] to MAC address 02:0f:b5:ff:37:a9	1	Friday, 07 Aug 2020 21:00:38	0.0.0.0	0.0.0.0
[DHCP IP: (192.168.0.46)] to MAC address 02:0f:b5:d7:74:b7	1	Friday, 07 Aug 2020 21:00:36	0.0.0.0	0.0.0.0
[WLAN access rejected: incorrect security] from MAC: 02:0f:b5:7c:d7:95	1	Friday, 07 Aug 2020 21:00:35	0.0.0.0	0.0.0.0

[WLAN access allowed] from MAC: 02:0f:b5:25:4f:b3	2	Friday, 07 Aug 2020 21:00:33	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:81:90:d6	2	Friday, 07 Aug 2020 21:00:30	0.0.0.0	0.0.0.0
[DHCP IP: (192.168.0.49)] to MAC address 02:0f:b5:ab:3b:91	1	Friday, 07 Aug 2020 21:00:28	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:e6:aa:e3	2	Friday, 07 Aug 2020 21:00:27	0.0.0.0	0.0.0.0
[DHCP IP: (192.168.0.23)] to MAC address 02:0f:b5:7c:d7:94	1	Friday, 07 Aug 2020 21:00:23	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:ab:3b:91	2	Friday, 07 Aug 2020 21:00:20	0.0.0.0	0.0.0.0
[WLAN access denied] from MAC: 02:0f:b5:d7:74:b7	2	Friday, 07 Aug 2020 21:00:16	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:7c:d7:94	2	Friday, 07 Aug 2020 21:00:12	0.0.0.0	0.0.0.0
[WLAN access denied] from MAC: 10:da:43:7c:d7:95	2	Friday, 07 Aug 2020 21:00:09	0.0.0.0	0.0.0.0
[WLAN access denied] from MAC: 12:da:43:7c:d7:95	2	Friday, 07 Aug 2020 21:00:07	0.0.0.0	0.0.0.0
[DHCP IP: (192.168.0.59)] to MAC address 02:0f:b5:65:e5:82	3	Friday, 07 Aug 2020 20:52:20	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:65:e5:82	2	Friday, 07 Aug 2020 20:52:17	0.0.0.0	0.0.0.0
[DHCP IP: (192.168.0.59)] to MAC address 02:0f:b5:65:e5:82	3	Friday, 07 Aug 2020 20:52:14	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:65:e5:82	2	Friday, 07 Aug 2020 20:52:05	0.0.0.0	0.0.0.0
[DHCP IP: (192.168.0.59)] to MAC address 02:0f:b5:65:e5:82	7	Friday, 07 Aug 2020 20:47:42	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:65:e5:82	2	Friday, 07 Aug 2020 20:47:19	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:77:b6:bb	2	Friday, 07 Aug 2020 20:47:07	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:65:e5:82	2	Friday, 07 Aug 2020 20:47:02	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:da:ba:f5	2	Friday, 07 Aug 2020 20:46:22	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:ab:3b:91	2	Friday, 07 Aug 2020 20:46:16	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:81:90:d6	2	Friday, 07 Aug 2020 20:46:14	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:e6:aa:e3	2	Friday, 07 Aug 2020 20:46:12	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:d7:91:63	2	Friday, 07 Aug 2020 20:46:10	0.0.0.0	0.0.0.0

[WLAN access denied] from MAC: 02:0f:b5:81:90:f4	2	Friday, 07 Aug 2020 20:46:08	0.0.0.0	0.0.0.0
[WLAN access denied] from MAC: 02:0f:b5:d7:74:b7	2	Friday, 07 Aug 2020 20:46:06	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:25:51:fd	2	Friday, 07 Aug 2020 20:46:04	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:25:4f:b3	2	Friday, 07 Aug 2020 20:46:01	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:ff:37:a9	2	Friday, 07 Aug 2020 20:45:59	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:7c:d7:94	2	Friday, 07 Aug 2020 20:45:57	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:da:ba:f5	2	Friday, 07 Aug 2020 20:45:47	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:25:51:fd	2	Friday, 07 Aug 2020 20:45:45	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:81:90:d6	2	Friday, 07 Aug 2020 20:45:43	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:25:4f:b3	2	Friday, 07 Aug 2020 20:45:41	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:ff:37:a9	2	Friday, 07 Aug 2020 20:45:39	0.0.0.0	0.0.0.0
[WLAN access denied] from MAC: 02:0f:b5:d7:74:b7	2	Friday, 07 Aug 2020 20:45:37	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:7c:d7:94	2	Friday, 07 Aug 2020 20:45:34	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:25:4f:b3	2	Friday, 07 Aug 2020 20:45:27	0.0.0.0	0.0.0.0
[WLAN access denied] from MAC: 02:0f:b5:81:90:f4	2	Friday, 07 Aug 2020 20:45:25	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:ff:37:a9	2	Friday, 07 Aug 2020 20:45:23	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:25:51:fd	2	Friday, 07 Aug 2020 20:45:21	0.0.0.0	0.0.0.0
[WLAN access denied] from MAC: 02:0f:b5:d7:74:b7	2	Friday, 07 Aug 2020 20:45:19	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:7c:d7:94	2	Friday, 07 Aug 2020 20:45:17	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:ff:37:a9	1	Friday, 07 Aug 2020 20:45:07	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:da:ba:f5	1	Friday, 07 Aug 2020 20:45:06	0.0.0.0	0.0.0.0
[WLAN access denied] from MAC: 02:0f:b5:81:90:f4	1	Friday, 07 Aug 2020 20:45:05	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:25:51:fd	2	Friday, 07 Aug 2020 20:45:04	0.0.0.0	0.0.0.0

[WLAN access allowed] from MAC: 02:0f:b5:25:4f:b3	2	Friday, 07 Aug 2020 20:45:02	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:25:51:fd	2	Friday, 07 Aug 2020 20:45:00	0.0.0.0	0.0.0.0
[WLAN access denied] from MAC: 02:0f:b5:d7:74:b7	2	Friday, 07 Aug 2020 20:44:58	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:ff:37:a9	2	Friday, 07 Aug 2020 20:44:55	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:25:4f:b3	2	Friday, 07 Aug 2020 20:44:53	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:da:ba:f5	2	Friday, 07 Aug 2020 20:44:51	0.0.0.0	0.0.0.0
[WLAN access denied] from MAC: 02:0f:b5:81:90:f4	2	Friday, 07 Aug 2020 20:44:49	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:7c:d7:94	2	Friday, 07 Aug 2020 20:44:46	0.0.0.0	0.0.0.0
[WLAN access allowed] from MAC: 02:0f:b5:da:ba:f5	2	Friday, 07 Aug 2020 20:44:14	0.0.0.0	0.0.0.0

Refresh

Clear Log

Send Log

Include in Log

- Attempted access to allowed sites
- Attempted access to blocked sites and services
- Connections to the Web-based interface of this Gateway
- Gateway operation (startup, get time etc)
- Known DoS attacks and Port Scans
- Port Forwarding / Port Triggering
- Wireless access
- Backup / Restore Settings

C6300

BASIC
ADVANCED
[Home](#)
[Cable Connection](#)
[Wireless](#)
[Attached Devices](#)
[Parental Controls](#)
[ReadySHARE](#)
[Guest Network](#)
Cable Connection
[Apply](#) [Cancel](#)
Frequency start Value

This field below allows you to modify the frequency the cable modem start with its scan during initialization and registration. Enter the new start frequency and restart the cable modem for it to take effect.

Starting Frequency
Startup Procedure

Procedure	Status	Comment
Acquire Downstream Channel	213000000 Hz	Locked
Connectivity State	Ok	Operational
Boot State	--	--
Configuration File	--	--
Security	Enabled	BPI+

Downstream Bonded Channels

Channel	Lock Status	Modulation	Channel ID	Frequency	Power	SNR	Correctables	UnCorrectabl
1	Locked	QAM 256	1	111000000 Hz	0.7 dBmV	40.3 dB	83	0
2	Locked	QAM 256	2	117000000 Hz	0.2 dBmV	40.9 dB	49	0
3	Locked	QAM 256	3	123000000 Hz	-0.2 dBmV	40.9 dB	2108	1717
4	Locked	QAM 256	4	129000000 Hz	-0.2 dBmV	40.3 dB	247865	0
5	Locked	QAM 256	5	147000000 Hz	-0.9 dBmV	40.3 dB	354	27
6	Locked	QAM 256	6	153000000 Hz	-1.0 dBmV	40.3 dB	12	0
7	Locked	QAM 256	7	159000000 Hz	-1.0 dBmV	40.3 dB	1	0
8	Locked	QAM 256	8	165000000 Hz	-1.4 dBmV	40.9 dB	40	28
9	Locked	QAM 256	9	171000000 Hz	-1.4 dBmV	40.9 dB	64	28
10	Locked	QAM 256	10	177000000 Hz	-1.5 dBmV	40.3 dB	111	119
11	Locked	QAM 256	11	183000000 Hz	-1.7 dBmV	40.3 dB	7	31
12	Locked	QAM 256	12	189000000 Hz	-1.7 dBmV	40.3 dB	8	0
13	Locked	QAM 256	13	195000000 Hz	-2.0 dBmV	40.9 dB	15	0
14	Locked	QAM 256	14	201000000 Hz	-2.0 dBmV	40.3 dB	7	0
15	Locked	QAM 256	15	207000000 Hz	-2.2 dBmV	40.9 dB	8	0
16	Locked	QAM 256	16	213000000 Hz	-2.5 dBmV	40.3 dB	11	0

Upstream Bonded Channels

Channel	Lock Status	US Channel Type	Channel ID	Symbol Rate	Frequency	Power
1	Locked	ATDMA	3	5120 Ksym/sec	24000000 Hz	40.8 dBmV
2	Locked	ATDMA	2	5120 Ksym/sec	30400000 Hz	42.3 dBmV
3	Locked	ATDMA	1	5120 Ksym/sec	36800000 Hz	42.3 dBmV
4	Not Locked	N/A	Unknown	0 Ksym/sec	0 Hz	0.0 dBmV

Current System Time: Fri Aug 7 22:56:05 2020

192.168.0.1

NETGEAR Gateway C6300

NETGEAR genie

C6300

You are currently logged in from another device. There can be only one device logged in at a time. If you log in from this device, the other device will be logged out. Do you want to proceed?

Yes No

Sat Aug 8 8:33 AM

Online Return Center Lable.pdf

Screen Recording 2020-0...AM.mov

Screen Recording 2020-0...AM.mov

clarence-rhode-1949.jpg