

Time	Priority	Description
2021-05-27, 10:45:36	Warning (5)	REG-RSP-MP Mismatch Between Calculated Value for P1.6hi Compared to CCAP Provided Value;CM-MAC=b0:b9:8a:af:d3:30;CMTS-MAC=dc:eb:94:b4:48:ed;CM-QOS=1.1;CM-VER=3.1;
2021-05-27, 10:46:51	Notice (6)	Honoring MDD; IP provisioning mode = IPv6
2021-05-27, 10:46:32	Critical (3)	Received Response to Broadcast Maintenance Request, But no Unicast Maintenance opportunities received - T4 time out;CM-MAC=b0:b9:8a:af:d3:30;CMTS-MAC=dc:eb:94:b4:48:ed;CM-QOS=1.1;CM-VER=3.1;
2021-05-27, 10:46:20	Critical (3)	No Ranging Response received - T3 time-out;CM-MAC=b0:b9:8a:af:d3:30;CMTS-MAC=dc:eb:94:b4:48:ed;CM-QOS=1.1;CM-VER=3.1;
2021-05-27, 10:46:20	Notice (6)	CM-STATUS message sent. Event Type Code: 6; Chan ID: 4; DSID: N/A; MAC Addr: N/A; OFDM/OFDMA Profile ID: N/A.;CM-MAC=b0:b9:8a:af:d3:30;CMTS-MAC=dc:eb:94:b4:48:ed;CM-QOS=1.1;CM-VER=3.1;
2021-05-27, 10:46:20	Critical (3)	No Ranging Response received - T3 time-out;CM-MAC=b0:b9:8a:af:d3:30;CMTS-MAC=dc:eb:94:b4:48:ed;CM-QOS=1.1;CM-VER=3.1;
2021-05-27, 10:46:19	Critical (3)	Received Response to Broadcast Maintenance Request, But no Unicast Maintenance opportunities received - T4 time out;CM-MAC=b0:b9:8a:af:d3:30;CMTS-MAC=dc:eb:94:b4:48:ed;CM-QOS=1.1;CM-VER=3.1;
2021-05-27, 10:15:14	Critical (3)	Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=b0:b9:8a:af:d3:30;CMTS-MAC=dc:eb:94:b4:48:ed;CM-QOS=1.1;CM-VER=3.1;
2021-05-26, 08:11:10	Warning (5)	Dynamic Range Window violation
2021-05-26, 08:11:10	Warning (5)	RNG-RSP CCAP Commanded Power Exceeds Value Corresponding to the Top of the DRW;CM-MAC=b0:b9:8a:af:d3:30;CMTS-MAC=dc:eb:94:b4:48:ed;CM-QOS=1.1;CM-VER=3.1;
2021-05-26, 08:11:10	Warning (5)	Dynamic Range Window violation
2021-05-26, 08:11:10	Warning (5)	RNG-RSP CCAP Commanded Power Exceeds Value Corresponding to the Top of the DRW;CM-MAC=b0:b9:8a:af:d3:30;CMTS-MAC=dc:eb:94:b4:48:ed;CM-QOS=1.1;CM-VER=3.1;
2021-05-26, 08:11:10	Warning (5)	Dynamic Range Window violation
		RNG-RSP CCAP Commanded Power Exceeds Value

2021-05-26, 08:11:10	Warning (5)	Corresponding to the Top of the DRW;CM-MAC=b0:b9:8a:af:d3:30;CMTS-MAC=dc:eb:94:b4:48:ed;CM-QOS=1.1;CM-VER=3.1;
2021-05-26, 08:11:10	Warning (5)	Dynamic Range Window violation
2021-05-26, 08:11:10	Warning (5)	RNG-RSP CCAP Commanded Power Exceeds Value Corresponding to the Top of the DRW;CM-MAC=b0:b9:8a:af:d3:30;CMTS-MAC=dc:eb:94:b4:48:ed;CM-QOS=1.1;CM-VER=3.1;
2021-05-26, 08:06:26	Critical (3)	Received Response to Broadcast Maintenance Request, But no Unicast Maintenance opportunities received - T4 time out;CM-MAC=b0:b9:8a:af:d3:30;CMTS-MAC=dc:eb:94:b4:48:ed;CM-QOS=1.1;CM-VER=3.1;
2021-05-26, 08:05:40	Notice (6)	CM-STATUS message sent. Event Type Code: 6; Chan ID: 5; DSID: N/A; MAC Addr: N/A; OFDM/OFDMA Profile ID: N/A.;CM-MAC=b0:b9:8a:af:d3:30;CMTS-MAC=dc:eb:94:b4:48:ed;CM-QOS=1.1;CM-VER=3.1;
2021-05-26, 08:03:17	Critical (3)	Received Response to Broadcast Maintenance Request, But no Unicast Maintenance opportunities received - T4 time out;CM-MAC=b0:b9:8a:af:d3:30;CMTS-MAC=dc:eb:94:b4:48:ed;CM-QOS=1.1;CM-VER=3.1;
2021-05-26, 06:19:24	Warning (5)	Dynamic Range Window violation
2021-05-26, 06:19:24	Warning (5)	RNG-RSP CCAP Commanded Power Exceeds Value Corresponding to the Top of the DRW;CM-MAC=b0:b9:8a:af:d3:30;CMTS-MAC=dc:eb:94:b4:48:ed;CM-QOS=1.1;CM-VER=3.1;
2021-05-26, 06:19:24	Warning (5)	Dynamic Range Window violation
2021-05-26, 06:19:24	Warning (5)	RNG-RSP CCAP Commanded Power Exceeds Value Corresponding to the Top of the DRW;CM-MAC=b0:b9:8a:af:d3:30;CMTS-MAC=dc:eb:94:b4:48:ed;CM-QOS=1.1;CM-VER=3.1;
2021-05-26, 06:19:24	Warning (5)	Dynamic Range Window violation
2021-05-26, 06:19:24	Warning (5)	RNG-RSP CCAP Commanded Power Exceeds Value Corresponding to the Top of the DRW;CM-MAC=b0:b9:8a:af:d3:30;CMTS-MAC=dc:eb:94:b4:48:ed;CM-QOS=1.1;CM-VER=3.1;
2021-05-26, 06:19:24	Warning (5)	Dynamic Range Window violation
2021-05-26, 06:19:24	Warning (5)	RNG-RSP CCAP Commanded Power Exceeds Value Corresponding to the Top of the DRW;CM-MAC=b0:b9:8a:af:d3:30;CMTS-MAC=dc:eb:94:b4:48:ed;CM-QOS=1.1;CM-VER=3.1;

		QOS=1.1;CM-VER=3.1;
2021-05-26, 04:56:27	Warning (5)	Dynamic Range Window violation
2021-05-26, 04:56:27	Warning (5)	RNG-RSP CCAP Commanded Power Exceeds Value Corresponding to the Top of the DRW;CM-MAC=b0:b9:8a:af:d3:30;CMTS-MAC=dc:eb:94:b4:48:ed;CM-QOS=1.1;CM-VER=3.1;
2021-05-25, 20:34:56	Critical (3)	Received Response to Broadcast Maintenance Request, But no Unicast Maintenance opportunities received - T4 time out;CM-MAC=b0:b9:8a:af:d3:30;CMTS-MAC=dc:eb:94:b4:48:ed;CM-QOS=1.1;CM-VER=3.1;
2021-05-25, 10:26:41	Warning (5)	Dynamic Range Window violation
2021-05-25, 10:26:41	Warning (5)	RNG-RSP CCAP Commanded Power Exceeds Value Corresponding to the Top of the DRW;CM-MAC=b0:b9:8a:af:d3:30;CMTS-MAC=dc:eb:94:b4:48:ed;CM-QOS=1.1;CM-VER=3.1;
2021-05-25, 10:26:41	Warning (5)	Dynamic Range Window violation
2021-05-25, 10:26:41	Warning (5)	RNG-RSP CCAP Commanded Power Exceeds Value Corresponding to the Top of the DRW;CM-MAC=b0:b9:8a:af:d3:30;CMTS-MAC=dc:eb:94:b4:48:ed;CM-QOS=1.1;CM-VER=3.1;
2021-05-25, 10:26:29	Critical (3)	Received Response to Broadcast Maintenance Request, But no Unicast Maintenance opportunities received - T4 time out;CM-MAC=b0:b9:8a:af:d3:30;CMTS-MAC=dc:eb:94:b4:48:ed;CM-QOS=1.1;CM-VER=3.1;
2021-05-25, 01:55:27	Critical (3)	Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=b0:b9:8a:af:d3:30;CMTS-MAC=dc:eb:94:b4:48:ed;CM-QOS=1.1;CM-VER=3.1;
2021-05-25, 01:53:14	Warning (5)	Dynamic Range Window violation
2021-05-25, 01:53:14	Warning (5)	RNG-RSP CCAP Commanded Power Exceeds Value Corresponding to the Top of the DRW;CM-MAC=b0:b9:8a:af:d3:30;CMTS-MAC=dc:eb:94:b4:48:ed;CM-QOS=1.1;CM-VER=3.1;
2021-05-25, 01:53:14	Warning (5)	Dynamic Range Window violation
2021-05-25, 01:53:14	Warning (5)	RNG-RSP CCAP Commanded Power Exceeds Value Corresponding to the Top of the DRW;CM-MAC=b0:b9:8a:af:d3:30;CMTS-MAC=dc:eb:94:b4:48:ed;CM-QOS=1.1;CM-VER=3.1;