

Clear Log

Refresh

Time	Priority	Description
Fri May 05 23:31:51 2023	Notice (6)	CM-STATUS message sent. Event Type Code: 4; Chan ID: 4; DSID: N/A; MAC Addr: N/A; OFDM/OFDMA Profile ID: N/A.;CM-MAC=80:cc:9c:b0:2c:f8;CMTS-MAC=00:01:5c:95:50:69;CM-QOS=1.1;CM-VER=3.1;
Fri May 05 23:31:24 2023	Warning (5)	MDD message timeout;CM-MAC=80:cc:9c:b0:2c:f8;CMTS-MAC=00:01:5c:95:50:69;CM-QOS=1.1;CM-VER=3.1;
Fri May 05 18:30:43 2023	Error (4)	DHCP RENEW WARNING - Field invalid in response v4 option;CM-MAC=80:cc:9c:b0:2c:f8;CMTS-MAC=00:01:5c:95:50:69;CM-QOS=1.1;CM-VER=3.1;
Wed May 03 00:14:42 2023	Notice (6)	CM-STATUS message sent. Event Type Code: 5; Chan ID: 25; DSID: N/A; MAC Addr: N/A; OFDM/OFDMA Profile ID: N/A.;CM-MAC=80:cc:9c:b0:2c:f8;CMTS-MAC=00:01:5c:95:50:69;CM-QOS=1.1;CM-VER=3.1;
Wed May 03 00:14:27 2023	Critical (3)	Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=80:cc:9c:b0:2c:f8;CMTS-MAC=00:01:5c:95:50:69;CM-QOS=1.1;CM-VER=3.1;
Wed May 03 00:14:21 2023	Notice (6)	DS profile assignment change. DS Chan ID: 32; Previous Profile: ; New Profile: 1 2.;CM-MAC=80:cc:9c:b0:2c:f8;CMTS-MAC=00:01:5c:95:50:69;CM-QOS=1.1;CM-VER=3.1;
Wed May 03 00:14:20 2023	Notice (6)	TLV-11 - unrecognized Oid;CM-MAC=80:cc:9c:b0:2c:f8;CMTS-MAC=00:01:5c:95:50:69;CM-QOS=1.1;CM-VER=3.1;
Wed May 03 00:14:20 2023	Error (4)	Missing BP Configuration Setting TLV Type: 17 9;CM-MAC=80:cc:9c:b0:2c:f8;CMTS-MAC=00:01:5c:95:50:69;CM-QOS=1.1;CM-VER=3.1;
Wed May 03 00:14:20 2023	Error (4)	Missing BP Configuration Setting TLV Type: 17 8;CM-MAC=80:cc:9c:b0:2c:f8;CMTS-MAC=00:01:5c:95:50:69;CM-QOS=1.1;CM-VER=3.1;
Wed May 03 00:14:20 2023	Error (4)	Missing BP Configuration Setting TLV Type: 17 3;CM-MAC=80:cc:9c:b0:2c:f8;CMTS-MAC=00:01:5c:95:50:69;CM-QOS=1.1;CM-VER=3.1;
Wed May 03 00:14:19 2023	Warning (5)	DHCP WARNING - Non-critical field invalid in response ;CM-MAC=80:cc:9c:b0:2c:f8;CMTS-MAC=00:01:5c:95:50:69;CM-QOS=1.1;CM-VER=3.1;
Wed May 03 00:13:53 2023	Notice (6)	Overriding MDD IP Initialization parameters; IP provisioning mode = IPv4
Wed May 03 00:13:32 2023	Critical (3)	No Ranging Response received - T3 time-out;CM-MAC=80:cc:9c:b0:2c:f8;CMTS-MAC=00:01:5c:95:50:69;CM-QOS=1.1;CM-VER=3.1;
Wed May 03 00:12:43 2023	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing.;CM-MAC=80:cc:9c:b0:2c:f8;CMTS-MAC=00:01:5c:95:50:69;CM-QOS=1.1;CM-VER=3.1;
Wed May 03 00:10:57 2023	Warning (5)	MDD message timeout;CM-MAC=80:cc:9c:b0:2c:f8;CMTS-MAC=00:01:5c:95:50:69;CM-QOS=1.1;CM-VER=3.1;
Wed May 03 00:10:56 2023	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing.;CM-MAC=80:cc:9c:b0:2c:f8;CMTS-MAC=00:01:5c:95:50:69;CM-QOS=1.1;CM-VER=3.1;
Wed May 03 00:10:51 2023	Warning (5)	MDD message timeout;CM-MAC=80:cc:9c:b0:2c:f8;CMTS-MAC=00:01:5c:95:50:69;CM-QOS=1.1;CM-VER=3.1;
Wed May 03 00:10:50 2023	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing.;CM-MAC=80:cc:9c:b0:2c:f8;CMTS-MAC=00:01:5c:95:50:69;CM-QOS=1.1;CM-VER=3.1;
Tue May 02 06:30:20 2023	Error (4)	DHCP RENEW WARNING - Field invalid in response v4 option;CM-MAC=80:cc:9c:b0:2c:f8;CMTS-MAC=00:01:5c:95:50:69;CM-QOS=1.1;CM-VER=3.1;