

Event Log

Clear Log Refresh

Time Priority Description

2023-07-23 07:18:59 Critical (3) Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=34:98:b5:2e:a6:78;CMTS-MAC=04:2a:e2:c6:24:ee;CM-QOS=1.1;CM-VER=3.1;

2023-07-23 00:28:16 Warning (5) DBC-REQ Mismatch Between Calculated Value for P1.6hi Compared to CCAP Provided Value;CM-MAC=34:98:b5:2e:a6:78;CMTS-MAC=04:2a:e2:c6:24:ee;CM-QOS=1.1;CM-VER=3.1 ;

2023-07-23 00:28:15 Critical (3) SYNC Timing Synchronization failure - Loss of Sync;CM-MAC=34:98:b5:2e:a6:78;CMTS-MAC=04:2a:e2:c6:24:ee;CM-QOS=1.1;CM-VER=3.1;

2023-07-23 00:16:10 Warning (5) Dynamic Range Window violation

2023-07-23 00:16:10 Warning (5) RNG-RSP CCAP Commanded Power Exceeds Value Corresponding to the Top of the DRW;CM-MAC=34:98:b5:2e:a6:78;CMTS-MAC=04:2a:e2:c6:24:ee;CM-QOS=1.1;CM-VER=3.1;

2023-07-23 00:16:10 Warning (5) Dynamic Range Window violation

2023-07-23 00:16:10 Warning (5) RNG-RSP CCAP Commanded Power Exceeds Value Corresponding to the Top of the DRW;CM-MAC=34:98:b5:2e:a6:78;CMTS-MAC=04:2a:e2:c6:24:ee;CM-QOS=1.1;CM-VER=3.1;

2023-07-23 00:16:10 Warning (5) Dynamic Range Window violation

2023-07-23 00:16:10 Warning (5) RNG-RSP CCAP Commanded Power Exceeds Value Corresponding to the Top of the DRW;CM-MAC=34:98:b5:2e:a6:78;CMTS-MAC=04:2a:e2:c6:24:ee;CM-QOS=1.1;CM-VER=3.1;

2023-07-23 00:16:10 Warning (5) Dynamic Range Window violation

2023-07-23 00:16:10 Warning (5) RNG-RSP CCAP Commanded Power Exceeds Value Corresponding to the Top of the DRW;CM-MAC=34:98:b5:2e:a6:78;CMTS-MAC=04:2a:e2:c6:24:ee;CM-QOS=1.1;CM-VER=3.1;

2023-07-23 00:16:10 Warning (5) Dynamic Range Window violation

2023-07-23 00:16:10 Warning (5) RNG-RSP CCAP Commanded Power Exceeds Value Corresponding to the Top of the DRW;CM-MAC=34:98:b5:2e:a6:78;CMTS-MAC=04:2a:e2:c6:24:ee;CM-QOS=1.1;CM-VER=3.1;

2023-07-23 00:16:10 Warning (5) REG-RSP-MP Mismatch Between Calculated Value for P1.6hi Compared to CCAP Provided Value;CM-MAC=34:98:b5:2e:a6:78;CMTS-MAC=04:2a:e2:c6:24:ee;CM-QOS=1.1;CM-VER=3.1 ;

2023-07-23 00:16:05 Notice (6) DS profile assignment change. DS Chan ID: 32; Previous Profile: ; New Profile: 1 2 3.;CM-MAC=34:98:b5:2e:a6:78;CMTS-MAC=04:2a:e2:c6:24:ee;CM-QOS=1.1;CM-VER=3.1;

1970-01-01 00:00:37 Notice (6) Honoring MDD; IP provisioning mode = IPv6

1970-01-01 00:00:24 Critical (3) SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol

timing;CM-MAC=34:98:b5:2e:a6:78;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.1;CM-VER=3.1
;
2023-07-22 13:22:40 Critical (3) Resetting the cable modem due to docsDevResetNow
2023-07-22 12:02:53 Critical (3) SYNC Timing Synchronization failure - Loss of
Sync;CM-MAC=34:98:b5:2e:a6:78;CMTS-MAC=04:2a:e2:c6:24:ee;CM-QOS=1.1;CM-VER=3.1;
1970-01-01 00:00:29 Critical (3) SYNC Timing Synchronization failure - Failed to acquire
QAM/QPSK symbol
timing;CM-MAC=34:98:b5:2e:a6:78;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.1;CM-VER=3.1
;
2023-07-21 17:42:31 Critical (3) Resetting the cable modem due to docsDevResetNow
2023-07-18 18:47:33 Critical (3) Started Unicast Maintenance Ranging - No Response
received - T3
time-out;CM-MAC=34:98:b5:2e:a6:78;CMTS-MAC=04:2a:e2:c6:24:ee;CM-QOS=1.1;CM-VER=
3.1;
2023-07-16 17:31:51 Critical (3) SYNC Timing Synchronization failure - Loss of
Sync;CM-MAC=34:98:b5:2e:a6:78;CMTS-MAC=04:2a:e2:c6:24:ee;CM-QOS=1.1;CM-VER=3.1;
1970-01-01 00:00:25 Critical (3) SYNC Timing Synchronization failure - Failed to acquire
QAM/QPSK symbol
timing;CM-MAC=34:98:b5:2e:a6:78;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.1;CM-VER=3.1
;
2023-07-16 16:05:59 Critical (3) Resetting the cable modem due to docsDevResetNow
2023-07-16 16:00:54 Critical (3) SYNC Timing Synchronization failure - Loss of
Sync;CM-MAC=34:98:b5:2e:a6:78;CMTS-MAC=04:2a:e2:c6:24:ee;CM-QOS=1.1;CM-VER=3.1;
1970-01-01 00:00:25 Critical (3) SYNC Timing Synchronization failure - Failed to acquire
QAM/QPSK symbol
timing;CM-MAC=34:98:b5:2e:a6:78;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.1;CM-VER=3.1
;
1970-01-01 00:02:38 Critical (3) No Ranging Response received - T3
time-out;CM-MAC=34:98:b5:2e:a6:78;CMTS-MAC=04:2a:e2:c6:24:ee;CM-QOS=1.1;CM-VER=
3.1;
1970-01-01 00:02:15 Critical (3) SYNC Timing Synchronization failure - Failed to acquire
QAM/QPSK symbol
timing;CM-MAC=34:98:b5:2e:a6:78;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.1;CM-VER=3.1
;
1970-01-01 00:00:30 Critical (3) SYNC Timing Synchronization failure - Failed to acquire
QAM/QPSK symbol
timing;CM-MAC=34:98:b5:2e:a6:78;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.1;CM-VER=3.1
;
;