

Event Log

Clear Log

Refresh

Time	Priority	Description
1970-1-1, 00:00:39	Warning (5)	DHCP WARNING - Non-critical field invalid in response ;CM-MAC=14:59:c0:80:20:c0;CMTS-MAC=00:17:10:94:2c:8e;CM-QOS=1.0;CM-VER=3.0;
1970-1-1, 00:00:37	Notice (6)	Honoring MDD; IP provisioning mode = IPv4
1970-1-1, 00:00:32	Notice (6)	WiFi Interface [wl1] set to Channel 161 (Side-Band Channel:157) - Reason:INIT
1970-1-1, 00:00:32	Notice (6)	WiFi Interface [wl0] set to Channel 6 (Side-Band Channel:N/A) - Reason:INIT
1970-1-1, 00:00:29	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;;CM-MAC=14:59:c0:80:20:c0;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.0;CM-VER=3.0;
2022-12-12, 22:54:33	Critical (3)	Resetting the cable modem due to docsDevResetNow
1970-1-1, 00:00:30	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;;CM-MAC=14:59:c0:80:20:c0;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.0;CM-VER=3.0;
2022-12-6, 13:21:25	Critical (3)	Resetting the cable modem due to docsDevResetNow
1970-1-1, 00:00:29	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;;CM-MAC=14:59:c0:80:20:c0;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.0;CM-VER=3.0;
2022-12-6, 13:19:51	Critical (3)	Resetting the cable modem due to docsDevResetNow
1970-1-1, 00:00:32	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;;CM-MAC=14:59:c0:80:20:c0;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.0;CM-VER=3.0;
2022-12-4, 13:03:19	Critical (3)	Resetting the cable modem due to docsDevResetNow
1970-1-1, 00:00:31	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;;CM-MAC=14:59:c0:80:20:c0;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.0;CM-VER=3.0;
2022-12-3, 08:56:31	Critical (3)	Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=14:59:c0:80:20:c0;CMTS-MAC=00:17:10:94:2c:8e;CM-QOS=1.1;CM-VER=3.0;
1970-1-1, 00:00:32	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;;CM-MAC=14:59:c0:80:20:c0;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.0;CM-VER=3.0;
2022-11-25, 11:32:32	Critical (3)	Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=14:59:c0:80:20:c0;CMTS-MAC=00:17:10:94:2c:8e;CM-QOS=1.1;CM-VER=3.0;
2022-11-16, 02:58:09	Critical (3)	Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=14:59:c0:80:20:c0;CMTS-MAC=00:17:10:94:2c:8e;CM-QOS=1.1;CM-VER=3.0;
2022-11-7, 00:14:23	Critical (3)	Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=14:59:c0:80:20:c0;CMTS-MAC=00:17:10:94:2c:8e;CM-QOS=1.1;CM-VER=3.0;
1970-1-1, 00:00:31	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;;CM-MAC=14:59:c0:80:20:c0;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.0;CM-VER=3.0;
1970-1-1, 05:10:38	Critical (3)	DHCP FAILED - Discover sent, no offer received;CM-MAC=14:59:c0:80:20:c0;CMTS-MAC=00:17:10:94:2c:8e;CM-QOS=1.0;CM-VER=3.0;
1970-1-1, 05:10:25	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;;CM-MAC=14:59:c0:80:20:c0;CMTS-