

192.168.1.1/debug.htm

ath0 Link encap:Ethernet HWaddr 8C:3B:AD:BC:1C:3A
inet6 addr: fe80::8e3b:adff:febc:1c3a/64 Scope:Link
UP BROADCAST RUNNING MULTICAST MTU:1500 Metric:1
RX packets:133939 errors:0 dropped:0 overruns:0 frame:0
TX packets:170540 errors:107 dropped:0 overruns:0 carrier:0
collisions:0 txqueuelen:0
RX bytes:22141807 (21.1 MiB) TX bytes:107306644 (102.3 MiB)

ath1 Link encap:Ethernet HWaddr 8C:3B:AD:BC:1C:38
inet6 addr: fe80::8e3b:adff:febc:1c38/64 Scope:Link
UP BROADCAST RUNNING MULTICAST MTU:1500 Metric:1
RX packets:534 errors:0 dropped:0 overruns:0 frame:0
TX packets:8744 errors:1 dropped:0 overruns:0 carrier:0
collisions:0 txqueuelen:0
RX bytes:183390 (179.0 KiB) TX bytes:1627540 (1.5 MiB)

br0 Link encap:Ethernet HWaddr 8C:3B:AD:BC:1C:38
inet addr:192.168.1.1 Bcast:192.168.1.255 Mask:255.255.255.0
inet6 addr: 2001:48f8:405d:7d:8e3b:adff:febc:1c38/64 Scope:Global
inet6 addr: fe80::8e3b:adff:febc:1c38/64 Scope:Link
UP BROADCAST RUNNING MULTICAST MTU:1500 Metric:1
RX packets:1333203314 errors:0 dropped:24 overruns:0 frame:0
TX packets:1728492458 errors:0 dropped:0 overruns:0 carrier:0
collisions:0 txqueuelen:0
RX bytes:9089886425 (8.4 GiB) TX bytes:132804382665 (123.6 GiB)

brwan Link encap:Ethernet HWaddr 8C:3B:AD:BC:1C:39

inet addr:24.111.158.186 Bcast:24.111.159.255 Mask:255.255.254.0
inet6 addr: fe80::8e3b:adff:febc:1c39/64 Scope:Link
inet6 addr: 2001:48f8:405c:0:2140:211a:d100:7491/128 Scope:Global
UP BROADCAST RUNNING MULTICAST MTU:1500 Metric:1
RX packets:21779548406 errors:0 dropped:4877 overruns:0 frame:0
TX packets:24192139577 errors:0 dropped:0 overruns:0 carrier:0
collisions:0 txqueuelen:0
RX bytes:147720175029 (137.5 GiB) TX bytes:56420092334 (52.5 GiB)

ethlan Link encap:Ethernet HWaddr 8C:3B:AD:BC:1C:38
inet6 addr: fe80::8e3b:adff:febc:1c38/64 Scope:Link
UP BROADCAST RUNNING MULTICAST MTU:1500 Metric:1
RX packets:18721896 errors:0 dropped:358 overruns:0 frame:0
TX packets:63581943 errors:0 dropped:0 overruns:0 carrier:0
collisions:0 txqueuelen:1000
RX bytes:3761334978 (3.5 GiB) TX bytes:87312792575 (81.3 GiB)
Interrupt:2

ethwan Link encap:Ethernet HWaddr 8C:3B:AD:BC:1C:39
inet6 addr: fe80::8e3b:adff:febc:1c39/64 Scope:Link
UP BROADCAST RUNNING MULTICAST MTU:1500 Metric:1
RX packets:106963205 errors:0 dropped:4873 overruns:0 frame:0
TX packets:32437617 errors:0 dropped:0 overruns:0 carrier:0
collisions:0 txqueuelen:1000
RX bytes:139073869579 (129.5 GiB) TX bytes:9314447411 (8.6 GiB)
Interrupt:255

lo Link encap:Local Loopback
inet addr:127.0.0.1 Mask:255.0.0.0

inet6 addr: ::1/128 Scope:Host

UP LOOPBACK RUNNING MTU:16436 Metric:1

RX packets:21986575 errors:0 dropped:0 overruns:0 frame:0

TX packets:21986575 errors:0 dropped:0 overruns:0 carrier:0

collisions:0 txqueuelen:0

RX bytes:848126552 (808.8 MiB) TX bytes:848126552 (808.8 MiB)

wifi0 Link encap:Ethernet HWaddr 8C:3B:AD:BC:1C:3A

UP BROADCAST RUNNING MULTICAST MTU:1500 Metric:1

RX packets:0 errors:0 dropped:0 overruns:0 frame:0

TX packets:0 errors:0 dropped:0 overruns:0 carrier:0

collisions:0 txqueuelen:539

RX bytes:0 (0.0 B) TX bytes:0 (0.0 B)

Interrupt:68 Memory:e1800000-e1a00000

wifi1 Link encap:Ethernet HWaddr 8C:3B:AD:BC:1C:38

UP BROADCAST RUNNING MULTICAST MTU:1500 Metric:1

RX packets:0 errors:0 dropped:0 overruns:0 frame:0

TX packets:0 errors:0 dropped:0 overruns:0 carrier:0

collisions:0 txqueuelen:539

RX bytes:0 (0.0 B) TX bytes:0 (0.0 B)

Interrupt:90 Memory:e1c00000-e1e00000

MemTotal: 483532 kB

MemFree: 209360 kB

Buffers: 24748 kB

Cached: 59704 kB

SwapCached: 0 kB

Active: 78820 kB

Inactive: 50840 kB
Active(anon): 48828 kB
Inactive(anon): 9948 kB
Active(file): 29992 kB
Inactive(file): 40892 kB
Unevictable: 0 kB
Mlocked: 0 kB
HighTotal: 0 kB
HighFree: 0 kB
LowTotal: 483532 kB
LowFree: 209360 kB
SwapTotal: 0 kB
SwapFree: 0 kB
Dirty: 0 kB
Writeback: 0 kB
AnonPages: 45204 kB
Mapped: 6204 kB
Shmem: 13568 kB
Slab: 111648 kB
SReclaimable: 5824 kB
SUnreclaim: 105824 kB
KernelStack: 1728 kB
PageTables: 2532 kB
NFS_Unstable: 0 kB
Bounce: 0 kB
WritebackTmp: 0 kB
CommitLimit: 483532 kB
Committed_AS: 254680 kB
VmallocTotal: 524288 kB

VmallocUsed: 51476 kB

VmallocChunk: 333016 kB

PID	Uid	VmSize	Stat	Command
1	root	404	S	init
2	root		SW	[kthreadd]
3	root		SW	[ksoftirqd/0]
4	root		DW	[kworker/0:0]
6	root		SW	[migration/0]
7	root		SW	[migration/1]
9	root		SW	[ksoftirqd/1]
10	root		SW<	[khelper]
111	root		SW	[irq/202-msmdata]
276	root		SW	[sync_supers]
278	root		SW	[bdi-default]
279	root		SW<	[crypto]
280	root		SW<	[kblockd]
285	root		SW<	[ata_sff]
289	root		SW<	[spi_qsd.5]
292	root		SW	[msm-spi-thread]
303	root		SW	[khubd]
395	root		SW<	[modem_notifier]
397	root		SW<	[smd_channel_clo]
398	root		SW<	[smsm_cb_wq]
423	root		SW<	[qmi]
452	root		SW<	[nmea]
454	root		SW<	[rpcrouter]
470	root		SW	[kswapd0]
515	root		SW	[fsnotify_mark]
545	root		SW<	[smux_notify_wq]

```
546 root    SW< [smux_tx_wq]
547 root    SW< [smux_rx_wq]
548 root    SW< [smux_loopback_w]
564 root    SW [scsi_eh_0]
579 root    SW [mtdblock0]
584 root    SW [mtdblock1]
589 root    SW [mtdblock2]
594 root    SW [mtdblock3]
599 root    SW [mtdblock4]
602 root    DW [kworker/1:1]
605 root    SW [mtdblock5]
608 root    288 S  sleep 3
610 root    SW [mtdblock6]
615 root    SW [mtdblock7]
620 root    SW [mtdblock8]
625 root    SW [mtdblock9]
630 root    SW [mtdblock10]
635 root    SW [mtdblock11]
640 root    SW [mtdblock12]
645 root    SW [mtdblock13]
655 root    SW [mtdblock14]
669 root    SW [ubi_bgt0d]
676 root    SW [mtdblock15]
685 root    SW [mtdblock16]
694 root    SW [mtdblock17]
699 root    Z [uhttpd]
703 root    SW [mtdblock18]
706 root    1672 S /usr/sbin/net-cgi
709 root    396 S  /bin/sh -c /sbin/enable_collect_console_log.sh >/dev/
```

```
710 root    416 S  /bin/sh /sbin/enable_collect_console_log.sh
711 root    1132 S /usr/sbin/uhttpd -D -I ndindex.html -h /www -r XR500
712 root          SW [mtdblock19]
713 root    1132 S /usr/sbin/uhttpd -D -I ndindex.html -h /www -r XR500
714 root    1624 R /usr/sbin/net-cgi
715 root    3056 R /usr/sbin/net-cgi
716 root    416 S  /bin/sh /sbin/basic_log.sh
717 root    416 S  /bin/sh /sbin/console_log.sh
718 root    252 R  /bin/sh /sbin/enable_collect_console_log.sh
719 root    424 S  /bin/sh /sbin/capture_packet.sh
721 root          SW [mtdblock20]
725 root    292 S  sleep 1
730 root          SW [mtdblock21]
731 root    408 R  ps
732 root    92 R  /bin/sh /sbin/capture_packet.sh
779 root          SW< [usbnet]
799 root          SW< [iewq]
800 root          DW [kinteractiveup]
809 root          SW< [msm-cpufreq]
813 root          SW< [rq_stats]
820 root          SW< [deferwq]
1309 root          SW [ubifs_bgt0_4]
1342 root    256 S  /bin/sh /etc/init.d/rcS S boot
1345 root    384 S  logger -s -p 6 -t sysinit
1350 root    244 S  init
1374 root    300 S  klogd
1377 root    612 S  /bin/datalib
1443 root    236 S  /sbin/watchdog -t 5 /dev/watchdog
1465 root          SW< [xfsalloc]
```

```
1466 root    SW< [xfs_mru_cache]
1467 root    SW< [xfslogd]
1484 root    SW< [gmac_workqueue]
1490 root    SW< [nss_freq_queue]
1491 root    SW< [coredump_wait]
1521 root    SW< [bond0]
1606 root    SW [kworker/0:6]
1672 root    552 S /sbin/hotplug2 --override --persistent --set-rules-fi
2666 root    SW [kworker/0:3]
2783 root    416 S /sbin/ubusd
2882 root    SW< [ecm_nss_ipv4_wo]
2883 root    SW< [ecm_nss_ipv6_wo]
2890 root    276 S /usr/bin/detcable 2
3891 root    DW [kworker/1:0]
4166 root    DW [kworker/1:2]
4170 root    936 S /usr/sbin/ssmtp -C/tmp/ssmtp.conf smiley3303@icloud.c
4280 root    376 S syslogd -m 0 -T GMT+6GMT,M3.2.0/2:00,M11.1.0/2:00 -c
4330 root    212 S aclhijackdns
4350 root    336 S /usr/sbin/ntpclient
4389 root    228 S /usr/bin/hd-idle -i 1800
4419 root    SW [checkSBusTimeou]
4420 root    SW [NU Work:6789]
4422 root    440 S /sbin/KC_BONJOUR
4423 root    408 S /sbin/KC_PRINT
4424 root    SW [NU TCP]
4425 root    SW [NU UDP]
4441 root    196 S /usr/sbin/tftpd-hpa -l -s /var/tftpd-hpa
4477 root    440 S /bin/sh /etc/openvpn/client/ovpn_sync_configs.sh
4504 root    624 S /usr/sbin/dnsmasq --except-interface=lo -u root -r /t
```



```
4538 root    264 S  /usr/sbin/ntgrddns -c /tmp/ntgrdns.conf
5549 root    632 S  /usr/sbin/dbus-daemon --system
5572 root   1248 S  avahi-daemon: running [XR500.local]
5732 root    192 S  potval
5733 root    452 S  /bin/sh /usr/sbin/netconn.sh
5892 root   1696 S  /usr/sbin/net-cgi
5893 root    396 S  /bin/sh -c /etc/email/send_log >/dev/console
5897 root    480 S  /bin/sh /etc/email/send_log
6107 root    352 S  /sbin/traffic_meter
6404 root    300 S  udhcpc -b -i brwan -h XR500 -r 0.0.0.0 -N 192.168.100
6852 root    416 S  /bin/sh /sbin/check_status.sh
7122 root    336 S  /usr/sbin/uhttpd -D -l ndindex.html -h /www -r XR500
8226 root   1440 S N /usr/sbin/afpd -F /etc/netatalk/afpd.conf -P /var/run
8237 root    428 S  /bin/sh /usr/sbin/check_time_machine
8447 root   1804 S  /usr/sbin/uhttpd -D -l ndindex.html -h /www -r XR500
8449 root    192 S  inetd
8477 root   1428 S  /usr/bin/lua /dumaos/ngcompat/main.lua
8482 root    444 S  /usr/bin/arpwatch -i 13 -p 8479 -d
8492 root    240 S  atd
8587 root    396 S  /usr/sbin/aws-iot
8592 root    308 S  /usr/sbin/icqm
8595 root    540 S  /usr/bin/ctwatch -d
8616 root   2788 S  lua /dumaos/api/cli.lua -p /dumaos/apps/system/com.ne
8869 root   3612 S  /usr/bin/lua /dumaos/api/cli.lua -p /dumaos/apps/usr/
8874 root   1928 S  /usr/bin/lua /dumaos/api/cli.lua -p /dumaos/apps/syst
8879 root   5540 S  /usr/bin/lua /dumaos/api/cli.lua -p /dumaos/apps/syst
8887 root   1668 S  /usr/bin/lua /dumaos/api/cli.lua -p /dumaos/apps/syst
8892 root   1840 S  /usr/bin/lua /dumaos/api/cli.lua -p /dumaos/apps/syst
8895 root   2768 S  /usr/bin/lua /dumaos/api/cli.lua -p /dumaos/apps/usr/
```

```
8898 root    1436 S  /usr/bin/lua /dumaos/api/cli.lua -p /dumaos/apps/syst
8903 root    3360 S  /usr/bin/lua /dumaos/api/cli.lua -p /dumaos/apps/syst
8911 root    2240 S  /usr/bin/lua /dumaos/api/cli.lua -p /dumaos/apps/syst
8915 root    3804 S  /usr/bin/lua /dumaos/api/cli.lua -p /dumaos/apps/syst
8921 root    2376 S  /usr/bin/lua /dumaos/api/cli.lua -p /dumaos/apps/usr/
9037 root     936 S  /usr/sbin/ssmtp -C/tmp/ssmtp.conf smiley3303@icloud.c
9411 root         DW [kworker/0:5]
10486 root   2732 S  /usr/bin/dpiclass -q 1 -s 1 -r -t 8 -u 8 -b 1048576
11395 root     936 S  /usr/sbin/ssmtp -C/tmp/ssmtp.conf smiley3303@icloud.c
11479 root   2424 S  /usr/bin/lua /dumaos/api/cli.lua -p /dumaos/apps/usr/
11979 root         SW [kworker/u:1]
15104 root    404 S  udhcpd /tmp/udhcpd.conf
15773 root    272 S  /usr/sbin/net-scan
15782 root    292 S  lld2d br0
15786 root    184 S  /usr/sbin/telnetenable
15896 root    364 S  /usr/sbin/miniupnpd
15955 root         SW [kworker/0:7]
16180 root   1696 S  /usr/sbin/net-cgi
16181 root    396 S  /bin/sh -c /etc/email/send_log >/dev/console
16182 root    480 S  /bin/sh /etc/email/send_log
20759 root    288 S  sleep 43200
20836 root    472 S  /usr/sbin/dhcp6c -c /tmp/dhcp6c.conf -3 brwan
21355 root   1060 S  hostapd -P /var/run/wifi-ath1.pid -B /var/run/hostapd
21357 root    320 S  hostapd_cli -i ath1 -P /var/run/hostapd_cli-ath1.pid
21387 root         SW [kworker/1:6]
21396 root    316 S  /usr/sbin/radvd -C /tmp/radvd.conf
21400 root    424 S  /usr/sbin/dhcp6s -3 -c /tmp/dhcp6s.conf br0
21406 root    668 S  /usr/sbin/ripngd -d -f /etc/ripngd.conf
21412 root    556 S  /usr/sbin/zebra -dk -f /etc/zebra.conf
```

```

21536 root    1096 S  hostapd -P /var/run/wifi-ath0.pid -B /var/run/hostapd
21538 root    320 S  hostapd_cli -i ath0 -P /var/run/hostapd_cli-ath0.pid
22006 root         DW [kworker/u:2]
22508 root    476 S  /usr/bin/geopip -d -n /usr/networks -g /usr/geoseq -i
24968 root         SW [kworker/1:4]
25159 root         SW [kworker/u:0]
25383 root    392 S  crond -c /tmp/etc/crontabs -T GMT+6GMT,M3.2.0/2:00,M1
25779 root         DW [kworker/u:3]
26272 root    396 S  /bin/sh -c /etc/email/email_full_log
26273 root    484 S  /bin/sh /etc/email/email_full_log
26828 root         DW [kworker/0:2]
26947 root   1672 S  /usr/sbin/net-cgi
26948 root    396 S  /bin/sh -c /etc/email/send_log >/dev/console
26949 root    480 S  /bin/sh /etc/email/send_log
27116 root    936 S  /usr/sbin/ssmtp -C/tmp/ssmtp.conf smiley3303@icloud.c
27272 root         DW [kworker/1:3]
28703 root         SW [kworker/1:7]
29233 root         DW [kworker/0:1]
30311 root         DW [kworker/1:5]
30323 root         SW [kworker/u:4]
30369 root    580 S  /opt/xagent/xagent -w -d --ca_file /opt/xagent/certs/
30374 root   2740 S  /opt/xagent/xagent -w -d --ca_file /opt/xagent/certs/
31115 root    980 S  /usr/bin/luajit /dumaos/apps/system/com.netdumasoftware.
32042 root         DW [kworker/0:4]
32284 root    288 S  sleep 60
32533 root    288 S  sleep 60

```

```

          total    used    free    shared    buffers
Mem:    483532    275800    207732         0    24748
Swap:      0         0         0

```

Total: 483532 275800 207732

nameserver 24.220.1.100

nameserver 8.8.8.8

nameserver 24.220.1.101

nameserver 2001:48f8::24:220:1:100

nameserver 2001:48f8::24:220:1:101

Kernel IP routing table

Destination	Gateway	Genmask	Flags	Metric	Ref	Use	Iface
default	24-111-158-1-dy	0.0.0.0	UG	0	0	0	brwan
24.111.158.0	*	255.255.254.0	U	0	0	0	brwan
192.168.1.0	*	255.255.255.0	U	0	0	0	br0
239.0.0.0	*	255.0.0.0	U	0	0	0	br0

IP address	HW type	Flags	HW address	Mask	Device
192.168.1.229	0x1	0x2	a8:c0:ea:18:3c:a1	*	br0
192.168.1.42	0x1	0x2	84:3a:4b:46:8a:d4	*	br0
192.168.1.13	0x1	0x2	b6:1c:00:a6:4f:8c	*	br0
192.168.1.33	0x1	0x0	00:00:00:00:00:00	*	br0
192.168.1.4	0x1	0x2	80:d6:05:84:67:e5	*	br0
192.168.1.24	0x1	0x2	a6:49:2e:8a:d4:00	*	br0
192.168.1.15	0x1	0x2	68:db:f5:67:0f:00	*	br0
192.168.1.35	0x1	0x2	74:d6:37:0b:21:7c	*	br0
192.168.1.6	0x1	0x2	84:10:0d:0d:ac:98	*	br0
192.168.1.26	0x1	0x2	78:11:dc:21:88:d6	*	br0
192.168.1.17	0x1	0x2	78:11:dc:20:e8:90	*	br0
192.168.1.37	0x1	0x2	7c:d5:66:dd:4e:73	*	br0
192.168.1.8	0x1	0x2	68:db:f5:42:8e:45	*	br0
192.168.1.28	0x1	0x2	78:11:dc:21:89:04	*	br0
192.168.1.19	0x1	0x2	78:11:dc:21:76:68	*	br0
192.168.1.39	0x1	0x2	78:11:dc:21:8a:32	*	br0

192.168.1.10	0x1	0x2	40:b4:cd:45:f6:7e	*	br0
192.168.1.30	0x1	0x2	24:4c:e3:5c:e5:eb	*	br0
192.168.1.50	0x1	0x2	18:74:2e:30:5d:86	*	br0
24.111.158.1	0x1	0x2	00:27:90:fe:b4:19	*	brwan
192.168.1.41	0x1	0x2	68:db:f5:d1:28:16	*	br0
192.168.1.12	0x1	0x2	a4:4c:c8:89:ef:84	*	br0
192.168.1.32	0x1	0x2	c8:85:50:12:fa:f9	*	br0
192.168.1.3	0x1	0x2	cc:32:e5:ff:57:28	*	br0
192.168.1.43	0x1	0x2	dc:56:e7:54:b7:4f	*	br0
192.168.1.34	0x1	0x2	00:f7:6f:d6:72:dc	*	br0
192.168.1.5	0x1	0x2	78:11:dc:21:8c:85	*	br0
192.168.1.16	0x1	0x2	f4:03:2a:ed:b2:e0	*	br0
192.168.1.36	0x1	0x2	08:12:a5:ee:65:19	*	br0
192.168.1.7	0x1	0x2	c2:d0:26:e6:e0:cf	*	br0
192.168.1.27	0x1	0x2	78:11:dc:21:75:a0	*	br0
192.168.1.29	0x1	0x2	30:59:b7:b4:5e:62	*	br0
192.168.1.40	0x1	0x2	7c:d5:66:ee:63:c8	*	br0
192.168.1.31	0x1	0x2	f4:ce:46:4d:73:d8	*	br0
192.168.1.2	0x1	0x2	50:dc:e7:a1:4f:18	*	br0

ath0 Link encap:Ethernet HWaddr 8C:3B:AD:BC:1C:3A

inet6 addr: fe80::8e3b:adff:febc:1c3a/64 Scope:Link

UP BROADCAST RUNNING MULTICAST MTU:1500 Metric:1

RX packets:248654 errors:0 dropped:0 overruns:0 frame:0

TX packets:289056 errors:1654 dropped:0 overruns:0 carrier:0

collisions:0 txqueuelen:0

RX bytes:30361134 (28.9 MiB) TX bytes:130981628 (124.9 MiB)

ath1 Link encap:Ethernet HWaddr 8C:3B:AD:BC:1C:38

inet6 addr: fe80::8e3b:adff:febc:1c38/64 Scope:Link

UP BROADCAST RUNNING MULTICAST MTU:1500 Metric:1

RX packets:541 errors:0 dropped:0 overruns:0 frame:0

TX packets:9292 errors:1 dropped:0 overruns:0 carrier:0

collisions:0 txqueuelen:0

RX bytes:183974 (179.6 KiB) TX bytes:1754845 (1.6 MiB)

br0 Link encap:Ethernet HWaddr 8C:3B:AD:BC:1C:38

inet addr:192.168.1.1 Bcast:192.168.1.255 Mask:255.255.255.0

inet6 addr: 2001:48f8:405d:7d:8e3b:adff:febc:1c38/64 Scope:Global

inet6 addr: fe80::8e3b:adff:febc:1c38/64 Scope:Link

UP BROADCAST RUNNING MULTICAST MTU:1500 Metric:1

RX packets:1333218023 errors:0 dropped:24 overruns:0 frame:0

TX packets:1728509679 errors:0 dropped:0 overruns:0 carrier:0

collisions:0 txqueuelen:0

RX bytes:9093034194 (8.4 GiB) TX bytes:132817609245 (123.6 GiB)

brwan Link encap:Ethernet HWaddr 8C:3B:AD:BC:1C:39

inet addr:24.111.158.186 Bcast:24.111.159.255 Mask:255.255.254.0

inet6 addr: fe80::8e3b:adff:febc:1c39/64 Scope:Link

inet6 addr: 2001:48f8:405c:0:2140:211a:d100:7491/128 Scope:Global

UP BROADCAST RUNNING MULTICAST MTU:1500 Metric:1

RX packets:21779565124 errors:0 dropped:4877 overruns:0 frame:0

TX packets:24192149223 errors:0 dropped:0 overruns:0 carrier:0

collisions:0 txqueuelen:0

RX bytes:147731016427 (137.5 GiB) TX bytes:56422666060 (52.5 GiB)

ethlan Link encap:Ethernet HWaddr 8C:3B:AD:BC:1C:38

inet6 addr: fe80::8e3b:adff:febc:1c38/64 Scope:Link

UP BROADCAST RUNNING MULTICAST MTU:1500 Metric:1

RX packets:18724689 errors:0 dropped:359 overruns:0 frame:0
TX packets:63585231 errors:0 dropped:0 overruns:0 carrier:0
collisions:0 txqueuelen:1000
RX bytes:3762735569 (3.5 GiB) TX bytes:87313695065 (81.3 GiB)
Interrupt:2

ethwan Link encap:Ethernet HWaddr 8C:3B:AD:BC:1C:39

inet6 addr: fe80::8e3b:adff:febc:1c39/64 Scope:Link
UP BROADCAST RUNNING MULTICAST MTU:1500 Metric:1
RX packets:106979916 errors:0 dropped:4878 overruns:0 frame:0
TX packets:32447254 errors:0 dropped:0 overruns:0 carrier:0
collisions:0 txqueuelen:1000
RX bytes:139084946560 (129.5 GiB) TX bytes:9317038732 (8.6 GiB)
Interrupt:255

lo Link encap:Local Loopback

inet addr:127.0.0.1 Mask:255.0.0.0
inet6 addr: ::1/128 Scope:Host
UP LOOPBACK RUNNING MTU:16436 Metric:1
RX packets:22019078 errors:0 dropped:0 overruns:0 frame:0
TX packets:22019078 errors:0 dropped:0 overruns:0 carrier:0
collisions:0 txqueuelen:0
RX bytes:849385199 (810.0 MiB) TX bytes:849385199 (810.0 MiB)

wifi0 Link encap:Ethernet HWaddr 8C:3B:AD:BC:1C:3A

UP BROADCAST RUNNING MULTICAST MTU:1500 Metric:1
RX packets:0 errors:0 dropped:0 overruns:0 frame:0
TX packets:0 errors:0 dropped:0 overruns:0 carrier:0
collisions:0 txqueuelen:539

RX bytes:0 (0.0 B) TX bytes:0 (0.0 B)

Interrupt:68 Memory:e1800000-e1a00000

wifi1 Link encap:Ethernet HWaddr 8C:3B:AD:BC:1C:38

UP BROADCAST RUNNING MULTICAST MTU:1500 Metric:1

RX packets:0 errors:0 dropped:0 overruns:0 frame:0

TX packets:0 errors:0 dropped:0 overruns:0 carrier:0

collisions:0 txqueuelen:539

RX bytes:0 (0.0 B) TX bytes:0 (0.0 B)

Interrupt:90 Memory:e1c00000-e1e00000

MemTotal: 483532 kB

MemFree: 23080 kB

Buffers: 27404 kB

Cached: 161036 kB

SwapCached: 0 kB

Active: 129220 kB

Inactive: 114740 kB

Active(anon): 61752 kB

Inactive(anon): 12480 kB

Active(file): 67468 kB

Inactive(file): 102260 kB

Unevictable: 0 kB

Mlocked: 0 kB

HighTotal: 0 kB

HighFree: 0 kB

LowTotal: 483532 kB

LowFree: 23080 kB

SwapTotal: 0 kB

SwapFree: 0 kB
Dirty: 100 kB
Writeback: 0 kB
AnonPages: 55548 kB
Mapped: 9628 kB
Shmem: 18644 kB
Slab: 174992 kB
SReclaimable: 18724 kB
SUnreclaim: 156268 kB
KernelStack: 1792 kB
PageTables: 2500 kB
NFS_Unstable: 0 kB
Bounce: 0 kB
WritebackTmp: 0 kB
CommitLimit: 483532 kB
Committed_AS: 242196 kB
VmallocTotal: 524288 kB
VmallocUsed: 51476 kB
VmallocChunk: 333016 kB

PID	Uid	VmSize	Stat	Command
1	root	404	S	init
2	root		SW	[kthreadd]
3	root		SW	[ksoftirqd/0]
4	root		DW	[kworker/0:0]
6	root		SW	[migration/0]
7	root		SW	[migration/1]
9	root		SW	[ksoftirqd/1]
10	root		SW<	[khelper]
111	root		SW	[irq/202-msmdata]

276	root	SW	[sync_supers]
278	root	SW	[bdi-default]
279	root	SW<	[crypto]
280	root	SW<	[kblockd]
285	root	SW<	[ata_sff]
289	root	SW<	[spi_qsd.5]
292	root	SW	[msm-spi-thread]
303	root	SW	[khubd]
395	root	SW<	[modem_notifier]
397	root	SW<	[smd_channel_clo]
398	root	SW<	[smsm_cb_wq]
423	root	SW<	[qmi]
452	root	SW<	[nmea]
454	root	SW<	[rpcrouter]
470	root	SW	[kswapd0]
515	root	SW	[fsnotify_mark]
545	root	SW<	[smux_notify_wq]
546	root	SW<	[smux_tx_wq]
547	root	SW<	[smux_rx_wq]
548	root	SW<	[smux_loopback_w]
564	root	SW	[scsi_eh_0]
579	root	SW	[mtdblock0]
584	root	SW	[mtdblock1]
589	root	SW	[mtdblock2]
594	root	SW	[mtdblock3]
599	root	SW	[mtdblock4]
602	root	DW	[kworker/1:1]
605	root	SW	[mtdblock5]
610	root	SW	[mtdblock6]

```
615 root    SW [mtdblock7]
620 root    SW [mtdblock8]
625 root    SW [mtdblock9]
630 root    SW [mtdblock10]
635 root    SW [mtdblock11]
640 root    SW [mtdblock12]
645 root    SW [mtdblock13]
655 root    SW [mtdblock14]
669 root    SW [ubi_bgt0d]
676 root    SW [mtdblock15]
685 root    SW [mtdblock16]
694 root    SW [mtdblock17]
703 root    SW [mtdblock18]
712 root    SW [mtdblock19]
716 root    436 S /bin/sh /sbin/basic_log.sh
717 root    436 S /bin/sh /sbin/console_log.sh
718 root    412 S /bin/sh /sbin/wireless_log.sh
721 root    SW [mtdblock20]
730 root    SW [mtdblock21]
758 root    4692 S tcpdump -i br0 -s 0 -W 1 -w /tmp/lan.pcap -C 5
759 root    4692 S tcpdump -i brwan -s 0 -W 1 -w /tmp/wan.pcap -C 5
779 root    SW< [usbnet]
799 root    SW< [iewq]
800 root    DW [kinteractiveup]
802 root    292 S sleep 300
809 root    SW< [msm-cpufreq]
813 root    SW< [rq_stats]
820 root    SW< [deferwq]
1309 root   SW [ubifs_bgt0_4]
```

```
1342 root    256 S  /bin/sh /etc/init.d/rcS S boot
1345 root    384 S  logger -s -p 6 -t sysinit
1350 root    244 S  init
1374 root    300 S  klogd
1377 root    616 S  /bin/datalib
1443 root    236 S  /sbin/watchdog -t 5 /dev/watchdog
1465 root          SW< [xfsalloc]
1466 root          SW< [xfs_mru_cache]
1467 root          SW< [xfslogd]
1484 root          SW< [gmac_workqueue]
1490 root          SW< [nss_freq_queue]
1491 root          SW< [coredump_wait]
1521 root          SW< [bond0]
1606 root          SW [kworker/0:6]
1672 root    552 S  /sbin/hotplug2 --override --persistent --set-rules-fi
2666 root          SW [kworker/0:3]
2783 root    416 S  /sbin/ubusd
2882 root          SW< [ecm_nss_ipv4_wo]
2883 root          SW< [ecm_nss_ipv6_wo]
2890 root    276 S  /usr/bin/detcable 2
3143 root          SW [scsi_eh_1]
3144 root          SW [usb-storage]
3424 root    1988 S N /usr/sbin/smbd -D
3432 root    728 S N /usr/sbin/smbd -D
3433 root    600 S N /usr/sbin/smbd -D
3698 root          SW [flush-ubifs_0_4]
3891 root          DW [kworker/1:0]
4166 root          DW [kworker/1:2]
4280 root    376 S  syslogd -m 0 -T GMT+6GMT,M3.2.0/2:00,M11.1.0/2:00 -c
```

```
4330 root    212 S  aclhijackdns
4350 root    336 S  /usr/sbin/ntpclient
4389 root    228 S  /usr/bin/hd-idle -i 1800
4419 root         SW [checkSBusTimeou]
4420 root         SW [NU Work:6789]
4422 root    440 S  /sbin/KC_BONJOUR
4423 root    408 S  /sbin/KC_PRINT
4424 root         SW [NU TCP]
4425 root         SW [NU UDP]
4441 root    196 S  /usr/sbin/tftpd-hpa -l -s /var/tftpd-hpa
4477 root    440 S  /bin/sh /etc/opensvpn/client/ovpn_sync_configs.sh
4504 root    624 S  /usr/sbin/dnsmasq --except-interface=lo -u root -r /t
4533 root         SW [flush-8:0]
4538 root    264 S  /usr/sbin/ntgrddns -c /tmp/ntgrdns.conf
5549 root    660 S  /usr/sbin/dbus-daemon --system
5572 root   1248 S  avahi-daemon: running [XR500.local]
5732 root    192 S  potval
5733 root    452 S  /bin/sh /usr/sbin/netconn.sh
6107 root    352 S  /sbin/traffic_meter
6404 root    300 S  udhcpc -b -i brwan -h XR500 -r 0.0.0.0 -N 192.168.100
6852 root    416 S  /bin/sh /sbin/check_status.sh
7122 root    336 S  /usr/sbin/uhttpd -D -l ndindex.html -h /www -r XR500
8226 root   1528 S  N /usr/sbin/afpd -F /etc/netatalk/afpd.conf -P /var/run
8237 root    428 S  /bin/sh /usr/sbin/check_time_machine
8447 root   1804 S  /usr/sbin/uhttpd -D -l ndindex.html -h /www -r XR500
8449 root    192 S  inetd
8477 root   1428 S  /usr/bin/lua /dumaos/ngcompat/main.lua
8482 root    444 S  /usr/bin/arpwatch -i 13 -p 8479 -d
8492 root    240 S  atd
```

```
8587 root    396 S  /usr/sbin/aws-iot
8592 root    308 S  /usr/sbin/icqm
8595 root    540 S  /usr/bin/ctwatch -d
8616 root    2788 S lua /dumaos/api/cli.lua -p /dumaos/apps/system/com.ne
8869 root    3612 S  /usr/bin/lua /dumaos/api/cli.lua -p /dumaos/apps/usr/
8874 root    1928 S  /usr/bin/lua /dumaos/api/cli.lua -p /dumaos/apps/syst
8879 root    5540 S  /usr/bin/lua /dumaos/api/cli.lua -p /dumaos/apps/syst
8887 root    1668 S  /usr/bin/lua /dumaos/api/cli.lua -p /dumaos/apps/syst
8892 root    1840 S  /usr/bin/lua /dumaos/api/cli.lua -p /dumaos/apps/syst
8895 root    2768 S  /usr/bin/lua /dumaos/api/cli.lua -p /dumaos/apps/usr/
8898 root    1436 S  /usr/bin/lua /dumaos/api/cli.lua -p /dumaos/apps/syst
8903 root    3360 S  /usr/bin/lua /dumaos/api/cli.lua -p /dumaos/apps/syst
8911 root    2240 S  /usr/bin/lua /dumaos/api/cli.lua -p /dumaos/apps/syst
8915 root    3804 S  /usr/bin/lua /dumaos/api/cli.lua -p /dumaos/apps/syst
8921 root    2376 S  /usr/bin/lua /dumaos/api/cli.lua -p /dumaos/apps/usr/
9411 root          DW [kworker/0:5]
10486 root   2732 S  /usr/bin/dpiclass -q 1 -s 1 -r -t 8 -u 8 -b 1048576
11479 root   2424 S  /usr/bin/lua /dumaos/api/cli.lua -p /dumaos/apps/usr/
13004 root          SW [scsi_eh_2]
13005 root          SW [usb-storage]
13049 root          DW [kworker/u:1]
13056 root    452 S  /sbin/hotplug2 --override --persistent --set-rules-fi
13059 root    388 S  /bin/sh -c /sbin/hotplug2.mount sdb1
13061 root    460 S  /bin/sh /sbin/hotplug2.mount sdb1
13430 root          SW [flush-8:16]
14465 root          Z [nmbd]
15104 root    404 S  udhcpd /tmp/udhcpd.conf
15773 root    272 S  /usr/sbin/net-scan
15782 root    292 S  lld2d br0
```

```
15786 root    184 S  /usr/sbin/telnetenable
15832 root    980 S  /usr/bin/lua /dumaos/apps/system/com.netdumasoftware.
15896 root    364 S  /usr/sbin/miniupnpd
15955 root         SW [kworker/0:7]
16119 root   1756 S  /usr/sbin/minidlna -f /tmp/etc/minidlna.conf
16123 root  15768 R N /usr/sbin/minidlna -f /tmp/etc/minidlna.conf
16607 root    288 S  sleep 60
16998 root    288 S  sleep 60
17645 root    288 S  sleep 3
17694 root   1468 S  /usr/sbin/net-cgi
17792 root    292 S  sleep 1
17793 root         Z [uhttpd]
17794 root         Z [uhttpd]
17809 root    288 S  sleep 1
17810 root         Z [uhttpd]
17833 root   1264 S  /usr/sbin/nmbd -D
17834 root    396 S  /bin/sh -c /sbin/cmdftp restart >/dev/console
17835 root    496 S  /bin/sh /sbin/cmdftp restart
17836 root    292 S  sleep 5
17842 root    408 R  ps
20759 root    288 S  sleep 43200
20836 root    472 S  /usr/sbin/dhcp6c -c /tmp/dhcp6c.conf -3 brwan
21355 root   1060 S  hostapd -P /var/run/wifi-ath1.pid -B /var/run/hostapd
21357 root    320 S  hostapd_cli -i ath1 -P /var/run/hostapd_cli-ath1.pid
21387 root         SW [kworker/1:6]
21396 root    316 S  /usr/sbin/radvd -C /tmp/radvd.conf
21400 root    424 S  /usr/sbin/dhcp6s -3 -c /tmp/dhcp6s.conf br0
21406 root    668 S  /usr/sbin/ripngd -d -f /etc/ripngd.conf
21412 root    556 S  /usr/sbin/zebra -dk -f /etc/zebra.conf
```

```

21536 root    1096 S  hostapd -P /var/run/wifi-ath0.pid -B /var/run/hostapd
21538 root    320 S  hostapd_cli -i ath0 -P /var/run/hostapd_cli-ath0.pid
22006 root         DW [kworker/u:2]
22508 root    476 S  /usr/bin/geoip -d -n /usr/networks -g /usr/geoseq -i
24968 root         SW [kworker/1:4]
25159 root         SW [kworker/u:0]
25383 root    392 S  crond -c /tmp/etc/crontabs -T GMT+6GMT,M3.2.0/2:00,M1
25779 root         SW [kworker/u:3]
26828 root         DW [kworker/0:2]
26947 root   1672 S  /usr/sbin/net-cgi
26948 root    396 S  /bin/sh -c /etc/email/send_log >/dev/console
26949 root    480 S  /bin/sh /etc/email/send_log
27116 root    936 S  /usr/sbin/ssmtp -C/tmp/ssmtp.conf smiley3303@icloud.c
27272 root         DW [kworker/1:3]
28703 root         SW [kworker/1:7]
29233 root         DW [kworker/0:1]
30311 root         DW [kworker/1:5]
30323 root         SW [kworker/u:4]
30369 root    580 S  /opt/xagent/xagent -w -d --ca_file /opt/xagent/certs/
30374 root   2740 S  /opt/xagent/xagent -w -d --ca_file /opt/xagent/certs/
32042 root         DW [kworker/0:4]

```

```

          total    used    free    shared    buffers
Mem:    483532    460508    23024         0    27404
Swap:         0         0         0
Total:   483532    460508    23024

```

nameserver 24.220.1.100

nameserver 8.8.8.8

nameserver 24.220.1.101

nameserver 2001:48f8::24:220:1:100

nameserver 2001:48f8::24:220:1:101

Kernel IP routing table

Destination	Gateway	Genmask	Flags	Metric	Ref	Use	Iface
default	24-111-158-1-dy	0.0.0.0	UG	0	0	0	brwan
24.111.158.0	*	255.255.254.0	U	0	0	0	brwan
192.168.1.0	*	255.255.255.0	U	0	0	0	br0
239.0.0.0	*	255.0.0.0	U	0	0	0	br0

IP address	HW type	Flags	HW address	Mask	Device
192.168.1.229	0x1	0x2	a8:c0:ea:18:3c:a1	*	br0
192.168.1.42	0x1	0x2	84:3a:4b:46:8a:d4	*	br0
192.168.1.13	0x1	0x2	b6:1c:00:a6:4f:8c	*	br0
192.168.1.4	0x1	0x2	80:d6:05:84:67:e5	*	br0
192.168.1.24	0x1	0x2	a6:49:2e:8a:d4:00	*	br0
192.168.1.15	0x1	0x2	68:db:f5:67:0f:00	*	br0
192.168.1.35	0x1	0x2	74:d6:37:0b:21:7c	*	br0
192.168.1.6	0x1	0x2	84:10:0d:0d:ac:98	*	br0
192.168.1.26	0x1	0x2	78:11:dc:21:88:d6	*	br0
192.168.1.17	0x1	0x2	78:11:dc:20:e8:90	*	br0
192.168.1.37	0x1	0x2	7c:d5:66:dd:4e:73	*	br0
192.168.1.8	0x1	0x2	68:db:f5:42:8e:45	*	br0
192.168.1.28	0x1	0x2	78:11:dc:21:89:04	*	br0
192.168.1.19	0x1	0x2	78:11:dc:21:76:68	*	br0
192.168.1.39	0x1	0x2	78:11:dc:21:8a:32	*	br0
192.168.1.10	0x1	0x2	40:b4:cd:45:f6:7e	*	br0
192.168.1.30	0x1	0x2	24:4c:e3:5c:e5:eb	*	br0
192.168.1.50	0x1	0x2	18:74:2e:30:5d:86	*	br0
24.111.158.1	0x1	0x2	00:27:90:fe:b4:19	*	brwan
192.168.1.41	0x1	0x2	68:db:f5:d1:28:16	*	br0
192.168.1.12	0x1	0x2	a4:4c:c8:89:ef:84	*	br0

192.168.1.32	0x1	0x2	c8:85:50:12:fa:f9	*	br0
192.168.1.3	0x1	0x2	cc:32:e5:ff:57:28	*	br0
192.168.1.43	0x1	0x2	dc:56:e7:54:b7:4f	*	br0
192.168.1.5	0x1	0x2	78:11:dc:21:8c:85	*	br0
192.168.1.16	0x1	0x2	f4:03:2a:ed:b2:e0	*	br0
192.168.1.36	0x1	0x2	08:12:a5:ee:65:19	*	br0
192.168.1.7	0x1	0x2	c2:d0:26:e6:e0:cf	*	br0
192.168.1.27	0x1	0x2	78:11:dc:21:75:a0	*	br0
192.168.1.29	0x1	0x2	30:59:b7:b4:5e:62	*	br0
192.168.1.40	0x1	0x2	7c:d5:66:ee:63:c8	*	br0
192.168.1.31	0x1	0x2	f4:ce:46:4d:73:d8	*	br0
192.168.1.2	0x1	0x2	50:dc:e7:a1:4f:18	*	br0

Booting Linux on physical CPU 0

Linux version 3.4.103 (iceway.zhang@cnsHADNICP02.DeltaOS.CORP) (gcc version 4.6.3 20120201 (prerelease) (Linaro GCC 4.6-2012.02)) #1 SMP Mon Aug 24 18:10:13 CST 2020

CPU: ARMv7 Processor [512f04d0] revision 0 (ARMv7), cr=10c5387d

CPU: PIPT / VIPT nonaliasing data cache, PIPT instruction cache

Machine: Qualcomm Atheros AP161 reference board

QCA command line: console=ttyHSL1,115200n8

DNI command line: console=ttyHSL1,115200n8 ubi.mtd=netgear root=/dev/mtdblock6

msm_reserve_memory: 0x44600000, 0x200000

memory pool 3 (start 5fc00000 size 400000) initialized

Memory policy: ECC disabled, Data cache writealloc

smem_find(137, 80): wrong size 72

socinfo_init: v6, id=280, ver=3.0, raw_id=17, raw_ver=17, hw_plat=0, hw_plat_ver=65536

accessory_chip=0 hw_plat_subtype=0

PERCPU: Embedded 8 pages/cpu @c0d53000 s10624 r8192 d13952 u32768

Built 1 zonelists in Zone order, mobility grouping on. Total pages: 123178

Kernel command line: console=ttyHSL1,115200n8 ubi.mtd=netgear root=/dev/mtdblock6

PID hash table entries: 2048 (order: 1, 8192 bytes)

Dentry cache hash table entries: 65536 (order: 6, 262144 bytes)

Inode-cache hash table entries: 32768 (order: 5, 131072 bytes)

Memory: 49MB 436MB = 485MB total

Memory: 482500k/488644k available, 14140k reserved, 0K highmem

Virtual kernel memory layout:

vector : 0xffff0000 - 0xffff1000 (4 kB)
fixmap : 0xffff0000 - 0xfffe0000 (896 kB)
vmalloc : 0xdf000000 - 0xff000000 (512 MB)
lowmem : 0xc0000000 - 0xdeb00000 (491 MB)
pkmap : 0xbfe00000 - 0xc0000000 (2 MB)
modules : 0xbf000000 - 0xbfe00000 (14 MB)
.text : 0xc0008000 - 0xc0636000 (6328 kB)
.init : 0xc0700000 - 0xc0802980 (1035 kB)
.data : 0xc0804000 - 0xc08a7cc0 (656 kB)
.bss : 0xc08a7ce4 - 0xc094f998 (672 kB)

SLUB: Genslabs=11, HWalign=64, Order=0-3, MinObjects=0, CPUs=2, Nodes=1

Hierarchical RCU implementation.

NR_IRQS:1689

sched_clock: 32 bits at 32kHz, resolution 31240ns, wraps every 134175798ms

Console: colour dummy device 80x30

Calibrating delay using timer specific routine.. 12.55 BogoMIPS (lpj=62790)

pid_max: default: 32768 minimum: 301

Mount-cache hash table entries: 512

CPU: Testing write buffer coherency: ok

CPU0: thread -1, cpu 0, socket 0, mpidr 80000000

Setting up static identity map for 0x4195a0b0 - 0x4195a138

CPU1: Booted secondary processor

CPU1: thread -1, cpu 1, socket 0, mpidr 80000001

Brought up 2 CPUs

SMP: Total of 2 processors activated (25.11 BogoMIPS).

dummy:

NET: Registered protocol family 16

AXI: msm_bus_fabric_init_driver(): msm_bus_fabric_init_driver

meminfo_init: smem ram ptable found: ver: 0 len: 5

Found 1 memory banks grouped into 8 memory regions

gpiochip_add: registered GPIOs 0 to 151 on device: msmgpio

smem_find(137, 80): wrong size 72

socinfo_init: v6, id=280, ver=3.0, raw_id=17, raw_ver=17, hw_plat=0, hw_plat_ver=65536

accessory_chip=0 hw_plat_subtype=0

msm_rpm_init: RPM firmware 3.0.16777364

clk_tbl_nss_fast - loaded

msm_dmov_memcpy_init: Success

sps:BAM 0x12244000 enabled: ver:0x5, number of pipes:20

sps:BAM 0x12244000 is registered.

sps:sps is ready.

msm_pcie_setup: link initialized

PCI host bridge to bus 0000:00

pci_bus 0000:00: root bus resource [mem 0x08000000-0x0fefffff]

PCI: bus0: Fast back to back transfers disabled

pci 0000:00:00.0: bridge configuration invalid ([bus 00-00]), reconfiguring

PCI: bus1: Fast back to back transfers disabled

msm_pcie_setup: link initialized

PCI host bridge to bus 0000:02

pci_bus 0000:02: root bus resource [mem 0x2e000000-0x31efffff]

PCI: bus2: Fast back to back transfers disabled

pci 0000:02:00.0: bridge configuration invalid ([bus 00-00]), reconfiguring

68:db:f5:67:0f:00 12 153 317M 170M 15 4320 0 65535 EP 0 b 0 AWPSM
00:26:03 RSN WME IEEE80211_MODE_11AC_VHT80 0

78:11:dc:21:88:d6 11 153 146M 10038M 47 4320 0 65535 EPs 0 b 0 WPS
00:26:03 RSN WME IEEE80211_MODE_11NA_HT40 0

78:11:dc:21:8c:85 15 153 146M 10038M 24 4320 0 65535 EPs 0 b 0 WPS
00:26:03 RSN WME IEEE80211_MODE_11NA_HT40 0

b6:1c:00:a6:4f:8c 18 153 845M 634M 36 0 0 65535 EP 0 b 0 AWPS
00:25:58 RSN WME IEEE80211_MODE_11AC_VHT80 1

84:3a:4b:46:8a:d4 19 153 237M 23069M 27 0 0 65535 EPs 0 b 0 WPGSM
00:25:56 RSN WME IEEE80211_MODE_11NA_HT40 0

c8:85:50:12:fa:f9 20 153 292M 0M 28 0 0 65535 EP 0 b 0 WPGS
00:25:42 RSN WME IEEE80211_MODE_11NA_HT40 1

80:d6:05:84:67:e5 21 153 210M 31M 13 0 0 65535 EP 0 b 0 WPGS
00:25:42 RSN WME IEEE80211_MODE_11NA_HT40 1

7c:d5:66:dd:4e:73 8 153 317M 170M 13 4320 0 65535 EP 0 b 0 AWPSM
00:21:45 RSN WME IEEE80211_MODE_11AC_VHT80 0

f4:03:2a:ed:b2:e0 9 153 422M 422M 39 4320 0 65535 EP 0 b 0 AWPSM
00:21:45 RSN WME IEEE80211_MODE_11AC_VHT80 0

08:12:a5:ee:65:19 10 153 422M 380M 27 4320 0 65535 EP 0 b 0 AWPSM
00:21:45 RSN WME IEEE80211_MODE_11AC_VHT80 0

7c:d5:66:ee:63:c8 7 153 422M 422M 31 4320 0 65535 EP 0 b 0 AWPSM
00:20:18 RSN WME IEEE80211_MODE_11AC_VHT80 0

68:db:f5:42:8e:45 14 153 422M 342M 27 4320 0 65535 EP 0 b 0 AWPSM
00:20:18 RSN WME IEEE80211_MODE_11AC_VHT80 0

68:db:f5:d1:28:16 17 153 380M 285M 23 4320 0 65535 EP 0 b 0 AWPSM
00:20:10 RSN WME IEEE80211_MODE_11AC_VHT80 0

84:10:0d:0d:ac:98 22 153 457M 342M 22 0 0 65535 EP 0 b 0 AWPS
00:20:05 RSN WME IEEE80211_MODE_11AC_VHT80 1

40:b4:cd:45:f6:7e 13 153 761M 5M 40 4320 0 65535 EPs 0 b 0 AWPS
00:18:32 RSN WME IEEE80211_MODE_11AC_VHT80 0

c2:d0:26:e6:e0:cf 24 153 845M 457M 23 0 0 device br0 entered promiscuous mode

device brwan entered promiscuous mode

recv: nf_ct_get failed

end action

current version: V1.0.0.392; new version: V1.0.0.392

=====
=====DNS_RESOLV

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

[wifi0] FWLOG: [30502489] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40006, 0x0, 0x2, 0x0)

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

Saving Data...

Done!

[wifi0] FWLOG: [30505485] WAL_DBGID_TX_BA_SETUP (0x44876c

recv: nf_ct_get failed

, 0x8ad40006, 0x117, 0x40, 0x1)

current version: V1.0.0.392; new version: V1.0.0.392

=====
=====DNS_RESOLV

end action

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

[wifi0] FWLOG: [30508664] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40003, 0x47, 0x40, 0x1)

[wifi0] FWLOG: [30510545] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40004, 0x2c6, 0x40, 0x1)

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

Switching to Tx Mode-1 Threshold 1000

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

[wifi0] FWLOG: [30515610] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40005, 0xbc4, 0x40, 0x1)

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

current version: V1.0.0.392; new version: V1.0.0.392

=====DNS_RESOLV=====

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

[wifi0] FWLOG: [30518610] WAL_DBGID_XCESS_FAILURES (0xffff, 0x1, 0x0)

[wifi0] FWLOG: [30520658] WAL_DBGID_XCESS_FAILURES (0xffff, 0x0, 0x0)

current version: V1.0.0.392; new version: V1.0.0.392

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

[wifi0] FWLOG: [30521658] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40003, 0x0, 0x2, 0x0)

[wifi0] FWLOG: [30521658] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40004, 0x0, 0x2, 0x0)

[wifi0] FWLOG: [30521658] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40005, 0x0, 0x2, 0x0)

[wifi0] FWLOG: [30521658] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40006, 0x0, 0x2, 0x0)

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

[wifi0] FWLOG: [30525959] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40006, 0x11a, 0x40, 0x1)

[LAN access from remote] from 89.248.174.3:36364 to 192.168.1.29:4500

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
current version: V1.0.0.392; new version: V1.0.0.392

=====
DNS_RESOLV

recv: nf_ct_get failed

[wifi0] FWLOG: [30531233] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40006, 0x0, 0x2, 0x0)

[wifi0] FWLOG: [30531948] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40005, 0xbcd, 0x40, 0x1)

[wifi0] FWLOG: [30536382] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40006, 0x11b, 0x40, 0x1)

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

current version: V1.0.0.392; new version: V1.0.0.392

=====
DNS_RESOLV

[wifi0] FWLOG: [30540828] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40005, 0x0, 0x2, 0x0)

usb 1-1: new high-speed USB device number 2 using xhci-hcd

usb 1-1: New USB device found, idVendor=0781, idProduct=5406

usb 1-1: New USB device strings: Mfr=1, Product=2, SerialNumber=3

usb 1-1: Product: U3 Cruzer Micro

usb 1-1: Manufacturer: SanDisk

usb 1-1: SerialNumber: 35120011D9424EC8

INFO008C: Add device intf d2618000, dev cff0d800

INFO0073: filter pure storage dev

scsi1 : usb-storage 1-1:1.0

scsi 1:0:0:0: Direct-Access SanDisk Cruzer 8.01 PQ: 0 ANSI: 0 CCS

sd 1:0:0:0: [sda] 15682559 512-byte logical blocks: (8.02 GB/7.47 GiB)

sd 1:0:0:0: [sda] Write Protect is off

sd 1:0:0:0: [sda] No Caching mode page found

sd 1:0:0:0: [sda] Assuming drive cache: write through

sd 1:0:0:0: [sda] No Caching mode page found

sd 1:0:0:0: [sda] Assuming drive cache: write through

sda: sda1

sd 1:0:0:0: [sda] No Caching mode page found

sd 1:0:0:0: [sda] Assuming drive cache: write through

sd 1:0:0:0: [sda] Attached SCSI removable disk

New USB disk mounted!!!

usb_port= usb1

usb_interface =dwc3.0

Saving Data...

Done!

Saving Data...

Done!

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 3, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

current version: V1.0.0.392; new version: V1.0.0.392

=====DNS_RESOLV

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

check minidlna ...

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 2

Switching to Tx Mode-1 Threshold 0

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 3, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

current version: V1.0.0.392; new version: V1.0.0.392

=====DNS_RESOLV

[wifi0] FWLOG: [30562522] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40004, 0x2cf, 0x40, 0x1)

current version: V1.0.0.392; new version: V1.0.0.392

start action

Saving Data...

Done!

current version: V1.0.0.392; new version: V1.0.0.392

current version: V1.0.0.392; new version: V1.0.0.392

current version: V1.0.0.392; new version: V1.0.0.392

current version: V1.0.0.392; new version: V1.0.0.392

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

Switching to Tx Mode-1 Threshold 1000

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

end action

current version: V1.0.0.392; new version: V1.0.0.392

start action

Saving Data...

Done!

current version: V1.0.0.392; new version: V1.0.0.392

current version: V1.0.0.392; new version: V1.0.0.392

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

current version: V1.0.0.392; new version: V1.0.0.392

current version: V1.0.0.392; new version: V1.0.0.392

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

end action

Switching to Tx Mode-1 Threshold 0

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

[wifi0] FWLOG: [30569566] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40004, 0x0, 0x2, 0x0)

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

Switching to Tx Mode-1 Threshold 1000

[wifi0] FWLOG: [30571033] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40005, 0xbd6, 0x40, 0x1)

Switching to Tx Mode-1 Threshold 0

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

current version: V1.0.0.392; new version: V1.0.0.392

=====DNS_RESOLV

recv: nf_ct_get failed

recv: nf_ct_get failed

recv: nf_ct_get failed

recv: nf_ct_get failed

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

recv: nf_ct_get failed

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

recv: nf_ct_get failed

recv: nf_ct_get failed

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

recv: nf_ct_get failed

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

recv: nf_ct_get failed

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

recv: nf_ct_get failed

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

recv: nf_ct_get failed

recv: nf_ct_get failed

[wifi0] FWLOG: [30579156] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40005, 0x0, 0x2, 0x0)

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
IPTV client : [701a8c0] join group [fb0000e0]
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
[wifi0] FWLOG: [30582195] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40004, 0x2ee, 0x40, 0x1)
[wifi0] FWLOG: [30582379] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40003, 0xbe, 0x40, 0x1)
recv: nf_ct_get failed
Switching to Tx Mode-1 Threshold 1000
recv: nf_ct_get failed
Switching to Tx Mode-1 Threshold 0
current version: V1.0.0.392; new version: V1.0.0.392
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
recv: nf_ct_get failed
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
[wifi0] FWLOG: [30582981] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40005, 0xbdf, 0x40, 0x1)
IPTV client : [701a8c0] join group [fb0000e0]
current version: V1.0.0.392; new version: V1.0.0.392
=====DNS_RESOLV=====

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
[wifi0] FWLOG: [30588740] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40003, 0x0, 0x2, 0x0)
[wifi0] FWLOG: [30588741] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40005, 0x0, 0x2, 0x0)
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Switching to Tx Mode-1 Threshold 1000
Switching to Tx Mode-1 Threshold 0
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
recv: nf_ct_get failed
[DoS Attack: SYN/ACK Scan] from source: 46.105.98.55, port 8004,
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
recv: nf_ct_get failed
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Switching to Tx Mode-1 Threshold 1000
recv: nf_ct_get failed
Switching to Tx Mode-1 Threshold 0
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
[wifi1] FWLOG: [80453810] WAL_DBGID_DEV_RESET (0xc01d, 0xdeaddead, 0x2)
[wifi1] FWLOG: [80453974] WAL_DBGID_XCESS_FAILURES (0xffff, 0x6, 0x0)
[wifi1] FWLOG: [80453974] WAL_DBGID_DEV_RX_TIMEOUT (0x1d1e, 0x4cba0b2, 0x4cb9d54, 0x3d04)
Switching to Tx Mode-1 Threshold 1000
current version: V1.0.0.392; new version: V1.0.0.392
=====DNS_RESOLV

Switching to Tx Mode-1 Threshold 0
current version: V1.0.0.392; new version: V1.0.0.392
start action
Saving Data...
Done!

current version: V1.0.0.392; new version: V1.0.0.392
current version: V1.0.0.392; new version: V1.0.0.392
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
current version: V1.0.0.392; new version: V1.0.0.392
current version: V1.0.0.392; new version: V1.0.0.392
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
end action
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Switching to Tx Mode-1 Threshold 1000
Switching to Tx Mode-1 Threshold 0
[wifi0] FWLOG: [30598312] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40004, 0x0, 0x2, 0x0)
[wifi0] FWLOG: [30598312] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40006, 0x0, 0x2, 0x0)
[wifi0] FWLOG: [30598578] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40006, 0x122, 0x40, 0x1)

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

Switching to Tx Mode-1 Threshold 1000

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

Switching to Tx Mode-1 Threshold 0

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

current version: V1.0.0.392; new version: V1.0.0.392

=====DNS_RESOLV=====

recv: nf_ct_get failed

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

recv: nf_ct_get failed

recv: nf_ct_get failed

Switching to Tx Mode-1 Threshold 1000

Switching to Tx Mode-1 Threshold 0

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

recv: nf_ct_get failed

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

[wifi0] FWLOG: [30607904] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40006, 0x0, 0x2, 0x0)

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

recv: nf_ct_get failed

recv: nf_ct_get failed

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

[wifi0] FWLOG: [30608987] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40006, 0x123, 0x40, 0x1)

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

recv: nf_ct_get failed

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

Switching to Tx Mode-1 Threshold 1000

recv: nf_ct_get failed

Switching to Tx Mode-1 Threshold 0

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

Switching to Tx Mode-1 Threshold 1000

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

Switching to Tx Mode-1 Threshold 0

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

recv: nf_ct_get failed

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

Switching to Tx Mode-1 Threshold 1000

Switching to Tx Mode-1 Threshold 0

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

current version: V1.0.0.392; new version: V1.0.0.392

=====DNS_RESOLV=====

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

Switching to Tx Mode-1 Threshold 1000

Switching to Tx Mode-1 Threshold 0

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

recv: nf_ct_get failed

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
current version: V1.0.0.392; new version: V1.0.0.392

=====DNS_RESOLV=====

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
[wifi0] FWLOG: [30634671] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40004, 0x311, 0x40, 0x1)

Switching to Tx Mode-1 Threshold 1000

Switching to Tx Mode-1 Threshold 0

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
current version: V1.0.0.392; new version: V1.0.0.392

=====
=====DNS_RESOLV

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Switching to Tx Mode-1 Threshold 1000

Switching to Tx Mode-1 Threshold 0

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
recv: nf_ct_get failed

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Saving Data...

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
Done!

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Switching to Tx Mode-1 Threshold 1000

Switching to Tx Mode-1 Threshold 0

[wifi0] FWLOG: [30641493] WAL_DBGID_XCESS_FAILURES (0xffff, 0x1, 0x0)

end action

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

[wifi1] FWLOG: [80458725] WAL_DBGID_DEV_RESET (0xc01d

recv: nf_ct_get failed

, 0xdeaddead, 0x2)

[wifi1] FWLOG: [80458889] WAL_DBGID_XCESS_FAILURES (0xffff, 0x6, 0x0)

[wifi1] FWLOG: [80458889] WAL_DBGID_DEV_RX_TIMEOUT (0x1d1e, 0x4cbb3e5, 0x4cbb01f, 0x3d05)

[wifi0] FWLOG: [30642517] WAL_DBGID_XCESS_FAILURES (0xffff, 0x0, 0x0)

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

Switching to Tx Mode-1 Threshold 1000

current version: V1.0.0.392; new version: V1.0.0.392

Switching to Tx Mode-1 Threshold 0

recv: nf_ct_get failed

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

[wifi0] FWLOG: [30646225] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40004, 0x0, 0x2, 0x0)

[wifi0] FWLOG: [30646225] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40006, 0x0, 0x2, 0x0)

recv: nf_ct_get failed

recv: nf_ct_get failed

recv: nf_ct_get failed

current version: V1.0.0.392; new version: V1.0.0.392

=====DNS_RESOLV====

recv: nf_ct_get failed

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

recv: nf_ct_get failed

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
[wifi0] FWLOG: [30650643] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40006, 0x12e, 0x40, 0x1)
[wifi0] FWLOG: [30650655] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40004, 0x31b, 0x40, 0x1)
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
recv: nf_ct_get failed
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Switching to Tx Mode-1 Threshold 1000
Switching to Tx Mode-1 Threshold 0
recv: nf_ct_get failed
recv: nf_ct_get failed
recv: nf_ct_get failed
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
recv: nf_ct_get failed
[wifi0] FWLOG: [30655819] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40004, 0x0, 0x2, 0x0)
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
current version: V1.0.0.392; new version: V1.0.0.392
=====
DNS_RESOLV
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
[wifi1] FWLOG: [80460773] WAL_DBGID_DEV_RESET (0xc01d, 0xdeaddead, 0x2)
[wifi1] FWLOG: [80460938] WAL_DBGID_XCESS_FAILURES (0xffff, 0x6, 0x0)
[wifi1] FWLOG: [80460938] WAL_DBGID_DEV_RX_TIMEOUT (0x1d1e, 0x4cbbbe5, 0x4cbb859, 0x3d06)
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
Switching to Tx Mode-1 Threshold 1000
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
Switching to Tx Mode-1 Threshold 0
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
recv: nf_ct_get failed
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Switching to Tx Mode-1 Threshold 1000
Switching to Tx Mode-1 Threshold 0

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
current version: V1.0.0.392; new version: V1.0.0.392

=====
=====DNS_RESOLV

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Switching to Tx Mode-1 Threshold 1000

Switching to Tx Mode-1 Threshold 0

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
recv: nf_ct_get failed

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
IPTV client : [d01a8c0] join group [fb0000e0]
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
recv: nf_ct_get failed
[wifi1] FWLOG: [80462207] WAL_DBGID_DEV_RESET (0xc01d, 0xdeadddead, 0x2)
[wifi1] FWLOG: [80462371] WAL_DBGID_XCESS_FAILURES (0xffff, 0x6, 0x0)
[wifi1] FWLOG: [80462371] WAL_DBGID_DEV_RX_TIMEOUT (0x1d1e, 0x4cbc17f, 0x4cbbde8, 0x3d07)
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
current version: V1.0.0.392; new version: V1.0.0.392
=====
DNS_RESOLV

IPTV client : [d01a8c0] join group [fb0000e0]
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Switching to Tx Mode-1 Threshold 1000
Switching to Tx Mode-1 Threshold 0
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Switching to Tx Mode-1 Threshold 1000
Switching to Tx Mode-1 Threshold 0
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
[wifi0] FWLOG: [30687595] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40004, 0x31c, 0x40, 0x1)
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
current version: V1.0.0.392; new version: V1.0.0.392
=====
DNS_RESOLV
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
[wifi0] FWLOG: [30694162] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40004, 0x0, 0x2, 0x0)
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
[wifi0] FWLOG: [30699095] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40004, 0x325, 0x40, 0x1)
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 2
Switching to Tx Mode-1 Threshold 1000
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Switching to Tx Mode-1 Threshold 0
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
recv: nf_ct_get failed
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
recv: nf_ct_get failed
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

recv: nf_ct_get failed

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

recv: nf_ct_get failed

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

Switching to Tx Mode-1 Threshold 1000

Switching to Tx Mode-1 Threshold 0

recv: nf_ct_get failed

current version: V1.0.0.392; new version: V1.0.0.392

=====DNS_RESOLV=====

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

recv: nf_ct_get failed

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

current version: V1.0.0.392; new version: V1.0.0.392

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

recv: nf_ct_get failed

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

Switching to Tx Mode-1 Threshold 1000

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

Switching to Tx Mode-1 Threshold 0

IPTV client : [d01a8c0] join group [fb0000e0]

[wifi0] FWLOG: [30713333] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40004, 0x0, 0x2, 0x0)

current version: V1.0.0.392; new version: V1.0.0.392

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

=====DNS_RESOLV====

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

[wifi0] FWLOG: [30714527] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40004, 0x326, 0x40, 0x1)

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

Switching to Tx Mode-1 Threshold 1000

Switching to Tx Mode-1 Threshold 0

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
recv: nf_ct_get failed
recv: nf_ct_get failed
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
IPTV client : [d01a8c0] join group [fb0000e0]
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
recv: nf_ct_get failed
Switching to Tx Mode-1 Threshold 1000
Switching to Tx Mode-1 Threshold 0
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Switching to Tx Mode-1 Threshold 1000
Switching to Tx Mode-1 Threshold 0
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
[wifi0] FWLOG: [30722913] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40004, 0x0, 0x2, 0x0)

[wifi0] FWLOG: [30722914] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40006, 0x0, 0x2, 0x0)

[wifi0] FWLOG: [30723179] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40006, 0x138, 0x40, 0x1)

Switching to Tx Mode-1 Threshold 1000

current version: V1.0.0.392; new version: V1.0.0.392

=====DNS_RESOLV

Switching to Tx Mode-1 Threshold 0

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

Switching to Tx Mode-1 Threshold 1000

Switching to Tx Mode-1 Threshold 0

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

[wifi0] FWLOG: [30727368] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40005, 0xbe0, 0x40, 0x1)

[wifi0] FWLOG: [30727442] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40004, 0x327, 0x40, 0x1)

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
[wifi1] FWLOG: [80467942] WAL_DBGID_DEV_RESET (0xc01d, 0xdeaddead, 0x2)
[wifi1] FWLOG: [80468106] WAL_DBGID_XCESS_FAILURES (0xffff, 0x6, 0x0)
[wifi1] FWLOG: [80468106] WAL_DBGID_DEV_RX_TIMEOUT (0x1d1e, 0x4cbd7e6, 0x4cbd2ff, 0x3d08)
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 3, off 2, len 2
[wifi0] FWLOG: [30731099] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40002, 0x10, 0x40, 0x1)
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 3, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
[wifi0] FWLOG: [30732521] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40005, 0x0, 0x2, 0x0)
[wifi0] FWLOG: [30732521] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40006, 0x0, 0x2, 0x0)
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Switching to Tx Mode-1 Threshold 1000
Switching to Tx Mode-1 Threshold 0
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
[wifi0] FWLOG: [30733619] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40006, 0x139, 0x40, 0x1)

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
recv: nf_ct_get failed

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
current version: V1.0.0.392; new version: V1.0.0.392

=====
DNS_RESOLV

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

Switching to Tx Mode-1 Threshold 1000

Switching to Tx Mode-1 Threshold 0

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

Switching to Tx Mode-1 Threshold 1000

Switching to Tx Mode-1 Threshold 0

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
usb 4-1: new SuperSpeed USB device number 2 using xhci-hcd

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
usb 4-1: New USB device found, idVendor=0411, idProduct=01f7
usb 4-1: New USB device strings: Mfr=1, Product=2, SerialNumber=3
usb 4-1: Product: HD-LXU3
usb 4-1: Manufacturer: BUFFALO
usb 4-1: SerialNumber: 0109B0009221
INFO008C: Add device intf d0050c00, dev d0229c00
INFO0C73: filter pure storage dev
scsi2 : usb-storage 4-1:1.0
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
scsi 2:0:0:0: Direct-Access BUFFALO HD-LXU3 0001 PQ: 0 ANSI: 6
sd 2:0:0:0: [sdb] 3906967728 512-byte logical blocks: (2.00 TB/1.81 TiB)
sd 2:0:0:0: [sdb] Write Protect is off
sd 2:0:0:0: [sdb] No Caching mode page found
sd 2:0:0:0: [sdb] Assuming drive cache: write through
sd 2:0:0:0: [sdb] No Caching mode page found
sd 2:0:0:0: [sdb] Assuming drive cache: write through
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
sdb: sdb1 sdb2
sd 2:0:0:0: [sdb] No Caching mode page found
sd 2:0:0:0: [sdb] Assuming drive cache: write through
sd 2:0:0:0: [sdb] Attached SCSI disk
New USB disk mounted!!!
usb_port= usb1
usb_interface =dwc3.0
usb_port= usb4
usb_interface =dwc3.1

[wifi0] FWLOG: [30742107] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40002, 0x0, 0x2, 0x0)

[wifi0] FWLOG: [30742107] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40004, 0x0, 0x2, 0x0)

Switching to Tx Mode-1 Threshold 1000

Switching to Tx Mode-1 Threshold 0

[wifi0] FWLOG: [30742823] WAL_DBGID_TX_BA_SETUP (vap-0:

[8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

0x44876c, 0x8ad40004, 0x340, 0x40, 0x1)

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

Switching to Tx Mode-1 Threshold 1000

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

Switching to Tx Mode-1 Threshold 0

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
current version: V1.0.0.392; new version: V1.0.0.392

=====DNS_RESOLV

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

Switching to Tx Mode-1 Threshold 1000

Switching to Tx Mode-1 Threshold 0

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

[wifi1] FWLOG: [80470195] WAL_DBGID_DEV_RESET (0xc01d, 0xdeaddad, 0x2)

[wifi1] FWLOG: [80470359] WAL_DBGID_XCESS_FAILURES (0xffff, 0x6, 0x0)

[wifi1] FWLOG: [80470359] WAL_DBGID_DEV_RX_TIMEOUT (0x1d1e, 0x4cbe0b3, 0x4cbdd41, 0x3d09)

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

IPTV client : [1801a8c0] join group [fb0000e0]

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
[wifi0] FWLOG: [30751685] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40004, 0x0, 0x2, 0x0)
[wifi0] FWLOG: [30751685] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40006, 0x0, 0x2, 0x0)
IPTV client : [1801a8c0] join group [fb0000e0]
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
[wifi0] FWLOG: [30754435] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40006, 0x13d, 0x40, 0x1)
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Switching to Tx Mode-1 Threshold 1000
Switching to Tx Mode-1 Threshold 0
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 2
Saving Data...
Done!

Saving Data...
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
Done!

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
current version: V1.0.0.392; new version: V1.0.0.392
=====DNS_RESOLV

Switching to Tx Mode-1 Threshold 1000

Switching to Tx Mode-1 Threshold 0

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

[wifi0] FWLOG: [30758041] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40004, 0x341, 0x40, 0x1)

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

IPTV client : [d01a8c0] join group [fb0000e0]

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

IPTV client : [d01a8c0] join group [fb0000e0]

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

Switching to Tx Mode-1 Threshold 1000

Switching to Tx Mode-1 Threshold 0

[wifi0] FWLOG: [30764377] WAL_DBGID_XCESS_FAILURES (0xffff, 0x1, 0x0)

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

check minidlna ...

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

[wifi0] FWLOG: [30765401] WAL_DBGID_XCESS_FAILURES (0xffff, 0x0, 0x0)

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

current version: V1.0.0.392; new version: V1.0.0.392

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
current version: V1.0.0.392; new version: V1.0.0.392

=====
=====DNS_RESOLV

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

recv: nf_ct_get failed

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

current version: V1.0.0.392; new version: V1.0.0.392

start action

Saving Data...

Done!

current version: V1.0.0.392; new version: V1.0.0.392

current version: V1.0.0.392; new version: V1.0.0.392

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 2

current version: V1.0.0.392; new version: V1.0.0.392

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

current version: V1.0.0.392; new version: V1.0.0.392

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

end action

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

[wifi0] FWLOG: [30770851] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40004, 0x0, 0x2, 0x0)

[wifi0] FWLOG: [30770851] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40006, 0x0, 0x2, 0x0)

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

Switching to Tx Mode-1 Threshold 1000

Switching to Tx Mode-1 Threshold 0

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

[wifi0] FWLOG: [30773478] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40004, 0x342, 0x40, 0x1)

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

[wifi0] FWLOG: [30775301] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40006, 0x140, 0x40, 0x1)

Switching to Tx Mode-1 Threshold 1000

Switching to Tx Mode-1 Threshold 0

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

current version: V1.0.0.392; new version: V1.0.0.392

=====DNS_RESOLV

current version: V1.0.0.392; new version: V1.0.0.392

current version: V1.0.0.392; new version: V1.0.0.392

current version: V1.0.0.392; new version: V1.0.0.392

current version: V1.0.0.392; new version: V1.0.0.392

current version: V1.0.0.392; new version: V1.0.0.392

current version: V1.0.0.392; new version: V1.0.0.392

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
current version: V1.0.0.392; new version: V1.0.0.392
current version: V1.0.0.392; new version: V1.0.0.392
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
current version: V1.0.0.392; new version: V1.0.0.392
current version: V1.0.0.392; new version: V1.0.0.392
current version: V1.0.0.392; new version: V1.0.0.392
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
[wifi0] FWLOG: [30780437] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40006, 0x0, 0x2, 0x0)
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
Switching to Tx Mode-1 Threshold 1000
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 2
Switching to Tx Mode-1 Threshold 0
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
current version: V1.0.0.392; new version: V1.0.0.392

current version: V1.0.0.392; new version: V1.0.0.392

current version: V1.0.0.392; new version: V1.0.0.392

current version: V1.0.0.392; new version: V1.0.0.392

current version: V1.0.0.392; new version: V1.0.0.392

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

current version: V1.0.0.392; new version: V1.0.0.392

current version: V1.0.0.392; new version: V1.0.0.392

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

current version: V1.0.0.392; new version: V1.0.0.392

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

current version: V1.0.0.392; new version: V1.0.0.392

current version: V1.0.0.392; new version: V1.0.0.392

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

Switching to Tx Mode-1 Threshold 1000

Switching to Tx Mode-1 Threshold 0

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

[wifi0] FWLOG: [30785598] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40006, 0x141, 0x40, 0x1)

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

Switching to Tx Mode-1 Threshold 1000

Switching to Tx Mode-1 Threshold 0

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

Switching to Tx Mode-1 Threshold 1000

Switching to Tx Mode-1 Threshold 0

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

Switching to Tx Mode-1 Threshold 1000

Switching to Tx Mode-1 Threshold 0

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

IPTV client : [401a8c0] join group [fb0000e0]

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

```

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
IPTV client : [ 401a8c0] join group [fb0000e0]
[wifi1] FWLOG: [80474496] WAL_DBGID_DEV_RESET ( 0xc01d, 0xdeaddad, 0x2 )
[wifi1] FWLOG: [80474660] WAL_DBGID_XCESS_FAILURES ( 0xffff, 0x6, 0x0 )
[wifi1] FWLOG: [80474660] WAL_DBGID_DEV_RX_TIMEOUT ( 0x1d1e, 0x4cbf180, 0x4cbee42, 0x3d0a )
[wifi0] FWLOG: [30799608] WAL_DBGID_TX_BA_SETUP ( 0x44876c, 0x8ad40004, 0x0, 0x2, 0x0 )
current version: V1.0.0.392; new version: V1.0.0.392
current version: V1.0.0.392; new version: V1.0.0.392
current version: V1.0.0.392; new version: V1.0.0.392
start action
current version: V1.0.0.392; new version: V1.0.0.392
current version: V1.0.0.392; new version: V1.0.0.392
current version: V1.0.0.392; new version: V1.0.0.392
current version: V1.0.0.392; new version: V1.0.0.392
Switching to Tx Mode-1 Threshold 1000
Switching to Tx Mode-1 Threshold 0
current version: V1.0.0.392; new version: V1.0.0.392
current version: V1.0.0.392; new version: V1.0.0.392
current version: V1.0.0.392; new version: V1.0.0.392
[wifi0] FWLOG: [30801328] WAL_DBGID_TX_BA_SETUP ( 0x44876c, 0x8ad40004, 0x345, 0x40, 0x1 )
ADDR          AID CHAN TXRATE RXRATE RSSI IDLE TXSEQ RXSEQ CAPS    ACAPS  ERP  STATE
MAXRATE(DOT11) HTCAPS ASSOCTIME  IEs  MODE PSMODE
78:11:dc:21:8a:32  1 153 118M  25M 19 4320  0 65535 EPs    0    b    0    WPS
00:31:04 RSN WME IEEE80211_MODE_11NA_HT40 0
78:11:dc:21:76:68  2 153 50M 10038M 11 4320  0 65535 EPs    0    b    0    WPS
00:31:04 RSN WME IEEE80211_MODE_11NA_HT40 0
74:d6:37:0b:21:7c  3 153 317M  84M 12 4320  0 65535 EP    0    b    0    AWPSM
00:31:04 RSN WME IEEE80211_MODE_11AC_VHT80 0

```

78:11:dc:21:75:a0	4	153	118M	25M	20	4320	0	65535	EPs	0	b	0	WPS
00:31:04 RSN WME IEEE80211_MODE_11NA_HT40 0													
78:11:dc:21:89:04	5	153	118M	10038M	23	4320	0	65535	EPs	0	b	0	WPS
00:31:04 RSN WME IEEE80211_MODE_11NA_HT40 0													
78:11:dc:20:e8:90	6	153	146M	10038M	24	4320	0	65535	EPs	0	b	0	WPS
00:31:04 RSN WME IEEE80211_MODE_11NA_HT40 0													
68:db:f5:67:0f:00	12	153	317M	114M	12	4320	0	65535	EP	0	b	0	AWPSM
00:31:03 RSN WME IEEE80211_MODE_11AC_VHT80 0													
78:11:dc:21:88:d6	11	153	146M	114M	44	4320	0	65535	EPs	0	b	0	WPS
00:31:03 RSN WME IEEE80211_MODE_11NA_HT40 0													
78:11:dc:21:8c:85	15	153	146M	10038M	20	4320	0	65535	EPs	0	b	0	WPS
00:31:03 RSN WME IEEE80211_MODE_11NA_HT40 0													
b6:1c:00:a6:4f:8c	18	153	845M	126M	33	0	0	65535	EP	0	b	0	AWPS
00:30:59 RSN WME IEEE80211_MODE_11AC_VHT80 1													
84:3a:4b:46:8a:d4	19	153	292M	23069M	27	0	0	65535	EPs	0	b	0	WPGSM
00:30:56 RSN WME IEEE80211_MODE_11NA_HT40 0													
c8:85:50:12:fa:f9	20	153	292M	14M	28	0	0	65535	EP	0	b	0	WPGS
00:30:42 RSN WME IEEE80211_MODE_11NA_HT40 1													
80:d6:05:84:67:e5	21	153	158M	94M	15	0	0	65535	EP	0	b	0	WPGS
00:30:42 RSN WME IEEE80211_MODE_11NA_HT40 1													
7c:d5:66:dd:4e:73	8	153	317M	84M	11	4320	0	65535	EP	0	b	0	AWPSM
00:26:45 RSN WME IEEE80211_MODE_11AC_VHT80 0													
f4:03:2a:ed:b2:e0	9	153	422M	422M	35	4320	0	65535	EP	0	b	0	AWPSM
00:26:45 RSN WME IEEE80211_MODE_11AC_VHT80 0													
08:12:a5:ee:65:19	10	153	422M	342M	27	4320	0	65535	EP	0	b	0	AWPSM
00:26:45 RSN WME IEEE80211_MODE_11AC_VHT80 0													
7c:d5:66:ee:63:c8	7	153	422M	380M	31	4320	0	65535	EP	0	b	0	AWPSM
00:25:19 RSN WME IEEE80211_MODE_11AC_VHT80 0													
68:db:f5:42:8e:45	14	153	422M	342M	25	4320	0	65535	EP	0	b	0	AWPSM
00:25:19 RSN WME IEEE80211_MODE_11AC_VHT80 0													
68:db:f5:d1:28:16	17	153	380M	256M	19	4320	0	65535	EP	0	b	0	AWPSM
00:25:11 RSN WME IEEE80211_MODE_11AC_VHT80 0													
84:10:0d:0d:ac:98	22	153	342M	342M	23	0	0	65535	EP	0	b	0	AWPS
00:25:05 RSN WME IEEE80211_MODE_11AC_VHT80 1													

40:b4:cd:45:f6:7e 13 153 761M 845M 40 4320 0 65535 EPs 0 b 0 AWPS
00:23:32 RSN WME IEEE80211_MODE_11AC_VHT80 0

50:dc:e7:a1:4f:18 16 153 457M 114M 11 4320 0 65535 EP 0 b 0 AWPS
00:22:34 RSN WME IEEE80211_MODE_11AC_VHT80 0

c2:d0:26:e6:e0:cf 24 153 845M 228M 24 0 0vap-0:
[8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

Switching to Tx Mode-1 Threshold 1000

Switching to Tx Mode-1 Threshold 0

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

check minidlna ...

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

[wifi1] FWLOG: [80475725] WAL_DBGID_DEV_RESET (0xc01d, 0xdeaddead, 0x2)

[wifi1] FWLOG: [80475889] WAL_DBGID_XCESS_FAILURES (0xffff, 0x6, 0x0)

[wifi1] FWLOG: [80475889] WAL_DBGID_DEV_RX_TIMEOUT (0x1d1e, 0x4cbf64d, 0x4cbf2a8, 0x3d0b)

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

current version: V1.0.0.392; new version: V1.0.0.392

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

[wifi0] FWLOG: [30809178] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40004, 0x0, 0x2, 0x0)

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

current version: V1.0.0.392; new version: V1.0.0.392

current version: V1.0.0.392; new version: V1.0.0.392

current version: V1.0.0.392; new version: V1.0.0.392

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

current version: V1.0.0.392; new version: V1.0.0.392

current version: V1.0.0.392; new version: V1.0.0.392

current version: V1.0.0.392; new version: V1.0.0.392

[wifi0] FWLOG: [30810613] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40004, 0x346, 0x40, 0x1)

current version: V1.0.0.392; new version: V1.0.0.392

current version: V1.0.0.392; new version: V1.0.0.392

current version: V1.0.0.392; new version: V1.0.0.392

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

Switching to Tx Mode-1 Threshold 1000

Switching to Tx Mode-1 Threshold 0

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

[Waring]: This HDD format failed to support the Time Machine!!!!!!

This HDD format can support the feature of Time Machine... ..

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 2

no process in pidfile '/var/run/forked-daapd.pid' found; none killed

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

current version: V1.0.0.392; new version: V1.0.0.392

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

current version: V1.0.0.392; new version: V1.0.0.392

current version: V1.0.0.392; new version: V1.0.0.392

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

current version: V1.0.0.392; new version: V1.0.0.392

Saving Data...

Done!

current version: V1.0.0.392; new version: V1.0.0.392

current version: V1.0.0.392; new version: V1.0.0.392

current version: V1.0.0.392; new version: V1.0.0.392

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
end action

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

[wifi1] FWLOG: [80477363] WAL_DBGID_DEV_RESET (0xc01d, 0xdeaddead, 0x2)

[wifi1] FWLOG: [80477527] WAL_DBGID_XCESS_FAILURES (0xffff, 0x6, 0x0)

[wifi1] FWLOG: [80477527] WAL_DBGID_DEV_RX_TIMEOUT (0x1d1e, 0x4cbfcb3, 0x4cbf8d7, 0x3d0c)

[wifi0] FWLOG: [30818762] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40004, 0x0, 0x2, 0x0)

Switching to Tx Mode-1 Threshold 1000

Switching to Tx Mode-1 Threshold 0

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

Switching to Tx Mode-1 Threshold 1000

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [fc:db:b3:db:8d:87]UAPSD bit settings from STA: 00vap-0: ieee80211_parse_htcap:SM powersave disabled

vap-0: ieee80211_parse_htcap:calculated updaterrates 0x1

vap-0: ieee80211_parse_htcap: ni_htcap 0x6f

vap-0: ieee80211_update_noderates: updating rates: smen 1 dyn 0 ratechg 0

[wifi0] FWLOG: [30823072] RATE: ChainMask 3, peer_mac 8d:87, phymode 10, ni_flags 0x06213006, vht_mcs_set 0xffffa, ht_mcs_set 0xfffff, legacy_rate_set 0x1d652da

[wifi0] FWLOG: [30823130] WAL_DBGID_SECURITY_UCAST_KEY_SET (0x8d87, 0x0)

[wifi0] FWLOG: [30823130] WAL_DBGID_SECURITY_ENCR_EN ()

[wifi0] FWLOG: [30823130] WAL_DBGID_SECURITY_ALLOW_DATA (0x448e6c)

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

[wifi0] FWLOG: [30823350] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40005, 0xbe2, 0x40, 0x1)

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

Switching to Tx Mode-1 Threshold 0

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 3, off 2, len 1

[wifi0] FWLOG: [30825181] WAL_DBGID_TX_BA_SETUP (0x448e6c, 0x8d870006, 0x2, 0x40, 0x1)

[wifi0] FWLOG: [30825183] RATE: ChainMask 3, peer_mac 8d:87, phymode 15, ni_flags 0x06213006, vht_mcs_set 0xffffa, ht_mcs_set 0xfffff, legacy_rate_set 0x8080801a

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

Switching to Tx Mode-1 Threshold 1000

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

[wifi0] FWLOG: [30826908] WAL_DBGID_TX_BA_SETUP (0x448e6c, 0x8d870000, 0x0, 0x40, 0x1)

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

[wifi0] FWLOG: [30827658] WAL_DBGID_TX_BA_SETUP (0x448e6c, 0x8d870005, 0x0, 0x40, 0x1)

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

current version: V1.0.0.392; new version: V1.0.0.392

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

recv: nf_ct_get failed

current version: V1.0.0.392; new version: V1.0.0.392

current version: V1.0.0.392; new version: V1.0.0.392

current version: V1.0.0.392; new version: V1.0.0.392

current version: V1.0.0.392; new version: V1.0.0.392

Switching to Tx Mode-1 Threshold 0

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

current version: V1.0.0.392; new version: V1.0.0.392

current version: V1.0.0.392; new version: V1.0.0.392

current version: V1.0.0.392; new version: V1.0.0.392

current version: V1.0.0.392; new version: V1.0.0.392

[wifi1] FWLOG: [80478592] WAL_DBGID_DEV_RESET (0xc01d, 0xdeaddead, 0x2)

[wifi1] FWLOG: [80478757] WAL_DBGID_XCESS_FAILURES (0xffff, 0x6, 0x0)

[wifi1] FWLOG: [80478757] WAL_DBGID_DEV_RX_TIMEOUT (0x1d1e, 0x4cc0180, 0x4cbfded, 0x3d0d)

[wifi0] FWLOG: [30837935] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40005, 0x0, 0x2, 0x0)

[wifi0] FWLOG: [30838283] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40004, 0x359, 0x40, 0x1)

/dev/sda1 on /tmp/mnt/sda1 type vfat

(rw,relatime,fmask=0000,dmask=0000,allow_utime=0022,codepage=cp437,iocharset=iso8859-1,shortname=mixed,usefree,utf8,errors=remount-ro)

/dev/sdb2 on /tmp/mnt/sdb2 type hfsplus (rw,nodev,noexec,noatime,umask=22,uid=0,gid=0,nls=utf8)

current version: V1.0.0.392; new version: V1.0.0.392

current version: V1.0.0.392; new version: V1.0.0.392

current version: V1.0.0.392; new version: V1.0.0.392

current version: V1.0.0.392; new version: V1.0.0.392

Switching to Tx Mode-1 Threshold 1000

current version: V1.0.0.392; new version: V1.0.0.392

current version: V1.0.0.392; new version: V1.0.0.392

current version: V1.0.0.392; new version: V1.0.0.392

current version: V1.0.0.392; new version: V1.0.0.392

current version: V1.0.0.392; new version: V1.0.0.392

Switching to Tx Mode-1 Threshold 0

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

current version: V1.0.0.392; new version: V1.0.0.392

start action

Saving Data...

Done!

current version: V1.0.0.392; new version: V1.0.0.392

current version: V1.0.0.392; new version: V1.0.0.392

current version: V1.0.0.392; new version: V1.0.0.392

current version: V1.0.0.392; new version: V1.0.0.392

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1

end action

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2

vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1


[wifi0] FWLOG: [30847511] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40004, 0x0, 0x2, 0x0)


[wifi0] FWLOG: [30847511] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40006, 0x0, 0x2, 0x0)


[wifi0] FWLOG: [30847523] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40006, 0x149, 0x40, 0x1)


vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1


vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
IPTV client : [1801a8c0] join group [fb0000e0]
IPTV client : [1801a8c0] join group [fb0000e0]
Switching to Tx Mode-1 Threshold 1000
[wifi0] FWLOG: [30853714] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40005, 0xbe4, 0x40, 0x1)
recv: nf_ct_get failed
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
Switching to Tx Mode-1 Threshold 0
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 3, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
Switching to Tx Mode-1 Threshold 1000
[wifi1] FWLOG: [80481460] WAL_DBGID_DEV_RESET (0xc01d, 0xdeaddead, 0x2)
[wifi1] FWLOG: [80481624] WAL_DBGID_XCESS_FAILURES (0xffff, 0x6, 0x0)
[wifi1] FWLOG: [80481624] WAL_DBGID_DEV_RX_TIMEOUT (0x1d1e, 0x4cc0cb3, 0x4cc08d5, 0x3d0e)
[wifi0] FWLOG: [30857100] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40006, 0x0, 0x2, 0x0)
[wifi0] FWLOG: [30857787] WAL_DBGID_TX_BA_SETUP (0x44876c, 0x8ad40006, 0x14a, 0x40, 0x1)
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 2, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 2
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 1, off 2, len 1
vap-0: [8c:3b:ad:bc:1c:3a]ieee80211_beacon_update: TIM updated, pending 0, off 0, len 1











Very faint, illegible text or noise, possibly a placeholder or a very low-quality scan. The content is not readable.

