

2018-05-21, 11:53:18.0	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;CM-MAC=08:02:8e:b6:6c:b0;CMTS-MAC=00:01:5c:86:b4:4e;CM-QOS=1.1;CM-VER=3.0;
2018-05-21, 11:53:12.0	Warning (5)	MDD message timeout;CM-MAC=08:02:8e:b6:6c:b0;CMTS-MAC=00:01:5c:86:b4:4e;CM-QOS=1.1;CM-VER=3.0;
2018-05-21, 11:53:11.0	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;CM-MAC=08:02:8e:b6:6c:b0;CMTS-MAC=00:01:5c:86:b4:4e;CM-QOS=1.1;CM-VER=3.0;
2018-05-21, 11:53:05.0	Warning (5)	MDD message timeout;CM-MAC=08:02:8e:b6:6c:b0;CMTS-MAC=00:01:5c:86:b4:4e;CM-QOS=1.1;CM-VER=3.0;
2018-05-21, 11:53:04.0	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;CM-MAC=08:02:8e:b6:6c:b0;CMTS-MAC=00:01:5c:86:b4:4e;CM-QOS=1.1;CM-VER=3.0;
2018-05-21, 11:51:46.0	Warning (5)	MDD message timeout;CM-MAC=08:02:8e:b6:6c:b0;CMTS-MAC=00:01:5c:86:b4:4e;CM-QOS=1.1;CM-VER=3.0;
2018-05-21, 11:51:46.0	Critical (3)	Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=08:02:8e:b6:6c:b0;CMTS-MAC=00:01:5c:86:b4:4e;CM-QOS=1.1;CM-VER=3.0;
2018-05-21, 11:42:43.0	Warning (5)	MDD message timeout;CM-MAC=08:02:8e:b6:6c:b0;CMTS-MAC=00:01:5c:86:b4:4e;CM-QOS=1.1;CM-VER=3.0;
2018-05-21, 11:42:43.0	Critical (3)	Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=08:02:8e:b6:6c:b0;CMTS-MAC=00:01:5c:86:b4:4e;CM-QOS=1.1;CM-VER=3.0;
2018-05-21, 11:34:32.0	Warning (5)	MDD message timeout;CM-MAC=08:02:8e:b6:6c:b0;CMTS-MAC=00:01:5c:86:b4:4e;CM-QOS=1.1;CM-VER=3.0;
2018-05-21, 11:34:32.0	Critical (3)	Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=08:02:8e:b6:6c:b0;CMTS-MAC=00:01:5c:86:b4:4e;CM-QOS=1.1;CM-VER=3.0;
2018-05-21, 11:07:27.0	Warning (5)	MDD message timeout;CM-MAC=08:02:8e:b6:6c:b0;CMTS-MAC=00:01:5c:86:b4:4e;CM-QOS=1.1;CM-VER=3.0;
2018-05-21, 11:07:27.0	Critical (3)	Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=08:02:8e:b6:6c:b0;CMTS-MAC=00:01:5c:86:b4:4e;CM-QOS=1.1;CM-VER=3.0;
2018-05-21, 10:40:21.0	Warning (5)	MDD message timeout;CM-MAC=08:02:8e:b6:6c:b0;CMTS-MAC=00:01:5c:86:b4:4e;CM-QOS=1.1;CM-VER=3.0;
2018-05-21, 10:40:21.0	Critical (3)	Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=08:02:8e:b6:6c:b0;CMTS-MAC=00:01:5c:86:b4:4e;CM-QOS=1.1;CM-VER=3.0;
2018-05-21, 09:56:34.0	Warning (5)	MDD message timeout;CM-MAC=08:02:8e:b6:6c:b0;CMTS-MAC=00:01:5c:86:b4:4e;CM-QOS=1.1;CM-VER=3.0;
2018-05-21, 09:56:34.0	Critical (3)	Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=08:02:8e:b6:6c:b0;CMTS-MAC=00:01:5c:86:b4:4e;CM-QOS=1.1;CM-VER=3.0;
2018-05-21, 09:54:45.0	Critical (3)	Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=08:02:8e:b6:6c:b0;CMTS-MAC=00:01:5c:86:b4:4e;CM-QOS=1.1;CM-VER=3.0;
2018-05-21, 09:54:44.0	Warning (5)	MDD message timeout;CM-MAC=08:02:8e:b6:6c:b0;CMTS-MAC=00:01:5c:86:b4:4e;CM-QOS=1.1;CM-VER=3.0;
2018-05-21, 09:42:05.0	Warning (5)	MDD message timeout;CM-MAC=08:02:8e:b6:6c:b0;CMTS-MAC=00:01:5c:86:b4:4e;CM-QOS=1.1;CM-VER=3.0;
2018-05-21, 09:42:05.0	Critical (3)	Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=08:02:8e:b6:6c:b0;CMTS-MAC=00:01:5c:86:b4:4e;CM-QOS=1.1;CM-VER=3.0;
2018-05-21, 09:27:29.0	Warning (5)	MDD message timeout;CM-MAC=08:02:8e:b6:6c:b0;CMTS-MAC=00:01:5c:86:b4:4e;CM-QOS=1.1;CM-VER=3.0;
2018-05-21, 09:27:29.0	Critical (3)	Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=08:02:8e:b6:6c:b0;CMTS-MAC=00:01:5c:86:b4:4e;CM-QOS=1.1;CM-VER=3.0;
2018-05-21, 09:16:10.0	Warning (5)	MDD message timeout;CM-MAC=08:02:8e:b6:6c:b0;CMTS-MAC=00:01:5c:86:b4:4e;CM-QOS=1.1;CM-VER=3.0;
2018-05-21, 09:16:10.0	Critical (3)	Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=08:02:8e:b6:6c:b0;CMTS-MAC=00:01:5c:86:b4:4e;CM-QOS=1.1;CM-VER=3.0;
2018-05-21, 09:03:09.0	Warning (5)	MDD message timeout;CM-MAC=08:02:8e:b6:6c:b0;CMTS-MAC=00:01:5c:86:b4:4e;CM-QOS=1.1;CM-VER=3.0;
2018-05-21, 09:03:09.0	Critical (3)	Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=08:02:8e:b6:6c:b0;CMTS-MAC=00:01:5c:86:b4:4e;CM-QOS=1.1;CM-VER=3.0;
2018-05-21, 08:11:31.0	Warning (5)	MDD message timeout;CM-MAC=08:02:8e:b6:6c:b0;CMTS-MAC=00:01:5c:86:b4:4e;CM-QOS=1.1;CM-VER=3.0;
2018-05-21, 08:11:31.0	Critical (3)	Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=08:02:8e:b6:6c:b0;CMTS-MAC=00:01:5c:86:b4:4e;CM-QOS=1.1;CM-VER=3.0;
2018-05-21, 07:51:21.0	Warning (5)	MDD message timeout;CM-MAC=08:02:8e:b6:6c:b0;CMTS-MAC=00:01:5c:86:b4:4e;CM-QOS=1.1;CM-VER=3.0;
2018-05-21, 07:51:21.0	Critical (3)	Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=08:02:8e:b6:6c:b0;CMTS-MAC=00:01:5c:86:b4:4e;CM-QOS=1.1;CM-VER=3.0;
2018-05-21, 07:22:01.0	Warning (5)	MDD message timeout;CM-MAC=08:02:8e:b6:6c:b0;CMTS-MAC=00:01:5c:86:b4:4e;CM-QOS=1.1;CM-VER=3.0;
2018-05-21, 07:22:01.0	Critical (3)	Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=08:02:8e:b6:6c:b0;CMTS-MAC=00:01:5c:86:b4:4e;CM-QOS=1.1;CM-VER=3.0;
2018-05-21, 06:42:56.0	Critical (3)	Resetting the cable modem due to docsDevResetNow
2018-05-21, 06:34:11.0	Warning (5)	MDD message timeout;CM-MAC=08:02:8e:b6:6c:b0;CMTS-MAC=00:01:5c:86:b4:4e;CM-QOS=1.1;CM-VER=3.0;
2018-05-21, 06:34:11.0	Critical (3)	Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=08:02:8e:b6:6c:b0;CMTS-MAC=00:01:5c:86:b4:4e;CM-QOS=1.1;CM-VER=3.0;
2018-05-21, 06:14:23.0	Critical (3)	Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=08:02:8e:b6:6c:b0;CMTS-MAC=00:01:5c:86:b4:4e;CM-QOS=1.1;CM-VER=3.0;
Time Not Established	Notice (6)	Honoring MDD; IP provisioning mode = IPv6
Time Not Established	Notice (6)	WiFi Interface [w0] set to Channel 11 (Side-Band Channel:N/A) - Reason:INIT
Time Not Established	Notice (6)	WiFi Interface [w1] set to Channel 157 (Side-Band Channel:N/A) - Reason:INIT