

Time	Priority	Description
Thu Jun 10 08:07:29 2021	Critical (3)	Received Response to Broadcast Maintenance Request, But no Unicast Maintenance opportunities received - T4 time out;CM-MAC=08:36:c9:3f:b1:18;CMTS-MAC=00:17:10:89:85:1a;CM-QOS=1.1;CM-VER=3.1;
Thu Jun 10 06:07:56 2021	Notice (6)	DHCP Renew - lease parameters Time Protocol Servers modified;CM-MAC=08:36:c9:3f:b1:18;CMTS-MAC=00:17:10:89:85:1a;CM-QOS=1.1;CM-VER=3.1;
Thu Jun 10 06:07:56 2021	Error (4)	DHCP RENEW WARNING - Field invalid in response v4 option;CM-MAC=08:36:c9:3f:b1:18;CMTS-MAC=00:17:10:89:85:1a;CM-QOS=1.1;CM-VER=3.1;
Thu Jun 10 06:07:42 2021	Critical (3)	Received Response to Broadcast Maintenance Request, But no Unicast Maintenance opportunities received - T4 time out;CM-MAC=08:36:c9:3f:b1:18;CMTS-MAC=00:17:10:89:85:1a;CM-QOS=1.1;CM-VER=3.1;
Thu Jun 10 01:25:21 2021	Error (4)	DHCP RENEW WARNING - Field invalid in response v4 option;CM-MAC=08:36:c9:3f:b1:18;CMTS-MAC=00:17:10:89:85:1a;CM-QOS=1.1;CM-VER=3.1;
Thu Jun 10 01:25:19 2021	Critical (3)	Received Response to Broadcast Maintenance Request, But no Unicast Maintenance opportunities received - T4 time out;CM-MAC=08:36:c9:3f:b1:18;CMTS-MAC=00:17:10:89:85:1a;CM-QOS=1.1;CM-VER=3.1;
Wed Jun 09 21:03:05 2021	Notice (6)	DHCP Renew - lease parameters Time Protocol Servers modified;CM-MAC=08:36:c9:3f:b1:18;CMTS-MAC=00:17:10:89:85:1a;CM-QOS=1.1;CM-VER=3.1;
Wed Jun 09 21:03:05 2021	Error (4)	DHCP RENEW WARNING - Field invalid in response v4 option;CM-MAC=08:36:c9:3f:b1:18;CMTS-MAC=00:17:10:89:85:1a;CM-QOS=1.1;CM-VER=3.1;
Wed Jun 09 21:02:38 2021	Critical (3)	Received Response to Broadcast Maintenance Request, But no Unicast Maintenance opportunities received - T4 time out;CM-MAC=08:36:c9:3f:b1:18;CMTS-MAC=00:17:10:89:85:1a;CM-QOS=1.1;CM-VER=3.1;
Wed Jun 09 17:02:41 2021	Notice (6)	CM-STATUS message sent. Event Type Code: 7; Chan ID: 10; DSID: N/A; MAC Addr: N/A; OFDM/OFDMA Profile ID: N/A.;CM-MAC=08:36:c9:3f:b1:18;CMTS-MAC=00:17:10:89:85:1a;CM-QOS=1.1;CM-VER=3.1;
Wed Jun 09 17:02:12 2021	Notice (6)	CM-STATUS message sent. Event Type Code: 6; Chan ID: 10; DSID: N/A; MAC Addr: N/A; OFDM/OFDMA Profile ID: N/A.;CM-MAC=08:36:c9:3f:b1:18;CMTS-MAC=00:17:10:89:85:1a;CM-QOS=1.1;CM-VER=3.1;
Wed Jun 09 17:02:12 2021	Critical (3)	Received Response to Broadcast Maintenance Request, But no Unicast Maintenance opportunities received - T4 time out;CM-MAC=08:36:c9:3f:b1:18;CMTS-MAC=00:17:10:89:85:1a;CM-QOS=1.1;CM-VER=3.1;
Wed Jun 09 16:59:42 2021	Critical (3)	Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=08:36:c9:3f:b1:18;CMTS-MAC=00:17:10:89:85:1a;CM-QOS=1.1;CM-VER=3.1;
Wed Jun 09 16:59:31 2021	Critical (3)	16 consecutive T3 timeouts while trying to range on upstream channel 8;CM-MAC=08:36:c9:3f:b1:18;CMTS-MAC=00:17:10:89:85:1a;CM-QOS=1.1;CM-VER=3.1;
Wed Jun 09 16:59:31 2021	Critical (3)	Unicast Maintenance Ranging attempted - No response - Retries exhausted;CM-MAC=08:36:c9:3f:b1:18;CMTS-MAC=00:17:10:89:85:1a;CM-QOS=1.1;CM-VER=3.1;
Wed Jun 09 16:59:31 2021	Critical (3)	Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=08:36:c9:3f:b1:18;CMTS-MAC=00:17:10:89:85:1a;CM-QOS=1.1;CM-VER=3.1;
Wed Jun 09 16:59:13 2021	Critical (3)	16 consecutive T3 timeouts while trying to range on upstream channel 8;CM-MAC=08:36:c9:3f:b1:18;CMTS-MAC=00:17:10:89:85:1a;CM-QOS=1.1;CM-VER=3.1;
Wed Jun 09 16:59:13 2021	Critical (3)	Unicast Maintenance Ranging attempted - No response - Retries exhausted;CM-MAC=08:36:c9:3f:b1:18;CMTS-MAC=00:17:10:89:85:1a;CM-QOS=1.1;CM-VER=3.1;
Wed Jun 09 16:59:13 2021	Critical (3)	Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=08:36:c9:3f:b1:18;CMTS-MAC=00:17:10:89:85:1a;CM-QOS=1.1;CM-VER=3.1;

Wed Jun 09 16:58:55 2021	Critical (3)	Unicast Maintenance Ranging attempted - No response - Retries exhausted;CM-MAC=08:36:c9:3f:b1:18;CMTS-MAC=00:17:10:89:85:1a;CM-QOS=1.1;CM-VER=3.1;
Wed Jun 09 16:58:55 2021	Critical (3)	Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=08:36:c9:3f:b1:18;CMTS-MAC=00:17:10:89:85:1a;CM-QOS=1.1;CM-VER=3.1;
Wed Jun 09 16:58:51 2021	Warning (5)	Dynamic Range Window violation
Wed Jun 09 16:58:51 2021	Warning (5)	RNG-RSP CCAP Commanded Power in Excess of 6 dB Below the Value Corresponding to the Top of the DRW;CM-MAC=08:36:c9:3f:b1:18;CMTS-MAC=00:17:10:89:85:1a;CM-QOS=1.1;CM-VER=3.1;
Wed Jun 09 16:58:51 2021	Warning (5)	Dynamic Range Window violation
Wed Jun 09 16:58:51 2021	Warning (5)	RNG-RSP CCAP Commanded Power in Excess of 6 dB Below the Value Corresponding to the Top of the DRW;CM-MAC=08:36:c9:3f:b1:18;CMTS-MAC=00:17:10:89:85:1a;CM-QOS=1.1;CM-VER=3.1;
Wed Jun 09 16:58:51 2021	Critical (3)	Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=08:36:c9:3f:b1:18;CMTS-MAC=00:17:10:89:85:1a;CM-QOS=1.1;CM-VER=3.1;
Wed Jun 09 16:58:46 2021	Warning (5)	Dynamic Range Window violation
Wed Jun 09 16:58:46 2021	Warning (5)	RNG-RSP CCAP Commanded Power in Excess of 6 dB Below the Value Corresponding to the Top of the DRW;CM-MAC=08:36:c9:3f:b1:18;CMTS-MAC=00:17:10:89:85:1a;CM-QOS=1.1;CM-VER=3.1;
Wed Jun 09 16:58:46 2021	Critical (3)	Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=08:36:c9:3f:b1:18;CMTS-MAC=00:17:10:89:85:1a;CM-QOS=1.1;CM-VER=3.1;
Wed Jun 09 16:58:41 2021	Warning (5)	Dynamic Range Window violation
Wed Jun 09 16:58:41 2021	Warning (5)	RNG-RSP CCAP Commanded Power in Excess of 6 dB Below the Value Corresponding to the Top of the DRW;CM-MAC=08:36:c9:3f:b1:18;CMTS-MAC=00:17:10:89:85:1a;CM-QOS=1.1;CM-VER=3.1;
Wed Jun 09 16:58:41 2021	Warning (5)	Dynamic Range Window violation
Wed Jun 09 16:58:41 2021	Warning (5)	RNG-RSP CCAP Commanded Power in Excess of 6 dB Below the Value Corresponding to the Top of the DRW;CM-MAC=08:36:c9:3f:b1:18;CMTS-MAC=00:17:10:89:85:1a;CM-QOS=1.1;CM-VER=3.1;
Wed Jun 09 16:58:41 2021	Critical (3)	Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=08:36:c9:3f:b1:18;CMTS-MAC=00:17:10:89:85:1a;CM-QOS=1.1;CM-VER=3.1;
Wed Jun 09 16:58:36 2021	Warning (5)	DBC-REQ Mismatch Between Calculated Value for P1.6hi Compared to CCAP Provided Value;CM-MAC=08:36:c9:3f:b1:18;CMTS-MAC=00:17:10:89:85:1a;CM-QOS=1.1;CM-VER=3.1;
Wed Jun 09 16:57:49 2021	Critical (3)	Received Response to Broadcast Maintenance Request, But no Unicast Maintenance opportunities received - T4 time out;CM-MAC=08:36:c9:3f:b1:18;CMTS-MAC=00:17:10:89:85:1a;CM-QOS=1.1;CM-VER=3.1;
Wed Jun 09 16:52:53 2021	Notice (6)	CM-STATUS message sent. Event Type Code: 6; Chan ID: 10; DSID: N/A; MAC Addr: N/A; OFDM/OFDMA Profile ID: N/A.;CM-MAC=08:36:c9:3f:b1:18;CMTS-MAC=00:17:10:89:85:1a;CM-QOS=1.1;CM-VER=3.1;
Wed Jun 09 16:52:47 2021	Critical (3)	Received Response to Broadcast Maintenance Request, But no Unicast Maintenance opportunities received - T4 time out;CM-MAC=08:36:c9:3f:b1:18;CMTS-MAC=00:17:10:89:85:1a;CM-QOS=1.1;CM-VER=3.1;
Wed Jun 09 16:50:56 2021	Notice (6)	CM-STATUS message sent. Event Type Code: 7; Chan ID: 10; DSID: N/A; MAC Addr: N/A; OFDM/OFDMA Profile ID: N/A.;CM-MAC=08:36:c9:3f:b1:18;CMTS-MAC=00:17:10:89:85:1a;CM-QOS=1.1;CM-VER=3.1;
Wed Jun 09 16:50:46 2021	Critical (3)	Received Response to Broadcast Maintenance Request, But no Unicast Maintenance opportunities received - T4 time out;CM-MAC=08:36:c9:3f:b1:18;CMTS-MAC=00:17:10:89:85:1a;CM-QOS=1.1;CM-VER=3.1;