

| Time | Priority | Description |
|----------------------|--------------|---|
| 2023-02-24, 16:03:32 | Critical (3) | Started Unicast Maintenance Ranging - No Response received - T3 time-out;----;CM-QOS=1.1;CM-VER=3.1; |
| 2023-02-13, 05:18:43 | Critical (3) | UCD invalid or channel unusable;----;CM-QOS=1.1;CM-VER=3.1; |
| 2023-02-13, 05:18:43 | Notice (6) | DS profile assignment change. DS Chan ID: 32; Previous Profile: ; New Profile: 1 2 3.;----;CM-QOS=1.1;CM-VER=3.1; |
| 2023-02-13, 05:18:33 | Notice (6) | Honoring MDD; IP provisioning mode = IPv6 |
| 2023-02-13, 05:18:30 | Critical (3) | UCD invalid or channel unusable;----;CM-QOS=1.1;CM-VER=3.1; |
| 2023-02-13, 05:18:15 | Notice (6) | Honoring MDD; IP provisioning mode = IPv6 |
| 2023-02-13, 05:17:34 | Critical (3) | SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;;CM-QOS=1.1;CM-VER=3.1; |
| 2023-02-13, 05:17:33 | Warning (5) | Lost MDD Timeout;;CM-QOS=1.1;CM-VER=3.1; |
| 2023-02-13, 05:16:44 | Critical (3) | SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;;CM-QOS=1.1;CM-VER=3.1; |
| 2023-02-13, 05:16:43 | Warning (5) | Lost MDD Timeout;;CM-QOS=1.1;CM-VER=3.1; |
| 2023-02-13, 05:16:34 | Critical (3) | SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;;CM-QOS=1.1;CM-VER=3.1; |
| 2023-02-13, 05:16:33 | Warning (5) | Lost MDD Timeout;;;CM-QOS=1.1;CM-VER=3.1; |
| 2023-02-13, 05:16:25 | Critical (3) | SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;;CM-QOS=1.1;CM-VER=3.1; |
| 2023-02-13, 05:16:23 | Warning (5) | Lost MDD Timeout;;CM-QOS=1.1;CM-VER=3.1; |
| 2023-02-13, 05:16:14 | Critical (3) | SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;;CM-QOS=1.1;CM-VER=3.1; |
| 2023-02-13, 05:16:13 | Warning (5) | Lost MDD Timeout;;CM-QOS=1.1;CM-VER=3.1; |
| 2023-02-13, 05:16:04 | Critical (3) | SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;;CM-QOS=1.1;CM-VER=3.1; |
| 2023-02-13, 05:16:03 | Warning (5) | Lost MDD Timeout;;CM-QOS=1.1;CM-VER=3.1; |
| 2023-02-13, 05:15:54 | Critical (3) | SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;;CM-QOS=1.1;CM-VER=3.1; |
| 2023-02-13, 05:15:53 | Warning (5) | Lost MDD Timeout;;CM-QOS=1.1;CM-VER=3.1; |
| 2023-02-13, 05:15:44 | Critical (3) | SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;;CM-QOS=1.1;CM-VER=3.1; |
| 2023-02-13, 05:15:43 | Warning (5) | Lost MDD Timeout;CM-QOS=1.1;CM-VER=3.1; |
| 2023-02-13, 05:15:34 | Critical (3) | SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;;CM-QOS=1.1;CM-VER=3.1; |
| 2023-02-13, 05:15:33 | Warning (5) | Lost MDD Timeout;;CM-QOS=1.1;CM-VER=3.1; |
| 2023-02-13, 05:14:51 | Critical (3) | SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;;CM-QOS=1.1;CM-VER=3.1; |
| 2023-02-13, 05:14:37 | Warning (5) | Lost MDD Timeout;;CM-QOS=1.1;CM-VER=3.1; |
| 2023-02-13, 05:14:18 | Critical (3) | SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;;CM-QOS=1.1;CM-VER=3.1; |
| 2023-02-13, 05:14:15 | Warning (5) | Lost MDD Timeout;;CM-QOS=1.1;CM-VER=3.1; |
| 2023-02-13, 05:13:51 | Critical (3) | SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;;CM-QOS=1.1;CM-VER=3.1; |
| 2023-02-13, 05:13:38 | Critical (3) | Received Response to Broadcast Maintenance Request, But no Unicast Maintenance opportunities received - T4 time out;----;CM-QOS=1.1;CM-VER=3.1; |
| 2023-02-13, 05:12:38 | Critical (3) | Started Unicast Maintenance Ranging - No Response received - T3 time-out;----;CM-QOS=1.1;CM-VER=3.1; |
| 2023-02-13, 05:12:30 | Warning (5) | Lost MDD Timeout;;CM-QOS=1.1;CM-VER=3.1; |
| 2023-02-13, 05:12:18 | Critical (3) | Received Response to Broadcast Maintenance Request, But no Unicast Maintenance opportunities received - T4 time out;----;CM-QOS=1.1;CM-VER=3.1; |
| 2023-02-13, 05:11:18 | Critical (3) | Started Unicast Maintenance Ranging - No Response received - T3 time-out;----;CM-QOS=1.1;CM-VER=3.1; |

| | | |
|----------------------|--------------|--|
| 2023-02-13, 05:11:06 | Critical (3) | SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;;CM-QOS=1.1;CM-VER=3.1; |
| 2023-02-13, 05:11:04 | Warning (5) | Lost MDD Timeout;;CM-QOS=1.1;CM-VER=3.1; |
| 2023-02-13, 05:10:56 | Critical (3) | SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;;CM-QOS=1.1;CM-VER=3.1; |
| 2023-02-13, 05:10:54 | Warning (5) | Lost MDD Timeout;;CM-QOS=1.1;CM-VER=3.1; |
| 2023-02-13, 05:10:46 | Critical (3) | SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;;CM-QOS=1.1;CM-VER=3.1; |
| 2023-02-13, 05:10:44 | Warning (5) | Lost MDD Timeout;;CM-QOS=1.1;CM-VER=3.1; |