

2020-06-22, 08:13:41	Notice (6)	DS profile assignment change. DS Chan ID: 32; Previous Profile: ; New Profile: 3.;CM-MAC=14:59:c0:f6:f2:10;CMTS-MAC=00:a3:d1:5d:a0:e9;CM-QOS=1.1;CM-VER=3.1;
2020-06-22, 08:13:36	Notice (6)	TLV-11 - unrecognized OID;CM-MAC=14:59:c0:f6:f2:10;CMTS-MAC=00:a3:d1:5d:a0:e9;CM-QOS=1.1;CM-VER=3.1;
2020-06-22, 08:13:36	Warning (5)	DHCP WARNING - Non-critical field invalid in response ;CM-MAC=14:59:c0:f6:f2:10;CMTS-MAC=00:a3:d1:5d:a0:e9;CM-QOS=1.1;CM-VER=3.1;
Time Not Established	Notice (6)	Honoring MDD; IP provisioning mode = IPv4
Time Not Established	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;CM-MAC=14:59:c0:f6:f2:10;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.1;CM-VER=3.1;
2020-06-22, 08:11:02	Critical (3)	Resetting the cable modem due to docsDevResetNow
Time Not Established	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;CM-MAC=14:59:c0:f6:f2:10;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.1;CM-VER=3.1;
2020-06-21, 16:00:05	Critical (3)	No Ranging Response received - T3 time-out;CM-MAC=14:59:c0:f6:f2:10;CMTS-MAC=00:a3:d1:5d:a0:e9;CM-QOS=1.1;CM-VER=3.1;
2020-06-21, 15:59:54	Critical (3)	Received Response to Broadcast Maintenance Request, But no Unicast Maintenance opportunities received - T4 time out;CM-MAC=14:59:c0:f6:f2:10;CMTS-MAC=00:a3:d1:5d:a0:e9;CM-QOS=1.1;CM-VER=3.1;
2020-06-21, 15:59:09	Critical (3)	Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=14:59:c0:f6:f2:10;CMTS-MAC=00:a3:d1:5d:a0:e9;CM-QOS=1.1;CM-VER=3.1;
Time Not Established	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;CM-MAC=14:59:c0:f6:f2:10;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.1;CM-VER=3.1;
Time Not Established	Critical (3)	Unicast Ranging Received Abort Response - Re-initializing MAC;CM-MAC=14:59:c0:f6:f2:10;CMTS-MAC=00:a3:d1:5d:a0:e9;CM-QOS=1.1;CM-VER=3.1;
Time Not Established	Critical (3)	Unicast Ranging Received Abort Response - Re-initializing MAC;CM-MAC=14:59:c0:f6:f2:10;CMTS-MAC=00:a3:d1:5d:a0:e9;CM-QOS=1.1;CM-VER=3.1;
Time Not Established	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;CM-MAC=14:59:c0:f6:f2:10;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.1;CM-VER=3.1;
2020-06-21, 15:24:05	Critical (3)	Unicast Ranging Received Abort Response - Re-initializing MAC;CM-MAC=14:59:c0:f6:f2:10;CMTS-MAC=00:a3:d1:5d:a0:e9;CM-QOS=1.1;CM-VER=3.1;
2020-06-21, 09:24:51	Critical (3)	Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=14:59:c0:f6:f2:10;CMTS-MAC=00:a3:d1:5d:a0:e9;CM-QOS=1.1;CM-VER=3.1;
2020-06-21, 02:10:53	Critical (3)	Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=14:59:c0:f6:f2:10;CMTS-MAC=00:a3:d1:5d:a0:e9;CM-QOS=1.1;CM-VER=3.1;
2020-06-21, 02:08:39	Critical (3)	Unicast Ranging Received Abort Response - Re-initializing MAC;CM-MAC=14:59:c0:f6:f2:10;CMTS-MAC=00:a3:d1:5d:a0:e9;CM-QOS=1.1;CM-VER=3.1;
2020-06-21, 02:07:57	Critical (3)	Unicast Ranging Received Abort Response - Re-initializing MAC;CM-MAC=14:59:c0:f6:f2:10;CMTS-MAC=00:a3:d1:5d:a0:e9;CM-QOS=1.1;CM-VER=3.1;
2020-06-21, 02:07:16	Critical (3)	Unicast Ranging Received Abort Response - Re-initializing MAC;CM-MAC=14:59:c0:f6:f2:10;CMTS-MAC=00:a3:d1:5d:a0:e9;CM-QOS=1.1;CM-VER=3.1;
2020-06-21, 02:05:18	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;CM-MAC=14:59:c0:f6:f2:10;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.1;CM-VER=3.1;
2020-06-21, 02:00:25	Critical (3)	Unicast Ranging Received Abort Response - Re-initializing MAC;CM-MAC=14:59:c0:f6:f2:10;CMTS-MAC=00:a3:d1:5d:a0:e9;CM-QOS=1.1;CM-VER=3.1;
2020-06-21, 01:59:17	Critical (3)	Unicast Ranging Received Abort Response - Re-initializing MAC;CM-MAC=14:59:c0:f6:f2:10;CMTS-MAC=00:a3:d1:5d:a0:e9;CM-QOS=1.1;CM-VER=3.1;
2020-06-21, 01:57:35	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;CM-MAC=14:59:c0:f6:f2:10;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.1;CM-VER=3.1;
2020-06-21, 01:55:41	Critical (3)	Unicast Ranging Received Abort Response - Re-initializing MAC;CM-MAC=14:59:c0:f6:f2:10;CMTS-MAC=00:a3:d1:5d:a0:e9;CM-QOS=1.1;CM-VER=3.1;
2020-06-21, 01:54:34	Critical (3)	Unicast Ranging Received Abort Response - Re-initializing MAC;CM-MAC=14:59:c0:f6:f2:10;CMTS-MAC=00:a3:d1:5d:a0:e9;CM-QOS=1.1;CM-VER=3.1;
2020-06-21, 01:54:12	Critical (3)	REG RSP not received;CM-MAC=14:59:c0:f6:f2:10;CMTS-MAC=00:a3:d1:5d:a0:e9;CM-QOS=1.1;CM-VER=3.1;
2020-06-21, 01:51:16	Critical (3)	Unicast Ranging Received Abort Response - Re-initializing MAC;CM-MAC=14:59:c0:f6:f2:10;CMTS-MAC=00:a3:d1:5d:a0:e9;CM-QOS=1.1;CM-VER=3.1;
2020-06-21, 01:49:33	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;CM-MAC=14:59:c0:f6:f2:10;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.1;CM-VER=3.1;
2020-06-21, 01:47:37	Critical (3)	Unicast Ranging Received Abort Response - Re-initializing MAC;CM-MAC=14:59:c0:f6:f2:10;CMTS-MAC=00:a3:d1:5d:a0:e9;CM-QOS=1.1;CM-VER=3.1;
2020-06-21, 01:44:46	Critical (3)	Unicast Ranging Received Abort Response - Re-initializing MAC;CM-MAC=14:59:c0:f6:f2:10;CMTS-MAC=00:a3:d1:5d:a0:e9;CM-QOS=1.1;CM-VER=3.1;
2020-06-21, 01:43:15	Critical (3)	Unicast Ranging Received Abort Response - Re-initializing MAC;CM-MAC=14:59:c0:f6:f2:10;CMTS-MAC=00:a3:d1:5d:a0:e9;CM-QOS=1.1;CM-VER=3.1;
2020-06-21, 01:41:16	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;CM-MAC=14:59:c0:f6:f2:10;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.1;CM-VER=3.1;
2020-06-21, 01:35:28	Critical (3)	Unicast Ranging Received Abort Response - Re-initializing MAC;CM-MAC=14:59:c0:f6:f2:10;CMTS-MAC=00:a3:d1:5d:a0:e9;CM-QOS=1.1;CM-VER=3.1;
2020-06-21, 01:33:44	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;CM-MAC=14:59:c0:f6:f2:10;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.1;CM-VER=3.1;
2020-06-21, 01:32:40	Critical (3)	Unicast Ranging Received Abort Response - Re-initializing MAC;CM-MAC=14:59:c0:f6:f2:10;CMTS-MAC=00:a3:d1:5d:a0:e9;CM-QOS=1.1;CM-VER=3.1;
2020-06-21, 01:27:38	Critical (3)	Unicast Ranging Received Abort Response - Re-initializing MAC;CM-MAC=14:59:c0:f6:f2:10;CMTS-MAC=00:a3:d1:5d:a0:e9;CM-QOS=1.1;CM-VER=3.1;
2020-06-21, 01:25:54	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;CM-MAC=14:59:c0:f6:f2:10;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.1;CM-VER=3.1;
2020-06-21, 01:24:23	Critical (3)	Unicast Ranging Received Abort Response - Re-initializing MAC;CM-MAC=14:59:c0:f6:f2:10;CMTS-MAC=00:a3:d1:5d:a0:e9;CM-QOS=1.1;CM-VER=3.1;